

**Basic  
Mechanical  
Engineering  
MCQs  
Part 3**

**1) Which of the following is a power transmitting element?**

- a. Nuts and bolts
- b. Sprockets and chains
- c. Axles
- d. All of the above

**ANSWER: Sprockets and chains**

---

**2) Machine elements such as bearings are \_\_\_\_\_**

- a. holding type elements
- b. supporting type elements
- c. power transmitting elements
- d. all of the above

**ANSWER: supporting type elements**

---

**3) The shaft directly connected to the power source is called as \_\_\_\_\_**

- a. line shaft
- b. counter shaft
- c. both a. and b.
- d. none of the above

**ANSWER: line shaft**

---

**4) Which of the following is a machine shaft?**

- a. Line shaft
- b. Counter shaft

- c. Crankshaft
- d. All of the above

**ANSWER: Crankshaft**

---

**5) Which of the following statements is/are true?**

- a. Axles are used to transmit power
- b. Shafts and axles are rotating elements
- c. Shafts transmit power while axles do not transmit power
- d. All of the above

**ANSWER: Shafts transmit power while axles do not transmit power**

---

**6) Which flat belt drive system has two pulleys mounted on driven shaft and one pulley on driving shaft?**

- a. Multiple belt drive
- b. Cone pulley drive
- c. Fast and loose pulley drive
- d. None of the above

**ANSWER: Fast and loose pulley drive**

---

**7) Which of the following statements are false for belt drives?**

- 1. Belt drive is used in applications having constant speed drive
- 2. Belt drives can be used at extremely high speeds
- 3. Belt drives have low power transmitting capacity
- 4. Belt drives need continuous lubrication

- a. 1 and 2
- b. 1, 2 and 3
- c. 2, 3 and 4
- d. 1, 2 and 4

**ANSWER: 1, 2 and 4**

---

**8) Determine power rating of an electric motor if it runs at 1440 r.p.m and line shaft transmits torque of 75 Nm. Assume Reduction ratio = 1.6**

- a. 10.36 kW
- b. 11.3 kW
- c. 7.068 kW
- d. 9.12 kW

**ANSWER: 7.068 kW**

---

**9) In simple gear trains the direction of rotation of driven gear is opposite to the direction of rotation of driving gear only if\_\_\_\_\_**

- a. even number of idler gears are present
- b. odd number of idler gears are present

**ANSWER: even number of idler gears are present**

---

**10) Why is an idler gear used in gear trains?**

- a. To obtain minimum centre distance between driving and driven shaft
- b. To have required direction of rotation
- c. Both a. and b.
- d. None of the above

**ANSWER: To have required direction of rotation**

---

**11) The process of creating mechanisms and shapes of mechanical elements for a machine to get the desired output for a given input is called as \_\_\_\_**

- a. analysis
- b. innovation

- c. synthesis
- d. designing

**ANSWER: synthesis**

---

**12) Which of the following is not a reason to design and redesign a product?**

- a. Optimum design
- b. Innovation
- c. Appearance
- d. None of the above

**ANSWER: None of the above**

---

**13) In design process, which process is followed after selecting the material?**

- a. Selecting factor of safety
- b. Synthesis
- c. Analysis of forces
- d. Determining mode of failure

**ANSWER: Determining mode of failure**

---

**14) Which design consideration deals with appearance of the product?**

- a. Ergonomics
- b. Aesthetics
- c. System design
- d. Creative design

**ANSWER: Aesthetics**

---

**15) The objective of considering ergonomics in machine design is to \_\_\_\_**

- 1. decrease physical stresses

- 2. make user adapt to the machine**
- 3. make machine fit for the user**
- 4. improve appearance of the product**

- a. only 2
- b. 3 and 4
- c. 1 and 3
- d. 1, 3 and 4

**ANSWER: 1 and 3**

---

**16) Hardness of a material enables it to resist \_\_\_\_\_**

- a. abrasion
- b. penetration
- c. plastic deformation
- d. all of the above

**ANSWER: all of the above**

---

**17) The component deforming progressively under load at high temperatures is called as**

- a. Resilience
- b. Creep
- c. Fatigue
- d. All of the above

**ANSWER: Creep**

---

**18) Which of the following ferrous alloys can be casted into intricate shapes?**

- a. Plain carbon steels
- b. Alloy steels

- c. Cast irons
- d. All of the above

**ANSWER: Cast irons**

---

**19) Which of the following is not a property of copper alloy?**

- a. High electrical conductivity
- b. High thermal conductivity
- c. High strength
- d. None of the above

**ANSWER: High strength**

---

**20) What is the percentage of carbon in plain carbon steel?**

- a. 60 to 80%
- b. Less than 1.7%
- c. Less than 7%
- d. None of the above

**ANSWER: Less than 1.7%**

---

**21) What are the minimum number of kinematic pairs required in a kinematic chain?**

- a. 2 kinematic pairs
- b. 3 kinematic pairs
- c. 4 kinematic pairs
- d. None of the above

**ANSWER: 4 kinematic pairs**

---

**22) According to Grashof's law in a four bar chain, one link can complete a rotation only**

if \_\_\_\_\_

- a. (sum of longest and shortest link length)  $\geq$  (sum of the remaining two link lengths)
- b. (sum of longest and shortest link length)  $\leq$  (sum of the remaining two link lengths)
- c. (sum of longest and shortest link length) = (sum of the remaining two link lengths)
- d. None of the above

**ANSWER: (sum of longest and shortest link length)  $\leq$  (sum of the remaining two link lengths)**

---

**23) Beam engine mechanism is an example of**

- a. double crank mechanism
- b. double lever mechanism
- c. crank and lever mechanism
- d. none of the above

**ANSWER: crank and lever mechanism**

---

**24) Which of the following inversions of four bar chain, convert oscillatory motion from one lever to another lever?**

- a. Ackermann steering gear mechanism
- b. Beam engine mechanism
- c. Coupled wheels of locomotive
- d. All of the above

**ANSWER: Ackermann steering gear mechanism**

---

**25) In the slider crank mechanism shown below, link 2 is fixed. This second inversion of slider crank mechanism is observed in \_\_\_\_\_**

- a. Reciprocating air compressor
- b. I. C. engine
- c. Whitworth quick return mechanism
- d. Crank and slotted lever quick return mechanism

**ANSWER: Whitworth quick return mechanism**

---

**26) Which of the following is a not a surface finishing process?**

- a. Honing
- b. Buffing
- c. Lapping
- d. Turning

**ANSWER: Turning**

---

**27) Match the following Manufacturing processes with their Types and select the correct option.**

1. Metal forming ----- A. Grinding  
2. Surface finish ----- B. Rivetting  
3. Sheet metal working ----- C. Extrusion  
4. Metal joining ----- D. Blanking

- a. 1 – A, 2 – C, 3 – D, 4 – B  
b. 1 – C, 2 – A, 3 – D, 4 – B  
c. 1 – B, 2 – A, 3 – D, 4 – C  
d. 1 – D, 2 – B, 3 – A, 4 – C

**ANSWER: 1 – C, 2 – A, 3 – D, 4 – B**

---

**28) Which of the following factors reduce strength of casted components?**

- a. Blow holes  
b. Gas cavities  
c. Non-metallic inclusions  
d. All of the above

**ANSWER: All of the above**

---

**29) In which of the following processes, material is neither added nor removed but is deformed into desired shape?**

- a. Surface finishing process  
b. Metal forming process  
c. Casting  
d. Machining

**ANSWER: Metal forming process**

---

**30) Which of the following component(s) is/are manufactured by powder metallurgy processes?**

- a. Gears

- b.** Cutting tools
- c.** Bearing bushes
- d.** All of the above

**ANSWER: All of the above**

---