Index

AAR plate B equipment clearance diagram, 11-30	Adhesive resins, performance of (table), 6-131	Air arc gouging, 13-32
Abaca (manila fiber), 6 -137	Adhesives, 6 -130	Air cleaners, characteristics of (table), 18-16
Abampere (def), 15-2	anaerobic, 6-131	Air compression, 14-28
Aberrations, 19-43	classification of (table), 6-130	multistage: power required in, 14-29
chromatic, 19-43	elastomeric, 6-131	theory of, 4 -12
spherical, 19-43	pressure-sensitive, 6 -131	power required for, 14-29
Ablators (heat-resisting materials), 6 -151	properties of (table), 6 -132	theory of, 4 -12
Abrasive cutoff wheels, 13-61	thermosetting, 6 -131	work of, 4 -12
Abrasive paper, 6 -130	uses of, 6 -130	Air compressors:
Abrasive tools (wood sanding), 13-75	table, 6 -132	centrifugal (see Centrifugal compressors)
Abrasive wheels (<i>see</i> Grinding wheels)	Adiabatic expansion of gases, 4 -9	efficiency of, 14 -29, 14 -30, 14 -38
Abrasives, 6-128	Admiralty brass (table), 6 -68	lubrication of, 14 -32
artificial, 6 -128	Admittance (electric circuits, def), 15 -3, 15 -19	oils for, 6 -184
coated, 6 -130	Advance (resistor alloy), 15 -61	rotary-vane, 14 -33
grains for, manufacture of, 6 -128	table, 15 -61	unloaders for, 14 -33
ABS resins: properties of (table), 6 -186	Aerodynamics (def), 11 -59	uses for, 14-28
ABS/Nylon resins: properties of (table), 6 -186	axes used in, 11-60	valves for, 14- 28
Absolute-pressure gages, 16 -9	coefficients in, 11-60	Air conditioning, 12 -71
Absolute systems (mechanics, def), 3-2	hypersonic (def), 11 -59	absorption systems, water and lithium
Absolute temperature scale, 4-2	(See also Supersonic and hypersonic aero-	bromide, 19 -17
Absolute zero, inferred, 15 -5	dynamics)	air distribution in, 12-89
Absorber, in refrigeration systems, 19 -17	speed in, 11-60	air infiltration (tables), 12 -68, 12 -69
Absorptance (heat, def), 4-62	subsonic (See also Airfoils)	atmospheric cooling for, 12 -92
Absorption:	supersonic (def), 11-59	of automobiles, 11 -16
coefficient of (sound), 12 -120	(See also Supersonic and hypersonic aero-	chilled-water systems, water distribution in,
of gases by water, 6 -7	dynamics)	12 -92
of light (def), 12 -99	transonic (def), 11-59	of cold storage rooms, 19-23
Absorption dynamometers, 16 -15	Aeronautics (see Airplanes)	comfort indexes for: ASHRAE comfort chart,
Absorption machines, refrigeration, 19 -17	Aerosols, particle sizes in, 18 -10	12 -62
Absorption refrigerators, 4 -18	Afterburners (jet engines), 11-83	effective temperature (chart), 12 -62
Absorptivity (heat, def), 4 -62	effect of, 11-83	temperature-humidity index, 12 -62
Acceleration (def), 3 -10	Aftercondensers, 9-82	cooling load formulas for, 12 -71
angular (def), 3-12	Agglomeration test (coal), 7-2	cooling loads for (table), 12-78
composition of, 3 -10, 3 -11, 3 -13	Aggregates for concrete, 6 -161	cooling towers for, 12 -92
conversion (table), 1-33	Aging of steel (hysteresis), 15 -10	duct air velocities (table), 12-89
causing curvilinear motion, 3-11	after temper rolling, 6-26	ducts, friction of air in (charts), 12-88, 12-89
equivalents (table), 1-32	AGMA gear standards, 8-100	ductwork for, 12-88
of gravity, 1 -25, 3 -2	Air:	fans for, 12 -89, 14 -50
measurement of, 16-17	ambient, quality standards for (table), 18-7	filters for, 12-91
resolution of, 3-11	composition of (table), 6-10	table, 12 -91
units of, 1 -18	dehumidification of, 4 -17	heat gain, 12 -73
Acceleration resistance (train), 11-39	by surface cooler, 4 -17	from appliances (table), 12-83, 12-84
Acceleration-time curve (kinematics), 3-10	density of (def), 4-15	from computer equipment (table), 12-83
Accelerometers, 3-78	at altitudes (table), 11-60	from electric motors (table), 12-85
Accidents: prevention of, 18-19 to 18-21	formula, 14 -45	factors for (table), 12-77
Accounting (see Cost accounting)	in ducts, friction in (charts), 12-88, 12-89	from lighting fixtures (charts), 12-73
Accumulators, hydraulic, 8 -39	enthalpy-pressure diagram for (chart), 4 -34	from occupants (table), 12-82
Acetal resins: properties of (table), 6 -187	heat transfer coefficients to or from, 4-84	from office equipment (table), 12 -83
Acetone (solvent), 6 -149	humidification of, spray chambers for, 4-17	from people (table), 12-82
Acid number of lubricating oil, 6 -179	ideal-gas, enthalpy and psi functions for	from restaurant appliances (table), 12 -84
Ackerman steering gear (automobiles), 11 -12	(table), 4 -31	through roofs (tables), 12 -74
Acme screw threads, 8-16	internal energy of (table), 4-28	through sunlit walls (table), 12 -72
Acoustics, in industrial plants, 12-16	liquefaction of, 19-26	heat rejection, 12 -91
(See also Sound)	moist, properties of, 4 -15	equipment for, 12 -91
Acrylic fibers, 6 -140	pressure of, at altitudes (table), 11-60	diagrams, 12 -91
Acrylic resins: properties of (table), 6 -188	solubility, in water, 6 -7	piping for, 12 -96
Acrylonitrile resins: properties of (table), 6 -188	surface conductance (table), 12 -70	friction losses in (charts), 12 -94, 12 -95
Active power (a-c circuits, def), 15 -2	surface resistance (table), 12 -70	of industrial plants, 12-13
Actuators, hydraulic, 8 -39	temperature at altitudes (table), 11 -60	inside design conditions (table), 12 -63
ACV (air cushion vehicles), 11 -58	temperature at artitudes (table), 11-66 temperature-entropy chart for, 4-32	makeup water for, 12 -91
Ada (computer language), 2-53	thermal conductivity of (table), 4-82, 4-85	moisture infiltration, 12-64
Addendum (gear teeth), 8 -88	velocity pressure, 14 -45	moisture load in, 12-85
Adhesion, coefficient of (locomotives), 11 -24	and water-vapor mixtures, 4 -15	outdoor air requirements (table), 12 -67
randon, coefficient of (locomotives), 11-24	and rater raper mixtures, 7-15	saldoor air requirements (table), 12-0/

1

Air conditioning, (Cont.):	Aircraft propellers (Cont.):	Airplanes (Cont.):
outside design temperatures (charts), 12-64,	blades, 11 -98	fuselage of, drag of, 11-69
12 -65	construction of, 11-98	gas turbines for, 9-124
overall heat-transfer coefficients (table), 12-70	centrifugal loads on, 11-98	gyrocompasses for, 3 -20
power input to (table), 12-92	coefficients for, 11-97	jet propulsion (see Aircraft jet propulsion)
processes, 4-16	power, 11 -97	landing speed of, 11-65
psychrometric chart for, 12-86	thrust, 11 -97	parasite drag of (def), 11-66
return face air velocities (table), 12 -89	torque, 11 -97	performance of, 11-65
supply-air rate, 12-87	control, 11 -99	with jet thrust, 11-66
supply-air temperature, 12 -87	beta, 11 -99	typical (table), 11 -67
Air ejectors, 9-82	counterweights, 11-98	power: available, 11 -65, 11 -66
capacities of (table), 9 -83	design, 11-98	table, 11 -66
hogging, 9-83	ENT (emergency negative thrust), 11 -99	range of (table), 11-67
materials for, 9 -83	excitation factor, 11-98	
		speed of (table), 11 -67
performance of, 9-82	fatigue strength, 11-98	stability, 11-70
priming, 9 -83	feathering, 11-99	stalling angle, 11-62
steam jet pressure for, 9 -82	gyroscopic forces on, 3-20, 11-99	stalling speed, 11-65
types of, 9 -82	hubs for, 11 -98	static stability, 11 -70, 11 -71
Air heaters, in furnaces, soot blowers for, 9-31	mechanical design, 11-98	struts, drag of, 11-68
Air meters, 16 -13	performance characteristics of, 11-96	tail surfaces, drag, 11-69
Air motor hoists, 10-14	advance ratio, 11-96	turn-indicator, 3-20
Air pollution, 18-7	velocity coefficient, 11-96	wings: delta, 11 -78
characteristics of (chart), 18-9	performance of, 11-97	drag of, 11-62, 11-69
classification of, 18 -10	compressibility effects, 11-97	flaps and slots, 11-64
control of, in industries, 18-15	noise, 11-98	scale effect, 11-63
from diesel engines, 9-120	reverse thrust, 11 -97	chart, 11 -63
dispersion from stacks, 18 -14, 18 -15	static thrust, 11-97	sections, 11-62, 11-77
effects on vegetation, 18 -12	pitch change mechanism for, 11 -98	(See also Airfoils)
emission standards for passenger cars and light	resonance, 11-98	,
	,	wire, streamline, drag (chart, table), 11 -69
trucks (table), 9-123	reversing, 11-99	Airslide conveyors, 10-54
fans for control of, 14-50	slipstream contraction, 11-95	AJM (abrasive-jet machining), 13 -67
from gasoline engines, 9-119	store damage, 11-98	Albumin glue (table), 6 -130
from heavy-duty engines, 9-124	vibratory stresses in, 11-98	Alclad alloys (aluminum), 6 -56, 6 -58
from internal-combustion engines, 9 -119	Airflow, through orifices, 4 -20	Alcohol, 6 -148
from light duty engines, 9 -124	Airfoils, 11-61	air for combustion of (table), 4 -27
particle sizing in, 18 -10	aerodynamic forces on, 11-60	compressibility, 6 -9
by power plants, 17-34	angle of attack (def), 11-61	denatured, 6 -141, 6 -148
principal pollutants (table), 18 -7	aspect ratio (def), 11-61	heat of combustion of (table), 4-26
sources of, 18-7	boundary layer control, 11-64	products of combustion of (table), 4-27
domestic, 18-8	camber line of, 11-62	solvents, 6 -148
table, 18 -8	characteristics of, 11-62	specific gravity and density (table), 6-8
industrial (table), 18 -8	drag (def), 11 -60 to 11 -62	wood, 6 -142, 6 -148
sulfur effects, 18 -12 to 18 -15	dynamic pressure (def), 11-61	Algol (computer language), 2 -53
from transportation engines (table), 9 -119	flaps and slots in, 11-64	Alkali cleansers, 6 -137
(See also Environmental control)	induced drag (def), 11-62	Alkalinity of boiler water, 9 -49
Air preheaters (boilers), 9-43	lift (def), 11 -60, 11 -61	All-day efficiency (transformers, def), 15 -35
	moment (def), 11 -60, 11 -61	Allowance (def), 8-43
Air resistance: of automobiles, 11-4		
Aircraft (def), 11-59	pressure distribution on, 11-64	for various types of fit, 8-43
Aircraft jet propulsion, 11-81	profile drag, 11-62	table, 8 -44
efficiency and power of, 11 -89	sections, properties of (charts), 11-63	Alloys:
equations, notation, 11-87	stagnation point (def), 11 -61	aluminum, 6 -53
fuels, 7 -13	stalling angle, 11-62	antifriction, 6 -61
ramjet, 11-82, 11-90	transonic, 11-63	for castings, 13-6
performance of, 11-90	wing section, selection of, 11 -62	copper, 6 -65
rocket engines, 11-85	Airplane propellers (see Aircraft propellers)	for bearings (table), 6 -61
electric, 11-86	Airplanes (def), 11-59	manufacturing properties of (table), 13 -12
electromagnetic, 11-87	aerodynamic forces on, 11-60	creep rates in (table), 5-11
electrostatic, 11-87	supersonic and hypersonic, 11-72	fusible (table), 6 -75
electrothermal, 11-87	ceiling, 11-66	for high temperature, 6 -77
liquid propellants, 11-85	climbing rate, 11-66	superalloys (tables), 6 -78 to 6 -80
nuclear heat-transfer, 11-86	climbing time, 11-66	lead, 6 -74
performance of, 11-93	compasses for (gyroscopic), 3 -20	magnesium, 6 -53
propellant combinations (table), 11 -86	control of, 11 -70	nickel, 6-88
scramjet, 11-82	dimensions of (table), 11 -67	nonferrous, 6 -49
solid propellant, 11 -85, 11 -94	drag of, 11-62, 11-66	hardening, 6 -52
thermal air-jet systems, 11-82	(See also Airfoils; Drag)	heat-treatment of, 6- 52 manufacturing properties of (table), 13- 13
thrust equations, 11-89	dynamic stability of, 11 -70, 11 -71	
turbofan, 11-83	engines for, 9-102	resistivity (table), 15-4
performance of, 11-92	carburetors, 9 -109	for resistor materials, 15 -61
turbojet, 11 -83	cooling, 9-118	specific gravity and density (table), 6-7
performance of, 11-90	drag of, 11 -69	steel, manufacturing properties of (table), 13 -12
Aircraft propellers:	table, 9 -102	(See also Steel, alloys)
aerodynamic theories: axial-momentum, 11-95	flaps and slots for, 11-64	superplastic, 5-11
blade element, 11-95	flaps for, table, 11-64	titanium, 6 -91
vortex, 11 -96	floats (seaplane), drag of, 11-69	zinc, 6 -93

Alnico (magnet material), 15-62	Ammonia (Cont.):	Annulus:
Alpha iron (def), 6 -16	saturated: properties of (table), 19-6	area of, 2 -7
Alpha particles, atomic, 9-134	superheated: properties of (table), 19 -5	number of contiguous circles in, 2-7
Alphabets:	Ammonia absorption machines, 19 -17	Anodizing, 6-111
German, 19 -44	Ammonia compressors:	Anomalistic year, 1-25
Greek, 19 -44 script, 19 -44	condenser pressure (table), 19 -15 horsepower per ton of refrigeration (table),	ANSI method of generator voltage regulation, 15 -32, 15 -33
Alternating-current instruments, 15 -21	19 -15	Anthracite (see Coal, anthracite)
Alternating currents (see Circuits, alternating-	volume of gas per ton of refrigeration (table),	Antifriction alloys, 6 -61
current; Currents, alternating; Electric	19-15	Antifriction curve, Schiele's, 2-23
motors; Generators)	Ammonia dynamites, 7-20	Antioch process (molding), 13-3
Alternation, electric current (def), 15 -18	Ammonia gelatins in explosives, 7-21	Antirolling gyroscopes (ships), 3-20
Alternators, 15-66	Amortisseur windings (a-c armatures),	Anvils, steam-hammer, 13-22
Altitude:	15-34	Aperiodic decay (def), 3-63
air volume correction factors due to (table),	Ampere (def), 1-17, 15-2	Aperture (optics), 19-41
12- 91 solar (table), 9 -12	Ampere-turn (def), 15 -4 Amplidyne (d-c generator), 15 -26	of lenses, 19 -41 numerical, 19 -42
variation of atmospheric pressure and tempera-	Amplification (def), 16 -22	API (American Petroleum Institute) scale (spe
ture with (table), 11-60	Amplifiers:	cific gravity) conversion tables, 1 -26
ALU (arithmetic logic unit), 15-80	difference, 15 -76	Apothecaries' liquid measure, 1 -16
Alumina brick, 6-151	differential (electronic circuit), 15-73	Apothecaries' weight, 1-17
Aluminum:	high-gain operational, 16-29	Apparent power (a-c circuits, def), 15-2,
conductors of, 6 -60, 15 -6	instrumentation, 15 -77	15 -18
table, 6 -60, 15 -49	radio, 15 -72	Apron conveyors, 10-44
current-carrying capacities for (table),	transistor, 15-69	table, 10 -45
15 -57	two-stage, 15-73	Aquifers, for water storage, 6 -169
corrosion resistance of, 6 -56	AMS specifications, for stainless steel, chemical	Arc furnaces, 7-52, 7-55
painting and lacquering of, 6-59	composition (table), 6 -34 Analog computers, 2 -40, 2 -53	Arc welding (see Welding, arc) Arch beams, 5-42
plastic range chart for, 13 -10 soldering of, 6 -56	Analog computers, 2-40, 2-33 Analog-to-digital converters, 16 -20	Arches:
tubing of, 8 -191	Analysis:	furnace, 6 -154
welding of, 6 -56, 13 -44	dimensional, 3-44 to 3-46	masonry, laying of, 12 -28
Aluminum alloys, 6 -53	of factory operations, 17-26	Archimedean spiral, 2 -23
aging, 6- 53	factors in, 17 -27	Arcs:
anodizing treatment of, 6-58	Analytical geometry, 2-18 to 2-24	circular, center of gravity of, 3-6
castings, composition and properties of	Anchor ring, volume and area, 2-10	of contact (belts), 8-53
(tables), 6 -57 to 6 -60	Ancit process (coke making), 7-35	Arcsine, 2-17
designations, 6 -53	Anemometers, 16-15	Arctangent, 2-17
die-casting, 6 -56	ANFO (explosive), 7-20	Are (def), 1-19
table, 6 -60	Angle of attack (aerodynamics, def), 11 -61	Area, units of, 1-16
heat-treatment (tables), 6 -53, 6 -54	induced, 11-61	Area meters, fluid flow, 16 -14
machining, 6 -56 magnesium, 6 -53	Angle of stall (airfoils, def), 11 -62 Angle valves, 8 -206	AREA railway line clearances, 11-38 Areas:
mold-casting, 6 -56	Angles:	centers of gravity for, 3 -6, 3 -7
protection, 6 -56	analytical geometry formulas, 2 -19	conversion tables, 1-30
riveting, 6 -56	bisection of, 2 -6	equivalent (table), 1 -30
silicon, 6 -53	complementary (def), 2-14	measurement of, 1 -16, 16 -7
soldering of, 6 -56	congruent (def), 2-14	methods of calculating, 2-7, 2-29, 2-30
strength at high temperatures (table), 6-55	conversion tables for, 1-15	moments of inertia of, 3-8
welding of, 6 -56, 13 -44	dihedral, 2-5	plane: centers of gravity of, 3-6, 3-7
wrought, 6 -53	half, functions of, 2-16	by graphics, 3 -9, 3 -10
composition and properties of (table), 6 -54	measurement of (surveying), 16 -53	moments of inertia of, by graphics, 3-9,
Aluminum brass: composition and properties of	units for, 2-15	3-10
(table), 6 -68 Aluminum bronze, 6 -67	multiple, functions of, 2 -16 negative, functions of, 2 -16	of similar figures, 2-5 of solids, 2-8 to 2-10
for bearings, 6 -61	solid, 2 -9	Arithmetic. 2-4
composition and properties of (table), 6 -68	steel: radii of gyration for two (tables), 12 -41,	fixed point, 2-41
Aluminum oxide, for wood sanding, 13-75	12-42	floating point, 2-41
Aluminum paint, 6 -109	with unequal legs (table), 12 -40	laws of, 2 -4
Aluminum pipe (table), 8-192	used as beams, 12-42	Arkansas oilstones, 6-129
Alundum (abrasive), 6 -130	tables, 12 -39 to 12 -42	Armature leakage reactance, 15-32
Amatol (explosive), 7-21	structural steel (tables), 12-39 to 12-42	Armature reactance and resistance, a-c genera-
American farm windmill, 9-6	sum and difference of, 2-16	tors, 15 -32
American National Standard pipe threads, 8-17	supplementary (def), 2-14	Armature reaction, 15 -29, 15 -32
American Standard wire gage, 15 -5	trigonometric formulas, 2-15	Arms, flywheel, 8-50
table, 8 -85 American Unified screw threads, 8 -8	Angular acceleration (def), 3-12 Angular displacement (def), 3-12	Artificial intelligence, 2 -52 Asbestos, 6 -139
American wire gage, copper wire sizes (table),	Angular momentum (def), 3-18	as brake material, friction of, 3-22
15-5	Angular momentum (der), 3-18 Angular velocity, 3-12	as magnet wire insulation, 15-65
Ammeters, 15 -20, 15 -21, 16 -16	conversion factors (table), 1 -32	specific gravity and density of (table), 6 -8
Ammonia:	Annealing:	thermal conductivity of (table), 4 -83
pipes for, valves and fittings, 8 -205	of nonferrous metals, 6 -52	Asbestos-cement pipes, 8 -194
properties of (chart), 4-34	of steel, 6 -17	Asbestos shingles, 6 -146
saturated (table), 4-33	Annual reports, 17-12	ASCII codes, 16-21
as refrigerant, 4 -24, 19 -3	Annuity tables, 1-7, 1-8	table, 2 -42

Ash:	Atomic number (def), 6-5	Automatic control, LQG/LTR systems,
coal, 9 -29	of elements (table), 6 -3	(Cont.):
tables, 7-4, 7-6	of metals (table), 6 -50	rise time, 16 -25
combustibles in, 9-35	Atomic power (see Power plants, nuclear)	robustness (def), 16-40
heat loss due to (chart), 9-35	Atomic reactors (see Reactors)	properties, 16-40
content in fuel oil, 9-31	Atomic weights:	sampled-data systems, 16 -38
analysis (table), 9-31	of elements (table), 6 -3	stability of, 16-39
deposits, 9-30	of metals (table), 6-50	signal flow representations, 16-28
eastern, 9-30	Attemperation of steam, 9-44	stability and performance of, 16 -37
effect of fuel additives on, 9-31	Attemperators, submerged-type, 9-45	gain margin (def), 16 -38
furnace fouling by, 9-30	Attenuation (automatic control, def), 16 -22	Nyquist stability criterion, 16 -37
fusibility, 7 -6	Attraction, laws of, 3 -19	phase margin (def), 16 -37
table, 7 -6	Austenite (def), 6 -16	Routh's stability criterion, 16 -38
lignitic, 9-30	grain size, 6 -18	steady-state performance, 16 -32
Ash collectors, 9-32	influence of alloys on (table), 6 -20	time constants in, 16 -26
Ash conveyors, pneumatic, 10 -53	Authority:	transient analysis of system, 16 -24
Ashlar masonry (table), 12 -28	functional (def), 17 -2	overshoot, 16 -25
ASHRAE comfort chart, 12 -62	staff (def), 17 -2	transient frequency, 16 -25
ASIC (application-specific integrated circuit),	Autofacturing, 17 -21	viscous-damped, 16-24
15-82	Autogiros (def), 11-59	z transformation, 16 -38
ASME specifications, for stainless steel (table),	Autoignition temperatures (gaseous fuels),	Automatic control systems (def), 16 -22
6 -37	9-115	Automatic controllers (def), 16 -22
Aspect ratio (aerodynamics, def), 11 -61	Automated storage and retrieval systems	Automatic guided vehicles, 10-56
Asphalt, 6-144	(materials handling), 10 -73	Automatic pilot (gyroscope), 3-20
roofing, 6-145	Automatic control:	Automatic vehicles (materials handling), 10 -36,
Asphaltum, specific gravity and density (table),	actuators for, 16 -30	10-56
6-8	basic system, 16 -22	Automobile engines, 9-94, 9-96
Assay ton (def), 1-17	block-diagrams for, 16 -27, 16 -32	in buses, 9 -97
Astigmatism (optics, def), 19 -43	algebra, 16 -27	compression, 9-93
ASTM specifications:	representation, 16 -27	compression ratio (tables), 9 -96
for alloy-steel castings (table), 6 -48	closed-loop, 16 -22	cooling, 9 -95, 9 -96, 9 -117
for brick (table), 6 -136	block-diagrams for, 16 -32	cylinders, 9 -95, 9 -111
for cement, 6 -159, 6 -160	commands, 16 -22	firing orders, 9-114
for chains (table), 10 -5, 10 -6	compensation: derivative, 16 -25	foreign, 9 -96
high-test, 10-5	error, 16 -26	table, 9 -96
proof-coil, 10 -5	input, 16 -26	fuel consumption (charts), 11- 5 to 11- 7
transport, 10-5	output, 16 -26	ignition, 9 -114, 15 -66
for commercial zinc (table), 6 -93	integral, 16 -26	lubrication of, 9-118
for copper wire, table, 6 -67	error, 16 -26	passenger-car data, 9-95
for fire resistance, 18 -24	definition of terms, 16 -22	pollution from, 18 -8 to 18 -10
for gypsum plaster, 6 -163	error coefficients, 16 -32	power (tables), 9-96
for Portland cement (table), 6-160	final control elements for, 16 -30	valve timing, 9-95
for stainless steel, chemical composition	frequency response, 16-33	Automobiles, 11-3
(table), 6 -34	equations for common elements (table),	acceleration, 11-5
mechanical properties (table), 6-34	16 -36	aero horsepower of, 11-4
for standard sieves (proportioning concrete,	graphical display, 16-34	air conditioning for, 11 -16
table), 6 -161	Bode diagrams, 16-34	cool-down test for, 11-17
for steel, 6 -26	Nyquist plots, 16-34	refrigeration capacity required,
tables, 6 -26	polar plots, 16-34	11 -17
structural, 6 -26, 12 -33	linear quadratic regulators, 16 -43	antilock brakes for, 11-16
for locomotives (table), 6-26	performance index for, 16 -44	body construction, 11-17
for ships (table), 6 -26	LQG/LTR systems, 16-40	brakes, 11 -13
for steel castings, 6-48	command following in, 16-42	adjustment, 11-14
Astroid, 2-22	compensator design procedure for, 16-44	caliper-disk, 11-15
Astronautics, 11-100	control systems analysis for, 16 -48	drums, 11 -14
(See also Space)	controllability of, 16 -41	hydraulic, 11-14
Astronomical unit (def), 11 -101	detectability of, 16-41	internal-expanding, 11-14
Asymptote:	example of, 16 -45	parking, 11 -14
of hyperbola, 2 -20	LQG controller design for, 16 -46	pedal pressure for, 11 -15
of tractrix, 2-23	LQG/LTR controller design for, 16 -46	power, 11 -15
Atgas process (gasification), 7 -35	multiplicative uncertainty of, 16 -43	self-energizing, 11 -14
Atmosphere:	noise rejection in, 16 -42	service, 11-14
control of, in industrial furnaces, 7-44	observability of, 16 -41	shoes, 11 -14
impurities in (chart), 18 -9	performance robustness of, 16 -41	split systems, 11 -14
international standard (table), 4 -33	PI controller design for, 16 -47	stopping distance (tables), 11 -14
of planets (table), 11 -107	precompensator design for, 16 -47	braking of, force required during, 11 -13
protective gas (heat treating, table), 7 -45	robustness of, 16 -40	reaction time in, 11 -13
standard (COESA, def), 11-59	stability robustness of, 16 -42	characteristics purchased, 11 -3
table, 11 -60	stabilizability of, 16 -41	
	modes vs. process characteristics (table),	cooling, 11-16 dimensions of, 11-3
upper, data on (COESA), 11-59	1 ''	
variation with altitude (table), 11 -60	16-33 nomanglatura 16-22	drag coefficients for (chart), 11-4
Atmospheric corrosion, 6-98	nomenclature, 16 -22	engines (see Automobile engines)
Atom (def), 6 -3, 9 -133	peak overshoot, 16 -25	features, 11-3
Atomic energy:	peak time, 16 -25	foreign, 9 -96
fusion systems, 9-148	pneumatic systems, 16 -28, 16 -30	front suspensions for, 11 -11
(See also Power plants, nuclear)	process characteristics for (table), 16 -33	front-wheel drive for, 11 -10

Automobiles (Cont.):	Babcock coefficient of friction (steam flow), 4-23	Batteries, storage, (Cont.):
fuel consumption of, 11-5	Backhoes, loaders with, 10-25	specific gravity for electrolyte, 15-13
charts, 11-5 to 11-7	Bagasse, as fuel, 7-10	stationary, 15-14
gear ratios for, 11-5	Bainite (def), 6 -18	voltage of, 15 -13
heating for, 11 -16	Balance:	Baumé scale (specific gravity), conversion
materials used in (table), 11-18	dynamic, 3 -15, 3 -67	tables, 1 -27
McPherson struts in, 11-11	standing, 3-15	Bauschinger effect, 5 -5
microprocessors in, 15-68	static, 3-66	Beam and crank mechanisms, 8-3
miles driven, 11-3	Balances:	Beam lengths:
rear axles, 11-10	equal arm, 16 -3	mean (radiation), 4-68
differentials for, 11 -10	spring, 16 -4	table, 4 -69
semifloating, 11 -10	torsion, 16-4	Beams, 5-20
rear suspensions, 11-11	Balancing, 3-15	angles used as, 12-42
registration in the United States, 11-3	of machines, 3-66	bending moment, 5-21
resistance, 11-3 air, 11-4	rotating, 3-65, 3-66 steam turbines, 9-62	cantilever (def), 5-21
tires, 11 -4	Ball bearings (<i>see</i> Bearings, rolling contact)	connections in steel-framed structures, 12 -43 constrained, 5 -32
starting and lighting systems, 15 -66	Ball-mill grindability test for coal, 7 -7	continuous, 5-32
steering, 11 -12	Ball valves (pump), 14 -13	uniformly loaded (table), 5 -33
Ackermann, 11 -12	Ballasts:	curved, strength of, 5 -42
power, 11 -12	for fluorescent lamps, 12 -101	deflection of, 5 -28, 12 -34
oil pumps for, 11 -13	instant start, 12-101	Castigliano's theorem, 5-36, 5-42
road feel of, 11 -13	rapid start, 12 -102	curve for, 5 -28, 5 -31
rack-and-pinion, 11-12	Balsa, as insulation, 6 -150	diagram, 5-22
recirculating ball, 11-12	Banana oil, 6 -149	formulas, 5-29
worm and roller. 11 -12	Band brakes, 8-41	as function of stress, 5-30
tires for (table), 11-4	friction of, 3-28	graphical method, 5-31
inflation pressure (table), 11-4	Band clutches, 8-39	Maxwell's theorem, 5 -36
(See also Tires)	Band saws, metal, 13-61	design of, 5-21
traction control for, 11-16	Bar codes, 10 -62	factors governing, 5-28
traction required in, 11-3, 11-5	Code 49, 10 -67	elastic curve, 5 -28
transmissions, 11-6	Code One, 10 -68	I (see I beams)
automatic, 11-9	Code 128, 10 -62	internal moment beyond elastic limit, 5-26
fluid couplings, 11-6	Code PDF417, 10 -67	internal resilience, formula, 5 -32
friction clutches, 11-6	Code 16K, 10 -67	loads and reactions, 5-21
manual, 11 -8	Code 39, 10 -62	diagram, 5 -31
gear ratios, 11-9	Data Matrix, 10-67	oblique, 5-22
synchromesh, 11-8	interleaved 2-of-5, 10 -62	rolling or moving, 5-32
overdrives, 11-9	scanners for, 10 -69, 10 -70	moment and shear diagrams for, 5-22 to 5-25,
torque converter, 11-7	2-of-5, 10 -62	5-32 to 5-36
trucks (see Trucks)	U.P.C., 10 -63	moments of inertia of various sections (table),
turning radius, 11-12	Barn (unit of nuclear cross section, def),	5-27
ventilation, 11-16	9-140 Parameters 3 24	neutral axis in (def), 5-21
wheel alignment, 11-12	Barometers, 3 -34 mercury, 16 -8	neutral plane and line of (def), 5-21
camber (def), 11 -12 caster (def), 11 -12	Barometric condensers, 9-81	radii of gyration of various sections, 5-27 rectangular, uniformly loaded, safe loads
toe-in (def), 11-12	Barrel, standard (def), 1 -16	(table), 5-25
Autotransformers, 15-36	BATEA (best available technology economically	reinforced-concrete, 12 -52
for squirrel-cage motors, 15 -37	achievable), 18- 5	resilience, 5-32
Available heat (def), 4 -6	Batteries, 15 -11	per unit volume (table), 5 -17
in steam engine cycle, 4 -19	dry, 15 -11	section modulus (def), 5-21
Aviation fuels, 7-13	block assembly, 15 -11	tables, 5 -27
Avogadro's number (def), 4-3	effect of temperature, 15 -12	sections, properties of (tables), 5 -27
Avoirdupois weight, 1-17	efficiency of, 15-11	shear in, 5 -21
AWG (American Wire Gauge), 15-5	flashlight, 15-12	shear diagram, 5-31
AWS specifications, for stainless steel, chemical	radio B, 15 -11	simple (def), 5-21
composition (table), 6 -34	Ruben-cell, 15 -12	slope diagram, 5 -31
Axial fans, 14 -44, 14 -45	electrodes, 15-11	steel, deflections (tables), 5-26, 12-47
characteristic curves, 14 -48	electromotive force of, 15 -11	maximum safe load on, 5-21
efficiency of (chart), 14 -48	Exide Ironclad, 15-14	table, 5 -26
formulas, 14 -45	ignition system, 15 -66	properties of (tables), 12 -35
performance curves for, 12-89, 12-90	polarization, 15 -11	proportions of, 12-34
Axial-flow pumps, 14 -15	poles, 15 -11	safe loads, 5 -21, 12 -42
Axis:	storage, 15 -13	table, 5 -26
of inertia, principal (def), 3-8 optical, 19-41	capacity of (table), 15 -14	short, calculation of, 12 -42
of oscillation, 3-16	care of, 15 -14, 15 -15	supports for, 12 -43 web connections for, 12 -43
Axles, of automobiles, 11 -10	charging, 15 -14, 15 -15 Edison, 15 -13, 15 -14	
Axies, of automobiles, 11-10 Azimuth (def), 16-54	efficiency of, 15 -14	stiffness of, 3 -73, 5 -30 strength of (formula), 5 -21
back (def), 16 -54	for mine locomotives, 10 -21	theory of flexure in, 5-21
solar (table), 9 -12	Nicad, 15 -13, 15 -15	uniform cross section: bending moments
55.11 (11010), 7 12	pasted-plate type, 15 -13	(table), 5-22 to 5-25
	Planté, 15 -13	vertical shear (table), 5 -22 to 5 -25
	portable, 15 -14	uniform strength, 5-36
Babbitt linings in large bearings, 8-122	rechargeable, 15 -15	table, 5 -34
Babbitt metal (table), 6 -61	removal from service, 15-14	vibration, 3 -73

woodcal, 32-28, 12-29 properties of (tables), 12-29 grouperties of (tables), 12-29 groupertie	Beams (Cont.):	Bearings (Cont.):	Belts (Cont.):
properties of (table), 12-29 safe loads (table), 25-3 safe loads (table), 25-3 safe loads (table), 25-3 safe loads (table), 25-3 safe loads (table), 25-4 safe loads (table), 26-1 safe loads (table), 26-1 safe loads (table), 6-61 suppose between the loads (table), 6-61 metal-poorder-sintened, oil-imprognated miscellamouns, 6-61 pooras, 6-61 grouns, 6-61 pooras, 6-61 p			
Bearing eache, 6-61 adminum alloys, 6-61 adminum alloys, 6-61 amel provider sintered, 6-10 metal powder sintered, 6-12 blain, 8-12 metal field, 8-12 metal field			
Bearing mentals, 6-61 adminism [1986, 6-61] adminism [1986, 6-61] adminism [1986, 6-61] ambilit (rable), 6-61 ambilit (rable), 6-61 ambilit (rable), 6-63 miscellaneous, 6-64 porous, 6-63 miscellaneous, 6-64 porous, 6-64 porous, 6-63 miscellaneous of soils and rock (table), 12-26 Bearings, 8-116, 8-132 dolls, 1-8-132 dolls, 1-8-134 fixt (table), 8-137 fixt (table), 8-137 missilla (table), 8-138 dolls, 1-8-132	safe loads (table), 5-25	(See also Bearings, rolling contact)	graphical methods of determining, 8-52
adminum alloys, 6-61 ababitt (table), 6-61 copper base (table), 6-61 copper base (table), 6-61 copper base (table), 6-61 copper base (table), 6-62 c			
babbit (table), 6-61 motal powder-aintered, old-limpregnated limits, old-limpregnated			,
oopper-base (table), 6-61 metal-powder-sintered oil-impregnated (table), 6-63 closures, 8-132 closures, 8-135 closures, 8-135 closures, 8-135 closures, 8-135 closures, 8-135 closures, 8-135 closures, 8-136 closures, 8-137 closures, 8-138			
meial-powder-sintered, oil-lampegnated (shale,) 6-63 miscellaneous, 6-63 miscellaneous, 6-63 miscellaneous, 6-63 miscellaneous, 6-63 composens, 8-132 composens, 8-132 composens, 8-132 miscellaneous, 6-64 miscellaneous, 6-65 mi		· · · · · · · · · · · · · · · · · · ·	
(uble), 6-63 miscellaneous, 6-61 porous, 6-62 porous, 6-6			
Comparable Dearing pressures of soils and rock (table), 12-26			
(i) Ge ado Babbitt, Brass; Bronze Bearings, 8-113c and rock (table), 12-26 Bearings, 8-116, 8-152 and rock (table), 12-26 bearings, 12-26 bearings, 12-26 bear dissipation from, 8-120 beart distriction, 8-125 propoler shaft, 11-57 propoler s			
Bearing pressures of soils and rock (table), 12-26 ball, 8-132 bal			
Bearings, 8-116, 8-132 (See also Bearings, rolling contact) for centifugal pumps, 14-19 closures for, 8-136 fitticion in, 3-27, 8-119 gas-lubricated, 8-127 compressibility parameter, 8-128 thrus, 8-127, 8-130 whirt stability of, 8-128 guide, 8-116 policy and the stability of, 8-128 guide, 8-116 policy and the stability of, 8-128 guide, 8-118 babbit finings, 8-122 clearance, 8-118 clements of, 8-122 clearance, 8-118 clements of, 8-122 clearance, 8-118 supplies-bluricated, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 load distribution, 8-126 length-diameter ratios, 8-118 load distribution, 8-125 porous-metal, 8-125 propoller shuft, 11-57 seads, 8-124 types of, 8-125 propoller shuft, 11-57 seads, 8-124 types of, 8-127 propoller shuft, 11-57 seads, 8-126 fiffilm thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 minimum oil feed			
ball, 8-132 (See das Bearings, rolling contact) for centrifugal pumps, 14-19 (fits (table), 8-137 friction, 8-136 conical, friction, 3-27 (ordinated), 8-136 loads and ratings, 8-138 loads and ratings, 8-137 tables, 8-138 loads and ratings, 8-137 markins, 8-127, 8-130 loads and ratings, 8-137 markins, 8-127, 8-130 loads and ratings, 8-137 markins, 8-128 maximum capacity, 8-132 maximum capacity, 8-137 radial, 8-132 rated life (deft, 8-134 selection procedure for, 8-13, 8-135 loads, 8-135 loads, 8-122 clearance, 8-118 clements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 stipped-ordinated, 8-127 variation with clearance, 8-118 stipped-ordinated, 8-127 variation with clearance, 8-118 side dissipation from, 8-120 load distribution, 8-123 load distribution, 8-125 load distribution, 8-125 load distribution, 8-125 load distribution, 8-125 load distribution, 8-126 friction, 3-28 lubrication, 8-126 loads for, 8-134 maximum capacity, 8-137 maximum, 8-120 m			
for centrifugal pumps, 14-19 (closures for, 8-136 conical, friction, 3-17 (conical, friction, 3-27 (conical, friction, 3-28 (conical, 8-116 (conical, 8-126 (conical, 8-1	6		
closures for, 8-136 conical, friction, 3-27 efficiencies of, 3-26 friction in, 3-27, 8-119 gas-lubricated, 8-127 gas-lubricated, 8-129 more shill play of, 8-128 more play of, 8-128 more shill play of, 8-128 more shill play of, 8-128 more play of, 8-129 more play of, 8-128 more	(See also Bearings, rolling contact)	fits (table), 8 -137	loads for, 13 -16
conical, friction, 3-27 cffiction in, 3-27 cffiction in, 3-27, 8-119 gas-lubricated, 8-127 compressibility parameter, 8-128 thus, 8-127, 8-130 whirk stability of, 8-128 guide, 8-116 journal of the stable, 8-118 table, 8-128 ta			
efficiencies of, 3-26 friction in, 3-27, 8-119 gas-lubricated, 8-127 compressibility parameter, 8-128 thust, 8-127, 8-130 whird stability of, 8-128 guide, 8-116 allowable mean pressures, 8-118 table, 8-118 lable, 8-118 lements of, 8-122 clearance, 8-118 elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 load distribution, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 load distribution, 8-123 for various load directions, 8-126 friction, 3-28 flubrication, 6-183 complet, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-120 semitud, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-120 semitud, 8-116 film thickness, 8-120 semitud, 8-116 film thickness, 8-120 semitud, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-120 semitud, 8-121 minimum oil feed, 8-120 mixed, 8-121 for oscillatory motion, 8-124 for oscillatory motion, 8-125 for oscillatory motion, 8-124 for oscillatory motion, 8-125 for oscillatory motion, 8-126 film thickness, 8-120 silms, 8-137 se			
friction in, 3-27, 8-119 gas-lubricated, 8-127 compressibility parameter, 8-128 thurst, 8-127, 8-130 whirt stability of, 8-128 guide, 8-116 journal, 8-116 journal, 8-116 table, 8-118 tabl			
gas-lubricated, 8-127 compressibility parameter, 8-128 thrust, 8-127, 8-130 whist stability of, 8-128 guide, 8-116 allowable mean pressures, 8-118 babbitt linning, 8-122 thickness, 8-123 buchings, 8-123 thickness in, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 load distribution, 8-123 for various load directions, 8-123 offers various load directions, 8-123 for various load directions, 8-123 pypes of, 8-125 pypes of, 8-126 mixed, 8-116 film thickness, 8-126 myper of, 8-127 mypes of, 8-127 mypes of, 8-127 mypes of, 8-127 minimum oif feed, 8-120 mixed, 8-116 film thickness, 8-117 mydrostatic oil lift, 8-121 minimum oif feed, 8-120 mixed, 8-116 film thickness, 8-120 mixed, 8-116 film thickness, 8-117 mydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-137 needle, 8-133 needle, 8-133 needle, 8-137 needle, 8-136 normal maximum capacity, 8-132 mounting, 8-137 needle, 8-136 normal maximum capacity, 8-132 mounting, 8-137 nipilow blocks, 8-137 radial, 8-132 mounting, 8-127 mounting, 8-128 mounting, 8-127 mounting, 8-128 mounting, 8-127 mounting, 8-128 normal mean pressures (able), 8-128 mounting selection procedure for, 8-133, 8-135 normal mean (able), 6-62 silver, 6-61			
compressibility parameter, 8-128 thrust, 8-127, 8-130 whirl stability of, 8-128 guide, 8-116 journal, 8-116 allowable mean pressures, 8-118 table, 8-122 thickness, 8-123 thickness, 8-123 thickness, 8-123 thickness, 8-127 trium, 8-116 thrust, 8-118 telements of, 8-122 thrust, 8-118 telements of, 8-122 thrust, 8-118 telements of, 8-122 thrust, 8-118 tolements of, 8-125 tolements of, 8-125 tolements of, 8-125 tolements of, 8-123 thrust bearings, 8-133, 8-135 types of, 8-123 thrust bearings, 8-133, 8-135 types of, 8-123 thrust bearings, 8-133, 8-135 types of, 8-123 tolements of,			
whirl stability of, 8-128 guide, 8-116 journal, 8-116 rand, 8-127 rated life (def.), 8-134 selection procedure for, 8-133, 8-135 table, 8-118 table, 8-118 sabbit timings, 8-122 spins, 8-123 spins, 8-122 clearance, 8-118 tements of, 8-122 timins for, 8-125 types of, 8-132 spins, 8-133, 8-135 types of, 8-122 timin thickness in, 8-117 rand, 8-125 the addistribution, 8-116 spins, 8-128 timin thickness in, 8-118 load distribution, 8-123 tubrication, 8-126 friction, 3-28 thrust, 8-125 propeller shaft, 11-57 seals, 8-125 propeller shaft, 11-57 seals, 8-125 propeller shaft, 11-57 seals, 8-126 friction, 3-28 tubrication, 6-183 complete, 8-116 failure, 8-116 failure, 8-116 mounting, 8-121 minimum oif feed, 8-120 mined, 8-116 mounting, 8-127 materials for, copper base (table), 6-62 friction, 3-28 ledlewille washers, 8-70 medele, 8-130 oilers, for, 8-121 mounting, 8-137 needle, 8-133 flat, selection of, 8-56 lighs, 8-51 mouding, 8-137 needle, 8-131 flat, selection, 8-51 leather, 8-51 flat, selection, 8-51 flat, selection, 8-51 flat, selection, 9-124 joins, 8-116 flather, 8-51			
guide, 8-116 allowable mean pressures, 8-118 table, 8-118 babbitt linings, 8-122 thickness, 8-123 bushings, 8-122 clearance, 8-118 elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 babditubrion, 8-120 length-diameter ratios, 8-118 ola distribution, 8-123 lubrication, 8-116 mean pressures (table), 8-118 olig grooves, 8-123 ubroault and stopping shall till-3 for various load directions, 8-123 for various load directions, 8-123 ubroault sale friction, 3-28 thrust, 8-10, 8-125 groves, 8-125 porous-metal, 8-125 porous-metal, 8-125 propeller shaft, 11-57 scale, 8-125 propeller shaft, 11-57 scale, 8-126 film thickness, 8-117 bydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-117 bydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-117 bydrostatic oil lift, 8-120 semifluid, 8-116 film thickness, 8-117 bydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-120 semifluid, 8-116 film thickness, 8-120 semifluid, 8-116 film thickness, 8-120 semifluid, 8-116 film thickness, 8-120 mixed, 8-120 semifluid, 8-116 film thickness, 8-120 mixed, 8-121 minimum oil feed, 8-120 mixed, 8-121 mounting, 8-137 needle, 8-133 needle, 8-133 nilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 for socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motion, 8-124 plain, 8-116 for lift in the socillatory motio			
journal, 8-116			
allowable mean pressures, 8-118 table, 8-118 table, 8-118 babbit linings, 8-122 thickness, 8-123 bushings, 8-122 clearance, 8-118 elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 beat dissipation from, 8-120 length-diameter ratios, 8-118 ola distribution, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 offer various load directions, 8-123 offer various load directions, 8-123 for various load directions, 8-125 propeller shaft, 11-57 scals, 8-125 propeller shaft, 11-57 scals, 8-125 friction, 3-28 lubrication, 6-183 ccomplete, 8-116 failure, 8-116 failure, 8-116 graphite-lubricated oil lift, 8-120 minimum oil feed, 8-120 minim			
table, 8-118 babbit lings, 8-122 thickness, 8-123 bushings, 8-122 clearance, 8-118 elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 haed dissipation from, 8-120 length-diameter ratios, 8-118 ola distribution, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 for various load directions, 8-125 propoller shaft, 11-57 seals, 8-124 types of, 8-125 propoller shaft, 11-57 seals, 8-125 propuler shaft, 11-57 seals, 8-126 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-17 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-17 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 munting, 8-125 mounting, 8-126 friction, 3-29 librication, 8-126 mine and stopping, 8-121 wicks, 8-121 minimum oil feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 mounting, 8-137 needle, 8-133 oilers for, 8-122 for oscillatory motion, 8-124 plain, 8-116 leather, 8-51 leather, 8-133 lemoulli's equation (hydraulics), 3-39, 3-41, lemounting shemoult is stipping, 2-3 lemoulli's equation (hydraulics), 3-39, 3-41, lemounting, 8-133 lemoulli's equation (hydraulics), 3-39, 3-41, lemounting, 8-135 lemoulli's equation (hydraulics), 3-39, 3-41, lemounting, 8-137 needle, 8-133 lemoulli's equation (hydraulics), 3-39, 3-41, lemounting, 8-126 lemoulli's equation (hydraulics), 3-39, 3-41, lemounting, 8-126 lemoull's equation, 2-32 lemoull's equation (hydraulics), 3-39, 3-41, lemounting, 8-125 lemoull's equation (hydraulics), 3-39, 3-41, lemounting, 8-125 lemoull's equation (hydraulics), 3-39, 3-41, lemounting, 8-125 lemoull's equation (hydraulics), 3-39, 3-41, lemoull's equation, 2-32 lemoull's equation (hydraulics), 3-39, 3-41, lemoull's equation, 2-32 lemoull's equation, 2-32 lemoull's equation, 2-35 lemoull's equation, 2-35 lemoull's equation			
babbit linings, 8-122 thickness, 8-123 bushings, 8-122 clearance, 8-118 elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 beat dissipation from, 8-120 length-diameter ratios, 8-118 olad distribution, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 off various load directions, 8-123 off various load directions, 8-125 propuler shaft, 11-57 seals, 8-125 propuler shaft, 11-57 seals, 8-125 lubrication, 6-183 complete, 8-116 film thickness, 8-126 film thickness, 8-117 hydrostatic oil lith, 8-120 minimum oil feed, 8-120 mixed, 8-116 menum of feed, 8-120 mixed, 8-116 film thickness, 8-17 hydrostatic oil lith, 8-120 minimum oil feed, 8-120 mixed, 8-116 menum of feed, 8-120 semifluid, 8-116 film thickness, 8-17 hydrostatic oil lith, 8-120 minimum oil feed, 8-120 mixed, 8-116 menum of feed, 8-120 mixed, 8-117 hydrostatic oil lith, 8-120 minimum oil feed, 8-120 mixed, 8-116 film thickness, 8-18 film thickness, 8-18 graphite-lubricated, 8-120 mixed, 8-133 needle, 8-131 neodie, 8-131 neodie, 8-131 neodie, 8-132 nounting, 8-120 nimimum oil feed, 8-120 mounting, 8-137 needle, 8-133 needle, 8-133 needle, 8-131 neodie, 8-132 nibrication, 8-116 nimimum oil feed, 8-120 nimight of this service, 10-10 nimimum oil feed, 8-120 nimimum oil f			
bushings, 8-122 clearance, 8-118 elements of, 8-122 fight mbickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 load distribution, 8-123 lubrication, 8-116 fight thickness, 8-123 for various load directions, 8-123 for various load directions, 8-123 for various load directions, 8-125 porous-metal, 8-126 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-117 hydrostatic step, 8-126 findiance, 8-116 gallure, 8-120		speed limits for, 8-136	
clearance, 8-118 elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 ola distribution, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 for various load directions, 8-123 offilm thickness, 8-123 for various load directions, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-125 porous-metal, 8-125 porous-metal, 8-125 propeller shaft, 11-57 seals, 8-124 types of, 8-132 lubrication, 8-118 oil grooves, 8-129 firction, 3-28 limit mickness, 8-120 lubrication, 8-180 lubrication, 8-181 film thickness, 8-126 lubrication, 6-183 complete, 8-116 film thickness, 8-117 hydrostatic coll lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 pressure feed, 8-120 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 leaber thus bearings, 8-133 shielded (rolling contact), 8-136 silver, 6-61 silver, 6-61 silver, 6-62 silver, 6-62 silver, 6-62 silver, 6-62 silding, 8-125, 8-126, 8-130 ball, 8-133 ball, 8-133 ball, 8-135 sebel casuly, 9-134 Beta function, 2-33 Beta function, 2-33 Beta function, 2-33 Beta function, 2-33 Beta function, 2-36 Beta functio		split, 8 -133	
elements of, 8-122 film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 slided, 6-61 sintered, iron-base (table), 6-62 sliding, 8-125 sliding, 8-125 sliding, 8-127 step, friction, 3-28 lubrication, 8-116 classing and stopping, 8-125 sliding, 8-127 film thickness, 8-126 friction, 3-28 sliding, 8-127 seasing and stopping, 8-121 wicks, 8-116 sliding and step individual sliding, 8-121 mounting, 8-116 sliding, 8-121 mounting, 8-121 mounting, 8-121 mounting, 8-121 mounting, 8-137 needle, 8-133 ollers for, 8-121 for oscillatory motion, 8-124 for oscillatory motion, 8-124 for oscillatory motion, 8-124 for oscillatory motion, 8-124 for oscillatory motion, 8-126 friction, 3-29 idler, 8-137 needle, 8-137 needle, 8-137 needle, 8-136 sliers for, 8-126 friction, 3-29 idler, 8-136 leather, 8-51 slier family and step			
film thickness in, 8-117 friction, 3-27 variation with clearance, 8-118 graphite-lubricated, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 oil grooves, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 oilless, 8-125 propuler shart, 11-57 seals, 8-124 types of, 8-125 lubrication, 6-183 complete, 8-116 failure, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-110 searling, 8-121 minimum oil feed, 8-120 mixed, 8-110 mean pressure (table), 6-62 sliding, 8-127 seals, 8-124 types of, 8-125 lubrication, 6-183 complete, 8-116 film thickness, 8-126 librication, 6-183 complete, 8-116 film thickness, 8-120 librication, 6-183 complete, 8-116 film thickness, 8-120 mixed, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 sliding, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 for seal and starting and stopping, 8-121 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 film thickness, 8-126 friction, 3-28 struction, 3-28 strutus, 8-126 friction, 3-28 strutus, 8-126 spar-lubricated, 8-127, 8-130 grooves, 8-126 hydrostatic step, 8-126 kingsbury strutus, 8-126 spar-lubricated, 8-127, 8-130 grooves, 8-126 hydrostatic step, 8-126 kingsbury, 8-126 spar-lubricated, 8-127, 8-130 spar-lubricated			
friction, 3-27			
variation with clearance, 8-118 graphite-lubricated, 8-125 sliding, 8-127 step, friction, 3-28 sliding, 8-123 lubrication, 8-118 load distribution, 8-123 lubrication, 8-118 oil grooves, 8-123 for various load directions, 8-123 oilles, 8-125 grooves, 8-125 grooves, 8-125 grooves, 8-125 grooves, 8-126 friction, 3-28 slubricated, 8-127, 8-130 grooves, 8-125 grooves, 8-126 friction, 3-28 slubricated, 8-127, 8-130 grooves, 8-126 friction, 3-28 slubricated, 8-127, 8-130 grooves, 8-126 friction, 3-28 slubricated, 8-127, 8-130 grooves, 8-126 slubrication, 6-183 complete, 8-116 slading, 8-116 slading, 8-116 slading, 8-116 slading, 8-121 wicks, 8-121 mounting, 8-121 wicks, 8-121 mounting, 8-137 needle, 8-133 needle, 8-137 needle, 8-133 needle, 8-137 needle, 8-136 liable, 8-136 liable, 8-136 liable, 8-136 liable, 8-138 liable, 8-139 liable, 8-138 liable, 8-13			
graphite-lubricated, 8-125 heat dissipation from, 8-120 length-diameter ratios, 8-118 load distribution, 8-123 lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 for various load directions, 8-123 friction, 3-28 friction, 3-28 friction, 3-28 friction coefficient, 8-126 porous-metal, 8-125 propeller shaft, 11-57 seals, 8-124 types of, 8-125 Kingsbury thrust, 8-126 friction, 3-28 lubrication, 6-183 complete, 8-116 failure, 8-116 failure, 8-116 failure, 8-116 film thickness, 8-127 hydrostatic oil lift, 8-120 mixed, 8-116 pressure feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 leather, 8-51			
length-diameter ratios, 8-118 ball, 8-123 ball, 8-133 capacities of (table), 8-127 ball, 8-133 capacities of (table), 8-126			
lubrication, 8-123 ball, 8-133 Bevel gears (see Gears, bevel)			
lubrication, 8-116 mean pressures (table), 8-118 oil grooves, 8-123 for various load directions, 8-123 porous-metal, 8-125 porous-metal, 8-125 porous-metal, 8-125 propeller shaft, 11-57 seals, 8-124 types of, 8-125 Kingsbury, 8-126 friction, 3-28 lubrication, 8-125 lubrication, 6-183 complete, 8-116 failure, 8-116 failure, 8-116 film thickness, 8-126 kingsbury, 8-126 friction, 3-28 lubrication, 8-127 hydrostatic step, 8-126 segmental, pivoted, 8-126 librication, 6-183 complete, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 leather, 8-51			
mean pressures (table), 8-118 oil grooves, 8-123 for various load directions, 8-123 oilless, 8-125 gas-lubricated, 8-126 gas-lubricated, 8-127, 8-130 grooves, 8-126 propeller shaft, 11-57 seals, 8-124 types of, 8-125 Kingsbury thrust, 8-126 friction, 3-28 Ringsbury thrust, 8-126 friction, 3-28 lubrication, 6-183 complete, 8-116 failure, 8-116 film thickness, 8-10 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-10 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-10 film thickness, 8-10 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-10 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 signal procedures, 12-17 Bifilar pendulums, 3-69 Binary numbers, 2-41 Binomial coefficients, 2-10 tables, 1-26 Binders, core, 13-6 Binders, 2-10 tables, 1-26 Binders, core, 13-6 Binde			
oil grooves, 8-123 for various load directions, 8-123 friction, 3-28 friction, 3-28 propuler shaft, 11-57 seals, 8-125 propeller shaft, 11-57 seals, 8-124 types of, 8-125 lubrication, 6-183 complete, 8-116 film thickness, 8-117 hydrostatic step illie, 8-120 minimum oil feed, 8-120 mixed, 8-121 materials for, copper base (table), 6-62 semifluid, 8-126 mine car, 10-21 mounting, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 for various load directions, 8-123 friction, 3-28 friction, 3-29 friction, 3-28 libinding energy (nuclear), 9-134 libinding forectures, 12-17 libinding friction, 3-26 libinding energy (nuclear), 9-134 libinding forectures, 12-16 libinding forectures, 12-16 libindine fore, 2-10 libinding forectures, 12-16 libinding forectures, 12-16 libindine fore, 2-10 libinding forectures, 12-16 libindine fore, 2-10 libindine f			
oilless, 8-125 porous-metal, 8-125 propeller shaft, 11-57 seals, 8-124 types of, 8-125 principler, 8-126 tingsbury, 8-126 trypes of, 8-125 lubrication, 6-183 complete, 8-116 film thickness, 8-117 hydrostatic stell, 8-126 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 semifluid, 8-116 pressure feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 plain, 8-116 prossure feed, 8-120 siles, 8-51 mounting, 8-137 needle, 8-133 oilers for, 8-121 plain, 8-116 prossure feed, 8-120 siles, 8-51 mounting, 8-137 needle, 8-133 oilers for, 8-121 plain, 8-116 prossure feed, 8-120 siles, 8-51 si			
porous-metal, 8-125 grooves, 8-126 propeller shaft, 11-57 popeller shaft, 11-57 popeller, 8-126 propeller shaft, 11-57 popeller, 8-126 propeller, 8-125 prolling contact, 8-126 proller, 8-133 popeller, 8-126 proller, 8-133 popeller, 8-126 proller, 8-133 poper, 8-126 popeller, 8-126			
propeller shaft, 11-57 seals, 8-124 types of, 8-125 Kingsbury thrust, 8-126 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-117 hydrostatic step, 8-126 minimum oil feed, 8-120 mixed, 8-116 pressure feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 plain, 8-116 for oscillatory motion, 8-124 find the service of table, 12-2 for oller, 8-123 for oller, 8-126 Kingsbury, 8-126 roller, 8-133 rollingsbury, 8-126 roller, 8-133 rollingsbury, 8-126 roller, 8-133 rolling sontact, 8-133 rolling contact, 8-133 rolling sontact, 8-133 rolling contact, 8-133 rolling sontact, 8-133 rolling contact, 8-133 rolling contact, 8-133 segmental, pivoted, 8-126 segmental, pivoted, 8-126 segmental, pivoted, 8-126 segmental, pivoted, 8-125 segmental, pivoted, 8-126 slibication, 2-10, 17-23 slinomial distribution, 2-10, 17-23 slinomial theorem, 2-10 slinomial theorem, 2-10 slinomial theorem, 2-10 slinomial theorem,			
seals, 8-124 Kingsbury, 8-126 Binomial coefficients, 2-10 types of, 8-125 Kingsbury thrust, 8-126 roller, 8-133 Binomial distribution, 2-10, 17-23 Kingsbury thrust, 8-126 rolling contact, 8-133, 8-135 Binomial distribution, 2-10, 17-23 friction, 3-28 Beché pneumatic forge hammer, 13-23 Binomial distribution, 2-10, 17-23 complete, 8-116 Beché pneumatic forge hammer, 13-23 Binomial distribution, 2-10, 17-23 segmental, pivoted, 8-126 Binomial distribution, 2-10, 17-23 segmental, pivoted, 8-126 Binomial distribution, 2-10, 17-23 segmental, pivoted, 8-126 Binomial distribution, 2-10, 17-23 Binomial coefficients, 2-10 Binomial distribution, 2-10, 17-23 segmental, pivoted, 8-126 Binomial distribution, 2-10 Biospas, as fuel, 7-10 Biospas, as fuel, 7-10			
types of, 8-125 Kingsbury thrust, 8-126 friction, 3-28 lubrication, 6-183			
Kingsbury thrust, 8-126 friction, 3-28 lubrication, 6-183 complete, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 semifluid, 8-126 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 plain, 8-116 friction, 3-28 segmental, pivoted, 8-133 pêcké pneumatic forge hammer, 13-23 Binomial distribution, 2-10, 17-23 Binomial distribution, 2-10, 17-23 Binomial distribution, 2-10, 17-23 Binomial distribution, 2-10 Biomass fuels, 7-7 Biomass fuels, 7-7 Biomass fuels, 7-7 Biomass fuels, 7-7 Bipropellants (rocket), 7-29 Birefringent coatings, 5-54 Birmingham wire and sheet-metal gages, 8-85 Bisection: of angles, 2-6 of lines, 2-5 of lines, 2-5 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bit			
lubrication, 6-183 complete, 8-116 failure, 8-116 failure, 8-116 failure, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-130 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 selbeville washers, 6-70 Bellows gages, 16-8 Bellows gages, 16-8 Bellows gages, 16-8 Bellows gages, 16-7 Bellows gages, 16-8 Birmingham wire and sheet-metal gages, 8-85 Bisection: of angles, 2-6 of lines, 2-5 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bit (computers), 2-40 Bit minous coal (see Coal, bituminous) Black-surface enclosures (radiant-heat), 4-63 Blacks, 4-62 Blades, fan, centrifugal, 14-45 Blasius equation (friction-drag-coefficient), 11-66 Biomass fuels, 7-7 Biomass fuels, 7-7 Biomass fuels, 7-7 Bipropellants (rocket), 7-29 Bipropellants (rocket), 4-29			
complete, 8-116 failure, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 starting and stopping, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 film thickness, 8-117 belleville springs, 8-70 Belleville springs, 8-70 Belleville springs, 8-70 Belleville springs, 8-70 Belleville washers, 8-70 Bispropellants (rocket), 7-29 Birringent coatings, 5-54 Birmingham wire and sheet-metal gages, 8-85 Bisection: of angles, 2-6 of lines, 2-5 of lines, 2-5 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bituminous coal (see Coal, bituminous) Black-surface enclosures (radiant-heat), 4-63 Blackody (def), 4-62 Blades, fan, centrifugal, 14-45 Blasts furnace (def), 6-13 Blast furnace (def), 6-13 Blast-furnace gas: cleaning of, 18-10, 18-11 flame temperatures (table), 4-29			· · · · · · · · · · · · · · · · · · ·
failure, 8-116 film thickness, 8-117 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 pressure feed, 8-120 semifluid, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 film thickness, 8-117 Belleville springs, 8-70 Belleville washers, 8-70 Birningham wire and sheet-metal gages, 8-85 Bisection: of angles, 2-6 of lines, 2-5 of lines, 2-5 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bit (computers), 2-40 Bit (computers), 2-40 Bit (computers), 2-40 Bit (def), 4-62 Black-surface enclosures (radiant-heat), 4-63 Blackbody (def), 4-62 Blast furnace (def), 4-62 Blast furnace (def), 6-13 Blast furnace (def), 6-13 Blast furnace gas: cleaning of, 18-10, 18-11 flame temperatures (table), 4-29			
film thickness, 8-117 hydrostatic oil lift, 8-121 Belleville springs, 8-70 Belleville springs, 8-70 Belleville springs, 8-70 Belleville washers, 8-70 Belleville washers, 8-70 Belleville washers, 8-70 Birrfringent coatings, 5-54 Birmingham wire and sheet-metal gages, 8-85 Birmingham vire and sheet-metal gages, 16-8 Birmingham vir			
hydrostatic oil lift, 8-121 minimum oil feed, 8-120 mixed, 8-116 pressure feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 mixerials for, copper base (table), 6-62 Michell, 8-126 mine car, 10-21 mounting, 8-137 neiled, 8-121 mounting, 8-130 niled, 8-121 plain, 8-116 hydrostatic oil lift, 8-121 minimum oil feed, 8-120 Bellows gages, 16-8 Bellows gages, 16-7 Bellows gages, 16-8 Birminigham wire and sheet-metal gages, 8-85 Bisection: of angles, 2-6 of lines, 2-5 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bit (computers), 2-			
minimum oil feed, 8-120 mixed, 8-116 pressure feed, 8-120 semifluid, 8-116 starting and stopping, 8-121 materials for, copper base (table), 6-62 Michell, 8-126 mine car, 10-21 mounting, 8-137 mounting, 8-137 noled, 8-121 for oscillatory motion, 8-124 plain, 8-116 Bellows gages, 16-8 Bisection: of angles, 2-6 of lines, 2-5 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bit (computers			
pressure feed, 8-120 semifluid, 8-116 semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 Belts, 8-51 arc of contact, 8-53 arc of contact, 8-53 arc of contact, 8-53 arc of contact, 8-53 conveyor, 10-48 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Black-surface enclosures (radiant-heat), 4-63 Black-surface enclosures (radiant-heat), 4-6			
semifluid, 8-116 starting and stopping, 8-121 wicks, 8-121 materials for, copper base (table), 6-62 (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 medle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 arc of contact, 8-53 arc of contact, 8-53 conveyor, 10-48 drives, 8-51 drives, 8-51 drives, 8-51 Bisphenol resins: properties of (table), 6-189 Bit (computers), 2-40 Bit (computers), 2-40 Bit (computers) (see Coal, bituminous) Bituminous coal (see Coal, bituminous) Bituminous			
starting and stopping, 8-121 conveyor, 10-48 drives, 8-51 Bisphenol resins: properties of (table), 6-189 wicks, 8-121 drives, 8-51 Bit (computers), 2-40 B			
wicks, 8-121 drives, 8-51 Bit (computers), 2-40 materials for, copper base (table), 6-62 arrangements, 8-51 Bit minous coal (see Coal, bituminous) (See also Bearing metals) efficiency, 3-26 Black-surface enclosures (radiant-heat), 4-63 Michell, 8-126 friction, 3-29 Blackbody (def), 4-62 mine car, 10-21 idler pulleys, 10-48 Blades, fan, centrifugal, 14-45 mounting, 8-137 power, 8-53 Blasius equation (friction-drag-coefficient), 11-66 needle, 8-133 flat, selection of, 8-56 Blast furnace (def), 6-13 oilers for, 8-121 high-strength, 10-48 Blast-furnace gas: for oscillatory motion, 8-124 joints, 8-51 cleaning of, 18-10, 18-10 plain, 8-116 leather, 8-51 flame temperatures (table), 4-29			
materials for, copper base (table), 6-62 (See also Bearing metals) (See also Bearing metals) Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 oilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 materials for, copper base (table), 6-62 arrangements, 8-51 efficiency, 3-26 Black-surface enclosures (radiant-heat), 4-63 Blac			
(See also Bearing metals) Michell, 8-126 Michell, 8-126 mine car, 10-21 mounting, 8-137 needle, 8-133 noilers for, 8-121 for oscillatory motion, 8-124 plain, 8-116 efficiency, 3-26 friction, 3-29 lidler pulleys, 10-48 llackbody (def), 4-62 llackbody (def), 4-63 llackbody (def), 4-62 l			
mine car, 10-21 idler pulleys, 10-48 Blades, fan, centrifugal, 14-45 mounting, 8-137 power, 8-53 Blasius equation (friction-drag-coefficient), 11-66 needle, 8-133 flat, selection of, 8-56 Blast furnace (def), 6-13 oilers for, 8-121 high-strength, 10-48 plant, 8-151 plan, 8-116 leather, 8-51 flame temperatures (table), 4-29			
mounting, 8-137 power, 8-53 Blasius equation (friction-drag-coefficient), 11-66 needle, 8-133 flat, selection of, 8-56 Blast furnace (def), 6-13 oilers for, 8-121 high-strength, 10-48 Blast-furnace gas: cleaning of, 18-10, 18-11 plain, 8-116 leather, 8-51 flame temperatures (table), 4-29	Michell, 8-126	friction, 3-29	Blackbody (def), 4-62
needle, 8-133 fflat, selection of, 8-56 Blast furnace (def), 6-13 oilers for, 8-121 high-strength, 10-48 Blast-furnace gas: for oscillatory motion, 8-124 joints, 8-51 cleaning of, 18-10, 18-11 plain, 8-116 leather, 8-51 fflame temperatures (table), 4-29			
oilers for, 8-121 high-strength, 10-48 Blast-furnace gas: for oscillatory motion, 8-124 joints, 8-51 cleaning of, 18-10, 18-11 plain, 8-116 leather, 8-51 flame temperatures (table), 4-29			
for oscillatory motion, 8-124 joints, 8-51 cleaning of, 18-10, 18-11 plain, 8-116 leather, 8-51 flame temperatures (table), 4-29			
plain, 8-116 leather, 8-51 flame temperatures (table), 4-29			
	porous, 6 -61, 8 -125	strength of, 8-51	Blasting gelatin, 7-20

Bleeding cycle (turbines), 4 -19	Boilers, nuclear (Cont.):	Brakes (Cont.):
Blind rivets, 8-30	PWR system, 9-53	band, 8 -41
Blocks, concrete, 12 -28	radioactivity in, 9-53	cone, 8-42
pulley, 8 -8 Blockwood (def), 7 -9	once-through type, 9-37, 9-45 package, 9-36	disk, 8 -42 dynamometers, 16 -15
Blowers, 14 -44	performance of: acceptance tests, 9-47	eddy-current, 8 -42
for draft, 14 -50	component tests, 9-48	dynamometer, 16 -15
rotary, 14 -44	draft loss, 9-46	electric, 8-43
for superchargers, 9-106	guarantees, 9-47	fan, 16 -15
for ventilation, 14-50	heat-absorption calculation, 9-47	friction, 3 -18, 3 -22, 3 -28
(See also Centrifugal compressors;	thermal losses, 9 -47, 9 -48	horsepower absorbed by, 3-18
Fans) Roard drop hammers 13 22	radiant, 9-37 rating (def), 9-47	for hoisting machinery, 10 -17
Board drop hammers, 13-22 Board measure (def), 1-16	recovery, 9 -37	hydraulic (automobile), 11 -14 internal, 8 -40
Boats, maximum safe power for, 11 -46	safety interlocks, 9-52	multidisk, 8-42
BOD (biological oxygen demand), 6 -172	start-up, 9-52	prony, 16 -15
Bode diagrams, 16-34	supercritical, 9-46	railway, 11-32, 11-35, 11-37
for controllers, 16-37	superheaters for, 9-41	vacuum, 11 -15
description of, 16 -22	tubes for: film coefficients for, 4 -84	Braking:
Bohr theory of atoms, 6 -5	radiation factors for rows of (chart), 4-66	of railway trains, 11 -32, 11 -35, 11 -37
Boiler furnaces:	standard dimensions (table), 8 -187	regenerative (def), 10 -10
cinder and fly-ash recovery, 9-32 combustion in, 9-34	types of, 9-36 waste-heat, 9-37	Brale (hardness-testing device), 5-12 Brass:
controls, 9-45	waste-neat, 9-37 water for (see Feedwater)	composition and properties of (tables), 6 -68
design and construction of, 9-37	water-tube, 9-36	leaded, 6 -65
draft losses in, 9-46	Boiling points:	table, 6 -68
heat transfer, 9-39	of the elements (table), 4-58	machinability of, 6 -73
heat transmission, 4-71	of hydrocarbons (tables), 4-50, 4-53	naval (table), 6 -68
mechanical draft, 9-46	of metals (table), 6-50	pipe (tables), 8 -189, 8 -190
pulverized-coal: firing, 9-32 to 9-35	of various substances, 4 -50, 4 -53, 4 -58	plastic range chart for, 13 -10
stokers, 9 -32	Bolometer, 16 -13	press forgings, mixtures for, 13 -19
walls, 9-37	Bolted joints, design of, 8 -24	rolled, mechanical properties of (table),
water-cooled, 9 -36 Boilers:	Bolts: carriage, 8-22	6- 72 strength at high temperatures, 5- 10
acid cleaning of, 9-52	drift, pulling resistance, 12 -33	(See also Copper alloys)
air preheaters for, 9-43	heads for, standard dimensions (table), 8-21 ,	Brass-aluminum alloys for condenser tubes,
boil-out, 9-52	8-22	6 -73
using carbon monoxide, 9-37	high-strength: direct tension indicators for, 8-27	Brayton cycle, 4-11, 4-13, 9-124, 9-135
care of, 9 -52	materials for, 8-22	Braze welding, 13-29
chemical cleaning of, 9 -52	ISO metric (table), 8-26	Brazing, 13 -29
circulation in, 9-45	strength of, 8-27	filler metals for (table), 6 -76
natural, 9-37, 9-45	and nuts, thread standards, 8-8	furnace, 13-29
codes for, 9-52 combined circulation, 9-37, 9-46	preload-indicating, 8 -27 proof loads for, 8 -22	induction, 13 -29 torch, 13 -29
controls for, 9-45	proof strength of, 8 -23	Brick, 6 -131
corner-fired, 9-35	for steel-framed structures, 12 -35	ASTM specifications (table), 6 -136
corrosion in, 6 -105, 9 -49	stress due to tightening, 8 -22	cement, 6 -135
draft loss through, 9-46	tension due to tightening nuts on, 3-27	chrome, 6 -152
dry storage of, 9-52	threads for, ANSI metric (table), 8-14	common, 6 -135
economizers for, 9-43	for timber trusses, 12 -31	red, 12 -27
efficiency of, 9-47	table, 12 -31	facing, 6 -135
calculation by heat balance, 9-47 emergency operation of, 9-52	U.S. Standard, wrench openings for (table),	fire (see Firebrick)
exhaust gas, 9-37	8-20 Bonus wage systems, 17-10	grades (table), 6 -136 high-alumina, 6 -151
explosions in, 9-52	Boolean algebra:	magnesite, 6 -151
external cleaning, 9-52	in circuit analysis, 15 -80	manufacture of, 6 -135
feedwater (see Feedwater)	truth table for, 2 -2	masonry: specific gravity and density of
fireside corrosion in, 6-107	Borers, wood, 13-74	(table), 6 -8
foaming in, 9 -49	Boring machines, 13 -55	strength of, 12-28
forced-circulation, 9-37, 9-45	Boring mills, 13-55	table, 12 -28
furnace (see Boiler furnaces)	Boron carbide (abrasive), 6 -128	paving, 6 -135
heat balance, 9-47 heat losses, 9-47	Boron nitride (abrasive), 6 -128 Borozon (boron carbide), as abrasive, 6 -128	prefabricated panels of, 6 -135 properties of (table), 6 -136
high-temperature-water, 9-37	Bosch fuel-injection pumps, 9-111	sand-lime, 6 -135
inspection and maintenance, 9-52	Boundary layer (def), 11-66	silica, 6 -151
normal operation, 9-52	in aerodynamics, 11-66	silicon carbide, 6 -152
nuclear, 9 -53	in fluid flow, 3-46	specialty, 6-135
BWR system, 9-53	Boundary-layer control (BLC), 11-64	Brickwork:
chemical poisons from, 9-53	Bourdon pressure gages, 16-8	lateral support, 12-28
chemical reactions in, 9-53	Boxboard, 6-144	laying and bonding, 12 -27
codes and specifications for, 9-53	BPCTCA (best practical control technology	strength of, 12 -27
design considerations, 9-53 economics of, 9-53	currently available), 18 -5 Brakes:	Brightness (illumination, def), 12 -99 Brine coolers, 19 -18
hazards, 9 -53	automobile and truck, 11 -13	double-pipe, 19 -18
heat transfer in, 9-53	composition of, 11-15	shell-and-tube, 19 -20
,,	·	

Brinell hardness number (def), 5-12	Building stone, 6-143	Cableways, tramways (Cont.):
for metals (table), 5-3	specific gravity and density of (table), 6-8	power required, 10-33
Brinell hardness test, 5-12, 16-18	Buildings:	rope, stresses in, 10-32
Brines:	closed, wind forces on, 12-19	transporting, 10-30
circulation of, 19-23	earthquake forces in, 12-18	types of, 10 -30
properties of (tables), 19 -19	exits and fire escapes, 18 -20	Cadmium, 6-83
for refrigerating plants, 19 -19 Briquettes, for coke ovens, 7 -34	fire protection, 18 -23 heating (<i>see</i> Heating)	Calsingto (calca making, def), 7, 24
British thermal units (Btu), 1-19, 4-3	industrial (see Industrial plants)	Calcinate (coke making, def), 7 -34 Calcium-carbide furnace (electric), 7 -59
mechanical equivalent, 1 -19	safety provisions, 18 -19	Calcium chloride:
British unit of refrigeration (def), 19 -2	soundproofing, 12 -119	brine, properties of (tables), 19 -19
Brittleness, impact tests for, 5 -7	ventilation (see Ventilation)	as freezing preventive, 6 -141
Broaches, 13-60	wind pressure on, 12 -19	Calculus, 2 -24 to 2 -31
speeds and feeds for, 13-61	Bulk flo conveyor, 10-41	rules for differentiation, 2-24
Broaching, 13-60	Bulk modulus of elasticity (def), 3-31, 5-17	table of integrals, 2-26 to 2-28
Broaching machines, 13 -61	of metals (table), 5-4	Calendars, 1-25
Bronze, 6 -65, 6 -67	of various liquids (table), 3 -32	Calipers, 16-4
aluminum (table), 6 -68	Bulldozers, 10-24	Calorie, IT (def), 4-3
for bearings, 6 -61	Buoyancy, 3-36	Calorific value (<i>see</i> Heat value) Calorimeters:
tables, 6 -68 cupronickels, 6 -67	center of, 3 -36 for ships (def), 11 -44	separating, 16 -18
tables, 6 -68	Burglar alarms, 12 -123	steam, 16 -18
as electrical conductor, 15 -6	Burners, 9-34	throttling, 16 -18
manganese, 6 -65	air-atomized, 9 -34, 9 -35	Calsum bronze, as electrical conductor, 15 -6
phosphor, 6 -67	for combustion furnaces, 7-41	Camber line, of airplane wing section, 11 -62
table, 6 -68	corner-fired, 9-35	Campbell diagram, 11-93
silicon, 6 -67	gas, 9 -35	Cams, 8-4
table, 6 -68	blast-furnace, 9-35	acceleration of (chart), 8-4
strength at high temperatures (table), 5-10	coke-oven, 9-35	design of, 8 -6
tin, 6 -67	oil, 9 -34	diagrams, 8-4
tables, 6 -68	pulverized coal, 9-34	jerk (chart), 8-4
various, uses of, 6 -67	primary air for, 9-34	pitch line, 8-4
Brown and Sharpe wire gage: scheme of, 15 -6 table, 8 -85	secondary air for, 9-34 Bus bars for switchboards, 15 -45	velocity of (chart), 8 -4 Candela (unit of luminous intensity, def), 1 -17,
(See also American wire gage)	Buses, engines in, 9 -97	1-18, 12 -99
Brown coat (plastering), 6 -163	(See also Automobiles)	Cantilever beams (def), 5-21
Btu (see British thermal units)	Bushel, U.S. and imperial (def), 1 -16, 1 -20	(See also Beams)
Bucket carriers, 10-45	Bushings, dimensions of (table), 8 -122	Capacitance, electrical, unit of (def), 15 -2
(See also Conveyors)	Butane:	Capacitances:
Bucket elevators, 10-46	in LPG (table), 7-15	of capacitors, 15-15
casings, 10 -47	properties of (table), 4-50, 4-52	in parallel, 15-16
Buckets:	as refrigerant (table), 19-4	in series, 15 -16
clamshell, 10-12	Butterfly valves for hydraulic turbines, 9-160	Capacitive circuit, 15 -17
dragline: scraper, 10-11	Butyl acetate, uses of, 6 -149	Capacitive reactance (def), 15 -3, 15 -18, 15 -19
self-filling, 10 -11 grab, 10 -12	Butyl rubber, 6 -147 BWG (Birmingham wire gage), 8 -85	Capacitor motors, 15 -39 Capacitors, 15 -15
electrohydraulic, 10 -12	Bypass engines (turbofan engines), 11-82	capacitors, 13-15
for impulse hydraulic turbines, 9-156	Byte (computers), 2-41	synchronous, 15 -40
orange-peel, 10-12	-) · · (· · · · · · · · · · · · · · · ·	Capacity and volume equivalents (tables), 1 -30,
for steam turbines, 9-62		1-31
Buckingham's II theorem (dimensional analysis),		Capillarity, in tubes (chart), 3-33
3-44, 3-45	C (computer language), 2-53	Capillary attraction, 3 -33
Buckling, of columns, 5-38	Cable length (nautical unit), 1 -16	in tubes (chart), 3 -33
Budgets, 17 -14, 17 -16	Cable tramways (see Cableways)	Car dumps:
Buffing, 13 -64	Cables:	cross-over, 10-22
of plastics, 13 -65 Buhrstones, 6 -129	aluminum, electrical properties of (table), 15-49	rotary, gravity, 10 -22 power, 10 -22
Building blocks, 12 -28	copper (table), 15 -6, 15 -51	unit-train, 10 -22
Building construction, 12 -17, 12 -18	resistance and reactance of (table), 15 -52	Car positioners (railroad), 10 -22
fire-resisting, 18 -23	electric: insulation for, 15 -50, 15 -56	Carat, metric (def), 1 -17
foundations, 12-26	paper for, 6 -139	Carbide, tungsten, 6 -62
industrial, 12-2	underground power, 15 -50	Carbides:
materials (see Building materials)	carrying capacity (tables), 15-51	cemented, for tools, 6-61
partitions: sound-adsorption coefficients	nonmetallic sheathed (interior wiring), 15 -56	composition, properties and uses of (table),
(table), 12 -121	service entrance (interior wiring), 15 -55, 15 -57	6 -64
sound-transmission loss (table), 12 -120	Cableways:	Carbolon (abrasive), 6 -128
reinforced-concrete (<i>see</i> Reinforced concrete) steel (<i>see</i> Steel-framed structures)	deflection, 10 -31 factor of safety, 10 -31	Carbon: air required for combustion, 4 -30
steel (see Steel-framed structures) steel for, allowable stresses in (tables), 12 -33	hoisting and conveying, 10 -30	heat of combustion of (table), 4 -26
structural design, 12-18	slackline, 10 -35	Carbon dioxide:
Building materials:	speeds and loads, 10 -31	dissociation of, 4 -29
fire resistance of, 12 -43, 18 -24	supporting towers, 10-32	emissivity (table), 4 -70
specific gravity and density of (table), 6-8	tramways, 10-31	measurement of, 16-18
thermal conductivity of (tables), 4-83, 4-84,	cables and traction ropes, 10-32	production of, 19-25
12 -75	loading and discharge terminals, 10-32	properties of (tables), 4 -35

Carbon dioxide (Cont.):	Cast iron (Cont.):	Castings, steel (Cont.):
as refrigerant, 19-5	corrosion of, 6 -101	allowances for machine finish, 6-48
chart, 19 -12	cutting speeds (lathe, table), 13-53	alloy, 6 -44
table, 19 -4	definition of, 6 -13	ASTM specifications for (table), 6 -48
solid, as refrigerant, 19-25	ductile, 6 -13, 6 -39	ASTM specifications for (table), 6 -48
Carbon monoxide:	gray, mechanical properties of, 6 -38	classification of, 6 -38
flame temperature and dissociation (table), 4-29	table, 6 -39	composition of, 6 -43
measurement of, 16 -18	malleable, 6-41	corrosion resistance of, 6 -45
Carbon-residue test for lubricating oils, 6 -179 Carbon resistors, 15 -62	mechanical properties of, 6 -38 tables, 6 -39, 6 -40	design of, 6 -49 dimensional tolerances for (table), 6 -49
Carbon steel (<i>see</i> Steel, carbon)	nodular, 6 -13	ductility, 6 -44
Carbon tetrachloride, as solvent, 6 -149	pipe (see Pipe, cast-iron)	endurance limit, 6 -45
Carbonic acid (see Carbon dioxide)	shrinkage of, 6 -43	heat resistance of, 6 -45
Carbonization of coal, 7 -31	strength of (tables), 6 -39, 6 -40	impact resistance of, 6-44
apparatus for, 7 -33	at high temperature (table), 5-11	machinability of, 6-45
briquettes for, 7 -34	tapping depth, 8-27	table, 6 -47
coal blending in, 7 -32	white (def), 6 -42	machine finish allowances for, 6 -48
coal-chemical recovery in, 7-34	(See also Castings)	table, 6 -49
heat-balances (table), 7-33	Cast steel:	minimum thicknesses for, 6 -47
coals for, 7-31	properties of (charts), 6 -46	properties of, 6 -44, 13 -6
coking process, 7 -32 coking rates in, 7 -32	strength of at high temperatures (table), 5 -11 Castable mixes for refractories, 6 -154	charts, 6 -46 shrinkage allowance for, 6 -47
gas yield (table), 7 -33	Castigliano's theorem (beam deflections), 5 -36,	specifications for, 6 -46
variations during (table), 7 -33	5-42	uses of, 6 -48
heat required for, 7-33	Casting:	wear resistance of, 6 -45
high-temperature: yields from, 7-31	of aluminum-base alloys, 13-7	weight range, 6-44
table, 7 -33	cold-chamber machines for, 13-5	welding of, 6 -46
pilot scale tests for, 7-32	of copper-base alloys, 13-7	white iron, ASTM specifications for, 6 -43
plastic zone, 7 -32	gooseneck machines for, 13-4	(See also Foundries; Molding)
preheated coal for, 7 -34	low pressure, 13-4	Catenary, 2-21
processes, 7-34	methods, design and cost features (table), 13-3	Cauchy-Euler equation, 2-33
temperature effects during, 7-33	pressure, 13-4	Cauchy's number, 3 -42 Cavitation (def), 12 -122
gradients in (diagram), 7 -32 thermal efficiency of, 7 -33	piston machines for, 13 -4 sand, 13 -2, 13 -3	as cleaning process, 12 -122
Carborundum (abrasive), 6 -128	basic steps, 13 -2	in displacement pumps, 14 -2
Carburetors, 9-109	patterns, 13-2	effects of, 6 -102
electronic, 9-109	processes, 13-3	in screw propellers, 11-53, 11-54
Carburizing of steel, 6 -21	by slush process, 13-4	Cavitation limits of hydraulic turbines, 9 -159
Cardan universal joints, 8-36	of steel: melting practice, 6 -47	CBN (cubic boron nitride), for cutting tools,
Cardboard, 6-144	with steel molds, 13-5	13-50, 13-62
Cardioids, 2-22	Castings:	CD (compact disk), 15-83
Carnot cycle, 4 -6, 4 -10 Carrene (refrigerant), 19 -7	alloys for, 13 -6 aluminum (table), 6 -57 to 6 -60	Ceiling (airplanes), 11-66 Cells:
Carriage bolts, 8-22	austempered ductile iron, 6 -40	lead, voltages of, 15 -13
Carrier wave (television), 15-89	austenitic ductile iron, ASTM specifications	wet, 15 -13
Carriers:	for, 6 -43	(See also Batteries)
open-top, 10 -45	austenitic gray iron, ASTM specifications for,	Cellulose acetate butyrate resins: properties of
pivoted-bucket, 10-45	6-43	(table), 6 -189
V-bucket, 10-45	cast iron, specialty, 6 -42	Cellulosic resins: properties of (table), 6 -189
capacities and weights (table), 10 -46 Cars:	compacted graphite iron, 6 -42 copper, 6 -70	Celsius, conversion to Kelvin (eq), 4 -2 Cement, 6 -159
box-body dump, 10 -21	corrosion resistant, ASTM designations for	autoclave soundness test for, 6 -160
gable-bottom, 10-21	(table), 6 -45	bricks, 6 -135
hopper-bottom, 10-21	designs for molding, 13-8	compressive strength of (table), 6 -160
industrial, 10-21	die, 13 -4	high-early-strength, 6 -159
mine, 10 -21	ductile iron, ASTM specifications for (table),	insulating, 6-151
friction resistance (table), 10 -21	6 -41	for masonry, 6-160
railway, 11 -27, 11 -33	mechanical properties of (table), 6 -41	plaster, 6 -163
for containers, 11-28	tensile requirements for (table), 6 -41	portland, 6-159
roller bearing resistance, 11 -39 wheels and axles for, 11 -31	gray iron, allowances for, 6 -43	air-entraining, 6 -160
rocker side-dump, 10 -21	composition and mechanical properties of, 13-7	ASTM specifications for (table), 6 -160 blast-furnace slag in, 6 -160
scoop-dump, 10-21	heat resistant, ASTM designations for (table),	high-early-strength, 6 -159
shakers for, 10-22	6 -45	low-heat, 6 -159
unloading machinery for, 10-22	inspection of, 13-7 , 13-8	modified, 6-159
Cartridge brass (table), 6 -68	iron, 6 -38	regulated-set, 6-160
Casein in glues, 6 -132	allowances for, 6 -42	shrinkage-compensated, 6-160
Casings, for centrifugal fans, 14 -44	magnesium alloy, 6 -84	specific gravity and density of (table), 6-8
Cast iron:	malleable-iron, 6 -41	strength of (table), 6 -160
alloys, composition and mechanical properties	composition and mechanical properties of,	sulfate-resisting, 6 -159 white, 6 -160
of (tables), 6 -39 to 6 -41 carbon in, 6 -38	ni-resist, corrosion resistance of (table), 6 -44	pozzolan, 6 -160
classification of, 6 -38	sand-blast cleaning of, 13 -7	sand for, tests for, 6 -161
columns (tables), 5 -39	steel, 6 -38, 6 -43	setting time, 6 -160
composition of, 6 -38	allowances for, 6-47	surfaces, painting of, 6-109

Cement (Cont.):	Centrifugal pumps (Cont.):	CERCLA (Comprehensive Environmental Re-
tests for, 6 -160	bearings for, 14 -19	sponse Compensation and Liability Act),
types and kinds of, 6 -159	casings, 14 -17	18 -18
waterproofed, 6-160	cavitation limits, 14-25	Cermets, 6 -63
Cement-lined pipe, 8-191	characteristic curves, 14 -24, 14 -26	Cetane index (fuels, def), 7-14
Cement plants: pollution from, 18 -15	influence of fluid properties on, 14 -24	Cetane number (fuels, def), 9-116
Cemented-carbide tools, 6 -62	influence of viscosity on, 14 -24	CFC (chlorofluorocarbon) chemicals, 19 -3
Cemented-carbides, 6 -61	classification of, 14 -15, 14 -17	Cgs system of units, 1-24
corrosion resistance of, 6 -63	condensate-injection sealing for, 14 -19	Chain (unit of length, def), 1 -16
design considerations for, 6 -62	couplings for, 14-20	Chain blocks:
inserts of, 6 -62 mechanical properties of, 6 -63	critical speeds of, 14 -19 diffuser type, 14 -16	differential, 8-8
micrograin, 6 -63	effect of speed change, 14 -23	triplex, 8 -8 Chain conveyors, 10 -45
Cementite (def), 6 -16	efficiency of (chart), 14 -21, 14 -22, 14 -24,	(See also Conveyors, bucket)
Center:	14-26	Chain drives, 8 -59
of buoyancy, 3 -36	fluid flow in, 3-43	inverted-tooth (silent), 8 -62
of curvature, 2 -26	head-capacity curves (charts), 14 -24, 14 -26	length of chain in, 8 -62
of gravity, 3-6, 3-7	hydraulic balancing devices, 14 -18	power ratings, 8-61
by experiment, 3 -7	hydraulic theory, 14 -21	table, 8 -60
of lines, 3-6	impellers (def), 14-15	roller, 8-59
of plane areas, 3-6	shapes for (chart), 14 -21	Chain-grate stokers, 9-32
by graphics, 3 -9, 3 -10	unbalanced forces on, 14-17	Chain hoists, 10-12
of solids, 3-7	velocity diagrams for, 14-22	data for (table), 10 -13, 10 -14
of mass, 3-6	installation of, 14 -26	Chains, 10 -4
of percussion, 3-16	lattice-effect coefficient (chart), 14-23	alloy, data on (tables), 10-5, 10-6
Centesimal measure of angles, 2-15	maintenance of, 14-26	ASTM specifications for (table), 10-5, 10-6
Centigrade, conversion to Fahrenheit, 4-2	materials for, 14-20	conveyor, 10-8
(See also Celsius)	table, 14 -21	end fittings for, 10-7
Centipoise (unit of viscosity, def), 3-31	mechanical construction, 14-15	grades of, 10-4
Centistoke (unit of kinematic viscosity), 3-33	mechanical seals for, 14-19	high-test, ASTM specifications for (table), 10-6
Central heating (See also Heating)	mixed-flow, 14-21	master links for, 10-7
Centrifugal casting, 13-4	motors for, 15-44	master rings for, 10-7
of iron pipe, 8 -187	mountings for, 14 -20	NACM specifications for (tables), 10 -5, 10 -6
Centrifugal compressors, 14-38	multistage, 14-17	power transmission, 10-8
axial thrust in, 14 -38	names of parts for (table), 14 -16	proof coil, ASTM specifications for (table),
efficiency of, 14 -38	nomenclature of, 14 -15	10-6
fluid flow in, 3 -43	NPSH (def), 14 -25	roller, 8 -59
Centrifugal fans, 14-44, 14-45	required for, 14-25	dimensions and speeds (table), 8 -60
for air conditioning, 12 -89	operation of, 14 -26	length calculations, 8 -62
fan laws for (table), 12 -90	packing for, 14 -19	multiple-strand, 8 -62
applications of, 14 -50	parallel operation of, 14 -26	power ratings (table), 8-60
blade forms, 14 -45 blowback in, 14 -50	parts of, recommended names of (table), 14-16	service factors (table), 8-64
casings for, 14 -44	performance of, 14 -21	sprocket wheels for, 8 -62 diameter formulas, 8 -62
characteristics of, 14 -47	priming of, 14- 26	teeth, 8 -62
charts, 14 -46 to 14 -49	series operation of, 14 -26	silent, 8 -62
compressibility factor (def), 14 -45	shaft sleeves for, 14 -19	power ratings (tables), 8-63, 8-64
cross-flow, 14-45	shafts for, 14 -18	service factors (table), 8 -64
efficiency of, 14-46	similarity laws for, 14 -23	sling, 10 -5
fluid flow in, 3-43	specific speed of (def), 14 -21	special, 10 -8
formulas, 14-45	stuffing boxes for, 14 -19	strength of, 10 -6
head (def), 14 -46	suction specific speed, 14 -25	tables, 10 -5, 10 -6
impeller types, 14 -44, 14 -45	system friction losses in, 14 -25	transport, ASTM Specifications for (table),
laws of, 14 -49	system-head curves for, 14-25	10-6
mixed-flow, 14-45	theory of, 14 -21	welded-link, 10-7
motors for, 15-44	vertical end-suction, 14-17	wheel, 10 -7
parallel operation of, 14 -48	vertical-shaft construction, 14-20	working loads (tables), 10-5, 10-6
performance curves for, 12-89, 12-90	volutes, 14 -16	Channels:
power output (def), 14 -46	water-seal packing for, 8-140	open (hydraulic), 3 -59
pressures in (def), 14 -45	wearing rings for, 14 -17	roughness coefficients (table), 3-59
puffing in, 14 -50	wet-pit, 14 -16, 14 -20	steel, properties of (table), 12-34
pulsation in, 14 -50	Centripetal force (def), 3-15	Chaos (automatic control), 16 -49
relative characteristics of (table), 12 -90	Centrode (def), 3-13	Characteristic curves:
series operation of, 14-48	Centroids (def), 3-6	of fans, 14 -46 to 14 -49
sound power in, 14 -46	of lines, 3-6	of pumps, 14- 24, 14- 26
stability of, 14 -49	of plane areas, 3-6	Charcoal, as fuel, 7-9
system characteristics of, 14 -46	of any quadrilateral, 3-6	Charpy impact test, 5-7, 5-14
system matching, 14 -47	of solids, 3-7	Chattering, of magnets, 15 -64
tubular, 14-45	Ceramic products, 6 -136	Chebyshev polynomials, 2-38
Centrifugal force (def), 3-15 Centrifugal pumps, 14 -15	Ceramics, 6 -136 grinding of, 6 -65	Chemical compounds (def), 6 -3 calculations of, 6 -7
application of, 14- 23	machinable, 6 -65	Chemical elements (def), 6 -3
application of, 14- 23 axial-flow, 14- 15, 14- 23	machining of, 6 -56	table, 6 -3
axial-flow, 14 -13, 14 -23 axial thrust in, 14 -17	manufacture of, 6 -136	Chemical fire extinguishers, 18 -27
balance drums and disks for, 14 -18	properties of, 6 -136	Chemical index, for coal, 9-30
balancing holes for, 14 -17	tool inserts of, 6 -136	Chemical processes: corrosion in, 6 -107
,		_K

Chemical symbols (table), 6-3	Circuits (Cont.):	Coal (Cont.):
Chemistry, 6-3	series-parallel, 15 -52	combustion of, 9-34
Chézy formula (hydraulics), 3 -59	street-lighting, 15 -52	spontaneous, 7-8
Chi-square distribution (statistics, table), 1 -11, 17 -23	three-wire: a-c, 15 -53, 15 -54 d-c, 15 -52	consumption of (table), 7 -8 density and specific gravity of, 7 -7
Chimneys:	resistance and reactance (tables), 15 -48,	firing in boiler furnaces, 9-34
compression at base, 5-40	15 -52	fixed carbon in, 7-6
draft, 9-46	Circular arcs (see Circles)	free-swelling, 7 -7
gases (see Flue gas)	Circular cutters, 13-16	free-swelling index for, 7 -32
winds on, pressure coefficients for (table),	Circular inch (def), 1-16	for gas manufacture (table), 7 -33
12-20, 12-23	Circular measure, 1-17	gasification of, 7 -35
(See also Stacks) Chip breakers, 13-47	of angles, 2 -15 tables, 1 -15	grindability of, 7 -7, 9 -34 tests, 7 -7
Chips, from cutting tools, 13 -46	Circular mil (def), 1 -16, 15 -4	gross calorific value (def), 7 -6
Chrome brick, 6 -152	Circular pitch (gears, def), 8-88	heat value (see Coal, calorific value)
Chromium, 6-78	Circular saws, 13-61	for industrial heating, 7 -41
in tool steel, 13-48	Circulation (aerodynamics, def), 11 -61	lignitic (def), 7-5
Chromizing, 6 -21, 6 -22 of steel, 6 -22	Clad steels, 6 -21 Cladding, by rolling, 13 -14	analyses of (tables), 7-2 to 7-5 meta-anthracite, 7-2
Chutes, 10-43	Clairaut, differential equation of, 2 -32	mineral-matter-free basis of classifying, 7-2
for bulk materials, 10 -43	Clapeyron equation, 4-6	mining, 7 -7
for lumpy materials, 10-43	Claude's system of liquefying air, 19-26	moisture in, 7 -5
spiral, 10 -44	Clay for firebricks, 6-151	net calorific value (def), 7-6
for unit loads, 10-43	Cleaning, sonic, 12 -122	piled, specific gravity and density of (table),
CIM (computer integrated manufacturing), 13-51	Cleansers, 6-137	6 -9
Cinder and fly ash, 9 -29, 9 -32, 9 -35 Cippoletti trapezoidal weir, 3 -57	Clearance in steam engines, 9 -56 Climb of airplanes, 11 -66	preparation of, 7 -7 production of, 7 -8
Circles:	Clock motors, 15-41	proximate analyses of (def), 7-2, 7-5
angles in, 2-5	Closed system (thermodynamics, def), 4 -4	tables, 7 -2, 7 -5
area of, 2 -7	Cloud point (petroleum oils, def), 6-179	pulverized: air supply for burning, 9-34
circumference of, 2-7	Cloudburst hardness test, 5-13	burners for, 9-34
constructions of, 2-6	Clouds (particles in suspension, def), 18 -10	fineness of, 9-34
equations of (analytic geometry), 2 -19 involute of, 2 -23	of large black particles, radiation from, 4-69	fly-ash recovery in burning, 9-32 mills for, 9-32
segments of (tables), 1-2, 1-3	Clutches, 8-37	pulverizing of, 9-32
theorems on, 2-5 to 2-7	allowable pressures in (table), 8 -38	purchase of, under specifications, 7-8
Circuit breakers, 15-46, 15-56, 15-61	cone, 8 -38	rank (def), 7 -2
air-blast, 15 -46	disk, 8 -38	mined in various states (table), 7-5
Circuits (electric), 15-8	for automobiles, 11-6	tables, 7-2 to 7-5
alternating-current: four-phase, 15 -20 interior wiring, 15 -55	dynamatic, for conveyors, 10 -49 friction, 8 -37	reserves, 9-3 sampling, 7-8
parallel, 15 -19	for automobiles, 11 -6	semianthracite (def), 7 -2
polyphase power: advantages of, 15 -20	coefficients of (table), 8-38	separators for, 7 -7
measurement of, 15 -22	jaw, 8 -37	slurry pipeline, 11 -132
quarter-phase, 15-20	multiple-disk (automobile), 11-6	specific gravity of, 7 -7
solution of problems, 15-19	overrunning, 8 -39 positive, 8 -37	table, 6 -8 specifications for, 7 -8
three-phase, 15 -20, 15 -22 two-phase, 15 -20	rim, 8 -39	spontaneous combustion of, 7-8
voltage drop, 15 -53	torque transmissible by, 11 -7	storage, 7-8
Mershon diagram, 15 -47, 15 -49	CM (chemical machining), 13 -66	subbituminous, 7-5
wiring calculations for, 15 -54	CMRR (common mode rejection ratio), 15-76	tables, 7 -3 to 7 -5
branch, voltage drop, 15 -53	CNC (computer numerical control), 13 -51	sulfur in, 7 -6, 7 -31
capacitive, reactance of, 15 -18 carrying capacity of conductors (tables),	Coach screws (table), 8-24 uses of, 8-21	tables, 7-4 sulfur removal from, 7-8
15 -51, 15 -57	Coal (def), 7 -2	transportation, 7-8
critical damping resistance of, 15 -17	analyses (tables), 7-2 to 7-5	ultimate analysis of: methods, 7 -6
dielectric, 15 -15	proximate, 7 -2, 7 -5	table, 7 -4
direct-current, wiring calculations, 15 -53	ultimate, 7-6	volatile matter in, 7-5
discrete component, 15 -71	anthracite (def), 7-2	tables, 7-3, 7-4
effective resistance, 15 -19 impedance of, 15 -18	ash in, 7 -6, 9 -29 composition of (table), 7 -6	Coal-chemical ovens, 7 -33 Coal gas, flame temperatures (table), 4 -29
inductive, 15 -17	fusibility, 7 -6	Coated carbides, as cutting tools, 13-49
time constant, 15 -17	table, 7 -6	Cocks, 8 -207
inductive reactance of, 15-18	bituminous, 7 -2, 7 -5	Code 49 (bar code), 10 -67
integrated, 15 -75	bulk density of, 7 -7	Code One (bar code), 10 -67
linear ramp generator, 15 -78	caking (def), 7 -7	Code 128 (bar code), 10 -63
loop, 15 -52 magnetic, 15 -8	calorific value, 7 -6 Dulong's formula for, 7 -6	Code PDF417 (bar code), 10 -67 Code 16K (bar code), 10 -67
multivibrator, 15-78	Parr formulas for, 7-2	Code 39 (bar code), 10 -62
natural frequency, 15 -17, 15 -19	tables, 7-2 to 7-4	Coefficients:
network, 15 -53	carbonization (see Carbonization of coal)	of area expansion, 4-2
parallel, 15 -8, 15 -52	classification of, 7-2	binomial, 2-10
phase difference, 15 -18 resonance, 15 -19	tables, 7 -2 to 7 -5 cleaning, 7 -7	of contraction, 3 -60 of discharge for liquids through orifices, 3 -56
sample and hold, 15 -78	coking characteristics of, 7 -31	3-60
series, 15 -8, 15 -52	coking process, 7-32	of excess air in combustion (def), 4 -25

Coefficients (Cont.):	Columns (Cont.):	Commutation in d-c generators and motors,
of expansion (def), 4 -2	classification (long and short), 5-38	15 -28, 15 -29
at low temperatures, 19-32	eccentrically loaded, stresses in, 5-40	Commutator motors, a-c, 15-40
film, 4 -83	ends, forms of, 5-38	Compensator (transformer), 15-36
of form (ships), 11-42	long: critical load, 5-38	starting, a-c motor, 15-37
of friction, 3-20 to 3-25, 4-23	Euler's formula, 5-38	Compiler, 2-52
in metalworking, 13-19	slenderness ratio, 5-38	Complex conjugate (def), 2-3
table, 13 -18	strength of (table), 5-39	Complex numbers (def), 2-3
Joule-Thomson, 4-5, 4-24	reinforced-concrete, 12-55	Composites: fiber (see Fiber composites)
of performance (def), 4-10, 4-18	round-ended, strength of, Euler's formula	Composition A (explosive), 7-22
of restitution, 3-19	(table), 5 -39	Composition B (explosive), 7-20
of rigidity (def), 5 -17	short (table), 5-39	Compound, chemical, 6 -3
Steinmetz (table), 15-10	formulas, 5-38	calculation of composition, 6 -7
of thermal expansion of metals (table), 6-11	steel: allowable unit stresses (tables), 5-39	Compound interest (tables), 1-5, 1-6
of transmission, through light-transmitting	pipe, 12 -43	Compound motors, electric, 15 -29
partitions (table), 12 -76	concrete-filled, 12 -56	Compound-wound generators, 15 -26
through skylights (table), 12 -76	table, 12 -43	Compressed air, for industrial plants, 12 -13
through windows (table), 12 -76	properties of (tables), 12 -36	Compressed-air machinery:
of velocity, 3 -60	proportions of, 12 -34	lubrication of, 6 -184
for steam, 4-23	strength of (tables), 5 -39	(See also Air compressors; Centrifugal
COESA atmosphere, 11 -59	timber, 12 -30	compressors)
COGAS (combined gas-turbine and steam-tur-	wooden, 12 -30	Compressibility of liquids, 6 -9
bine, ships), 11-52	working stresses (table), 12 -30	table, 6 -9
Cohesion of liquids, 3 -33	wrought-iron pipe, strength of (tables), 5 -39	Compressible fluids, flow of, 4 -20
	Coma (optics, def), 19-43	
Coils, pipe, 8-185		Compression:
Coining (metal squeezing), 13 -20	Combinations and permutations, 2-10	of air (see Air compression)
Coke, 7-31	Combined-cycle turbines, 9-69	of saturated and superheated vapors, 4 -13,
analyses of (table), 7 -31	Combined flexure and longitudinal force, 5-39	4-14
blast-furnace, 7-31	and torsion, 5 -18, 5 -19	Compression couplings, 8-34
foundry, 7 -31	Combined stresses, 5-18	Compression-ignition (engines), 9-113
high-temperature, 7 -31	Combustion, 4-24	Compression machines, vapor, theory of, 4-18
low-temperature, 7 -31	air required by gaseous fuels, 4-25	Compression ratios (internal-combustion en-
medium-temperature, 7 -31	in boiler furnaces, 9-32 to 9-35	gines, def), 9 -90
petroleum, 7 -31	of coal, 9 -32 to 9 -35	permissible, 9-117
pitch, 7 -31	spontaneous, 7-8	Compression testing, 5 -5
specific gravity and density of (table), 6 -9	control of, in boilers, automatic, 9-45	Compressors:
Coke-oven gas (table), 7 -33	dissociation of gases, 4 -29	accessories for, 14 -33
Coke ovens, 7 -33	equations, 4-25	adiabatic analysis of, 14 -28
briquettes for, 7 -34	excess air for (charts), 4 -30	air (see Air compressors)
heat balances of (table), 7-33	flame temperatures (table), 4 -29	ammonia, 19 -14
pollution controls for, 7 -34	of gaseous fuels, 4-25	centrifugal (see Centrifugal compressors)
preheated coal for, 7 -34	products (table), 4-27	cylinders, 14-32
Coking properties of coal, 7 -31	temperature (table), 4 -29	cooling of, 14-33
tests, 7 -31	of gases: air required for, 4-25	dual, 19 -14
Cold-air refrigerating machines, 19-17	products, 4-25	dynamic versus positive-displacement,
Cold-diffuser conditioning of storage rooms,	heat of formation (def), 4 -27	14 -29
19 -24	heat value of fuels, 4-27	efficiencies, 14-28, 14-38
Cold forging of metals, 13-19	heats of (def), 4-25	for gas turbines, 9-131
Cold storage, 19-21	table, 4 -26	kinetic, 19 -14
insulation requirements, 19 -23	incomplete, loss due to, 4 -30, 9 -35	lubrication, 14 -32
lockers, 19-24	of liquid fuels, 4 -27	motors for, 15 -40, 15 -44
product data (table), 19 -22	products of, 4-25, 4-30	multiple effect, 19-14
rooms: air conditioning, 19 -23	table, 4 -27	multistage sizing, 14 -29
piping, 19 -23	radiation from, 4 -68	nonlubricated cylinders for, 14 -32
	of solid fuels, 4 -30	orbiting-scroll, 14 -37
temperatures, 19-23		
vapor barriers for, 19 -21 Cold-working of metals, 13 -10	air required, 4-30	piston rings for, 14-32
	excess air for (charts), 4-30	piston-rod packing for, 14-32
nonferrous metals, 6 -52	temperatures attained in, 4-29	polytropic process in, 14-28
Colebrook equation for friction, 3-48	volume contraction due to, 4-25	real gas effects in, 14-29
Collapsing pressure of tubes, formula, 5 -45	Combustion chambers:	reciprocating, 14 -30, 19 -14
Collimators, 16-6	for internal-combustion engines, 9-111	refrigeration, 19-14
Color, codes, in industrial plants, 12 -15	axial swirl in, 9-112	relief valves for, 14 -33
designation of, 12 -107	fast-burn, 9 -112	rolling-piston, 14 -34
use, in industrial plants, 12 -15	pent-roof, 9-112	rotary, dry-lobe, 14-37
Color-measurement systems, 12-107	long, radiation in, 4-75	single-screw, 14-36
Color scale for temperatures of iron and steel, 4 -57	partially stirred: radiation in, 4-76	twin-screw, 14-34
Color television, 15-90	Combustion furnaces (see Furnaces)	rotary vane, 19-14
Color test for lubricating oils, 6-179	Combustion turbines (see Gas turbines)	screw, 19 -14
Color vision, 12-99	Come-alongs, 10-13	standard conditions for, 14 -28
Colorimeters, 16-18	Comfort conditions (table), 12 -63	surging in, 14 -30
Colors, for electrical wiring, 15 -61	Comfort indexes, 12-61	trochoidal, 19-14
for identifying piping, 8 -214	Communications channels, bandwidth of, 2 -46,	valves for, 14 -31
Colpitts oscillator, 15 -73	2-48	volumetric efficiency of, 14 -30
Columbium, 6 -79	Communications networks, 2 -47	Wankel, 19 -14
Columns:	layers for, 2-47	wet compression, 19 -14
cast-iron, 12-43	standards for, 2 -47	Computer-aided design, 2-55
strength of (tables), 5-39	Commutating-pole motors, d-c, 15 -29	Computer-aided manufacturing, 2 -55
suchgui of (moics), 3-37	Commutating-poic motors, u-c, 13-27	Computer-aiueu manuraeturing, 4-33

Concrete (Cont.): Computers: Conductors, electric (Cont.): analog, **2**-40 economical cross sections, 15-47 water reducers for, 6-162 applications of, 2-51 watertightness, 6-167 estimating resistances and weights, 15-6 arithmetic in, 2-41 weight, 6-167 materials for, 15-5 compilers for, 2-52 Concrete blocks, 6-135, 12-28 properties of metals and alloys (table), 15-4 specific resistance of (table), 15-4 digital, 2-40 Concrete mixers, 6-166 components for, 2-42 to 2-45 input to, 2-44, 2-45 Condensate pumps, 9-80 temperature coefficients of resistance of (def), Condensation, 9-75 15-4 languages for, problem-oriented, 2-53 Condensers: table, 15-4 procedure-oriented, 2-53 types and applications of (table), 15-57 circulating water, United States temperatures letters in, representation of, 2-42 (map), 9-77 (See also Cables) cooling water, air in (table), 9-82 Conduits for interior wiring (table), 15-59 mathematical programming with, 2-53 direct-contact, low-level, **9**-81 electrical (*see* Capacitors) Cone pulleys, 8-52 memory, 2-43 multiprocessors in, 2-43 Cones, surface and volume of, 2-9 numbers in, representation of, 2-41, 2-42 evaporative, 4-18 Conical pendulum, 3-15 operating systems for, 2-52 refrigeration, 19-14 Conradson carbon-residue test for lubricating operation of, 2-43 double-pipe, 19-14 oils, 6-179 output from, 2-45 evaporative, 19-14 Conservation: of energy, **3**-2, **3**-17, **3**-39, **4**-4, **9**-134 of mass, **3**-2, **3**-39 steam, 9-75 personal, 2-45 air-cooled, 9-81 program-preparation systems for, **2**-42 programming languages for, 2-52, 2-53 air ejectors for, 9-82 of matter, 9-134 programs for, 2-52 to 2-55 two-stage, 9-82 of momentum, 3-2, 3-19 simulation with, 2-53 barometric, 9-81 Consolidation Coal process (coke making), 7-35 software for, 2-51 to 2-55 deaeration of, 9-75 Constant-entropy expansion: speed of, 2-43 direct-contact, 9-81 of gases, 4-9 tapes for, 2-44 ejectors for, 9-82 of vapors, 4-14 flow-induced vibrations in, 9-75 timesharing in, 2-52 Constant-pressure expansion: words in (def), 2-41 movements in, 9-76 of gases, 4-9 Concrete, 6-163 of vapors, 4-14 noncondensibles, removal of, 9-82 Constant-temperature expansion: accelerators for, 6-162 pressure and circulating-water temperatures admixtures, 6-162 of gases, 4-9 for (table), 9-77 of vapors, 4-14 aggregates for, 6-161 surface-type, 9-75 air-entrained, 6-167 calculations, 9-76 Constant-velocity joints, 8-36 air-entraining agents for, 6-162 of size, 9-76 Constant-volume expansion: of gases, 4-9 blast-furnace slag for, 6-161 circulating-water pumps for, 9-80 clay in sand for, 6-168 cleanliness factors for, 9-77 of vapors, 4-14 compaction of, 6-167 condensate pumps for, 9-80 Constrained beams, 5-32 configurations, 9-75 Construction (see Building construction) consistency of, 6-166 curing of, 6-167 expansion in, 9-76 Constructions, geometrical, 2-5 to 2-7 deformation properties of, 6-168 materials for (table), 9-79 Containerization, packaging for, 10-23 dry rodded weight, 6-166 performance curves. 9-79 Containers, 11-134 effect of freezing on, 6-168 proportions of (table), 9-78 condensation in, 11-134 effect of oils and acids on, 6-168 sizing, **9**-76 freight cars for, 11-28 effect of seawater on, 6-168 tube-bundles for, 9-75 handling equipment for, 11-135 fineness modulus of (def), 6-161 owners of, 11-135 tubes: cleanliness, 9-76, 9-77 fly ash as additive for, 6-162 heat-transfer rates, 4-87 refrigerated, 11-134, 11-135 forms for, **6**-167 water boxes for, 9-75 ships for, 11-59 sizes of, 11-134 lightweight aggregates for, 6-161 water velocities in, 9-77 masonry, specific gravity and density (table), steam tables for (tables), 4-44 specifications for, 11-134 tube selection for, 9-75 6-8 terminals for, 11-135 (See also Cooling towers) types of, 11-134 for masonry units, 6-167 materials for, per cubic yard (table), 6-165 Condensing water, cooling of, 9-84 Contaminants: mica in sand for, 6-168 Conductance: in drinking water: limits of (table), 6-170 a-c (def), **15**-19 mixes for, for small jobs, 6-163 in water: removal processes for (table), 18-6 table, 6-164 Continuity equation (in fluid flow), 3-37, 4-20 electrical (def), 15-2 mixing, 6-166 Conductances: Continuous beams, 5-32 painting of, **6**-109 piles, **12**-26, **12**-58 thermal, 4-80 Contour lines (maps, def), 16-55 conversion table, 1-34 Contour mapping (surveying), 16-55 pipe, 8-193 Conduction: Contracts, 12-17 placement of, 6-167 and convection, 4-80 Control: proportioning, **6**-163 heat transmission by, 4-79 automatic (see Automatic control) quality control, 6-166 of material flow, 10-62 Conductivity: ready-mixed, 6-166 electrical (def), 15-2 Control action (automatic control, def), 16-22 reinforced (see Reinforced concrete) thermal (tables), 4-80 to 4-84 Control charts (quality control), 17-24 retarders for, 6-162 conversion table, 1-34 Control systems: sand for, 6-161 of insulation (tables), 4-84 adaptive (def), 16-22 of liquids and gases (table), 4-82 seawater used for, 6-161 hydraulic, 16-30 silica fume for, 6-161 in materials for low temperatures (table), Controllable-pitch propellers: airplane, **11**-98 marine, **11**-54 slump test for, 6-166 of metals (tables), 4-80, 4-81 table, 6-165 strength of, 6-167 of miscellaneous solids (table), 4-83 Controllers: Bode plots for, 16-37 variation with age (table), 6-167 (See also Heat transmission) Convection: transverse strength of, 6-168 Conductors, electric, 15-4 coefficients of, 4-83 water for, 6-161 aluminum (table), 6-60 and conduction, 4-80 water and air requirements for (tables), 6-164, copper alloys for (table), 6-67 heat transmission by, 4-86 cross-sectional areas (table), 15-59 natural, 4-86 6 - 165water content (tables), 6-164, 6-165 current-carrying capacities (table), 15-57 Convers-Labarre method (pile spacing), 12-27

Conversion, of mass to energy, 9-134	Conveyors (Cont.):	Cooling towers (Cont.):
Conversion equations, for kinematic viscosity,	drives for, 10 -49	mechanical-draft in, 9-85
3 -33	feeders for, 10 -52	performance calculations for, 9-85
Conversion tables: for accelerations, 1-32, 1-33	flight, 10 -40 arrangements for, 10 -42	performance of (curve), 9- 85 for thermal pollution reduction, 17- 35
for angular measure: decimals of degrees,	scraper type, 10 -40	wet-bulb temperatures (map), 9-84
minutes, and seconds, 1-15	suspended-chain type of, 10 -40	where used, 18-5
velocity, 1-32	suspended-flight type of, 10 -40	Cooling water systems, corrosion in, 6 -107
for areas, 1-30	gravity roller, 10-52	Coordinates:
for conductance, thermal, 1-34	hydraulic, 10-54	polar, 2 -19
for conductivity, thermal, 1-34	noncarrying, 10 -40	rectangular, 2-18
for density, 1-26, 1-27, 1-34	oscillating, 10-52 overhead, 10-35	transformation of, 2 -19 COP (coefficient of performance, def), 19 -2
for energy, 1 -33 for flow of heat, 1 -34	components of, 10 -37, 10 -39	Copes (molding), 13-5
for heat, 1-33	control, 10 -39	Copper, 6 -65
for length, 1-16, 1-28, 1-29	drop-lift, 10 -40	alloys (see Copper alloys)
for mass, 1 -31	power-and-free, 10-38, 10-39	for bus bars, 15 -45
for power, 1-34	powered, 10 -35	cable, resistance and reactance of (table),
for pressure, 1-32	safety guards, 10-38	15-48, 15-52
for specific gravity and density, degrees API and Baumé, 1-26, 1-27	switching, 10 -38, 10 -39 controls, 10 -39	conductors, current-carrying capacities (table), 15 -57
for velocity, 1-32	track for, 10 -37	oxygen-free, 6 -67
for volume, 1 -16, 1 -30, 1 -31	transfer devices, 10-38	resistivity of, 15 -4
for weight, 1-31	trolleys, 10-37	tough-pitch, 6-67
for work, 1 -33	turns, 10 -37	tubing, 8 -191
Converters:	for plant uses (table), 10 -36	welding of, 6-73 , 13-45
analog-to-digital, 15 -78	platform, 10-53	Copper alloys, 6 -67 for bearings, 6 -61
digital-to-analog, 15 -78 phase, 15 -39	pneumatic, 10 -53 reciprocating plate feeder for, 10 -52	table. 6 -61
synchronous, 15-42	Redler, 10 -41	brazing of, 6 -73
switchboard equipment for, 15 -46	ribbon, 10 -42	castings, composition and properties of (table),
Conveying:	roller, 10 -52	6 -71
bucket, 10 -45	runaround, 10-41	distribution of (table), 6 -70
(See also Conveyors, bucket)	scraper, 10 -40	classification of, 6 -65
cableways, 10-30	screw, 10-42	table, 6-65
(See also Cableways; Conveyors) Conveyors:	cut-flight, 10 -42 paddle, 10 -42	copper-aluminum, plastic range chart for, 13 -10 for copper-base castings, 6 -70
apron, 10 -44	power required, 10 -43	properties of (table), 6- 71
table, 10 -45	short-pitch, 10-42	copper-nickel (tables), 6 -68
in assembly operations, 10-37	speeds and capacities (tables), 10-43	copper-silicon (tables), 6-68
belt, 10 -47	variable-pitch, 10 -42	copper-tin, 6 -67
arrangements, 10 -47, 10 -52	spiral, 10 -42	copper-zinc, 6 -67
belts for, 10 -48 capacities of (table), 10 -50	speeds and capacities of (table), 10 -43 suction for, 10 -53	corrosion resistance of, 6 -73 effects of temperature on, 6 -72
changing direction of materials on, 10 -54	trolley, 10 -35	electrical conductivities of, 6 -72
diverters for, 10 -55	vertical, 10 -40	for electrical conductors (tables), 6 -67, 15 -4 to
drive calculations, 10-51	vertical interfloor, 10-40	15 -6
drives for, 10 -49	vibrating feeders for, 10 -52	extruded, 6 -70
electromagnetic separators for, 10 -51	wheel, 10 -53	fabrication of, 6 -73
feeders, 10-52	Convolution: of functions (def), 2-36	heat treating of, 6-70
horsepower required for, 10 -49 idler pulleys for, 10 -48	Convolution integrals (vibration), 3 -69 Coolants (cutting fluids), 13 -50	machining of, 6 -67, 6 -73 mechanical properties of, 6 -70
intersections for, 10-55	Coolers:	processing of, 6 -70
life of, 10 -48	for air conditioning systems, 12-91	soldering of, 6 -73
magnetic pulleys for, 10-51	brine, 19 -18	fluxes for, 6-73
maximum slope (table), 10 -49	capacity of (table), 19-19	strength of (tables), 6 -68
portable, 10 -52	heat-transfer coefficients (table), 19 -24	temper designation codes for (table), 6 -66
pulleys for, 10 -48, 10 -51 sectional, 10 -52	Cooling: effect of throttling, 4 -24	thermal conductivities of, 6 -72 turning of, 6 -73
shuttle, 10 -52	of internal-combustion engines, 9-117	welding of, 6- 73, 13- 45
sliding, 10 -52	thermoelectric, 19 -17	wrought, composition and properties of
slope for various materials (table), 10-49	Cooling ponds, 9-86	(table), 6 -68
speed (table), 10 -51	for thermal pollution reduction, 17 -35	(See also Brass; Bronze)
take-ups, 10 -49	Cooling sprays, 9-86	Copper-nickels, 6 -67
trippers, 10 -49, 10 -51 width required for lumps (table), 10 -51	Cooling towers, 4 -18, 9 -84 for air conditioning systems, 12 -92	Copper pipe, 8-191 Copper tubing, 8-191
bucket, 10-45	approach (def), 9-84	Copper wire:
open-top, 10 -45	cooling range of (def), 9-84	alloys for (table), 6 -68
Peck carrier, 10-46	corrosion in, 6 -107	ASTM specifications for (table), 6-67
pivoted, 10 -45	cost evaluation, 9-85	insulation for, 15 -57
capacities (table), 10 -46	drift in, 9 -84	reactance (tables), 15 -48, 15 -52
V-bucket, 10 -45 capacities and weights (table), 10 -45	dry, 9- 86 height of, 9- 85	resistance (tables), 15 -5, 15 -6, 15 -48, 15 -52, 15 -56
Bulk flo, 10 -41	hyperbolic, 9-85	temperature coefficient of, 15 -4
carrying, 10 -45	induced-draft, 9-85	weight (table), 15-5
continuous-flow, 10-41	makeup for, 9-84	Coppers, 6 -65, 6 -67
drag-chain, 10-40	materials for, 9-85	Copperweld (electrical conductor), 15-6

Copy (printing):	Corrosion (Cont.):	Costs (Cont.):
fitting, 19 -43	inhibitors, 6 -104	of materials, 17-14
preparation of, 19 -43 Copyrights, 18 -30	intergranular, 6 -101	variable, characteristics of, 17-12
Cord (lumber measure, def), 1 -16, 7 -9	kinetics of, 6 -96 activation polarization in, 6 -96	Cotangent (trigonometry), 2 -15 Cotter pins, 8 -33
Cordage, 6 -137	active/passive metals in, 6 -96	Cotton, mercerized, 6 -140
Core binders, 13 -6	equilibrium potential in, 6 -96	Cotton fibers (tables), 6-141
Core blowers, 13-6	mixed polarization in, 6-96	Coulomb (def), 15-2
Core boxes, 13-2	passive films in, 6 -96	Counters (event measurement), 16-2
Core driers, 13-6	6-97	electric, 16-3
Core molding, 13-3	passivity in, 6 -97	electronic, 15-81
Core ovens, 13-6 Core sands, 13-6	polarization in, 6 -96 protective films in, 6 -97	mechanical, 16 -2 pickups for, 16 -3
Coremaking methods, 13 -6	resistance polarization in, 6 -96	Counterweights for elevators, 10 -18
Cores (def), 13 -2	as knife-line attack, 6 -101	Couple (mechanics, def), 3 -3
Coriolis acceleration, 3-13	liquid-metal embrittlement in, 6-102	Couples:
Cork, specific gravity and density of (table), 6-7	microbiologically influenced, 6-98	composition of, 3-4
Corkscrew rule (magnetism), 15 -11	Nernst equation for, 6 -95	displacement of, 3-3
Corner test (statistics), 17-21	nonabsorbent gaskets to prevent, 6 -100	moment of, 3-3
Corona (electrical discharge), 15 -50	organic inhibitors for, 6 -105	rotation moments of, 3-3
Corrosion 6 05	oxygen scavengers in, 6 -106	Coupling:
Corrosion, 6 -95 with anodic protection, 6 -105	passivators, 6 -104 as pitting, 6 -100	Couplings: clutch (see Clutches)
in boilers, 9 -49	pitting factors for, 6 -100	compression, 8-34
cathodic inhibitors for, 6 -105	potential-pH plots in, 6 -95	constant velocity, 8 -36
with cathodic protection, 6-105	Pourbaix diagrams for, 6 -95	fire-hose: ANSI (table), 8-214
caustic, 6-101	precipitators for, 6-105	screw threads for, 8-214
as caustic gouging, 6 -101	prevention of, 6 -104	flanged-face, 8-34
by cavitation, 6 -102	protective coatings against, 6 -104	flexible, 8 -34
chemical, 6 -95	solid-metal-induced embrittlement in, 6 -102	chain, 8 -35
coatings for, 6-104	in steam-generating systems, 6 -105	Falk Steelflex, 8-35
conversion coatings, 6 -104 crevice, 6 -99	in steam turbines, 6 -016 by stray-current electrolysis, 6 -99	Fast, 8 -35 Oldham, 8 -35
by dealloying, 6 -101	by stray-currents, 6 -99	Waldron, 8-35
by dezincification, 6 -101	stress, cracking, 6 -102	fluid, 8 -36
as ductile gouging, 6-101	as surface carburization, 6-101	for automobiles, 11-6
economic impact of, 6-95	testing, 6 -103	torque capacity (eq), 8-36
effects of galvanic metals on, 6 -99	using corrosion coupons for, 6 -103	torque converter, 8 -37
effects on safety, 6 -95	electrochemical techniques for, 6 -103	ribbed clamp, 8-34
electrochemical, 6 -95	standardized methods for, 6 -103	rigid, 8 -34
Ellingham diagrams for, 6 -96 by environmentally induced cracking, 6 -102	thermodynamics of, 6 -95 as uniform attack, 6 -99	rubber, 8 -35 sleeve (pipe), 8 -185
erosion (def), 6 -101	as wick boiling, 6 -101	slider, double, 8 -35
factors influencing, 6 -97	Corrosion coupons, 6 -103	universal, Hooke's joint, 8-36
cold-working, 6 -97	Corrosion fatigue of metals, 5 -9	CPM (critical path method), 17-5
concentration cells, 6-98	Corrosion precipitators, 6-105	CPU (central processing unit), 15-82
dissimilar electrodes, 6 -98	Corrugated paper, 6-144	Cracked gasoline, 7-12
environment, 6 -97	Corrugated sheets, for building walls, 12 -25,	Cramer equation for pollution calculations, 18 -14
freshwater, 6 -97 hard water, 6 -97	12 -43 Corundum (abrasive), 6 -129	Cranes: capacities of (table), 10-28, 10-30
heat treatment, 6 -97	Cosecant (trigonometry), 2 -15	derricks, 10 -27, 10 -29
high-purity water, 6 -97	Cosine (trigonometry), 2-15	efficiency of, 3-26
inclusions, 6 -97	Cosines, law of, 2-17	gantry, 10 -27
microfouling organisms, 6-98	Cost accounting, 17-11	hand-power, 10-27
residual stresses, 6 -97	accrual basis, 17-12	hooks, 10 -7
seawater, 6-98	activity based, 17-15	industrial (table), 10 -28
soft water, 6 -97	break-even, 17 -17	jib, 10 -27
soil corrosivity, 6 -98 soil resistivity, 6 -98	budgeting control systems in, 17 -16 cash basis, 17 -12	locomotive, 10- 27, 10- 29 motors for, 15- 44
sulfate-reducing bacteria, 6 -98	cost management by, 17 -18	overhead, 10 -26
temperature, 6 -98	direct costing methods for. 17 -18	special purpose, 10-27
thermal cycling, 6 -98	factory overheads in, 17-12, 17-14	power shovels as, 10-33
thermogalvanic cells, 6-98	labor, 17 -14	rotary, 10 -27
time of wetness, 6 -98	materials, 17-14	telescoping boom, 10 -33
welding, 6 -97	methods of, 17 -14	traveling, 10-26
fatigue, 6 -102 feedwater treatment against, 6 -105, 6 -106	process cost method of, 17 -14 for product costing, 17 -12	electric, 10 -27 truck, 10 -29
galvanic, 6 -99	purposes of, 17-11	Crank mechanism, 8-3
Gibbs free energy in, 6 -95	standard costs, 17 -16, 17 -17	Crankshafts, 8 -47, 8 -50
graphite, 6 -101	transaction costing in, 17 -15	flywheels for, 8 -65
with graphitization, 6-101	transfer pricing by, 17 -17	forces and torques on, 8-65
of gray cast iron, 6-101	types of systems for, 17-16	(See also Shafts)
high-temperature, 6 -103	Cost analysis, 17-17	Creep (def), 13 -9
hydrogen embrittlement in, 6 -102	Costs:	of low-chromium steel (table), 5 -11
hydrogen evolution reaction (HER) in, 6 -95	elements of, 17-12	of metals (def), 5 -10, 6 -77
hydrogen interactions in, 6 -102 by impingement attack, 6 -102	fixed, characteristics of, 17 -12 of labor, 17 -14	testing, 5 -10 of zinc and zinc alloys, 6 -94
5) mpmbement attack, 0-102	01 M001, 17 1 T	or zine and zine anoys, 0-74

Creep rates:	Currents, alternating, waves (Cont.):	Cutting tools (<i>Cont.</i>):
of iron (table), 5-11	phasor representation, 15-18	wear notches in, 13-47
of metals and alloys (table), 5-11	vector representation, 15-18	wood, 13 -72
of steel (table, chart), 5-10, 5-11	electric, unit of (def), 15 -2	(See also Machine tools)
Crescent beams, 5-42	heat developed by, 15-8	Cyaniding (heat-treatment), 6 -21
Critical cooling rate (steel), 6 -18	wattless, 15 -18	Cycle:
Critical damping resistance, 15 -17	(See also Circuits; Electric motors)	alternating-current (def), 15 -18
Critical data for various gases (tables), 4 -50,	Curvature, radius and center of, 2 -26	ideal gas, 4 -10
4-58	Curve resistance (train), 11 -39	for perfect gases, 4 -10
Critical flow pressure, in gas or vapor flow,	Curved beams, 5-42	steam, 4 -19
4-21	eccentrically curved (table), 5-42	bleeding, 4 -19
Critical path method of scheduling, 12 -18, 17 -5	Curves, railway, radii of, 11-38	Rankine, 4-19
Critical points:	Curvilinear motion, 3-11, 3-12	reheating, 4-19
of the elements (table), 4-58	Cut and fill:	Cycloid, 2 -22
of various substances (table), 4-50	defining limits of, 16 -58	Cyclone furnaces, 9-35
Critical pressure (def), 4-13	determining land area for, 16 -57	Cyclone separators, 18 -10
Critical speed, 3-66	establishing boundaries for, 16 -57	for dust exhaust systems, 18-10
Critical state for gases (tables), 4-50, 4-58	Cutters:	Cylinder-boring machines, 13 -55
Critical temperature (def), 4 -13	circular, 13-16	Cylinder grinders, 13 -64
Critical temperatures:	milling, 13 -57	Cylinders:
of the elements (table), 4-58	Cutting:	air resistance of (table), 11-68
of iron (def, chart), 6 -16	with laser beams, 13-30	of automobile engines, 9-111
of various substances (table), 4-50	thermal, 13 -31	collapsing pressure, 5 -45
Crocus (abrasive), 6-129	oxyfuel, 13 -31	hollow, volume of, 2-8
Cross product (mathematics, def), 2-11	plasma arc, 13-31	of internal-combustion engines, 9-111
Crossover frequency (control theory), 17-41	(See also Metal cutting)	oval hollow, strength of, 5-47
Crowding (metalworking), 13-15	Cutting fluids (machining), 13-50	rolling down a plane, 3-16
Crushed steel (abrasive), 6-128	Cutting-off machines (metals), 13-61	shrink-fit effects, 5 -46
Cryogenic refrigerators, 19-27	Cutting oils, 6-184	of steam engines, jackets, effect on economy,
Cryogenics, 19-26	Cutting processes, 13-31	9-55
applications of, 19 -29	gears, 13 -59	stiffening rings for, 5-45
cryogen hazards, 19 -40	Cutting tools:	surface and volume of, 2-8
definition of, 19 -27	action of, 13 -46	thick-walled, 5-46
equipment materials, 19 -32, 19 -38	applications of, materials for (table), 13 -49	thin-walled, 5 -45
stress analysis, 19-41	back rake of, 13 -52	
gas liquefaction for, 19 -29	broaches, 13-60	D (107
instruments for, 19 -37	carbide, 13 -49	Dacron rope, 6 -137
insulation for, 19 -38	ceramic, 13-50	D'Alembert forces (def), 8-65
selection of, 19 -40	chip formation by, 13-46	Dalton's law for gases, 4-9, 4-15
level measurements, 19 -37	cutting angle of, 13-46	Dampers, viscous, 3 -61
by capacitance gage, 19-37	cutting ratios for, 13-46	Damping:
by weighing, 19-37	diamond, 13-50	in automatic control (def), 16 -22
steels for service in, 6-28	drills, troubleshooting of (table), 13 -54	critical, 3-63
temperature measurements, 19 -38	fluids for, 13-50	friction, 3-21
vent systems for, 19 -40	hardness vs. temperature (chart), 13 -48	hysteretic, 3-66
Cryogens: burns from, 19 -41	for lathes: life of, 13-47	structural, 3 -66 of vibrations, 3 -62, 3 -66
compressibility of, 19 -36	power requirements of, 13-47 shapes for, 13-52	viscous (automatic control), 16 -24
	troubleshooting of (table), 13 -54	Damping ratio (automatic control, def), 16 -24
liquid density, quantum-mechanical correla- tion, 19 -35	materials for, 13-48	Darcy formula in pipeline flow, 11 -131
properties of (table), 19 -34	characteristics of (tables), 13 -48, 13 -49	Darlington connection (electronic circuit), 15 -71,
specific heat (chart), 19 -37	milling machines, 13-57	15-73
thermal conductivity, 19 -37	feeds and speeds for (table), 13 -58	Darrieus wind rotor, 9-5, 9-7
thermal-expansion coefficient, 19 -36	troubleshooting of (table), 13-58	D'Arsonval galvanometer, 15 -20
vapor pressure (chart), 19 -36	nomenclature of, 13 -46, 13 -52	Dashpot, 3-61
viscosity, 19-37	nonferrous, 13-49	Data, coding of, for electronic transmission, 16-20
volumetric latent heats (table), 19 -34	nose radius of, 13-52	Data-flow diagrams, 2-50
Crystalline alumina (abrasive), 6 -128	planers, 13 -60	Data logging, 16 -19
Crystolon (abrasive), 6 -128	rake angle of, 13 -46, 13 -52	systems for, 16 -20
Crystoplastic (def), 13 -9	reamers, 13 -57	Data Matrix (bar code), 10 -67
Cubic measure, conversion tables, 1 -30, 1 -31	relief angle of, 13 -46, 13 -52	Databases, for computers, 2 -49
Cubical expansion, coefficient of (def), 4 -2	shapers, 13 -60	Day:
Cupolas, 13-7	shapes of, 13 -52	definitions of, 1 -25
Cupronickel, 6 -67	shear angles for, 13-46	lengths of, sidereal, solar, and stellar, 11-101
tables, 6 -68	shear plane of, 13 -46	Dead-weight gage tester, 16 -9
Curl, vector, 2-34	shear strain in, 13-46	Deaeration: of feedwater, 9-49, 9-89
Current regulators (automobiles), 15-66	side-cutting edge angle, 13-52	Deaerators, 9-89
Current transformers, 15 -23	side rake of, 13 -52	Decibel (sound, def), 12 -117
Currents:	steel, 13 -48, 13 -49	Decimal equivalents (table), 1 -15
alternating, 15-18	surface finish by, 13-48	Decision making, 17-7
active or energy (def), 15 -18	threading, 13-57	cost accounting to support, 17-18
circuits (see Circuits, alternating-current)	tool condition monitoring, 13-47	under certainty, 17 -7
reactive or wattless (def), 15-18	tool temperatures in, 13-47	under uncertainty, 17-7
waves: average value, 15-18	tungsten carbide, 13-49	Declination, solar, annual variation (table), 9-12
effective value, 15 -18	classification of (table), 13-49	Dedendum (gear teeth), 8-88
form factor, 15-18	wear of, 13 -47	Definite integrals, 2-29

Deflection:	Diesel engines:	Direct energy conversion (Cont.):
angular, under torsion (table), 5-37	analysis of engine process, 9-91	thermionic generation, 9-24
of beams (see Beams, deflection of)	combustion chambers, 9-113	Fermi level, 9-25
Defoamants, in engine oil, 6 -182	cooling systems for, 9-117	work-function barrier, 9-25
Deformation (def), 5-15 plastic flow theory, 5-50	cycle for, 4 -11, 9 -90 efficiency of: indicated, 9 -91	thermoelectric generation, 9 -24 figure of merit for, 9 -24
of spheres and cylinders under compression,	theoretical, 9 -91	Direct view factors (radiation, def), 4 -63
5 -45	volumetric, 9-92	Directrix:
Degrees:	emissions control strategies, 9-122	of catenary, 2-21
API (table), 1 -26	exhaust-gas analysis of (table), 9 -94	of ellipse, 2 -20
Baumé (table), 1-27	exhaust temperatures, 9-94	of hyperbola, 2 -20
Dehumidification of air, 4-17 (See also Air conditioning)	exhaust treatments, 9 -122 fuel injection in, 9 -110	of parabola, 2 -19 Discharge coefficients for flow of liquids, 3 -54,
Delco-Remy distributors, 15 -66	nozzles for, 9-111	3-56, 3-58
Delta connections, three-phase circuits, 15 -20	fuel lines for, 9-111	Discounted cash flow, 17-18
Delta iron (def), 6 -16	fuel sprays, 9-111	Disk brakes, 8 -42, 11 -15
Demand factor of buildings (electric power),	fuels for, 9 -104	Disk clutches, 8 -38, 11 -6
15-61 Demodulation of radio ways 15.74	table, 9-104	Disk wheels, steam turbine, 5 -51
Demodulation of radio waves, 15 -74 De Morgan's theorem (Boolean algebra), 15 -80	(See also Diesel fuels) governing of, 9-117	Disks: air resistance of (table), 11 -68
Denier (unit of fineness of fibers), 6 -140	intake manifolds for, 9-106	computer, 2-45, 15 -83
Density (def), 1 -26	locomotive (see Locomotives, diesel-	controllers for, 15 -83
of air (formula), 14-45	electric)	nutating, liquid-meter, 16-7
conversion table, 1-34	lubrication of, 6 -183	rotating: with central hole, 5 -50
equivalents (table), 1-34	marine, 9 -99	with noncentral hole, 5-51
of metals (table), 6-7 , 6-11 , 6-50 of various substances (table), 6-7	data on (tables), 9 -98, 9 -99 medium-size (table), 9 -101	Dispersants: in engine oil, 6 -182 Dispersion (optical), 19 -41
of water (table), 6-8 , 6-10	pollution from, 18 -10	Displacement:
Depreciation of power equipment, 17 -36	pump injection, 9-110	motions, 3-10
Derivative compensation (automatic control),	stationary, 9 -99	of ships (def), 11-41
16-25	data on (table), 9-98	Displays (radar), 15-88
Derivatives:	supercharging, 9-106	Dissociation:
calculus, 2 -24, 2 -25 partial, 2 -25	for tractors, 9 -98 for trucks and buses, 9 -97	in combustion of gases, 4-29 of gaseous fuels and explosion temperatures
Derricks, 10 -29	Diesel fuels, 7 -12, 7 -13, 9 -116	(table), 4 -29
Design stresses (mechanics), 5-20	additives, 7-14	Distance:
Desktop publishing, 2-54	distillation curves, 7-11	measurement of, 16-4
Destec coal-gasifier unit, 7-39	grades, 7 -13	analytic geometry formulas for, 2-19
Detergents, 6-137	specifications for (table), 7-14	in surveying, 16 -50, 16 -51, 16 -55
Determinants, 2-13 Detonation (knock), 7-12	Differential calculus, 2 -24 to 2 -26 Differential chain block, 8 -8	Distillation of crude oils (chart), 7-11
(See also Knock)	Differential equations:	Distribution systems, electric (<i>see</i> Electric power distribution)
Deuterium as cryogen, 19 -34	homogeneous, 2-32	Distributions (probability), 2 -10, 2 -11
Deviation, in automatic control (def), 16-22	Laplace transforms, 2-35	Distributors (electric ignition), 15-66
Dew point, 4 -15, 12 -87	partial, 2 -34	Disturbance (automatic control, def), 16 -22
Dew point method of humidity measurement, 4-15	solutions of, 2-31, 2-34	Divergence:
Dewpoint recorders, 16 -18 Dextrin baked cores, 13 -6	Differential transformer pick-ups, 3-79	of nozzles for steam flow, 4-23 vector, 2-34
Diametral pitch (gears, def), 8 -88	Differentials:	Divergence theorem, 2 -35
Diamond (abrasive), 6 -128, 6 -129, 13 -62	in automobiles, 11 -10	Diverters, for belt conveyors, 10 -55
Diamond cutting tools, 13-50	calculus, 2-24	DMA (direct memory access) controller, 15-83
Diamond-pyramid hardness (def), 5-13	Differentiation: rules for, 2-24	Docks, loading, design of, 10-73
Diaphragm gages, 16-8	Digital-to-analog converters, 16 -20	Dodecahedron, 2-9
Diaphragms to replace packing, 8 -142 Diatomaceous silica (abrasive), 6 -129	Dihedral (def), 11-71 Dimensional analysis, 3-44 to 3-46	Dolomite, composition of, 6 -152 Domain (algebra, def), 2 -3
Die blocks:	theorems, 3-44	Domestic refrigerating machines, 19 -16
materials for, 13-20	Dimensionless numbers, 3-41 to 3-43	Doors, coefficients of heat transmission through
proportions of, 13-20	Dimensions:	(table), 12 -70
Die casting, 13-4	of common variables (table), 3-45	for industrial plants, 12-15
alloys for, zinc-base (table), 6 -94 machines for, 13 -4	of a quantity (def), 3-44 Dings lifting magnets, 10 -11	Dot product (mathematics, def), 2 -11 Draft:
Dielectric (def), 15 -15	Dings magnetic separators, 10 -51	forced, 9-46
Dielectric circuit, 15 -15	Diode (electronics), 15 -68	induced, 9-46
Dielectric constant (def), 15-2	free-wheeling, 15-71	natural, 9-46
of insulating materials (table), 15 -16	Dip brazing, 13-29	of ships (def), 11 -42
Dielectric heating, 7-55 , 15-87	Dipole function, 2-36	stack effect (table), 9-47
Dielectrics, 15 -15, 15 -16 Dieline (refrigerant), 19 -7	Dirac delta function, 2 -36 Direct-current circuits, wiring calculations for,	Draft loss (def), 9 -46 Draft tubes (hydraulic turbines), 9 -155
Dies:	15-53	Drafting, geometrical constructions in, 2 -6
clearances required in, 13 -15	(see Generators, direct-current)	Drag (aerodynamics):
resistance to shearing in (table), 13-15	Direct-current instruments, 15-20	coefficients of, for various bodies, 11-67
threading, 13-57	Direct energy conversion:	of floats, 11-69
Diesel cycle, 4 -11, 9 -90 Diesel-electric drives:	fuel cells, 9-25 notable surface of action in, 9-25	of fuselage, 11-69 in hydraulics, 3-47
locomotive, 11-20	magnetohydrodynamic generation, 9-26	induced, 11 -61, 11 -62
table, 11 -21	photovoltaic generation, 9-26	interference, 11-70

Drag (Cont.):	Ducts (Cont.):	EBM (electron-beam machining), 13-67
of nacelles, 11-69	design of, 12 -88	Eccentric angle in ellipse, 2 -20
parasite, 11-66	equal friction method for, 12-88	Eccentric loads:
profile, 11-62, 11-69	static regain method for, 12-88	on circular rings, 5-40
supersonic (see Supersonic and hypersonic	noise in, 12 -90	on cylinders, 5-40
aerodynamics) of tail surfaces, 11-69	pressure loss in, 12-88	on short blocks, 5-40 on various cross sections, 5-40
of various bodies (table), 11 -68	return face velocities (table), 12 -89 Dulong and Petit's rule (specific heat), 4 -3	Eccentricity:
of wings, 11-62, 11-69	Dulong's formula (calorific value of coal), 7 -6	of ellipse, 2 -20
Drag coefficients (table), 11 -68	Dumbwaiters, 10 -19	of hyperbola, 2 -20
Drag forces, 11-66	Dumpers (earth moving), 10 -26	ECDG (electrochemical discharge grinding),
Drag-free satellites, 11 -111	Duralumin, creep rates for, 5-10	13 -66
Drag-link mechanisms, 8-3	Dust (def), 7 -22, 18 -8, 18 -10	ECG (electrochemical grinding), 13-66
Dragline buckets:	explosive, characteristics of (table), 7-23	Ecology (def), 18-2
scraper, 10-11	removal of: by electrostatic collectors, 9-32	(See also Environmental control)
self-filling, 10 -11	by mechanical separators, 9-32	Economic lot size, 17-6
Dragline excavators, 10 -22, 10 -33, 10 -34 Drags (molding), 13 -5	screen scale for (table), 18 -11 size of particles in, 18 -8, 18 -10	Economics, industrial, 17-2
Drain pipe (table), 8 -194	velocity of settling (chart), 18 -9	Economizers, 9 -43 corrosion in, 9 -43
Drainage fittings, threaded (table), 8 -205	Dust collectors, 9-32	size of, 9 -43
Dram or drachm:	Dust explosions:	types of, 9 -43
apothecaries' liquid measure (def), 1 -16	building design to prevent, 7 -27	Ecosystems, 18-2
apothecaries' weight (def), 1-17	characteristics of (table), 7 -23	Eddy-current brakes, 8-42, 16-15
avoirdupois weight (def), 1-17	composition of atmosphere and dust in, 7-22	Eddy-current losses, 15-11
Drawbar horsepower, of locomotives, 11-24	concentration of dust in, 7-26	Eddy-current testing of materials, 5-66
Drawing of metals, 13 -16	definition of, 7 -22	EDG (electric-discharge grinding), 13-66
pressure in, 13-17	effects of inerts on, 7-25	Edison storage cell, 15 -13, 15 -14
various shapes, 13-18	explosibility index of (def), 7-26	EDM (electric-discharge machining), 13-65
work done in, 13 -18	factors affecting, 7-22, 7-27	(electronic distance meter), 16 -51
Dredges: diesel, 10 -34	fineness of dust in, 7 -22 ignition sources, 7 -22, 7 -27	EDS (Exxon donor solvent), 7-18 EER (energy efficiency ratio, def), 19-2
digging ladders for, 10 -33, 10 -34	ignition temperatures for, 7 -26	Effective temperatures (wind chill, table), 12 -62
elevator, 10 -34	inerted atmosphere to prevent, 7 -27	Efficiency:
hydraulic, 10-34	maximum pressure in, 7-26	of Carnot cycle, 4 -6
placer, 10 -33	minimum concentrations for, 7-26	of machine elements (table), 3-26
Driers, for paint, 6 -108	minimum energy to ignite, 7 -26	Eigenvalues, 2-14
(See also Evaporators)	oxygen concentrations for, 7 -25	Eigenvectors, 2-14
Drift bolts, pulling resistance of, 12 -33	particles in, sizes of, 7-22	Ejectors:
Drilling:	surface area of, 7-22	air (see Air ejectors)
of plastics, 13-65	pressure-rise rates, 7-26	high-vacuum, 14 -39
sonic, 12 -122 various metals (table), 13 -56	prevention of, 7 -27 relative hazards, 7 -26	table, 14 -40 Elastic constants of metals (table), 5 -4
Drilling machines, 13 -55	relief venting for, 7 -27	Elastic limit (def), 5-2, 5-17
sizes of, 13 -55	turbulence in, 7 -22	in flexure, 5-27
Drills:	of various materials (table), 7-23	proportional (def), 5-2
for pipe taps (table), 8-20	Dynamic balance, 3-67	Elastic solid (def), 3-30
sizes of (table), 8-86	Dynamic braking:	Elasticity (def), 5-17
tap, sizes of (table), 8-30	of locomotives, 11-23, 11-26	modulus of (def), 5-17
troubleshooting of (table), 13-56	of transit cars, 11-35, 11-37	for metals (tables), 5 -4, 6 -50
twist, 13 -55 sizes of (table), 8 -86	Dynamic electricity (def), 15 -15 Dynamic similarity (models), 3 -41	theory of, 5-44
Drop-forge dies, 13 -19	Dynamic unbalance (def), 3-67	Elastomers (rubberlike substances), 6 -146 comparative properties of (table), 6 -147
Drop forging, 13 -19	Dynamics, 3-14 to 3-17	properties of, at low temperatures, 19 -34
Drop hammers, 13 -19, 13 -22	of fluids, 3 -37 to 3 -41	Electric apparatus:
Drop presses, 13-22	Dynamites, 7-20	efficiency calculations, 15 -43
Drop-weight test, 5-7	ammonia, 7 -20	rating, 15 -43
Dropping point (greases), 6 -180	ammonia gelatin, 7 -20	symbols for, 15-7
Drums:	gelatin, 7 -20	temperature limits, 15 -43
for hoisting: rope for, 10 -8	straight, 7-20	(See also Electric instruments)
for wire rope, minimum groove dimensions	Dynamometers, 16 -15	Electric-arc welding (see Welding)
for (table), 8 -80 ratios for, 8 -79	Dyne (def), 1 -24	Electric brakes, 8 -43 Electric circuits (<i>see</i> Circuits)
Dry batteries (<i>see</i> Batteries, dry)		Electric conductivity, 15 -2
Dry-bulb temperature (def), 4 -15, 12 -87	E transformer, 16-5 , 16-6	Electric current (see Current)
Dry cells, 15 -11	Earth:	Electric-discharge machining of metals, 13-66
Dry ice (solid carbon dioxide), 19-25	mass of, 11 -101	Electric energy:
Dry measure, 1-16	moment of inertia of, 11-101	measurement of, 15 -23
DSP (digital signal processor), 15 -85	orbital speed of, 11 -101	units of (def), 15 -2
Dual (linear programming), 17 -9	packed and loose, specific gravity and density	Electric equipment, safety devices for, 18 -20
Dual-fuel engines, 9-90	of (table), 6-8	Electric-furnace steel (def), 6 -13
advantages, 9 -90 Ductile cast iron (def), 6 -13, 6 -38, 6 -39	planetary constants for (tables), 11 -101, 11 -103 Earthmoving equipment, 10 -24	Electric furnaces: arc, 7 -55
Ductis:	Earthquake forces in buildings, 12 -18	arcs in, 7 -56
air friction in (charts), 12 -88, 12 -89	Earthquakes, 12 -51	charges, 7 -56
air velocities in (table), 12 -89	design for, 12-51	electrode consumption, 7 -59

Electric furnaces, arc (Cont.):	Electric motors, alternating current, induction	Electric resistor materials, 15-61
rating and sizes of (table), 7 -56	(Cont.):	table, 15 -61
reactance, 7 -57	switchboard equipment, 15 -46	Electric steel, 6 -14
refractories for, 7 -55	wiring calculations, 15 -54	Electric switchboards, 15-44
regulation characteristics of (chart), 7 -57	as induction generator, 15 -34	Electric switches, 15 -46
single-phase, 7 -57	industrial applications, 15-44	Electric vehicles, storage batteries for, 15 -14
submerged-arc, 7 -59	laminated pole, 15 -40	Electric waves:
temperature in, 7 -56	round-rotor, 15-41	average value, 15-18
three-phase, 7-55	salient-pole, 15 -40	form factor, 15 -18
atmosphere: artificial, 7 -53	single phasing of, 15 -39	Electric welding (see Welding)
natural, 7 -52 dielectric heating, 7 -55	slip-ring, 15-40	Electric wiring (see Wiring)
energy consumption of (table), 7 -59	synchronous, 15-40	Electrical engineering, 15 -2 Electrical machinery, symbols for, 15 -7
	performance of (table), 15 -41	
high-temperature, resistors for, 7 -53 induction, 7 -52, 7 -57	power and weight of (table), 15 -41 synchronous induction, 15 -41	Electrical resistivity of metals (table), 6 -50 Electrical symbols (table), 15 -3, 15 -7
core-type, 7-58	synchronous reluctance, 15 -41	Electrical transmission systems, 15 -46
coreless, 7 -57	turbine, 15 -41	Electrical units, 15-2
frequency for, 7 -58	direct-current, 15 -27	table, 15 -3
operation, 7 -57	armature reaction, 15 -29, 15 -32	Electricity:
sizes of (table), 7-58	commutating pole, 15 -28, 15 -29	dynamic (def), 15 -15
induction heating for, 7 -55	commutation, 15 -29	static (def), 15 -15
power requirements for (table), 7 -58	compound, performance of (table), 15 -29	Electrochemical machining, 13 -66
for refining steel, 6 -14	computer control of, 15 -86	Electrodynamometer, 15 -21
resistance, 7-52 , 7-59	cumulative compound, 15 -29	Electrohydraulic forming, 13 -19
with fixed or movable electrodes, 7-59	full-load currents (table), 15-60	Electrolux Servel process of refrigeration, 19-1
uses of, 7 -59	fundamental equations, 15 -27	Electrolytic cells (def), 6 -95
resistor, 7 -52	industrial applications, 15-44	reference electrodes for, 6-95
bath heating, 7 -53	series, 15 -28	standard hydrogen electrodes for, 6-95
heating chamber, 7 -52	speed control, 15-30, 15-85	Electrolytic iron: properties and uses of, 6 -13
high-temperature, 7 -54	shunt, 15-28	Electromagnetic spectrum (chart), 19-42
losses from, 7 -54	armature resistance control, 15-30	Electromagnets, 15-63
operating efficiency, 7-54	control by changing impressed voltage,	alternating-current, 15-64
ovens, 7 -54	15 -30	exciting coils for, 15-65
resistors for, 7 -53, 15 -61	field-current control, 15-30	heating of, 15 -65
sizes of, 7 -54	speed control, 15 -30, 15 -85	lifting, 15 -64
temperature regulation of, 7 -54	stabilizing windings for, 15 -28	polyphase, 15 -64
for tempering, 7 -54	starters, 15-28	sparking of, 15 -64
ventilation of, 7 -55	speed and torque characteristics (chart), 15 -28	tractive, 15-64
types of, 7 -52	industrial applications, 15 -44	wire for, 15 -65
Electric generators (see Generators)	selection of, 15-44	Electromotive force:
Electric ignition systems (see Ignition sys-	speed control of, 15 -30, 15 -85	induced, direction of, 15 -11
tems)	regulation of (def), 15 -28	unit of, 15 -2
Electric instruments, 15 -20, 16 -16	traction, 15 -30	Electron (def), 6-5 , 9-133
alternating-current, 15 -21	Ward-Leonard, 15-30	Electron capture (def), 9-134
direct-current, 15-20	universal, 15 -40	Electron tubes, 15 -71
high-voltage, 15-24	Electric power (def), 15-2	Electronic components, 15 -68
impedance bridges, 16 -17	active (def), 15 -2	Electronic voltmeters, 15 -21
transformers for, 15 -23	apparent (def), 15 -2	Electronics, industrial, 15-85
Electric lamps, 12 -100	cost of, 17 -32 formulas, 15 -8	Electrostatic collectors (fly ash), 9-32
Electric locomotives, 10 -19	*	Electrotype metal (table), 6 -75
(See also Locomotives) Electric measurements, 15 -20	measurement of, 15 -21, 15 -22 reactive (def), 15 -2	Elektrolift magnets, 10 -11 Elementary substance (def), 6 -3
Electric measurements, 15-20	Electric power distribution:	Elements:
Electric motors:	circuits, 15 -52	chemical (def, table), 6 -3
adjustable bases for, 8 -57	demand factor (buildings), 15 -61	periodic table of, 6 -6
alternating-current: branch-circuit maximum	feeders and mains, 15 -53	physical properties of (table), 6 -50
ratings (table), 15 -60	load centers, 15-61	Elevator dredges, 10 -34
brushless, 15-40	networks, a-c, 15 -53	Elevators:
capacitor, 15-39	service wires, 15 -57	automatic control of, 10 -18
commutator, 15-40	systems, 15 -51	belt-and-bucket, 10-47
computer control of, 15-86	three-wire: a-c, 15 -53	bucket, 10-46
heat gain from (table), 12-85	d-c, 15 -52	capacity of (table), 10-47
induction, 15 -37	wire resistance and reactance (tables), 15 -48,	casings, 10 -47
breakdown torque, 15-37	15 -52	continuous, 10-47
efficiency of (table), 15-39	wiring calculations, 15-53	gravity discharge, 10-47
polyphase, 15-37	Electric power plants (see Power plants)	power requirements for, 10 -47
power and weight (table), 15-39	Electric power transmission, 15 -46	supercapacity, 10-47
power factor (table), 15-38	corona in, 15 -50	car mileage of, 10 -19
resistor starters for, 15-38	d-c, high-voltage, 15-50	controls for, 10-18
rotors, 15 -37	lines: Mershon diagram, 15-47, 15-49	counterweights for, 10-18
single-phase, 15-39	overhead, reactance of (table), 15-48, 15-52	dispatch systems for, 10-19
starting, 15-39	voltage drop in, 15-49	drives for, 10-18
speed control, 15-38	symmetrical system, 15-47	flight times for, 10-18
squirrel-cage, 15-37	underground cables, 15-50	gearless, 10-18
starting compensator, 15-37	ampacities (table), 15-51	high-rise, 10 -18

Elevators (Cont.):	Energy equivalents (table), 1-33	Epicyclic gear trains, 8-7
hydraulic, 10 -18	Energy sources:	Epicycloid, 2 -22
load ratings for, 10 -19	geothermal (see Geothermal power)	Epitrochoid, 2 -22
low-rise, 10 -18 medium-rise, 10 -18	heat of the seas, 9-22 hydroelectric, 9-4	Epoxy resins: properties of (table), 6 -189 EPROM (erasable programmable read-only
motors for, 10 -18, 15 -44	reserves, 9-3	memory), 15 -83
power consumption and efficiency of, 10 -19	coal, 9 -3	Equations:
traction-type, 10-18	natural gas, 9-3	Cauchy-Euler equidimensional, 2 -33
Ellingham diagrams (corrosion), 6 -96	nuclear, 9-4	for circle, 2 -19
Ellipses:	petroleum, 9-3	differential, 2 -31, 2 -34
area and perimeter of, 2-8	shale oil, 9-3	linear, 2 -32, 2 -34
properties of, 2-20	tar sands, 9-3	methods of solving, 2 -31
quadrant, center of gravity of, 3 -7 Elliptic integrals, 2 -29	solar (see Solar energy) from thorium, 9-4	for ellipse, 2-20
Elliptical differential equations, 2 -34	from uranium, 9-4	linear, 2 -32 of parabola, 2 -19
Elongation due to tension (table), 5 -3	from vegetation, 9-10	simultaneous, 2-13
Embossing of metals, 13 -20	from waves, 9-22	of state (thermodynamics), 4 -7
Emery (abrasive), 6 -129	from wind, 9-8	of a straight line, 2-18
Emery wheels (see Grinding wheels)	Energy storage, 9-28	Equilibrium (mechanics, def), 3-3
Emissions:	in flywheels, 9 -27	forces, in mechanics, 3-2 to 3-6
engine design conditions to reduce, 9-121	Engineering employees, 18 -31	laws of, in mechanics, 3 -3
engine operating conditions to reduce, 9-121	Engineering statistics, 17 -19	Equilibrium diagram, iron-iron carbide (chart), 6 -16
exhaust treatments to reduce, 9-121	Engineer's liability insurance, 18 -31	Erg (def), 1 -21
from internal-combustion engines, 9-119	Engines:	Error:
Emissivity (radiant heat, def), 4 -62 of carbon dioxide (table), 4 -70	airplane (see Airplanes, engines) automobile (see Automobile engines)	absolute and relative, 2 -4 in automatic control (def), 16 -22
gas, 4-68	balancing of, 3 -67	in measurement, 16 -2
of various surfaces (table), 4 -64, 19 -39	cranks, 8 -65	Error compensation (automatic control), 16 -26
of water vapor (table), 4- 70	cycles for: internal combustion, 4 -11	Escalators, 10-19
Emittance (radiant heat, def), 4-62	steam, 4 -19	Escape velocity, 11-101
Employee relations, 17-10	diesel (see Diesel engines)	Esters (solvents), 6-149
grievance procedures, 17-11	hot-air, 9 -20	Ethane: as refrigerant, 19-7
promotions, 17-11	internal-combustion (see Internal-combustion	Ethyl alcohol, as solvent, 6 -148
Employees: of engineers, 18 -31	engines)	Ethyl cellulose resins: properties of (table), 6 -189
Empty set (def), 2-2 Emploiens, cutting fluid (machining), 13-50	jet (see Aircraft jet propulsion) marine (see Marine engines)	Ethylona and polyathylona copolymor rasing:
Emulsions, cutting fluid (machining), 13 -50 Enamel coatings, 6 -108	reciprocating, balancing of, 3 -67	Ethylene and polyethylene copolymer resins: properties of (table), 6 -196
Energy (def), 3 -2, 3 -17	reciprocating parts in: inertia force of, 8 -65	Ethylene glycol (antifreeze), properties of, 6 -142
atomic (see Atomic energy)	motion of, analysis of, 8 -65	Euler method, 2 -39
conservation of, 3 -2, 3 -17, 3 -39	velocity and acceleration of, 8-65	Euler number, 3-42
thermodynamics, 4-4	steam (see Steam engines)	Euler's equations of motion, 3-19
conversion table for, 1 -33	Enthalpy (def), 4 -4	Euler's formula for long columns, 5 -38
electric (see Electric energy)	of gases, 4-29	Eutectoid (steel), 6-17
free (def), 4-6	for ideal-gas air (table), 4-31	Evaporative condensers, 4-18, 19-14
Helmholtz (def), 4 -6 internal: of perfect gas, 4 -9	of perfect gases, 4 -9 Enthalpy-pressure diagram, for air (chart), 4 -34	Evaporative cooling of condenser water, 9 -84 Evaporators:
kinetic (def), 3-17	(See also Pressure-enthalpy chart)	heat transmission in, maximum (table), 4 -88
law of conservation of, 3 -2, 3 -17, 3 -39	Entropy (def), 4 -6	refrigeration, 19 -15
mass equivalence of (formula), 9-133	of ideal gas, 4-9	vapor binding in, 4-88
of moving fluid, 3 -37	Environmental control, 18-2	Everdur, 15-6
nuclear (see Atomic energy)	air- and gas-cleaning devices for (table), 18-16	Evolute of a curve (def), 2 -26
potential (def), 3-17	air-cleaning apparatus for, 18 -10	Excavating machines, 10 -33
solar (see Solar energy)	air pollution: sources of, 18 -7	Excavation, volume computation in, 16 -56
Energy conversion: direct (see Direct energy conversion; Energy	tables, 18 -8 condenser water cooling, 18 -3	Excavators, 10 -26 dragline, 10 -34
converters)	construction projects, considerations for, 18-5	Excess air for combustion (charts), 4 -30
to mass (formula), 9-133	cost-benefit calculations for, 18 -3	coefficient of, 4-25
Energy converters, 9-27	cyclone separators for, 18 -10	Exchangers, heat (see Heat exchangers)
bioenergetic, 9-27	federal legislation on: air pollution, 18-7	Exciters, switchboard equipment for, 15-46
EHD water drop, 9-27	water pollution, 11-47, 18-5	Exfoliation, of aluminum, 6 -56
electrohydrodynamic, 9-27	industrial discharge permits, 18-5	Exhaust gas:
electrokinetic, 9-27	national policy, 18-2	analysis of (chart), 9 -94
electron convection, 9-27	process selection for, 18-6	apparatus for, 16 -18 Exhaust systems, fans for, 14 -50
ferroelectric, 9 -27 magnetostrictive, 9 -27	purposes of, 18 -2 of radioactive waste, 18 -17	Exide ironclad battery, 15 -14
magnetostrictive, 9-27 magnetothermoelectric, 9-27	recycling, 18-6	Expansion:
Nernst effect, 9-27	scrubbers for, 18 -11	of bodies by heat, 4 -2
particle-collecting, 9-27	size of airborne particles (chart), 18 -9	coefficients of (table), 6 -50
photoelectromagnetic, 9-27	standards for industrial discharges (table), 18-6	of petroleum products (table), 7-12
photogalvanic, 9 -27	of sulfur gases and particulates, 18-12	in compound engines, 9-55
piezoelectric, 9-27	sulfur oxides removal for, 18-13	of functions in series, 2 -31
pyroelectric, 9-27	thermal discharges, 18-4	of gases (formulas and tables), 4-9
superconducting, 9-27	in various industries, 18 -15	of pipelines, stresses due to, 5 -55
thermophotovoltaic, 9-27 Van der Graaff, 9-27	waste disposal, 18 -6 wastewater, 18 -5	of saturated and superheated vapors (formulas), 4-13, 4-14
water drop, 9 -27	Environmental releases, radioactive, 18 -17	thermal, coefficients of (def), 4-2
F,		

Expansion joints for steam pipes (table), 8-208	Feedwater:	Fibers:
Expansion ratio, effect on engine economy, 9-55	alkalinity, 9 -49	animal, 6 -140
Expected value (def), 2 -10 Expenses:	amines for, 9 -49 ammonia in, 6 -106	for cordage, 6 -137 creep of, 6 -140
fixed, characteristics of, 17 -12	blowdown, 9 -49, 9 -51	denier (unit of fineness), 6 -140
variable, characteristics of, 17 -12	combined water treatment for, 6 -107	elastic properties (table), 6 -141
Expert systems, 2 -52	corrosion by, 6 -106	glass, 6 -139
Explosion welding, 13 -31	deaeration of, 9-89	table, 6 -141
Explosions: detonation rates of (table), 7 -21	evaporation, 9 -49 filtering, 9 -48	heat endurance, 6 -140 identification of, 6 -140
of dusts (see Dust explosions)	heating, regenerative (turbines), 9 -72	inorganic, 6 -139
in internal-combustion engines, 4 -30	impurities in, 9 -48	nylon, 6 -140
Explosive D, 7 -22	effect in boiler, 9 -49	table, 6 -141
table, 7 -21	limits, ABMA (table), 9-51	properties of (table), 6 -141
Explosive forming, 13-19 Explosives, 7-19	oil and grease in, 9 -48 oxygen removal, 6 -106, 9 -49	synthetic, 6 -140
ballistic mortar strength of, 7 -21	oxygen scavengers for, 6 -106	vegetable, 6 -140 Fibonacci series, 2 -38
deflagrating (def), 7-20	oxygenated treatment for, 6 -107	Field of force, 3 -19
dynamite, 7 -20	pH, 9 -49	Field intensity (magnetic, def), 15-4
emulsions, 7-20	hydrogen-ion measurement, 9-50	Film coefficients, 4 -83
military, 7-21	indicators for, 9-50	for boiling liquids, 4-87
table, 7 -21 permissible in mines, 7 -21	table, 9-50	combined convection and radiation, 4 -88
water-based, 7 -20	polishing of, 6 -106 purification of, 6 -106	condensing vapors, 4 -87 extended surfaces, 4 -86
Exponential series, 2 -31	sampling and analysis, 9-51	factors influencing, 4 -83
Exponents (algebra), 2-4	scale from, 9-48	forced-circulation evaporators, 4 -88
Extraction turbines, 9-64	settling of, 9-48	for gases, 4 -83, 4 -84
Extrusion of metals, 13-20	silica in, 9-50	heat transmission (def), 4-80, 4-83
Eyebolts, 8-19	sludge, 9-48 , 9-49	for high-velocity gases, 4-83, 4-84
proportions and strength of (table), 8 -23	softening, 9 -48 thermal deaerators for, 6 -106	laminar flow, 4 -86 natural convection, 4 -86
	treatment of, 6 -105, 6 -106	over tubes, 4-83, 4-84, 4-86
F distribution (statistics, table), 1-13	amines, use of, 9-49	turbulent flow, 4 -83, 4 -84
Fabrics, 6 -140	cation exchange, 9-48	Film speed, photographic, 19-42
impregnated, for insulation, 6 -139	chemical, 9-48	Filmogen (paint, def), 6-108
Face brick, 6-135	demineralization, 9-48	Filters, capacitor, 15 -71
Factories (see Industrial plants) Factory accounts (see Cost accounting)	hardness elimination, 9 -50 lime-soda process, 9 -48	Filtration of sound, 12 -119 Fineness modulus (concrete, def), 6 -161
Fahrenheit:	of raw water, 9-48	Finish shearing, 13 -16
conversion to Celsius (eq), 4 -2	solids removal, 9-48	Finite-difference methods, in torsion calcula-
conversion to Rankine (eq), 4-2	Zeolite process, 9-48	tions, 5 -37
Failure, theories of, 5 -48	Feedwater heaters:	Finite-element methods, for space-vehicle analy-
Falk flexible couplings, 8-35	deaerators, 9-89	sis, 11 -117 in torsion calculations, 5 -37
False position (root finding), 2 -38 Fans:	spray-type, 9 -89 tray-type, 9 -89	for vibration analysis, 3- 77
axial-flow, 14 -44	desuperheating section, 9 -89	FIR (finite impulse response), 15 -84
centrifugal (see Centrifugal fans)	drain-cooling section, 9-89	Fire extinguishing, hand apparatus for, 18-27
classification of, 14 -44	friction loss (table), 9-88	Fire hose, 18 -27
forced-draft, 9-46	heat-transfer rates, 9-87	couplings for: ANSI (table), 8-214
induced-draft, 9-46 jet, 14-51	high-pressure, 9-87	screw threads, 8-214 Fire point of oil (def), 6 170
laws of, 14 -49	length of, 9-86 low-pressure, 9-87	Fire point of oil (def), 6-179 Fire protection, 18 -19, 18 -23
propeller, 14 -44	materials for, 9 -89	building construction for, 18 -23
(See also Blowers)	open-feed, 9-89	hose for (see Fire hose)
Farad (capacitance, def), 15-2	performance calculations, 9-88	hydrants for, 18-27
Fast flexible couplings, 8-35	pressure drop in, 9-86	information sources on, 18 -23
Fast Fourier transform, 2-38 Fasteners, aluminum, properties of (table),	regenerative cycle for, 4 -19 tube-wall thickness (table), 9 -88	by isolation, 18 -24 loss limitation in, 18 -23
6 -60	types of, 9-86	pumps for, 18 -26
Fathom (def), 1 -16	vent condensers for, 9 -89	resistant materials for, 18 -24
Fatigue:	Felts, 6 -140	sprinkler equipment for, 18-24
endurance limit in (table), 5-9	roofing, 6 -145	standpipes for, 18-27
of metals, 5-8 effects of corrosion on, 5-9	Ferrite (def), 6 -16 Ferroalloy furnace (electric), 7 -59	with temporary heating, 18 -24 with temporary storage, 18 -24
effects of corrosion on, 5-9	FET (field effect transistor), 15 -70	underground piping for, 18 -26
effects of overstressing and understressing	FHB (fluid-bed hydrogenization), 7-40	water supply for, 18 -26
on, 5 -9	Fiber composites, 6 -202	Fire pumps, 18-26
Fatigue failure, 5 -8	advanced, 6-203	Fire resistance of building materials, 12-43, 18-24
of shafts, 8 -47	design of, 6 -204	Firebrick, 6-152
Fatigue limit (def), 5-8 Faure storage battery, 15 -13	fiber properties (table), 11 -112 fibers in, 6 -203	coatings for, 6 -154 heat losses and heat-storage capacity of
Feedback loop (automatic control), 16 -28	properties of (table), 6 -203	(table), 6 -155
Feeder panels, equipment for, 15 -46	manufacture of, 6 -204	manufacture of, 6 -151
Feeders:	matrices for, 6-203	mortars for, 6-153
belt conveyor, 10-52	for space applications, 11 -112	plastics and ramming mixtures for, 6 -154
of electric distribution systems, 15-53	Fiber optics, 19 -43	selection of, 6 -154

Firebrick (Cont.):	Flow:	Flywheel effect (def), 3-9
shapes and sizes of, 6 -152	of air: measurement of, 16 -13	Flywheels:
table, 6 -153	in pipes, 4 -23	arms, design of, 8-50
(See also Refractories)	in pneumatic conveyors, 10-53	for energy storage, 9-27
Fireclay refractories, 6 -151	coefficients of friction, 4-23	high-speed, stresses in rims, 8-51
table, 6 -153 Fires, from dusts, combatting of, 7 -27	of compressible fluids, 3 -49, 3 -50, 3 -55, 3 -56, 4 -20	rims, 8- 50 split-rim, 8- 50
Fischer-Tropsch process, 7-18	through nozzles, 3 -54 to 3 -56, 4 -21	stresses in, 8 -50
Fission of nuclei (see Nuclear fission)	through orifices, 3-55, 4-21, 16-14	vehicles powered by, 9 -29
Fits, 8-43	in pipes, 4 -23	weight determination, 8 -66
allowances and tolerances, 8-43	friction loss, 4 -23	Wittenbauer's analysis, 8 -66
classification of, 8 -43	of cryogens, measurement of, 19-38	FMC coke process, 7 -35
force, 8 -44	of gases: fundamental equations, 4-21	Foaming, in boilers, 9-49
international, tolerances for (table), 8-46	measurement of, 16 -13	Focal length of lenses, 19 -41
limits for (table), 8 -48	of heat, 4 -79	Focus:
locational interference, 8 -44	conversion table for, 1-34	of ellipses, 2-20
metric, 8 -44	(See also Heat transmission)	of hyperbola, 2 -20
preferred (table), 8-45	of liquids: dimensional analysis of, 3-44 to	of parabola, 2 -19
press, 8 -44 pressures in (charts), 8 -46	3 -46 laminar, 3 -46	Foil, laminated, 13 -14 Follow boards (mold making), 13 -3
pressures required in making, 8-45	measurement of, by metering pump, 16 -15	Food-board, 6 -144
stresses due to, 8 -45	(See also Flowmeters)	Foot (def), 1 -16
torsional holding of, 8 -46	through orifices, 3-55	Foot-lambert (def), 12 -99
running, allowances for (table), 8 -44	in pipes, 3 -47 to 3 -53	Footings:
shrink: allowances for (table), 8-44	turbulent, 3 -46, 3 -48	for foundations, 12 -26
stresses due to, 8-45	(See also Flow, of water)	reinforced-concrete, 12-58
transition, 8-43	of materials, in plants, 10-2	Force (def), 3 -2
Fittings, pipe (see Pipe fittings)	(See also Materials handling)	centrifugal, 3-15
Flakeboard, 6-128	of metal at high temperatures (creep), 5-10	centripetal, 3-15
Flame propagation in gaseous fuels, 7-16	of steam: through labyrinth packings, 9-63	components of, 3-3, 3-4
Flame radiation, 4-68	through nozzles, 4-21 to 4-23	composition of, 3-4
Flame speed, in internal combustion engines,	through orifices, 4-21	definition of units, 1 -24
9-114 Flore temperatures, of gesseus fuels (table)	in pipes, 4 -23 friction loss due to, 4 -23	equilibrium of, 3-3
Flame temperatures, of gaseous fuels (table), 4-29	resistance of fittings to, 4-23	external and internal (def), 3-3 field of, 3-19
Flame travel, in internal-combustion engines, 9-93	saturated, 4-23	intensity of (def), 3 -19
Flammability of fuels:	of water: measurement of (see Flowmeters)	fundamental equation of, 3-2
gaseous, 7-16	through notches, 3 -57, 3 -58	line of (def), 3 -19
table, 7 -16	through nozzles, 3-54, 3-55	supporting, 3-4 to 3-6
limits of (table), 7 -16	in open channels, 3-59	unbalanced, 3-14
Le Chatelier's equation for, 7-16	in pipes, 3 -47 to 3 -53	units of, 1 -24, 4 -2
Flanged-face couplings, 8 -34	Chézy equation for, 3-59	Force fits, 8-44
Flanged fittings:	Manning formula for, 3-59	Force polygon, 3-5
cast-iron, 8 -195	in streams: estimation by surveying, 16 -58	Forced-circulation boilers, 9-37, 9-45
steel, 8 -197	venturi meter for, 3-54	Forced draft, 9 -46 Forces:
Flanges: cast-iron, 8 -195	over weirs, 3 -57, 3 -58 Flowers: effects of sulfur dioxide on (table),	on irregular surfaces (mechanics), 3 -35
steel, 8 -197	18-12	in mechanical linkages, 8 -4
unions, 8 -201	Flowmeters, 3 -53 to 3 -59, 16 -7, 16 -14	resultant of, 3 -3
Flash intercoolers, for refrigeration systems,	electromagnetic, 16 -15	system of, in equilibrium, 3 -6
19 -15	integrators, 16-15	Forging, of metals, 13 -10
Flash point, of lubricating oils (def), 6-179	nozzle, 16 -14	Forging dies, 13 -19
Flasks (molding), 13-5	propeller, 16-14	Forging hammers, 13 -19, 13 -22, 13 -23
Flats, of bolts and nuts (table), 8-21	Flue gas:	Forging steel (table), 6 -22
Flax, properties of (tables), 6 -141	analysis of, 4 -25, 4 -30	uses of, 6 -30
Flexible metal hose and tubing, 8 -215	apparatus for, 16 -18	Fork trucks, 10 -23
Flexure, theory of (beams), 5 -21	cleaning of, 9-32	Form factor, a-c waves, 15-18
Flight (see Aerodynamics) Flight conveyors, 10 -40	heat loss in, 9 -48 Fluid couplings (<i>see</i> Couplings)	Formation, heats of (def), 4-27 Formcoke (coke making), 7-34
Flip-flop (electronic circuit), 15 -79	Fluid volume, measurement of, 16 -7	Forms, for reinforced concrete, 12 -60
JK circuit, 15-80	Fluidized beds, in furnaces, 9 -29	Forsterite (refractory), 6 -152
Float (scheduling), 17 -6	Fluids (def), 3-31	Fortran, 2 -53
Float glass, 6 -142	coefficients of friction (formulas), 4 -23	Forward path (automatic control, def), 16 -28
Floors:	flow (see Flow)	Fossil fuels, reserves of, 9-3
earthquake-resistant, 12-19	ideal (def), 3 -31	Foucault-current losses, 15-10
industrial plant, 12-15	for machining, 13-50	Fouling index, of coal, 9-30
loads on, 12 -18	measurement of, 1 -16	Foundations:
plank, safe load on, and deflection (table),	(See also Flowmeters)	bearing pressure on soils, 12 -26
12 -28	Newtonian (def), 3-31	caisson methods for, 12 -26
reinforced-concrete, 12-56	nonNewtonian (def), 3 -31	deep, 12-26
safety provisions for, 18 -19 trusses for, 12 -22	throttling of, 4 -24 Fluorescent lamps, 12 -101	excavation, computations in, 16 -56 footings for, 12 -26
chart, 12 -22	Fluoroplastic resins: properties of (table),	pile, 12 -26
wood, 12 -28	6 -190	setting stakes for, 16 -57
joists for, 12 -28	Flux density (magnetic, def), 15 -3	spread (reinforced-concrete columns),
wood-block, 12 -15	Fly ash, sintering of, 9 -30	12-58

Foundries, 13-2 casting inspection in, 13-7	Friction head (liquid), 3 -37 Friction loss in pipe fittings (table), 3 -51	Fuels, gaseous (<i>Cont.</i>): odorization of, 7 -15
cleaning equipment for castings in, 13-7	Friction resistance of ships, 11-45	physical constants of, 7-16
melting processes used in, 13-7	Friction sawing (metal), 13-61	specifications for, 7-15
molding equipment for, 13-5	Frigorie, European unit of refrigeration (def), 19 -2	heat value (def), 4 -25, 7 -6
(See also Castings; Molding)	Fringes (optics), 19-42	high and low (def), 4-25
Four-cycle engines, 9-91 advantages, 9-91	Froude's law (ship resistance), 11 -46 Froude's number, 3 -42, 3 -44, 3 -60, 11 -42, 11 -45	heats of formation, 4-27
Fourier coefficients, 2-36	Frustum, of cone or pyramid, volume of, 2 -9	for industrial heating, 7 -41 for internal-combustion engines, 7 -12 to 7 -14,
Fourier integral equation, 2-37	Fuel cells, 9 -25, 15 -34, 18 -10	9-104
Fourier series, 2-36	Fuel injection:	table, 9 -103
Fourier transform, 2-37	for diesel engines, 9-110	jet, 7 -13
Fourier's law (heat conduction), 4-80	fuel lines for, 9-111	table, 7 -13
FPGA (field-programmable gate array), 15 -82	nozzles for, 9-111	knock rating, 9-115
Fractionating high-vacuum pumps, 14 -41	pump injection systems, 9-111	knock suppressors (table), 9-116
Fractions, decimal values (table), 1-15	pumps for, 9-111	liquid, 7-10
Fracture: at low stress, 5-7	system characteristics, 9-111 for spark ignition engines, 9-109	ash content, 9-31 combustion of, 4-25, 4-30
under tension and compression, 5-7	central, 9-110	air required (table), 4 -27
Fracture mechanics, 5-7	injector pulse, 9-110	products of (table), 4-27
Fracture stress (def), 5-2	port, 9 -110	heat values (tables), 4-25, 7-11 to 7-13
Frame of reference (mechanics, def), 3-2	speed-density controls for, 9-110	for industrial heating, 7 -41
Framed structures, steel (see Steel-framed struc-	systems, 9 -110, 9 -111	molecular weight (table), 4 -25
tures)	Fuel oils:	properties of, 7-11
Francis turbines, 9-150, 9-151 Free energy (thermodynamics), 4-6	analyses of (table), 7-11	volatility of (def), 9 -104 nuclear (<i>see</i> Nuclear fuels)
Free-swelling index test for coal, 7-7, 7-32	API and specific gravity of (tables), 7-11 to 7-13, 7-19	oils (see Fuel oils)
Freezing points:	ash content (tables), 7 -14, 9 -31	peat, 7-9
of the elements (table), 4 -58	combustion in boiler furnaces, 9-34	products of combustion of (table), 4 -27
of various substances (table), 4-50	crude, 7 -10	rocket, 7 -28
Freezing preventives, 6 -141	flash point of, 7-14	solid, combustion of, 4-30
Freight cars, 11-27	grades of, 7-14	air required for, 4 -30
axles for, 11-31	heat of vaporization of, 7 -11	products of, 4-30
coupler cushioning for, 11-31	table, 7-12	specific gravity and density of (table), 6 -8 synthetic, 7 -16
design of, 11 -30 dimensions of, 11 -27, 11 -28	heat values (tables), 7-11, 7-12 pour point of, 7-14	liquefaction of, 7 -17
discharge gates for, 11 -32	specific heat of, 7-11	from coal, 7-18
lading restraints for, 11-32	specifications of (table), 7-14	wood, 7 -9
suspensions for, 11 -31, 11 -39	(See also Fuels, liquid)	Full annealing (def), 6-17
train resistance, 11-39	Fuels, 4 -24, 4 -25, 4 -30, 7 -2, 7 -41	Full-duplex (data transmission method), 16-21
wheels for, 11 -31	alternative, 9-106	Fuller-Kinyon system, 10-54
Freon, properties of (chart, table), 19 -4, 19 -12	autoignition temperatures, 9-115	Functions:
(See also Refrigerant) Freon 22: pressure-enthalpy chart for, 19-8	aviation turbine, 7-13 table, 7-13	algebraic (def), 2 -3 gamma, 2 -29, 2 -37
Frequency:	biomass, 7-8	hyperbolic (tables), 2 -18
a-c (def), 15 -3, 15 -18	for boilers, 9 -29	series for, 2 -31
natural, 15 -17, 15 -19	briquets, 7 -9	implicit, 2 -25
Frequency bands (tables), 15-87	by-product (table), 7 -10	trigonometric, 2-15
Frequency modulation (radio), 15-74	combustion of (see Combustion)	series for, 2 -31
Frequency response:	consumption of (automobiles), 11-5	of two or more variables, 2-25
of automatic controls, 16 -33	cost, in power plants, 17 -36	Furan resins: properties of (table), 6 -191
graphical display, 16 -34 Fresh air requirements for various locations	diesel, 9 -104 table, 9 -105	Furlong (unit of length, def), 1 -16 Furnace brazing, 13 -29
(table), 12-67	(See also Diesel fuels)	Furnaces:
Friction:	flame speed in, 9-114	arches for, 6 -154
coefficients of (def), 3-21	flammability of, 7 -16	boiler (see Boiler furnaces)
clutches (table), 8-38	table, 7 -16	combustion, 7 -41
fluid flow in pipes, 4 -23	fossil, reserves of, 9-3	combustion chambers for, partially stirred, 4 -76
journal bearings, 3 -27, 8 -119	for gas turbines, grades of, 7-14	performance of, 4-78
rolling (table), 3-25 static and sliding (def), 3-21	gaseous, 7-14	cyclone, 9-35
tables, 3-21 to 3-24	analysis of, 7 -15, 7 -16 combustion of, 4 -25, 4 -30	electric (<i>see</i> Electric furnaces) for electric steel, 6 -14
tables, 3-21 to 3-24	air required, 4-25	forced convection, 7 -41
thrust bearings, 3 -28, 8 -126	table, 4 -27	heat transmission in, 4 -71
for various materials, 3-21 to 3-24	in boiler furnaces, 9-34	incineration (see Incinerators)
dry (def), 3 -20	dissociation in, 4-29	induction, 6-14
effect of sliding velocity on, 3-22	table, 4 -29	industrial-heating, 7 -41
of liquids in pipes, 3-47 to 3-53	products of (table), 4 -27	automatic controls for, 7 -44
of machine elements, 3 -25 to 3 -29	temperature, 4-29	classification of, 7 -41
rolling (def), 3-25 skin (aerodynamics), 11-66	volume contraction, 4-25 composition of (table), 7-15	construction of, 7 -44 efficiency of (table), 7 -43
of steam engines, 9-54	flame propagation, 7-16	firing methods for, 7 -41
Friction brakes, horsepower absorbed by, 3 -18	flammability, 7-16	flue velocities in (tables), 7 -44
Friction clutches (automobile), 11-6	table, 7 -16	fuel requirements of (table), 7-43
Friction factors for pipes (liquid flow), 3-47 to	heat value (table), 4-26	fuels for, 7 -41
3 -53	for industrial heating, 7-41	heat balance in (table), 7 -43

Furnaces, industrial-heating (Cont.):	Gainsharing (bonus plan), 17 -10	Gas turbines (Cont.):
heat conservation, 7-44	Gallon (def), 1-16	categories, 9-124
heat input to, 7 -42 heat losses in, 7 -42	imperial (def), 1 -16	aeroderivative, 9-124 as frame machines, 9-124
heat transfer in, 7 -42	Galvanic corrosion, in aluminum, 6 -56 Galvanic series: for metals and alloys (table),	heavy-duty, 9 -124
heating and soaking time, 7 -42	6 -100	closed, 9-129
material handling, 7-42	Galvanized conductors (electrical), 15 -6	combined cycle, 9 -69, 9 -127, 9 -129
metal parts for, 7-44	Galvanized surfaces, paints for, 6 -110	bottoming, 9 -129
protective gas atmospheres for, 7 -45	Galvanizing, 6 -93	cogeneration, 9-130
table, 7 -45	Galvanometer, 15-20	for district heating, 9-130
recuperators and regenerators for, 7-44	Gamma functions, 2 -29, 2 -37	fired, 9 -129
size of, factors influencing, 7 -42	Gamma iron (def), 6 -16	overall system efficiency of, 9-127, 9-129
temperature control of, 7 -44, 7 -54	Gamma rays, 9-134, 9-142	steam injection, 9-130
temperatures in (table), 7-42	irradiation by, 9-142	total energy plant, 9-130
useful heat in, 7 -42	Gang saws, 13 -72	unfired, 9 -129
liquid-bath, 7-41	Gangue of iron, 6 -13 Gantry cranes, 10 -27	combustors, 9-131
melting (casting), 13 -7 muffle, 7 -41	Gantry cranes, 10-27 Gantt charts (scheduling), 17-5	combustion chambers in, 9-131 components, 9-131
oven, 7 -41	Garnet (abrasive), 6 -129	compressors for, 9-131
pressure-fired, 9-46	for wood sanding, 13-75	axial flow, 9-131
radiant-tube fired, 7 -41	Gas:	centrifugal flow, 9-131
radiation in, 4 -71	adiabatic expansion of, 4 -9	dual-speed, 9-131
from nongray gas, 4-75	change of state, 4-9	concentric shaft, 9-129
recirculating, 7 -41	cleaning (see Gas cleaning)	configurations for, 9-128
refractories for (see Refractories)	combustion (see Combustion)	closed system, 9-129
resistors for, materials for (table), 15-61	compressibility factors (chart), 4-8	concentric shaft, 9-129
walls for, 6 -154, 9 -37	compressors (see Air compressors; Centrifugal	dual speed, 9-128
air-cooled, 6-154	compressors)	external combustion, 9-129
expansion joints for, 6 -154	constant-pressure expansion of, 4-9	free turbine, 9-128
heat losses and heat storage (table), 6-155	constant-volume expansion of, 4 -9	open system, 9-129
membrane tube, 9 -41 water-cooled, types of, 9 -37	enthalpy of, 4-9, 4-29 entropy of, 4-9	cycles for, 4 -13, 9 -126 Brayton, 9 -125
water-cooled, types of, 9-37 water-cooled, 9-37	expansion of, 4-9	Joule, 9-125
construction of, 9-37	with variable specific heat, 4 -9	effect of ambient conditions, 9 -130
heat transfer in, 9 -39	flow of (see Flow, of gases)	effect of inlet temperatures (chart), 9 -126
Fuses, 15 -61	flue (see Flue gas)	effect of pressure ratios (charts), 9-126
sizes for motor branch circuits (table), 15-60	ideal: changes of state in, 4-9	fuels for, 9-124
Fusible alloys, 6 -75	equation of state for, 4-8	inlet temperatures in, 9-126
table, 6 -75	ideal cycles with, 4 -10	intercooled, 9-126
Fusion:	laws of, 4 -8	intercooled and regenerative, 9-127
heat of (tables), 4 -50, 4 -58	internal energy of, 4-9, 4-29	marine, 9-132
nuclear (see Nuclear fusion)	table, 4-28	maximum cycle temperature (def), 9-126
Fusion points, of refractories (tables), 6 -153,	isentropic expansion of, 4-9	open, 9-129
6 -156 Fuzzy control, 16 -49	isothermal expansion of, 4 -9 liquefaction of, 19 -25	operating characteristics of, 9-130 at partial load, 9-130
FWPCA (Federal Water Pollution Control Act),	natural (see Natural gas)	for peaking units, 9-132
11-48, 18-5	perfect (see Gas, ideal)	power rating curves for, 9-130
11 10, 10 5	polytropic expansion of, 4 -9	for power stations, cost of, 17 -34
	producer (see Producer gas)	pressure ratio, 9-128
G and g, value of, 1 -25, 3 -2	properties of, 4-8	effect of (charts), 9-126
GAAP (generally accepted accounting princi-	radiation from, 4-68, 4-69, 4-71	regenerative, 9-126
ples), 17 -12	radioactive, control of, 18 -17	reheat, 9 -127
Gage blocks, 16-5	solubility in water (table), 6 -7	ship propulsion, 9-132
Gages:	thermal conductivity of (table), 4 -82	specific power (def), 9-126
absolute pressure, 16 -9 bellows, 16 -8	thermal expansion of, 4-2	superalloys for, 6 -77
Bourdon-tube, 16 -8	waste, heat in, 7 -42 water (<i>see</i> Water gas)	turbines for, 9 -131 types of, 9 -128
dead-weight tester for, 16 -9	Gas chromatography, 7-16	Gas welding (see Welding, gas)
depth, 16 -5	Gas cleaning: apparatus for (table), 18 -16	Gaseous fuels (see Fuels, gaseous)
dial, 16 -5	Gas cycles, 4-10	Gases:
diaphragm, 16-8	for nuclear reactors, 9-135	mixtures of: partial pressures in, 4-9
go no-go, 16- 5	Gas engines (see Internal-combustion engines)	specific heat of, 4 -9
ionization, 16-9	Gas meters, 16 -7, 16 -13	total pressure of (Dalton's law), 4-9
pneumatic, 16 -6	Gas oil (petroleum distillate), 7-14	natural, pipeline transmission of, 11-126
pressure, 16-8	Gas pipe (see Pipe)	Gasification, 7-35
railway track, 11 -35, 11 -37	Gas producers (see Gasification; Producer	of coal, 7 -35
sheet metal (table), 8-85	gas)	of liquid hydrocarbons, 7-39
strain, 5-53	Gas turbines, 9-124	processes for, 7 -35
in vibration, 3-79 thermocouple, for vacuum measurement,	aircraft, 9 -124 applications of, 9 -132	Gasifiers: entrained flow in, 7 -38
16-9	electric power, 9-132	fixed-bed, 7 -35
thread, 16 -5	industrial, 9-132	types of, 7 -35
U-tube, 16 -8	marine, 9 -132	Gaskets, 8 -138
using beta radiation, 16- 7	as mechanical drive, 9 -132	for ammonia fittings, 8 -205
using X-rays, 16-7	in military aviation, 9-132	compressibility (chart), 8-140
wire (table), 8 -85	as small engine, 9-132	materials for, for common uses (table), 8-140

Gaskets (Cont.):	Gears (Cont.):	Gears, worm (Cont.):
nonabsorbent, to prevent corrosion, 6 -100	helical, 8 -94	friction, 3-27
O-ring, 8 -138 Gasoline, 7 -12, 9 -104	axial pitch (def), 8 -94	nonreversibility of, 8 -99 single-enveloping, 8 -99
aviation, 7 -13	calculations for, 8 -95 contact ratio (def), 8 -91	teeth, proportions of (table), 8 -89
grades of (table), 7 -13	crossed axis, 8-94	velocity ratios for (def), 8 -99
properties and specifications of (table),	formulas (table), 8-95	Geiger counters, 16 -19
7-13	friction, 3-27	Geisler plastomer coal test, 7-32
condensation temperature of (table), 9 -106 cracked, 7 -12	over-pins measurements for, 8 -94 parallel shafts, 8 -94	Gelatin, in explosives, 7 -20 GEM (ground effect machines), 11 -59
distillation curves for, 7 -11	skew shafts, 8 -94	General Motors two-cycle engines, 9-107
heat value of (table), 7 -11, 7 -13	tooth thickness of, 8 -94	Generally accepted accounting principles, 17 -12
knock characteristics of, 7-12	Helicon, 8-100	Generators:
knock rating of, 9-115	herringbone, 8 -94	absorption refrigeration, 19 -17
knock suppressors in (table), 9 -116 natural, 7 -12	hypoid, 8 -95, 8 -99 figure, 11 -10	alternating-current, 15 -31 armature reaction in, 15 -32
reformed, 7 -12	Lewis formula for strength, 8-100	armature resistance, effective, 15 -32
reformulated, 7 -12	load distribution factor for, 8-102	classes of, 15 -31
constituents (table), 7-12	long and short addendum, 8-93	construction of, 15-31
road ratings of, 9-116	lubricants for (tables), 8 -114 to 8 -116	design of, 15 -32
straight-run, 7-12	lubrication of, 6-183, 8-113	efficiencies of (tables), 15 -31
vapor pressure of (table), 7 -13 Gasoline engines, 9 -90	materials for, 8 -108 tables, 8 -102, 8 -107, 8 -108	excitation for, 15 -33 frequency, 15 -32
(See also Internal-combustion engines)	mesh ratio (def), 8 -89	ground resistors for, 15 -34
Gasynthan (synthetic gas process), 7 -40	metric, 8 -89	hunting, prevention of, 15 -34
Gate valves, 8-206	American equivalents (table), 8-90	induced emf of, 15 -32
Gauss (magnetic flux density, def), 15 -3	design equations for (table), 8 -94	parallel operation, 15-34
Gear-cutting processes, 13 -59 Gear pumps, 14 -11	ISO specifications, 8 -89 tooth proportions and standards, 8 -89	performance of (tables), 15 -31 regulation of, 15 -32
Gear ratio (def), 8 -89	use of, 8 -90	synchronous, 15 -32
Gear-shaving machines, 13 -60	metric module, 8 -89	voltage regulation of, 15 -32
Gearing, 8-87	miter, 8 -96	automobile, 15-66
Gears:	modified, 8 -93	direct-current, 15-25
AGMA standards for, 8-100	nomenclature for, 8 -87, 8 -88, 8 -91, 8 -94, 8 -96	armature reaction in, 15 -29
AGMA strength and durability ratings for, 8-100	noncircular, 8 -100 oils for, 6 -180, 6 -183	commutating poles in, 15 -29 commutation in. 15 -29
allowable bending stress in, 8 -102	overload factor for, 8 -100	compound-wound, 15 -26
allowable contact stress in, 8-102	pitch: circular (def), 8-88	performance of (table), 15-26
angular spiral, 8 -98	diametral (def), 8-88	induced emf of, 15 -26
angular spiral bevel, 8 -98	pitch circle of (def), 8-88	parallel operation, 15 -27
automobile, 11- 8 backlash in, 8- 92	pitting resistance of, 8 -101 plastic, 8 -111	series, 15 -26 shunt, 15 -26
bevel, 8 -95	pressure angle of (def), 8 -88	as synchronous converters, 15 -42
angular, 8 -96	profile shifted, 8 -93	double-current, 15-42
cutting processes for, 13-60	reliability factor for, 8-102	efficiency calculations, 15 -43
definition of terms, 8 -96	rolling of, 13-60	induction, 15-34
dimensions of, 8 -96 efficiency of, 3 -27	safety factor for, 8 -102 shaving, 13 -60	switchboard equipment for, 15 -46 synchronous (<i>see</i> Generators, alternating-
Coniflex, 8 -96	sintered metal, 8 -108	current)
Gleason, 8-96	size factor for, 8-102	Geometric constructions, various, 2-5 to 2-7
hypoid, 8 -95	speed ratio, 8-89	Geometric distribution, 2-10
mounting surfaces, 8 -96	spiral, bevel, 8 -98, 13 -60	Geometric progression, 8-215
recommended backlash (table), 8 -97 registering surfaces, 8 -96	Spiroid, 8 -100 spur, 8 -88	Geometric similarity (models), 3-41 Geometrical series, 2-31
spiral, 8 -98	contact ratio (def), 8 -91	Geometry:
dimensions of (table), 8 -98	friction, 3-27	analytical, 2-18 to 2-24
straight, 8 -98	metric, design equations for (table), 8-94	elementary, 2-5 to 2-10
dimensions of (table), 8 -97	over-pins measurements of, 8 -92	Geothermal heat pumps, 9-20
Zerol, 8 -99 Beveloid, 8 -100	pitch (def), 8 -88 speed ratios, 8 -89	Geothermal power, 9-17 electric energy conversion, 9-18
Buckingham equation: for durability, 8 -100	teeth of: proportions of, 8 -89	processes, 9-18 to 9-20
dynamic, 8-100	tables, 8 -89, 8 -94	environmental considerations, 9-20
center distance, 8 -91	surface condition factor for, 8-102	exploration technology, 9-18
computer modeling of, 8-116	teeth of: nomenclature for, 8 -88	resources of, 9-18
computerized calculations for, 8 -116 contact ratio (def), 8 -92	proportions of (table), 8 -89 thickness of, 8 -92	German fraktur alphabet, 19 -44 Gibbs free energy: in corrosion calculations, 6 -95
charts, 8 -92, 8 -93	temperature factor for, 8 -102	Gibbs function (thermodynamics), 4 -6
cutters for, 13-59	testing radius, 8 -92	Gifford-McMahon refrigerator (cryogenics),
design standards, 8-100	tooth-to-tooth composite error (def), 8 -93	19- 28
durability, 8 -100	total composite error (def), 8 -93	Gilbert (magnetomotive force, def), 15 -3
efficiencies, 3 -27 enlarged, 8 -93	trains: bevel, 8 -8 epicyclic, 8 -7	Gilbreth's micromotion study, 17 -27 Girders, steel, proportions of, 12 -34
geometry factor for, 8 -102	types of, 8 -88	(See also Beams)
greases for, 6 -183	worm, 8 -99	Glass, 6 -142
grinding, 13 -60	double-enveloping, 8-99, 8-100	cellular, uses of, 6 -143
hardness factor for, 8-102	efficiency of, 3 -27	composition of, 6-142

Class (Ct).	C (C+).	Harlinger's famous for strength of and
Glass (Cont.):	Greases (Cont.):	Hankinson's formula for strength of wood,
fiber, 6 -139	performance of, 6 -181	6 -116
properties of (table), 6-141	soaps as thickeners for, 6 -180	Hard-coal (def), 7-2
as insulation, 6-142	texture of, 6 -181	Hard finish (plastering), 6-163
properties of, 6 -143	unworked penetration of, 6 -180	Hard soldering, 13-29
		<i>C</i> ,
at low temperatures, 19-34	Greek alphabet, 19-44	Hardenability of steel (def), 6 -18
safety, 6 -142	Green's theorem, 2-35	Jominy test, 6-18
shading coefficients for (tables), 12-81, 12-82	Gregorian calendar, 1-25	Hardening:
	,	2
specific gravity and density of (table), 6 -7	GRH (gas recycle generator), 7-40	of nonferrous alloys, 6 -52
tempered, 6 -142	Grid (electron tube), 15 -71	by precipitation, 6 -52
types of, 6 -142	Grinding, 13 -61	of steel, 6 -17
wire, 6 -142	allowances for, 13-63	Hardgrove machine-grindability test for coal, 7-7
wool, 6 -150	of ceramics, 13-65	Hardness:
Glass blocks, 6 -135, 6 -142	cross feeds, 13-63	of materials (def), 5-12
Gleason bevel gears, 8-96	depth of cut in, 13-63	Mohs scale of, 1 -25, 5 -12
Globe valves, 8-206	surface speeds, 13-63	tests for, 5-12
Glued-laminated timber, for structures, 12 -30	workpiece speeds, 13-63	of wood, 5 -13
Glues, 6 -130	Grinding machines:	Harmonic motion, 3-11
(See also Adhesives)	centerless, 13-64	Harmonic oscillation, 3 -63
Glulam (glued-laminated wood), 6-123, 12-30	cylinder, 13-64	Harmonic series (def), 2-30
Glycerol as freezing preventive, 6-141	drill, 13 -64	Hartley oscillators, 15 -73
GMR Stirling thermal engine, 9-20	internal, 13 -64	Hastelloy (tables), 6 -78 to 6 -80, 6 -89, 6 -90
Gold, uses of, 6 -74	surface, 13-64	Haulage:
Goodman diagram (weld design), 13-40	types of, 13 -64	by locomotives, 10 -19
Gouging, 13 -32	universal, 13-64	off-highway, 10 -24
air arc, 13 -32	Grinding wheels, 6 -129, 13 -62	wire rope for, 10-8
plasma arc, 13 -32	abrasives in, 13-62	(See also Conveying)
Governing, of internal-combustion engines, 9 -117	bonding processes for, 6 -129	HAWT (horizontal-axis wind turbines), 9- 5
Governors:	dressing of, 13-63	rotors for, 9-7
for hydraulic turbines, 9-159	grades of, 6 -129	Hayward grab buckets, 10-12
for steam turbines, 9-64	grain size in, 6 -129	electrohydraulic, 10 -12
	£ ,	
GPIB (general-purpose interface bus), 16 -21	speeds, 6 -129, 13 -63	HBX (explosive), 7 -22
GPS (global positioning system), 15 -91, 16 -58	standard marking system for (chart), 13-62	HCFC (hydrochlorofluorocarbon) refrigerant,
surveying using, 16 -58	truing of, 13 -63	19-3
Grab buckets, 10-12	Grindstones, friction, 3 -22	HCFC-123: pressure-enthalpy chart for, 19 -9
Grad (angular measure, def), 16-4	Grip-springs, 8-32	HFC (hydrofluorocarbon) refrigerant, 19-3
Grade resistance (railroads), 11-39	Grips, for test specimens, 5-13	HFC-134a: pressure-enthalpy chart for, 19 -10
Graders, motor, 10-25	Grog (calcined clay), 6 -151	Head:
Grading, volume of earth, computation of, 16 -56	Ground-fault interrupters, 15 -61	loss due to fittings (table), 3-51
Grain size, austenitic (metallography), 6-18	Grounding, of transformer secondary, 15 -53	potential (hydraulics), 3 -37
Granite, composition of, 6-143	Grounds for interior wiring, 15-59	pressure (hydraulics), 3 -37
Graphical relations, in beams, 5-31	GR-S rubber, 6 -147	velocity (hydraulics), 3 -37
Graphical statics, problems, 3 -5	table, 6 -148	Head gates, for hydraulic turbines, 9-160
Graphite:	Gunter's measure (surveying), 1 -16	Heading operations, steel for, 13-19
bearings lubricated by, 8-125	Gust loads (wind force), 12-21	Heat:
specific gravity and density of (table), 6-8	Gutta percha, 6-148	available (def), 4 -6
Graphite corrosion, 6 -101	GWP (global warming potential), 19 -3	of combustion (table), 4 -26
Graphitization of pipe, 8-211	Gypsum blocks, 6-135	conduction (see Heat transfer; Heat transmis-
Graphitizing furnace (electric), 7-59	Gypsum plaster, 6-163	sion; Thermal conductivity)
Grashof's formula for steam flow, 4 -21, 4 -22	Gyration, radius of (def), 3 -8	conversion table for, 1-33
Gravel:	Gyrocompasses, 3-20	developed by electric current, 15-8
for concrete, 6 -161	Gyroscopes:	of earth, power from, 9-18
specific gravity and density of (table), 6-8	applications of, 3-20	into the environment (table), 18-4
Gravitation, law of, 3 -2	motion of, 3 -19	expansion by, 4 -2
Gravitational systems (def), 3-2	theory of, 3 -19, 3 -20	of formation: of fuels, 4 -27
Gravity:		of inorganic compounds (table), 4 -27
acceleration of, 1-25		of fusion: of the elements (table), 4-58
center of, 3-6		of metals (table), 6-50
	II 1	
equation for, 3-2	H-coal process, 7 -18, 7 -35	of various materials (tables), 4 -50
specific (see Specific gravity)	H-S diagrams, description of, 4 -14	latent, 4-4
standard (def), 1-25	(See also Mollier diagram)	of vaporization (tables), 4-50, 4-58
standard acceleration of, 1 -25		measurement of, 4-3
	Hack saws, 13-61	
Gray cast iron (def), 6 -13, 6 -38	Half-duplex (data-transmission method), 16 -21	mechanical equivalent of, 4-3
corrosion of, 6 -101	Half-life (def), 5-65	of seas, power from, 9-22
Gray iron castings: allowances for, 6 -43	Half-life of nuclei (def), 9-134	specific (see Specific heat)
Gray surfaces (radiant heat transfer), 4 -66		units of, 4 -3
• *	Hammerlocks (chain couplers), 10 -7	
Greases:	Hammers:	of vaporization: of the elements (table), 4 -58
bleed of, 6 -180	drop, 13 -22	of liquids (tables), 4-50 , 4-58
characteristics of (table), 6 -181	energy of blows (tables), 13 -23	of various substances (table), 4 -50
consistency of, 6 -180	pneumatic, 13-23	Heat capacity (def), 4-3
consistency numbers for (table), 6 -180	steam, 13 -22	Heat equation, 2-37
consistency tests, 6 -180	Hand (unit of length, def), 1-16	Heat exchangers:
dropping point of, 6 -180	Hand cleaners, 6-137	corrosion in, 6 -106
firmness of, 6 -180	Hand-operated squeezer and molding machines,	in power plants, 9-75
lubricity of, 6-181	13 -5	tubes for (table), 8-186
penetration of, 6 -180	Hand rule (magnetism), 15 -11	Heat flow, conversion table, 1 -34
r or, o 100	, to 11	,

TT .	T . 1 (G .)	W. 1
Heat gains:	Heat value (Cont.):	High-vacuum pumps (Cont.):
from equipment, 12 -75	of petroleum products, 7-11	turbomolecular, 14-42
internal, 12 -73	tables, 7 -11, 7 -13	types and sizes of (tables), 14 -40
from lighting, 12 -73	of various liquid fuels, 7 -11	ultimate pressure (def), 14 -39
from people, 12 -73	of various solid fuels, 7 -10	ultrahigh vacuum, 14 -40
solar, 12 -73	of wood, 7 -9	vapor contamination in, 14 -42
table, 12 -73	tables, 7 -9	High-voltage measurements, 15 -24
Heat insulators (see Insulators)	Heaters:	Hill climbing (optimizing), 2 -52
Heat pumps, 19-2	Heating, 12 -85	Histograms, 17-10
Heat rates:	air infiltration (tables), 12-68, 12-69	Hitches, in rope, 8-81
gross (def), 9 -71	dielectric, 7 -55, 15 -87	Hitenso bronze (electrical conductor), 15-6
net (def), 9 -71	ductwork for, 12-88	Hobbing processes, 13-60
for central stations (table), 9-71, 9-72	inside design conditions (table), 12-63	Hodograph (def), 3-11
net station (def), 9-71	moisture infiltration effects on, 12-64	Hogging (ships, def), 11-43
Heat transfer:	outdoor air requirements (table), 12-67	Hogging ejectors, 9-83
coefficients of (def), 4-80	overall heat-transfer coefficients (table), 12-70	capacity of (table), 9-83
to or from air, 4 -83, 4 -84	steam piping for, 12-96	materials for, 9-83
to or from boiling liquids, 4-87	pipe capacities of, 12 -96	Hohmann transfer (space maneuver), 11-106
combined convection and radiation, 4-88	tables, 12 -98	Hoisting:
to or from condensing vapors, 4-87	Heating coils, film coefficients for, 4-84	cableways for, 10-30
in refrigerating plants (table), 19 -24	Heating systems:	drums for, 10-9
for scale deposits (table), 4-85	corrosion in, 6 -107	load-suspension devices for, 10-7, 10-10
to or from steam (chart), 4 -87	fans for, 14 -50	speeds in, 10 -17
to or from water, 4 -83, 4 -84	Heave (ships, def), 11 -45	wire rope for, 10 -8
(See also Film coefficients)	Heaviside function, 2 -36	Hoisting machinery:
in dielectrics, 19 -29	Heavy water, 9-140	drums, 10 -9
across evacuated space, 19-38	Hectare (def), 1 -21	sheaves, 10 -10
through pipe insulation, 4 -88	Helical gears, 8 -94	tackle blocks, 10 -10
chart, 4-88	Helicon gears, 8-100	Hoisting mechanisms, 8 -8
radiation shield for, refrigerated, 19 -39	Helicopters, 11 -71	Hoists:
radiative, 19 -38	definition of, 11-59	air-motor, 10 -14
in steam boilers, 9 -39	Helium dilution refrigerators, 19 -28	brakes for, 10 -13, 10 -14, 10 -17
U values resulting from additional insulation	Helmholtz free energy (thermodynamics), 4 -6	chain, 10 -12
(table), 12-71	Helve hammers, 13-22	electric, 10-14
Heat transmission:	Hemispherical flux density, total (heat radiation,	tables, 10 -15
coefficients of, 4 -80	def), 4 -62	Koepe, 10 -16
(See also Film coefficients; Heat transfer)	Hemp, 6 -136, 6 -140	lever-operated, 10-13
in condensers, 4 -87	properties of (table), 6 -141	table, 10 -14
by conduction, 4 -80, 4 -81	Henequen fiber, 6 -137	load brakes for, 10 -10
and convection, 4 -80	Henry (inductance, def), 15 -2	mine, 10 -16
laws of, 4 -80	Herbert cloudburst test, 5-13	balanced (def), 10-16
by convection, 4 -80, 4 -81	Herbert pendulum hardness test, 5-13	electrical equipment for, 10-17
and conduction, 4-80	Hermetian matrices, 16 -41	motors for, 10 -17
natural, 4-86	Herringbone gears, 8 -94	monorail, 10 -26
and radiation, 4-88	Hexadecimal numbers (computers), 2-41	table, 10 -26
conversion table, 1-34	Hexagon (geometric construction), 2-6	pneumatic, 10-14
in evaporators, 4 -88	Higas process (gasification), 7-35	power: motors for, 15 -44
with extended surfaces, 4-86	High heat value of fuels, 4-26	wire rope for, 10-8
in furnaces (calculations), 4-72	High-speed steel, 6 -30	skip, 10 -16
to high-velocity gases, 4-85	composition and uses of (tables), 6 -32	trolley, 10 -13
with laminar flow, 4-86	tools, 13 -49	Holding, of materials, 10-3
mean temperature difference, 4-81	High-vacuum pumps:	Holding mechanisms, 10-10
nomenclature for, 4 -79	applications of, 14 -43	Holland formula, for stack plumes, 18-14
by radiation, 4 -62, 4 -79	baffles and traps for, 14 -42	Hollow building blocks (table), 12 -28
in surface condensers, 9-76	compression ratio of (def), 14 -40	Honing, 13 -64
temperature gradient in, 4-81	conductance, 14 -43	Hooke's joint (coupling), 8-36
between tubes and boiling liquids (table), 4 -87	cryopumps, 14-41	Hooke's law, 5-17
units of, 4 -79	diffusion, 14 -39, 14 -42	Horizontal-piston power pumps, 14 -2
Heat treatment:	forepressure in, 14 -40	Horsepower (def), 1-21
of iron and steel, principles of, 6-17	fractionating, 14 -41	Hose:
of nonferrous alloys, 6-5 2	gas-ballast, 14-42	ANSI: couplings for: threads for, 8-214
of steel (see Steel)	gas flow at low pressure in, 14 -43	table, 8 -214
Heat value (def), 4-25	getter-ion, 14-41	fire, 18 -27
of by-product fuels (table), 7-10	installation of, 14 -42	ANSI: couplings, 8-214
of coal (tables), 7-2 to 7-4	Knudsen number for, 14-43	dimensions of (table), 8-214
of coke (table), 7-31	mercury-vapor, 14-41	screw thread, 8-214
at constant pressure (def), 4-26	net pumping speed of, 14 -43	flexible metal, 8-215
at constant volume (def), 4-26	outgassing rates of, 14 -43	pressure, 8-214
of fuels (def), 4-25, 7-6	pressure range (table), 14-40	for hydraulic fluids, 8 -40
Dulong's formula for, 7-6	pumping speed of (def), 14-39	rubber-lined, 8-214
high and low (def), 4-25	Roots-type, 14-43	SAE standard, 8-40
table, 4 -26	rotary mechanical, 14-39	Hoses, SAE standard (table), 8-40
per unit of gaseous combustible, 4-26	roughing time of, 14 -43	Hot-air engines:
(See also Calorific value)	sorption, 14-41	internally focusing regenerative, 9-21
of gaseous fuels (table), 7-15	sputter-ion, 14-41	solar, 9 -21
of hydrocarbons (table), 4 -26	throughput of (def), 14-39	for space power, 9-21

Hot drawing, 13-18	Hydraulic turbines, impulse (Cont.):	Hypalon, uses of, 6-148
Hot-working of metals, 13-9	tailwater level, 9-156	Hyperbola:
Hotchkiss drive (automobile), 11-11	usual head limits (table), 9-151	area of, 2-8
Household refrigerating machines, 19 -16	model tests of (chart), 9-158	conjugate, 2-21
HP 80: pressure-enthalpy chart for, 19 -11	number of units in plant, 9-150	equation for, 2-20
HSPF (heating season performance factor, def), 19-2	Pelton-type (<i>see</i> Hydraulic turbines, impulse) pressure regulators, 9 -160	equilateral, 2-21
Human factors engineering, 17 -39	propeller-reaction: adjustable-blade runners,	properties of, 2 -20 Hyperbolic differential equations, 2 -34
Human-generated power, 9-4	9-151	Hyperbolic functions (sinh, cosh, tanh), 2-18
Humans:	Kaplan-type, 9-151	graphs of, 2-18
energy output of, 9-5	specific speed, 9-152	series for, 2 -31
in bursts, 9-5	tĥrust, 9 -153	Hypereutectoid (steel), 6 -17
metabolic balance for, 11-120	usual head limits (table), 9-151	Hypergeometric distribution, 2-10
table, 11 -120	proportionality laws for, 9-150, 9-158	Hypersonic aerodynamics (see Supersonic and
physiological limits of, 9-5	reaction, 9-151	hypersonic aerodynamics)
Humidification of air, 4-17	axial-flow, 9-151	Hypocycloid, 2-22
(See also Air conditioning)	types of, 9-151	Hypoeutectoid (steel), 6-17
Humidity: measurement, 4 -15	bearings for main shaft, 9-154 case velocities (chart), 9-154	Hypoid gearing, 8 -95 Hypotrochoid, 2 -22
by chemical analysis, 4 -15	characteristics of, 9-153	Hysteresis, magnetic, 15 -10
molal (def), 4 -15	design of, 9-152	Hysteresis loop, 15 -10
relative (def), 4 -15	draft tubes for, 9-155	Hysteresis loss, in magnetic metals (table), 15 -10
specific (def), 4-15	general arrangement (table), 9-151	Steinmetz's law of, 15-10
Huntington's postulates (Boolean algebra), 15-80	number of runners (table), 9-151	Hysteretic damping, 3-66
Huygen's approximation to length of circular	runners, 9 -154	Hytemco (resistor alloy), 15-62
arc, 2 -8	settings for (table), 9-151	table, 15 -61
Hydrated lime, 6-160	specific speeds, 9-152	
Hydraulic brakes, 11-14	spiral cases for, 9-154	
Hydraulic control systems, 16 -30	stay rings for, 9-154	T 1
Hydraulic conveyors, 10 -54 Hydraulic couplings, 8 -36, 11 -6, 11 -7	thrust bearings for, 9-154 usual head limits (table), 9-151	I beams:
Hydraulic grade line (def), 3 -37	wearing rings for, 9-154	deflection of (tables), 12 -42, 12 -47 safe loads for, 12 -42
Hydraulic jacks, 10 -16	reversible pump, 9-157	standard, properties of (tables), 12 -35
efficiency of, 3-26	runaway speed, 9 -153, 9 -157	wide-flange, properties of (tables), 12-36
Hydraulic power transmission, 8-39	selection of, 9-150	IC (see Integrated circuits)
flow velocities in, 8 -40	specific speed (def), 9-150	Ice, specific gravity and density (table), 6-8
fluids for, 6-184	speed regulation, 9-159	Ice making, 19-24
hose fittings for, 8 -40	requirements, 9 -160	can system, 19-24
pipe for, 8 -40	speed selection, 9-150	extrusion method, 19-24
tubing for, 8 -40	surge tanks for, 9-160	Flakice method, 19 -24
tubing fittings for, 8 -40 Hydraulic presses, 13 -21	tests of, 9 -160 types of, 9 -150	PakIce method, 19-24 Lee sketing rinks, pining for 19-25
Hydraulic radius, 3-50	general arrangements (table), 9-151	Ice-skating rinks, piping for, 19 -25 ICI color method, 12 -107
table, 3 -38	selection of, 9-150	Icosahedron, 2-9
Hydraulic torque converter (automobiles), 11-7	usual head limits (table), 9-151	Ideal gas law, 3 -39
Hydraulic turbines:	vacuum breakers for, 9-155	Ideal radiator (def), 4 -62
auxiliaries for, 9-160	valves for, 9-156	Ignition coils, 15-66
cavitation in, 9-159	water hammer in penstocks of, 9-160	Ignition lag (internal-combustion engines), 9-115
plant sigma for prevention, 9-159	wicket gates and mechanisms for, 9-154	Ignition quality of fuels, 9 -116
classification of, 9 -150 computer-aided design of, 9 -160	Hydrazine (rocket fuel), 7 -29 Hydrocarbons:	Ignition systems: in automobile engines, 9 -114
Francis (see Hydraulic turbines, reaction)	air for combustion of (table), 4 -27	battery, 15 -66
fundamental formulas, 9 -149	boiling points of (table), 4-50, 4-53	electrical, 15-66
general arrangements (table), 9-151	heats of combustion of (table), 4- 26	magnetos for, 15-67
governors, 9-159	products of combustion of (table), 4-27	spark gaps for, 9-114
electric, 9-159	Hydroelectric power stations, cost of, 17-34	Ignition temperatures, for fuels, 9-115
electronic, 9-159	Hydrofoil craft, 11 -41, 11 -57	IIR (infinite impulse response), 15 -84
head limits (table), 9-151	lift-drag ratios (chart), 11-58	Ilgner method of motor-speed control, for mine
homologous turbines, 9-158	Hydrogasification processes (gas making), 7-35	hoists, 10 -17
impulse, 9-150, 9-155 basic dimensions, 9-156	Hydrogen: air for combustion of (table), 4 -27	Illuminance (def), 12 -99 Illumination, 12 -99
blade forces in, 3-40	as cryogen. 19 -34	calculation of, 12 -107
buckets, 9-156	flame temperature and dissociation (table), 4 -29	calculation sheet for, 12 -114
efficiency of, 9-156	as fuel, 9-23	coefficients of utilization of, 12 -107
general arrangement (table), 9-151	heat value (table), 4-26	color of, 12 -100
housings, 9-156	liquid (rocket fuel), 7-29	dimming systems for, 12-116
jet deflectors, 9-156	normal saturated, properties of (table), 4-37	fixtures (see Lighting fixtures)
nozzles, 9-156	products of combustion of (table), 4-27	glare in, 12 -105
regulation of, 9-156	Hydrogen peroxide as rocket fuel, 7-29	industrial, 12-11
runaway speed, 9-157 runners, 9-156	Hydrogenation, of coal, 7 -40 Hydrometers, 3 -36	prescribing of, 12 -105
settings for, 9-156	scale for, 1 -27	for various activities (table), 12 -106 for various locations (table), 12 -106
table, 9 -151	Hydrophones, 12 -118	visual-comfort criteria, 12 -106
specific speeds, 9-156	Hydrostatics, 3-33 to 3-36	(See also Lamps; Lighting)
speed selection, 9-156	Hygrometer, 4 -15, 16 -18	Imaginary numbers (def), 2 -3

Impact, 3-18, 5-43	Inductive circuits, 15-2, 15-17	Industrial plants (Cont.):
collinear, 3-18	Inductive reactance, 15 -3, 15 -18, 15 -19	support functions for, 12 -4
definition of, 3 -18, 5 -43	Industrial accidents, prevention of, 18 -19 to 18 -21	system balancing of, 12 -2
of elastic and inelastic bodies, 3-19	Industrial accounting, 17 -11	system integration of, 12 -2
oblique, 3-18	balance sheets, 17 -12	truck access to, 12-14
stress due to, 5-44	Industrial cars, 10-21	utilities for. 12-4
of water jet against plate, 3 -19	Industrial electronics, 15 -85	walls for, 12 -25
Impact tests, 5-7	Industrial engineering, 17-25	warehousing in, 12-4
Impedance (electric circuits, def), 15 -3, 15 -18	Industrial heating furnaces, 7-41	waste disposal from, 12 -16
synchronous, 15-32	Industrial management, 17-2	waste disposal from, 12 -10 water for, 12 -12
Implicit functions, 2-25	Industrial organization, 17-2	wind forces on, 12 -19
Impregnating compounds (motor coils), 6 -138	Industrial plants, 12-2	windows for, 12 -7, 12 -11
Improshare (bonus plan), 17 -10	activities in, 12-3	windows for, 12-7, 12-11 working drawings for, 12-17
Impulse:	air conditioning of, 12 -13	Inertia (def), 3-2
	aisle space in (for accident prevention), 18 -19,	force of reciprocating-engine parts, 8 -65
angular (def), 3-18 linear (def), 3-18	18- 20	moment of (see Moments, of inertia)
Impulse function, 2-36		
*	automatic control in (see Automatic control)	principal axis of (def), 3-8
Impulse turbines (see Hydraulic turbines; Steam	bay sizes for, 12-14	product of (def), 3-8
turbines)	beams in, 12-14	radius of (def), 3-8
Incentive wage systems, 17 -10	bearing walls for, 12 -25	Inflammability (see Flammability)
Inch:	braced frames for, 12-25	Inflection, points of (calculus), 2 -25
circular (def), 1-16	building orientation of, 12-5	Information, coding of, for electronic transmis-
miner's (def), 1 -16	color codes for, 12-15	sion, 16 -21
Incinerators, 7-46	color use in, 12 -15	Infrared testing of materials, 5 -67
air-pollution control of, 7 -49, 18 -16, 18 -18	columns in, 12 -14, 12 -25	Infusorial earth (abrasive), 6 -129
air supplies to, 7 -46	compressed air for, 12-13	Ingot iron, 6 -13
blower capacities for, 7-46	configuration of, 12-6	effect of cold rolling on (chart), 6 -13
energy from (table), 7 -47	construction contracts for, 12 -17	Ingots:
flues for, 7-48	contracts for, 12-17	steel, 6 -14
fuel used in, 7 -45	cost estimates for, 12 -17	defects in, 6 -14
furnace configurations in, 7 -46	design of, 12-3	Inhibitors (corrosion), 6 -104
furnace design, 7 -46	doors for, 12 -15	Inner product (mathematics, def), 2-11
furnace feed for, 7 -46	electric power for, 12 -11	Inorganic compounds, heat of formation of, 4 -29
furnace types, 7 -46	emergency egress from, 12-14	Inspection of castings, 13-7
grates for, 7 -46	equipment replacement in, 17-7	Instant center, 8-4
heat calculations for, 7 -49	equipment specifications for, 12-4	Instantaneous axis (kinematics), 3-13, 8-4
heat recovery from, 7 -47	exterior walls for, 12-15	Instruments, 16-2
locations for, 7 -46	flexibility of, 12 -2	accuracy of (def), 16-2
materials balance in (table), 7 -51	floors for, 12 -15	for cryogenics, 19-37
plant cross section (fig), 7-48	footings for, 12-14	electrical (see Electric instruments)
plant design, 7 -46	foundations for, 12-14	error in, 16 -2
for refuse-derived fuel (RDf), cross section of,	functions required from, 12-2	gages (see Gages)
7 -49	geographic location of, 12-5	nuclear radiation, 16-19
refuse-handling facilities for, 7-46	heating and ventilating in, 12-13	precision of (def), 16-2
residue disposal from, 7 -49	interior walls for, 12-15	for pressure measuring, 16 -8
salvage from, 7-51	lighting in, 12 -11, 12 -102	recording, 16-19
waste-to-energy (WTE), 7-51	locating of, 12 -2	resolution of (def), 16-2
energy from (table), 7 -47	material flow in, 12-3	sensitivity of (def), 16-2
Inclined planes, laws of, 3-14	natural light in, 12-11	Insulating materials:
Income statement (accounting), 17-12	noise in, 12 -16	electrical, 6-138
Inconel:	sources of, 12 -16	properties of (table), 15 -16
composition and properties of (tables), 6-78,	obsolescence in, 12-2	thermal conductivity of (tables), 4-83
6-79 , 6-89 , 6-90	parking at, 12-14	Insulating paper, 6 -139, 15 -51
strength of, at high temperatures (tables), 6 -78,	for trucks, 12 -14	Insulating varnishes, 6 -138
6-79 , 6-89 , 6-90	partitions for, 12-15	Insulation:
Indentation hardness, 5-13	people movement in, 12 -3	additional, U values resulting from (table),
Indeterminate forms (calculus), 2 -25	planning of, 12 -2	12- 71
Index of refraction, 19 -41	plans and specifications for, 12 -17	electric, 15 -15, 15 -16
Indicator diagrams of steam engines, 9-54	plant security for, 12 -14	classes of, 15 -43
Indicators:	plumbing for, 12 -12	copper wire, 15 -56
for engines: electric, 16 -15	purpose for. 12 -2	impregnated fabrics, 6 -139, 15 -50
high-speed, 16 -16	ramps for, 12 -15	impregnated paper, 15 -51
Induced angle of attack (aerodynamics, def), 11-	raw materials in, 12-4	for magnet wire, 15 -65
61	real estate for, 12-2	resistance: measurement of, 15 -24
Induced drag (aerodynamics), 11 -61, 11 -62	regulations covering, 12 -15	of underground cable, 15 -50
Induced emf, 15 -16	roof profiles for, 12 -15	reflective. 6 -151
direction of, 15 -11	roofs for, 12 -15	thermal, 6 -131
Inductance (electrical circuits), 15 -16	safety provisions in, 18 -19 to 18 -21	of cold-storage rooms, 19 -23
units of (def), 15-2	seasonal variations affecting, 12-3	
	seasonal variations affecting, 12-3 services in, 12-10	for cryogenics 19-38
Induction (electrical circuits), 15 -17		for cryogenics, 19-38
Induction brazing, 13-29	shear walls for, 12-25	for high temperatures, 6-150
Induction furnaces, 7 -57	site selection for, 12-5	for moderate temperatures, 6 -150
Induction generators, 15 -34	space requirements in, 12-3, 12-4	multilayer, 19 -39
Induction heaters, 7-52, 7-55, 15 -87	specifications for, 12-17	of pipes, heat transmission through, 4-88
Induction watt-hour meters, 15 -23	sprinklers for, 12 -12	powder, 19 -39

1 1 2 4 1 (0)		•
Insulation, thermal (<i>Cont.</i>): reflective, 6 -151	Internal-combustion engines (<i>Cont.</i>): fuel lines, 9 -108, 9 -111	Involutes: of circles, 2 -23
for refrigeration, heating, and air condition-	fuels, 9 -104	of curves (def), 2 -26
ing, 6 -150	table, 9 -103	Ionization, effects of, on materials, 9-138
rigid-foam, 19 -39	antiknock compounds (table), 9-116	Iridium, uses of, 6 -74
Insulators: conductivity of (tables), 4 -84	autoignition temperatures, 9-115 cetane number (def), 9-116	Iron: alloys, machinability of, 13 -47
electric properties of (tables), 15 -16	flame speed in, 9-114	alpha (def), 6 -16
heat transmission through, 4-88	gasoline (see Gasoline)	cast (see Cast iron)
Integers (def), 2 -3	ignition quality, 9 -116	castings (see Castings)
Integral calculus, 2-26 to 2-30	ignition temperatures (table), 9-114	classification of, 6 -13
Integral compensation (automatic control), 16 -25 Integrals:	injection for, 9 -109, 9 -110 kerosine (<i>see</i> Kerosine)	corrosion (<i>see</i> Corrosion) creep rates of (table), 5-11
approximate computation of, 2 -29	knock rating, 9-115	delta (def), 6 -16
definite, 2 -29	knock suppression, 9-116	foundry practice (see Foundries)
double, 2 -29	knock suppressors (table), 9-116	gamma (def), 6 -16
elliptic, 2 -29 indefinite (table), 2 -26 to 2 -28	octane number (def), 9-115 permissible compression ratios, 9-117	ingot, 6 -13 malleable, 6 -41
probability, 2 -29	road ratings, 9-116	physical properties of, 6 -17
triple, 2 -30	vapor lock, 9-108	pig, 6 -13
volume, 2 -30	volatility of, 9-104	and steel, 6 -13
Integrated circuits, 15 -75	gas lines, 9-108	strength of at high temperature (table), 5-11
computer, 15 -82 digital, 15 -79	horsepower, 9 -91 idling jets, 9 -109	wrought (see Wrought iron) Iron-iron carbide equilibrium diagram, 6-16
linear, 15 -75	ignition systems (see Ignition systems)	Iron ore, sources of, 6 -13
Intensifiers (pumps), 14 -3, 14 -10	indicators, high-speed, 16-16	Ironing (thinning of metal in bending, def), 13-16
Intensity:	intake manifolds, 9-106	Irradiation, effects of, 9-142
field, unit of, 3-19	knock, combustion causing, 9-115 (See also Internal-combustion engines,	(See also Radiation) Irrational numbers (def), 2-3
of radiation (heat transfer), 4 -62 of sound (def), 12 -117	fuels)	ISCC-NBS color method, 12 -107
Intercondensers, 9-82	L-head, 9 -112	Isentropic expansion:
Interest, compound, tables for, 1-5, 1-6	locomotive, 9-102	of gases, 4-9
Interference: optical, 19-42	lubrication, 6 -181, 9 -118	of vapors, 4 -14
Interference drag, 11-70 Interference fits, 8-44	marine, 9 -99 mean effective pressure in, 9 -91	ISO 9000: registration, 18 -2
preferred metric sizes (table), 8-45	mixture distribution, 9-108	quality control under, 17 -6
Interferometer, 19-42	muffle pits for, 9-106	Iso-butane, properties of (table), 4 -36
Interior wiring (see Wiring)	mufflers for, 9-106	ISO metric screw threads (table), 8-14
Internal brakes, 8-40	oil cooling, 9-118	Isoclinics (stress analysis), 5-52
Internal-combustion engines, 9 -90 air cooling for, 9 -118	outboard (table), 9 -99 pistons (<i>see</i> Pistons)	Isolation, of vibrations, 3-65 Isostatics (stress analysis), 5-52
air lines, 9-108	precombustion chambers for, 9-113	Isothermal expansion:
air pollution from, 9-119	pumping work, 9 -92	of gases, 4 -9
airplane (see Airplanes, engines)	for recreation vehicles, 9-100	of vapors, 4 -14
analysis of engine process, 9 -91 automobile (<i>see</i> Automobile engines)	regulation of (speed and load), 9 -117 scavenging, 9 -107	Isotherms, of winter temperatures (chart), 12 -63 Isotopes, 6 -7, 9 -133
back pressure, 9-106	scavenging, 9-107 small, 9-100	IT calorie (International Steam Table) (def),
carburetion, 9 -109	table, 9 -101	1-20, 4-3
metering characteristics, 9-109	spark advance, 9-114	mechanical equivalent of, 1-20
combustion chambers, 9-111	spark-ignition, 9 -90, 9 -111	
divided, 9 -113 open, 9 -113	stationary, 9 -99 stratified-charge spark-ignition, 9 -113	Jacks, 10-15
combustion knock, 9-115	supercharging of, 9-106	rack and lever, 10 -16
combustion process, 9-93	tractor, 9-98	Jaw clutches, 8-37
combustion roughness, 9-112	truck and bus, 9-97	Jet condensers, 9-81
compression-ignition, 9-90, 9-113 compression pressure in, 9-90	two-cycle, 9 -91 utility, 9 -100	Jet fans, 14-51 Jet propulsion (see Aircraft jet propulsion)
compression process, 9-93	volumetric efficiency, 9 -92	Jets:
compression ratios, 9 -90	table, 9 -93	pressure of: against blades, 3 -40
cooling systems, 9-117	water cooling of, 9-117	water: impact of, 3-19
cycles, 4 -11, 9 -90	Internal energy of gases, 4-9, 4-29	JFET (bipolar junction field effect transistor),
deviations from ideal processes, 9 -92 diesel (<i>see</i> Diesel engines)	table, 4-28 Internal-friction theory (stress analysis), 5-49	15 -70 Jib cranes, 10 -27
dissociation, 4-30	International Aluminum Standard, 15 -6	Jig boring machines, 13 -55
dual-fuel, 9 -90	International Copper Standard, 15-5	Jig transits, 16-6
exhaust-gas, analysis of, 9-94	Interpoles in d-c generators and motors,	JIT (just in time) delivery, 17-4
temperatures, 9 -94 exhaust manifolds for, 9 -106	15-29 Inventions, patents for, 18-28 to 18-30	Job evaluation, of workers, 17 -10
exhaust manifolds for, 9-106 exhaust process, 9-93	Inverse hyperbolic functions, 2 -18	Job-order costing, 17 -14 Job standardization, 17 -28
expansion process, 9-93	Inverse trigonometric functions, 2-17	Johnson counter, 15-81
explosions in, 4-30	Inversion temperature (Joule-Thomson effect),	Joints:
flame travel, 9-93	4-24	in belts, 8 -51
four-cycle, 9 -91 fuel injection, 9 -109, 9 -110	Investment process (molding), 13-4 Involute gear teeth, 8-88	knuckle, 8 -33 method of (stress determination), 3 -6
pumps, 9 -109, 9 -111	Involute gear teeth, 8-88 Involute splines, 8-33	pin, friction in, 3-28
* * * * * * * * * * * * * * * * * * *	A	

Joints (Cont.):	Knuckle joints, 8-33	Law of cosines, 2-17
pipe (see Pipe, joints)	Knudsen number, 14-43	Law of sines, 2-17
riveted (see Riveted joints)	Koepe hoists, 10-16	Lay cables, 15-6
toggle, 8 -8 universal, 8 -36	Koppers-Totzek process, 7-38 Kort nozzle system (ship propulsion), 11-55	copper (table), 15 -6 Layers, for communications networks, 2 -47
Joists, steel, 12 -43	Kraft paper, 6 -144	Layouts, industrial, 17-4
Jolt molding machines, 13 -5	Mart paper, v 111	LBM (laser-beam machining), 13 -67
Jominy hardenability test, 6-18		L.B.P. (length between perpendiculars, def),
Joule (unit of work, def), 1 -18, 15 -2	Labor, energy produced by, 9-4	11-42
Joule cycle, 4-11, 4-13, 9-125	Labyrinth seal, 8-142	LDPE copolymer resins: properties of (table),
Joule-Thomson coefficient (def), 4 -5, 4 -24 Joule-Thomson effect (throttling), 4 -24	for steam turbines, 9-63 Lac (resin), 6-112	6 -196 Lead:
Joule's law (electric currents), 15-8	Lacquers, 6-108	chemical, specifications (table), 6 -75
Journal bearings (see Bearings)	composition and uses of, 6 -112	corroding, specifications (table), 6 -75
Journals (see Shafts)	Lag bolts, allowable lateral loads on (table), 12-33	creep rates for (table), 5-10
Jupiter, planetary data for (tables), 11-102, 11-103	Lag screws:	specifications (table), 6-75
Jute fiber, properties of (table), 6 -141	holding power of, 12 -32 lead holes for, 12 -32	in type metals (table), 6 -75 Lead alloys, for bearings (table), 6 -61
	proportions of (table), 8-24	Lead solders, melting points of (table), 6 -76
Kalman filter (control theory), 16-44	uses of, 8-21	Leaded-coppers, 6 -67
Kanthal:	Lambert surfaces (radiant heat, def), 4-63	League (unit of length, def), 1 -16
as resistor material, 15-62	Lamé's formula for collapse of thick tubes, 5-46	Leakage, magnetic, 15 -10
table, 6 -78	Laminar flow, 3-46, 3-47, 3-49	Leakage loss, through steam turbines, 9-63
Kaolin in firebrick, 6-152	Laminated foil, 13 -14 Laminated wood, 6 -123	Least work principle of 5 36
Kaplan-type turbines (hydraulics), 9-151 Kármán vortices, 12-21	Lamps:	Least work, principle of, 5-36 Leather:
Karnaugh maps (circuit analysis), 15 -80	ballasts for, 12 -101	in belts (see Belts)
Keene's cement (plaster), 6-163	circuits (chart), 12-103	specific gravity and density of, 6-7
Kelly ball test for concrete, 6 -166	economics of installations, 12-116	Leclanché cell, 15-11
Kelvin (unit of temperature, def), 1-17, 1-25	electric, 12 -100	Ledoux bell flowmeter, 16 -14
Kelvin absolute temperature scale, 4-2 conversion to degrees Celsius (eq), 4-2	energy distribution from (fig), 12 -116 fluorescent: characteristics of (table), 12 -104	Leidenfrost point (def), 4 -87 Lemniscate, 2 -24
Kelvin double bridge, 15 -25	life of (table), 12 -104	Length:
Kelvin's law for economical conductor size, 15 -47	preheat circuits for, 12 -101	conversion table for, 1-28, 1-29
Kepler's laws (satellites), 11-105	high-intensity-discharge, 12-102	equivalents (table), 1-28
Kern (def), 5 -40	characteristics of (table), 12 -104	of plane figures, 2-7
Kernel (matrix, def), 2-14	figure, 12-105	units of (def), 1 -16, 1 -17, 1 -24
Kerosine, 7 -13 Keys, 8 -31	high-pressure sodium vapor, 12 -102 figure, 12 -105	Lenses, 19 -41 power of, 19 -41
feather, 8 -31	incandescent, 12 -100	Leveling, 16 -51
flat, 8 -31	bases for, 12 -100	with transit and stadia, 16-55
gib-head (table), 8 -32	bulbs, 12 -100	Levels:
sunk (table), 8 -33 taper, 3 -26, 8 -31	characteristics of (table), 12 -102 metal halide, 12 -102	adjustment of, 16 -52 automatic, 16 -52
table, 8 -32	figure, 12 -105	inspection of, 16-52
Woodruff (table), 8 -32	starting circuits for, 12 -101	setup and use of, 16 -51
Kilocalorie, mechanical equivalent of, 1-33	vapor, 12 -102	surveying, 16-6
Kilogram (unit of mass, def), 1-17	Lanchester-Prandtl theory (aerodynamics), 11 -62	Lever (mechanism), 8-3
Kilovars (reactive current, def), 15 -2, 15 -19 Kilowatt (def), 15 -8	Land measure, units of, 1 -16	Lewis formulas for strength of gear teeth, 8-100
Kilowatt-hour (def), 15 -3, 15 -8	Landfill, 18 -18 Lang-lay wire rope, 10 -8	Liability insurance, 18 -31 Licensing of engineers, 18 -31
Kinematic similarity (models), 3 -41	Laplace equation, 2-34	Lift (aerodynamics, def), 11-60
Kinematic viscosity, 3-33	Laplace operator, in automatic control analysis,	in hydraulics, 3 -47
Kinematics (def), 3-10	16- 26	Lift coefficient (def), 11-61
of fluids, 3-36	Laplace transformation mathematics, 2 -35, 2 -36	Lift trucks, 10-23
(See also Mechanism) Kinescope (television), 15 -89	Laplace transforms, 2-35 table, 2-35	Lifting magnets, 10 -11, 15 -64 Lifting tongs, 10 -10
Kinetic friction (def), 3-21	Lapping, 13 -64	Light:
Kingsbury thrust bearings, 8-126	Lapping machines, 13 -64	sources of, 12 -100
coefficient of friction of, 3-28	Larson-Miller parameter (creep), 6-77	units of, 12 -99
Kirchoff's laws:	Lasers, 15-74, 19-42	velocity of, 19 -41
in electrical circuits, 15 -8 of radiation (def), 4 -62	for machine alignment, 16 -6 Latent heats (def), 4 -4	wavelengths of (chart), 19 -42 (<i>See also</i> Illumination)
Kirsten-Boeing ship propellers, 11-55	of fusion (tables), 4-50 , 4-58	Light meters, 12 -99
Klystron, 15 -74, 15 -88	of vaporization (tables), 4-50, 4-58	Light year, 11 -101
Knock (detonation), 7-12	Latex, 6 -148	Lighting, 12 -99
suppression of, 9-116	Lathes, 13-51	artificial, 12 -11, 12 -105
Knock rating: of gasolines, 7 -12, 9 -115	cutting tools for (see Cutting tools) sizes of, 13-52	economics of, 12 -116 heat from, 12 -116
aviation, 9 -115	troubleshooting of (table), 13 -54	of industrial plants, 12 -11, 12 -105, 12 -107
motor, 9-115	turning recommendations for (table), 13 -53	natural, 12 -11
research, 9-115	turret, 13 -52	of offices, 12 -106
supercharge, 9-115	Latus rectum:	(See also Illumination)
Knot (nautical unit, def), 1 -16 Knots in rope, 8 -81	of parabola, 2 -19 semi-, of ellipse, 2 -20	Lighting design, cavity reflectances (table), 12-108, 12-112
ranous in rope, 0-01	sein-, or empse, 2-20	12-100, 12-112

Lighting fixtures, 12 -100	Locomotives, diesel-electric (Cont.):	Lubricants (Cont.):
heat gain from (charts), 12 -73	braking, 11 -23	health considerations, 6 -185
Lighting systems:	dynamic, 11 -23	for hydraulic systems, 6 -184
for automobiles, 15 -66	cabs for, 11 -23	for industrial applications, 6-183
design of, 12 -107	characteristics of (table), 11-21	for internal-combustion engines, 6 -181
Lignite, 7 -5	compatibility of, 11-25	for machining operations, 6 -184
analysis of (table), 7 -3 to 7 -5	controls for, 11-22	oils (see Oil, lubricating)
combustion of, 9 -30	chart, 11 -26	for press work, 13-18
Lime:	propulsion, 11-23	properties of, 6 -177
common (quicklime), 6 -160	wheel slip detection, 11-23	solid, 3 -22, 6 -181
granulated, 6 -160	engines for, 11-21	sulfated-ash test for, 6 -179
hydrated, 6 -160	governors for, 11-21	synthetic, 6 -177
magnesium, 6 -160	generators for, 11-22	table, 6 -178
specific gravity and density of (table), 6 -8	power control of, 11-22	tests for, 6 -178
Lime mortar, 6 -160	horsepower of, 11-24	unbonded, 6 -181
Lime-soda process (feedwater treatment),	brake, 11 -24	viscosity of, 6-178
9 -48	drawbar, 11 -24	(See also Lubrication)
Limestone, composition of, 6 -143	indicated, 11-23	Lubrication, 6 -177
Linde liquid-air system, 19 -26	rail, 11 -24	of air compressors, 6 -184, 14 -32
Line integrals, 2-34	maximum speed of, 11-25	of automobile engines, 9-118
Line organization (def), 17 -2	performance of, 11-23	of bearings, 6 -183, 8 -117, 8 -137
Linear differential equations, 2-32, 2-34	adhesion, 11-24	boundary (def), 3 -20, 6 -178
Linear equations, solution of, 2-12, 2-32, 2-38	efficiency (thermal), 11-24	complete (def), 3 -20, 8 -116
Linear expansion, coefficient of (def), 4-2	speed-tractive effort, 11-24	elastohydrodynamic, 6-178
Linear measurements, 16-4	traction motors for, 11-22, 11-24, 11-25	fluid, 8 -116
Linear programming (optimization), 2 -52, 17 -8	characteristics of, 11-22, 11-24, 11-25	of gears, 6 -183
to minimize costs, 17-8	wheel slip of, control of, 11-23	greasy (def), 3 -20
Lines:	efficiency of, 3-26	hydrodynamic, 6-178
bisection of, 2-5	electric, 11-25	hydrostatic, 6-178
center of gravity of, 3-6	arrangement of (chart), 11-26	incomplete, 3 -20
equations of, 2 -12, 2 -18	drives, 11-25	of internal-combustion engines, 6 -181,
of force (mechanics, def), 3 -19	traction motors for, 11-27	9 -118
directions of (magnetic), 15-11	voltages used for, 11-25	and journal friction, 3-27
geometric constructions of, 2-5, 2-6	electric haulage: mine, 10-19	mixed-film, 6-178
rope, breaking strength of (table), 8-81	weight required for, 10-20	of refrigerating machinery, 6-184
Link (unit of length, def), 1-16	engines for, 9-102	regimes of, 6 -178
Linkages, 8-3	(table), 9 -101	semifluid, 8-116
Linotype metal (table), 6 -75	mine, 10 -19	of steam turbines, 6-183
Linseed oil, 6-108	haulage capacity of (table), 10-20	of thrust bearings, 8-126
Liquid-level sensors, 12-123	speed-tractive effort (curves), 11-24, 11-25	viscous (def), 3-20
Liquid measure, 1-16	steel for, ASTM specifications (table),	(See also Lubricants)
Liquid meters, 16-14	6 -26	Lubrication systems, 6-181
Liquids (def), 3 -33	storage-battery, 10-20	Lüders lines (rolled steel), 5-3, 6-25
boiling, heat-transfer coefficients to or from,	Logarithmic decrement (vibrations), 3-63	Lumber, 6 -112 to 6 -128
4 -87	Logarithmic function, series for, 2-31	allowable unit stresses in (table), 6-115 to
coefficients of thermal expansion of, 4-2	Logarithmic mean temperature difference, 4-81,	6 -124
compressibility, 6 -9	4-83	commercial standards for, 6-128
densities of (table), 3 -31	Logarithmic spiral, 2-23	composite, laminated veneer, 6-123
evaporation temperatures of (tables), 4-50,	Logging of data, 16-19	parallel-strand, 6-123
4-53, 4-58	Logs, for buildings, 6-124	properties of, 6-123
flow of (see Flow)	Loop (automatic control), 16-24	stress-graded, 6 -119, 6 -123
general properties of, 3-31 to 3-33	Loop circuit, 15-52	structural, composite, 6-123
latent heats of (tables), 4-50, 4-58	Loop gain (automatic control, def), 16-28	types of, 6 -123
mechanics of, 3-29 to 3-61	Loran (navigational aid), 15-90	dimensional, 6-119
pressure of, law of, 3 -33	Lost-wax process (molding), 13-4	glued-laminated, 6-123
radioactive, control of, 18-17	Loudness level, 12-118	machine-evaluated, 6-123
at rest, properties of, 3-33 to 3-36	Low heat value of fuels (table), 4-26	machine-stress-rated, 6-123
specific gravity and density of (table), 6-8	LOX (liquid-oxygen explosive), 7-21	shrinkage in, 6 -119
surface tension of (table), 3-33	LP (linear programming), 17-8	stress-graded, 6-119
thermal conductivity of (table), 4 -82	LPG (liquified petroleum gas):	temperature effects on, 6-121
Liter (def), 1 -17	in manufactured gas, 7-15	visually graded, 6 -119
Litre (def), 1 -17	specifications for (table), 7-15	(See also Plywood; Wood)
Loaders, 10-24	LQG/LTR (linear quadratic gaussian with loop	Lumen (unit of luminous flux, def), 12-99
Loading:	transfer recovery), 16-39	Luminaires, 12-102
by power shovel, 10 -33	LSI (large-scale integrated circuit), 15-81	dirt depreciation factors for (chart, table),
safety factors for, 5-20	Lubricants, 6-177	12 -113
Loading docks, design of, 10-73	bonded, 6 -181	lenses for, 12 -105
Lobe-type pumps (rotary), 14 -12	coefficients of friction when using, 3-22	reflectors for, 12-105
Lock nuts, 8-19	disposal of used, 6-185	utilization coefficients for (table), 12-110
Locking fasteners (fig), 8-24	extreme-pressure, 6-180	Luminance (def), 12-99
Locomotive cranes, 10-29	fats as, 6 -177	Luminous efficiency (chart), 12-100
Locomotives, 11-20, 11-25	fire-resistant, 6-184	Lune, 2 -9
characteristics of (table), 11-21	for gas engines, 6-183	Lurgi process (gasification), 7-35
diesel-electric, 11-20	for gas turbines, 6 -183	LVDT (linear-variable differential transformer),
airbrake controls for, 11-23	for gears (tables), 8-114 to 8-116	16-5
batteries for, 11-23	greases, 6 -180	L.W.L. (length on load waterline, def), 11-42

Manometers, 3-34, 16-8 McAdams and Sherwood coefficient of friction Magnesium alloys (Cont.): (fluid flow), 4-23 joining of, **6**-85 amplification of pressures in, 16-8 Mach angle (aerodynamics), 11-74 machining of, 6-85 inclined, 3-34, 16-8 Mach cone (aerodynamics), 11-74, 11-77 properties of (tables), 6-85 U tube, 3-34, 16-8 Mach number (aerodynamics), 11-60, 11-61, 11-72 resistance to corrosion of, 6-85 well type, 3-34, 16-8 (fluid flow), 3-42, 3-43 surface protection of, 6-85 Mantissa (def), 2-4 Mach-Zehnder interferometer, 11-81 welding of, 6-85 Manufactured gas, 7-15 Machinability (def), 13-47 Magnesium chloride brine, properties of (table), Manufacturing: Machine elements, 8-8 **19**-19 autofacturing, 17-41 designing for, 17-41 efficiencies of (table), 3-26 Magnet wire, 15-65 diameters of (table), 15-65 rotary and reciprocating, 8-65 automatic, 17-41 Machine screws: Magnetic circuits, 15-8 automatic assembly, 17-41 driving recesses for (fig), 8-22 Ohm's law of, 15-9 procedures for, 17-41 head types for, 8-17, 8-19 Magnetic coercive force (def), 15-10 Manufacturing plants (see Industrial plants) heads for, standards for (tables), 8-21, 8-22 Magnetic drag dynamometer, 16-15 Mapping, contour, 16-55 Maraging steel, 6-27 threads for, 8-8 Magnetic field intensity (def), 15-4 standards for (tables), 8-10 to 8-13 Marble, composition of, 6-143 Magnetic flux (def), 15-3 Marbon-B, uses of, 6-148 Machine-shop practice, 13-45 Magnetic flux density (def), 15-3, 15-9 Machine tools, 13-45 Magnetic flux direction, 15-11 Marine compass, 3-20 automation of, 13-50 Magnetic forming, 13-19 Marine engineering, 11-40 boring machines, 13-55 Magnetic hysteresis, 15-10 (See also Ships) broaching with, 13-60 Magnetic leakage, 15-10 Marine engines: diesel, 9-99 chatter in, 13-48 coefficient of, 15-10 cutting fluids for, 13-50 Magnetic metals: powdered, properties of (table), gas turbine, 9-132 cutting-off, 13-61 6-88 internal-combustion, 9-99 Magnetic permeability (def), 15-4 drilling with, 13-55 Marine Plastic Pollution Control Act of 1987, gear cutting with, 13-59 Magnetic permeance (def), 15-4 11-48 Magnetic pickups, 16-3 grinders, 13-64 Marine steam turbines, 9-64 Mark (data transmission), 16-21 lathes (see Cutting tools; Lathes) Magnetic pole (def), 15-3 milling with, 13-57 Magnetic pulleys, for conveyors, 10-51 Mars, planetary data for (tables), 11-102, 11-103 mist cooling for, 13-50 Magnetic refrigeration, 19-28 Martensite, 6-17 numerical control of, 13-51 Magnetic reluctance (def), 15-4 Mash weld. 13-30 planers, 13-60 Masonry: Magnetic reluctivity (def), 15-4 Magnetic remanence (def), 15-10 ashlar, 6-143, 12-28 reamers, 13-56 saws, metal-cutting, 13-61 Magnetic symbols (table), 15-3 construction, 12-27 screw machines, 13-55 mortar for (tables), 6-162 Magnetic tape (computers), 2-44 shapers, 13-60 specific gravity and density of (table), 6-8 Magnetic units, 15-3 tool shapes for, 13-52 table, 15-3 stone, properties of (table), 6-144 Magnetism, 15-9 tools for (see Cutting tools) terms for, 6-143 turret lathes, 13-52 Magnetization curves, 15-9 working compression (table), 12-28 variable-speed transmissions for, 13-52 Magnetohydrodynamics, 9-26 Mass (def), 3-2 for woodworking, 13-72 Magnetomotive force (def), 15-3, 15-9 center of, 3-6 Machine vision, 10-70 Magnetos, for ignition systems, 15-67 conversion to energy, 9-133 Machinery steel, 6-28 Magnetrons, 15-74 conversion table for, 1-31 Magnets, 15-62 Machines: energy equivalence of, 9-133 guarding of, 18-20 lifting, 10-11, 15-64 equivalents (table), 1-31 point of operation (def), 18-20 law of conservation of, 3-2, 3-39 permanent, 15-62 safety devices for, 18-20 specialty, 10-11 relativistic, 9-134 Machining, 13-65 Magnification, of optical systems, 19-41 units of, 4-2 adaptive control for, 13-51 Magnifying power of lenses, 19-41 defined, 1-17 Magno (resistor alloy), 15-62 of ceramics, 13-65 variable, 3-19 by chemical milling, **13**-66 table, **15**-61 Mass defect, nuclear, 9-134 Mains for electric distribution systems, 15-53 cutting fluids for, 13-50 Materials: Malleable cast iron, **6**-13, **6**-38, **6**-41 classification of, 13-50 general properties of, **6**-3 mechanical properties of, 5-2, 5-17 by electrical discharge, 13-66 Malleable castings (see Castings) electrochemical, 13-66 at low temperatures, 19-32 of plastics, 13-65 energy output of, 9-5 storage of, 10-62 recommendations, 13-59 in bursts, 9-5 equipment used in, 10-71 physiological limit of, 9-5 Materials handling: residual stress after, 13-48 ultrasonic, 13-67 Man-machine interactions, 17-39 automated storage and retrieval systems for, (See also Machine tools; Metal cutting) Management: 10 - 73classification of materials for, 10-3 Machining centers, 13-51 controlling by, 17-15 Maclaurin's series, 2-30 functions of, 17-15 equipment used in (table), 10-36 McLeod gage (high-vacuum), 16-9 industrial, 17-2 feeding devices for, 10-3 McPherson struts (automobiles), 11-11 holding devices used in, 10-3 organizing by, 17-15 participative, 17-3 McRuer's rule (operator-controlled machines), planning for, 17-4 **17**-41 planning by, 17-15 positioning devices for, 10-4 McQuaid-Ehn test (austenitic grain size), 6-18 responsibilities of, 17-2 Materials testing, 5-13 Manganese steel (table), 6-28, 6-29 Magnaflux inspection of castings, 13-8 Mathematical models, 2-52, 2-53 Mathematical tables, 1-2 to 1-15 Magnesite brick, 6-151 Manganin (resister alloy), 15-62 Magnesium, 6-84 table, **15**-61 Mathematics, 2-2 to 2-39 Manila fiber, properties of (table), **6**-141 Manila rope, U.S. specifications for (table), arc welding of, 6-85 Matrices: sheets, 6-85 addition of, 2-12 Magnesium alloys, 6-84 6 - 138inverses of, 2-13 casting, mechanical properties (table), 6-85 MAN/MWM stirling engines, 9-21 multiplication of, 2-12

Manning formula for flow in open channels, 3-59

forgings, 6-85

nonsingular (def), 2-13

0 <u>2.</u>		
Matrices (Cont.):	Mechanical seals, 8-141	Metals (Cont.):
row operations on, 2-13	Mechanics:	fatigue of, 5-8
singular (def), 2 -13	of fluids, 3 -29 to 3 -61	f.c.c., for cryogenic equipment, 19-32
special, 2-14	of materials, 5-14	flow lines in, 13-9
Matrix (def), 2 -12	Newton's laws of, 3-2	forging of, 13 -10
diagonal (def), 2-12	of solids, 3-2 to 3-20	galvanic series for (table), 6 -100
identity (def), 2 -12	Mechanism, 8-3	h.c.p., for cryogenic equipment, 19-34
square (def), 2 -12	Megger (measurement of electrical insulation re-	heat content at various temperatures (chart), 7-42
zero (def), 2 -12 Matrix algebra, 16 -41	sistance), 15 -24 Megohmit (electrical insulation), 6 -138	heat of fusion of (tables), 6 -50
Matter:	Megotalc (electrical insulation), 6 -138	for high-temperature use, 6-77
conservation of, 9-134	Meissner effect, 19-30	hot-working of, 13 -9
particles of, 9-133	Melting points:	jewelry, 6 -74
Maxima and minima, 2-25	of brazing alloys (table), 6 -76	machinability of, 13-47
Maximum-distortion-energy theory (stress analy-	of the elements (table), 4-58	melting point of (table), 4-81, 6-50
sis), 5 -49	of fusible alloys (table), 6 -76	modulus of elasticity of (table), 5-4, 6-50
Maximum-shear theory (stress analysis), 5-48	of metals (table), 6-11 , 6-50	molten, properties (table), 4 -81
Maximum-strain-energy theory (stress analysis),	of refractories (tables), 4-57 , 6-153 , 6-156	nonferrous, 6 -49
5-46 Maximum strain theory (stress analysis) 5-49	of resistor alloys (table), 15 -61 of solders (table), 6 -76	for nuclear-energy applications, 6 -82 physical constants of (table), 6 -50
Maximum-strain theory (stress analysis), 5-49 Maximum-stress theory (stress analysis), 5-48	of various substances (table), 4 -50, 4 -57	plastic range of, 13-9
Maxwell (magnetic flux, def), 15-3	Melting pots, resistor heating of, 7 -54	chart, 13 -10
Maxwell's relations (thermodynamics), 4 -6	Membranes:	powdered, fabrication of, 6 -62, 6 -87
table, 4 -7	elastomeric (table), 6-146	(See also Powdered metals)
Maxwell's theorem (beam deflections), 5-36	vibration of, 3 -73	properties of (table), 6 -7
Mean, arithmetic, 17-19	Mercury:	relaxation test for, 5-10
Mean camber line (airfoils, def), 11-62	planetary data for (tables), 11 -102, 11 -103	resistivity (table), 15-4
Mean effective pressure, 4-11	properties of (tables), 4-51 , 4-55 , 4-58	resistor materials, 15-61
in steam engines, 9-54	uses of, 6 -74	shearing of, 13 -14
Mean specific heats (see Specific heat)	Mercury thermometers, 16 -9, 16 -10	specific gravity and density of (table), 6 -7
Mean temperature difference in heat transmission, 4 -81	Mercury vapor lamps, 12 -102 Merit rating, of workers, 17 -10	specific heat (table), 6 -50 spinning of, 13 -14
Mean value theorem, 2 -29	Mershon diagrams:	squeezing of, 13 -19
Measurements, 16-2, 16-3	for a-c voltage drop, 15 -47, 15 -49	stamping of, 13-20
absolute systems (mechanics), 3-2	chart, 15 -49	strain limit in, 13 -10
of acceleration, 16-17	Mesh connections, in three-phase circuit, 15-20	strength of (table), 5-4
of angles, 16-4	Metacenter, 3-36	at high temperatures, 5-10, 5-11
of areas, 16 -7	of ships (def), 11 -44	stress relief of, 13 -9
counting, 16-2	Metal cutting, 13-46	structure of, working, 13-8
electrical, 15 -20, 16 -16	basic mechanics of, 13-46	superplasticity in, 5-11
of fluid flow, 16 -13 integrators for, 16 -15	chips produced, 13-46 forces in, 13-46	surface finish for, 13 -67 swaging of, 13 -19
of fluid volume, 16 -7	power requirements for, 13 -47	thermal conductivity of (tables), 4 -80, 4 -81,
of force, 16-7	principles of, 13 -46	6 -50
of frequency, 16-3	tools for (see Cutting tools; Machine tools)	true-stress-strain curves for, 13-11
gravitational systems (mechanics), 3-2	vibration effects during, 13-48	for type, composition and properties of (table),
of heat, 4 -3	Metal working (see Metalworking)	6 -75
of humidity, 16 -18	Metallurgy, powder, 6 -62, 6 -87	welding of (see Welding)
linear, 16 -4	(See also Alloys; specific metals)	workability of, 13 -10
of liquid level, 16 -9	Metals:	Metalworking, 13-8, 13-10
of mass, 16 -3 of nuclear radiation, 16 -19	annealing of, 13 -9 antifriction, 6 -61	equipment for, 13 -21 plastic working, 13 -10
of physical and chemical properties, 16 -18	atomic numbers of (table), 6 -50	Meter constants, for watthour meters, 15 -23
of plasticity, 16 -18	atomic weights of (table), 6 -50	Metering pumps, 14-3
of power, 16 -15	b.c.c., for cryogenic equipment, 19-33	Meters, 16 -2
of pressure, 16-8	bearing (see Bearing metals)	air, 16 -13
of pressure differences, 16 -9	bending of, 13 -16	differential-pressure, 16-9
standards for, 16-2	boiling points of (table), 6 -50	displacement, 16-7
of temperature, 4-2 , 16-9	chemical symbols (table), 6 -50	electric, 15 -20
of thickness, 16 -5 of time, 16 -3	coefficients of thermal expansion of, 4-2	gas, 16 -13
of torque, 16 -7	tables, 6 -50 coining of, 13 -20	liquid, 16 -13 mass flow, 16 -15
of vacuum, 16 -8	cold-working of, 13 -10	nutating disk, 16 -7
of velocity, 16 -17	corrosion of (see Corrosion)	piston, 16 -7
of viscosity, 16-18	creep in (table, chart), 5-10, 5-11	venturi, 3-54 , 16-14
of weight, 16 -3	for cryogenic equipment, 19-32	vortex-shedding, 16-15
Measures and weights:	crystal structure of (table), 6-50	(See also Electric instruments; Measurements)
metric (see Metric measures and weights)	density of (table), 6 -7, 6 -50	Methane (see Hydrocarbons)
U.S., 1 -16, 1 -17	dispersion hardening of, 13-9	Methanol (wood alcohol), 6-148
Measuring instruments (see Instruments; Meters)	drawing of, 13-16	Method of joints (stresses in structures), 3-6
Mechanical draft, 9-46 Mechanical efficiency of steam engines, 9-54	elastic constants of (table), 5 -4 electrical resistivity of (table), 6 -50, 15 -4 to	Method of sections (stresses in structures), 3-6 Methods design, 17-26
Mechanical equivalent of heat (def), 4-3	15-6	Methods engineering, 17-26
Mechanical movements, 8-3	embossing of, 13-20	Methyl alcohol, 6 -148
Mechanical properties of materials, 5 -2	emissivity of (table), 4 -64	as freezing preventive (table), 6 -142
Mechanical refrigeration (see Refrigeration)	extrusion of, 13-20	as solvent, 6 -148

Methyl chloride:	Modulus (Cont.):	Moments (Cont.):
as refrigerant, 19-5	of rupture (def), 5 -26	of momentum, 3-18
thermal properties of, 4 -51, 4 -55	of strain hardening (def), 13 -10	of resistance (beams, def), 5 -21
Metre (unit of length, def), 1 -17	Young's (def), 5-2, 5-17	and shear in beams, 5-31
Metric measures and weights, 1 -24	table, 5-4	units of rotation (def), 3 -3
conversion tables and equivalents, 1 -19 to 1 -24	Mohr's circle, in moments of inertia, 3-8	Momentum (def), 3-18
prefixes, 1-19	Mohr's strain circle, 5 -19	angular (def), 3 -2
Metric system, 1 -17	Mohr's stress circle, in stress analysis, 5-18	law of conservation of, 3 -2, 3 -19
Metric units (see SI units)	Mohs scale (hardness), 1 -25, 5 -12	linear (def), 3 -2
MHD (magnetohydrodynamics), 9-26	Moisture:	moment of, 3-18
Mica, 6 -138	in air, measurement of, 4-15	Monel, 6-89 to 6-91
Micanite (electrical insulation), 6 -138	in steam, measurement of, 16-18	composition and properties of (table), 6 -89,
Michell bearing, 8-126	Mol (def), 4 -3	6 -90, 15 -61
Microfarad (capacitance, def), 15-15	Mold making, 13-5	heat treatment of, 6 -89
Micrometers, 16-4	cement-sand process of, 13-4	machining of, 6-89
Micron (def), 1 -22	hand ramming in, 13-5	magnetic properties of, 6-91
Microphones, 12-118	sand preparation for, 13-5	mechanical properties of (table), 6-90
Microprocessors (computers), 15-82	aerators for, 13-5	at high temperature (table), 6 -90
Microscopes, measuring, 16 -6	sand cutters for, 13-5	at low temperature, 6-91
sonic, 12 -123	Molding (def), 13-2	Monopropellants (rocket), 7-29
Mil, circular (def), 1 -16	centrifugal processes for, 13-4	Monorail hoists, 10-14
Mill-construction floors, 12-28	dry and green sand for, 13-3	Monorails, 10-26
Milling, of plastics, 13-65	floor, 13 -3	trolley dimensions (table), 10-26
Milling cutters, 13 -57	investment process, 13-4	Monotron hardness test, 5-13
Milling machines, 13 -57	lost-wax process, 13-4	Monotype metal (table), 6 -75
feeds and speeds for (table), 13-58	pit, 13 -3	Monte Carlo simulations, 17-10
troubleshooting of (table), 13-58	processes, 13-3	Month:
types of, 13 -57	sand for, 13 -3, 13 -5	sidereal, 11 -101
Millivoltmeters, 15 -20	sand preparation, 13-5	synodic, 11 -101
Mills, pulverized coal, 9-32	Shaw process, 13-4	tropical, 11-101
Millstones, 6-129	shell, 13 -3	Moody formula for hydraulic turbine efficiency,
Mine cars, 10 -21	(See also Casting; Castings; Cores)	9-158
Mine hoists, 10-16	Molding machines:	Moon:
Mine locomotives, 10 -19	flasks for, 13 -5	mass of, 11 -101, 11 -103
Mineral spirits (solvent), 6 -149	jolt and squeeze, 13-5	planetary data for (tables), 11-101 to 11-103
Minerals, specific gravity and density (table), 6 -8	sand slinger, 13-5	Morse standard taper pins (table), 8-34
Miner's inch (def), 1 -16	vibrators, 13-5	Mortar, 6 -162
Mines:	Molds:	for brick masonry, 12 -27
open-pit, 7 -7	carbon-dioxide process, 13-3	for firebrick, 6 -153
underground: roof supports for, 7 -7	facing sands for, 13-6	lime, 6 -160
ventilation of, 7-7	floor, 13 -3	for masonry construction, 12 -27
Minim (apothecaries' liquid measure, def), 1 -16 Minimum (point on a curve), 2 -25	full, 13 -4 graphite, 13 -4	mix proportions for, 6 -163 for plastering, 6 -162
Mining, long-wall, 7 -7	permanent, 13-4	sand for, 6 -161
Minute (circular measure, def), 1 -17	pit, 13 -3	for stonework and masonry (table), 6 -162
Minutes to decimals of a degree (table), 1 -15	plaster, 13 -3	types of, 6 -162
Miter gears, 8-96	semipermanent, 13-4	MOSFET (metal oxide semiconductor field ef-
Mixed gas (def), 7-15	washers for, 13-6	fect transistor), 15 -70
Mixing of two atmospheres, 4 -17	Mole (unit of amount of substance, def), 1 -17	Motion:
Mixture (chemical, def), 6 -3	Molecular weights:	angular, 3-12
Mixtures:	of common gases (tables), 4-25, 4-27	curvilinear, 3 -11, 3 -12
of air and water vapor, 4-15	of liquid fuels (tables), 4-25, 4-27	forces causing, 3-15
of liquid and vapor (thermodynamics), 4-14	Molecule (def), 6 -3	harmonic, 3-11
Mmf method of generator voltage regulation,	Mollier diagrams, description of, 4-14	plane (def), 3 -12, 3 -13, 3 -17
15 -33	Molten salt gasification process, 7-35	forces causing, 3 -14, 3 -18
Models:	Molybdenum, 6-78	polygon of, 3-11
mathematical, 2 -52, 2 -53	as electric furnace resistor, 7-54	rectilinear, 3-18
similarity of, 3 -41	Molybdenum alloys, 6 -79	forces causing, 3-14
theory of, 3-41	Moment diagrams for beams, 5-21, 5-31 to	relative, 3-13
for wind-pressure tests, 12 -21	5 -33	uniform, 3-10
Moderators (for slowing neutrons), 9-138, 9-142	Moments:	uniformly accelerated or retarded, 3-10
table, 9 -139	in aerodynamics, 11-61	Motion economy, principles of, 17-4
Modified PE-TFE resins: properties of (table),	of a couple, 3-3	Motion study, 17-27
6-190 Madula 2 (commutantan ang 252	of a force, 3-4	elements of, 17 -27
Modula-2 (computer language), 2 -53 Modulators:	of inertia, 3-8 of areas (def), 3-8	motion classification, 17 -28
amplitude-modulation (AM), 15 -74	of beam sections (tables), 5-27	principles of, 17 -27 time standards for, 17 -31
frequency-modulation (FM), 15-74	of builtup sections, 3-9	Motor vehicles (<i>see</i> Automobiles; Trucks)
Modulus:	determined experimentally, 3-16	Motors (see Airplanes, engines; Automobile en-
bulk: of elasticity (def), 5-17	about parallel axes, 3-8	gines; Electric motors)
table, 5-4	of plane areas, by graphics, 3-9, 3-10	MRG (methane rich gas), 7-40
of elasticity (def), 5-17	polar (def), 3-8	Muffle furnaces, 7-41
of metals (tables), 5 -4, 6 -50	principal, 3-8	Mufflers (exhaust), 9 -106, 12 -120
table, 5-4	referred to any axis, 3 -9	Mullers (molding), 13-5
of resilience (def), 5 -17	of solid body (def), 3-8	Multiple-effect compression (refrigeration), 19 -14
of rigidity, tables, 5-4	of various solids, 3-9	Multiplication: arithmetical, 2-4

Munsell color scales, 12-107	Nitriding (heat-treatment), 6-21	Nuclear fuels, 9-138
Muntz metal (copper-zinc alloy, table), 6 -68	steels for, 6 -21	costs of, 9 -143
Muscular energy, 9-4	Nitrile rubber, 6-147	chemical reprocessing, 9-144
Mutual inductance, 15 -2, 15 -3, 15 -17	Nodular cast iron (def), 6-13	enrichment, 9-144
	Noise, 12-117	fabrication, 9-144
NACM specifications, for chains (tables), 10 -5,	from aircraft engines, 11 -93 control of, 12 -119, 18 -21	fuel-burnup, 9-144
10-6	by damping, 12 -119	shipping charges, 9-144 fabrication of, 9-137
Nails, 8 -82	by design changes, 12 -119	properties of (table), 9 -139
cut steel (table), 8-84	by filtration, 12 -119	reconversion of, 9-137
holding power of, 12 -31	by isolation, 12 -119	reprocessing of, 9-137
lateral resistance in wood, 12 -31	by quieting, 12 -120	storage and transportation of, 9-137
table, 12 -32	by shielding, 12 -120	uranium and plutonium recycle, 9-137
points for, 8-82	in duct systems, 12-90	uranium enrichment for, 9-137
wire (table), 8 -82 to 8 -84	occupational exposure to, 18 -21	waste disposal of, 9-138
Naphtha, solvent, 6 -149	permissible exposures (tables), 12 -123, 18 -21	Nuclear fusion, 9-134
Napier's formula for steam flow, 4 -21	safe levels of, 12 -123	energy released in, 9-134
Natural frequencies, 3 -63 Natural gas:	as undesired sound, 12 -119 (<i>See also</i> Sound)	systems for, 9-148 Nuclear particles:
composition of (table), 7-15	Noise reduction coefficient (def), 12 -121	binding energy of, 9-134
flame temperatures (table), 4 -29	Nonferrous metals, 6 -49	elementary, 9-133
Natural numbers (def), 2 -2	annealing of, 6 -52	Nuclear physics, 9-133
Nautical units of length and speed, 1 -16	casting of, 6 -52	Nuclear power, 9-133
Naval brass (table), 6 -68	cold-working of, 6 -52	boilers for (see Boilers, nuclear)
Negative binomial distribution, 2-11	effects of environment on, 6-53	Nuclear power plants (see Power plants, nuclear)
Neoprene, 6-147	effects of temperature on, 5 -10	Nuclear radiation instruments, 16 -19
NEPA (National Environmental Policy Act),	precipitation hardening of, 6 -52	Nuclear reactors (see Reactors)
18-2, 18-7	(See also Alloys; specific metals)	Nucleus:
Neptune, planetary data for (tables), 11 -102,	Normal curves, magnetization, 15 -10	cross section of, 9-140
11-103 Nernst equation (corrosion), 6 -95	Normal density function (statistics), cumulative, ordinates of (table), 1 -10	fission of, 9-134 half-life of, 9-134
Networks, for computers, 2 -46	ordinates of (table), 1-9	radioactivity of, 9 -134
local area, for computers, 2-48	Normal distribution (statistics), cumulative, ordi-	Nullity, of a matrix (def), 2 -14
Neutral axis (beams, def), 5-21	nates of (table), 1 -10	Numbers, 2-2
Neutron balance, 9-140	ordinates of (table), 1-9	preferred, 8-215
Neutron diffractrometry, 9-135	Normal induction curves (magnetization),	scientific notation for, 2-4
Neutron-level instruments, 9-142	15 -10	Numerical differentiation, 2-39
Neutron radiography, 9-135	Notch sensitivity in fatigue of metals (def),	Numerical integration, 2-39
Neutrons, 6-5 , 9-133	5-9	Nutating disk (flowmeter), 16- 7
mass of, 9 -133 thermal, absorption and scattering cross sec-	Notches (see Weirs) Nozzles, 3 -40, 3 -54	Nuts: force required to tighten or loosen, 3 -27
tions (table), 9-141	divergence of, 4-23	lock, 8 -19
Newton-Raphson method, 2-38	flow in: of compressible fluids, 4 -22	materials for, 8-22
Newtonian fluid (def), 3-31	formula for, 3 -54, 3 -55	ISO metric (table), 8-26
Newtonian mechanics, 3-2	of steam, 4 -22, 9 -56 to 9 -60	standard threads for, 8-8
Newton's law (mechanics), 3-2	for flow measurement, 16 -14	threads for, ANSI metric (table), 8-14
Nicad battery, 15 -13, 15 -15	fuel-injection (diesel engines), 9-111	wrench openings for (table), 8-20
Nichols diagrams:	for hydraulic turbines, 9-156	Nuveyor pneumatic ash handling, 10 -53
description of, 16 -22 uses of, 16 -34	steam, design of, 9-57 NPSH (net positive suction head), for pumps	Nylon, electrical uses of, 6 -139
Nichrome (resistor alloy), 15 -62	(def). 14 -2	Nylon fibers, 6 -140 properties of (table), 6 -141
table, 15 -61	Nuclear boilers (see Boilers, nuclear)	Nylon rope, 6 -138
Nickel, 6 -88	Nuclear energy:	Nylon type 6 resins: properties of (table), 6 -192
alloys: composition and properties of (tables),	alloys for, 6 -82	Nylon type 66 resins: properties of (table),
6 -78 to 6 -80, 6 -89, 6 -90	beryllium as absorber, 6-84	6 -193
copper (see Monel)	control rods, 6 -83	Nyquist plots, uses of, 16 -34
heat-resisting, 6 -77	boron, 6 -83	Nyquist stability criterion (automatic control),
heat treatment of, 6 -89	cadmium, 6 -83	2 -35, 16 -37
magnetic properties of, 6 -91 mechanical properties if (table), 6 -90	gadolinium, 6 -84 hafnium, 6 -83	
strength of, at high temperatures (table),	coolants, metallic, 6 -82	Obsolescence, plant, 12-2
5 -11, 6 -78 to 6 -80, 6 -90	fuels, 6 -83	Occupational diseases, prevention of, 18 -21
composition and properties of (table), 15 -61	metals for, 6 -82	Octagon, construction of, 2 -6
electroplating of, 6 -88	moderators (table), 6-82	Octahedron, 2-9
high-temperature properties of (table), 6 -90	nuclear properties, 6-82	Octal numbers (computers), 2-41
production of, 6 -88	reactor component requirements (table),	Octane number (def), 9-115
properties of (tables), 6 -89, 6 -90	6-82	mechanical, 9-116
resistor, 15-62	slow neutron absorption (table), 6 -83	ODP (ozone depletion potential), 19-3
Nickel plating, 6 -88	sodium, resistance to (table), 6 -83	Oersted (magnetic field intensity, def), 15 -3
Nickel silver, 6 -67 table, 6 -68	stainless steel, uses of, 6 -84 zircoloys, uses of, 6 -84	Ohm (def), 15 -2 Ohm's law, 15 -8
Nickel steel (see Steel, nickel)	zirconium, uses of, 6 -84	of magnetic circuits, 15 -9
Nimonic (superalloy, table), 6 -78	(See also Atomic energy)	Oil:
Niobium, 6 -79	Nuclear fission, 9-134	acidity of, tests for, 6 -179
uses of, 6 -81	energy available from, 9-134	additives for, 6-177

Oil (Cont.):	Optical comparators, 16-6	Packing, 8-138
animal, 6 -177	Optical pyrometers, 16 -10, 16 -13	carbon, for steam turbines, 9-63
burners for, 9-34	Optics, 19 -41	common forms of (fig), 8-139
castor, 6 -108	design of, 19 -42	conical ring, 8-140
cloud point in, 6-179	Optimization:	diaphragms to replace, 8-142
compressibility of, 6-9	under certainty, 17 -7	dynamic, 8 -139
core binder, 13-6	using computers, 2-52	jamb, 8 -141
crude, as fuel, 7-11	using linear programming, 17-8	labyrinth, for steam boilers, 9 -63
cutting fluid (machining), 6-184, 13-50	under uncertainty, 17-7	liquid seal, 8-139
density of, 6 -179	Orbiting-scroll compressors, 14-37	O-ring, 8 -139
engine, 6 -181	Orbits, elements of, 11-105	oil seals, 8-141
antiwear additives for, 6-182	Ores:	ring, for steam turbines, 9-63
corrosion inhibitors for, 6-182	extraction and refining of, 6-52	shaft, 8 -139
defoamants for, 6-182	pipelines for, 11 -131	soft, 8 -141
detergents for, 6-182	specific gravity and density of (table), 6-7	steam turbine, 9-63
dispersants for, 6 -182	Organization:	Painting, 6-109
friction modifiers for, 6-182	good, requirements for, 17-3	of aluminum, 6 -110
oxydation inhibitors for, 6-182	industrial, 17-2	of concrete, 6-109
pour-point depressants in, 6 -182	Organization charts (fig), 17-2	of copper, 6 -110
rust inhibitors for, 6 -182	Orifice meters, 3 -55, 16 -14	exterior, 6 -109
SAE viscosity grades for (table), 6-182	Orifices, 16 -14	by flame spraying, 6-110
viscosity grade system for, 6-182	diaphragm meters for, 16-14	of galvanized iron, 6-110
viscosity-index improvers in, 6-182	discharge coefficients for, 3-56	interior, 6 -109
extreme pressure, 6 -180	table, 3 -56	of magnesium, 6-110
fish, 6 -177	flow of air through, 4-21	of masonry, 6 -109
flash and fire points (def), 6-179	flow of compressible fluids through, 3-56, 4-21	of plastics, 6-110
fuel (see Fuel oils)	flow of gas through, 4 -21	spray methods for, 6-110
in gas manufacture, 7 -39	flow of steam through, 4-21	spreading rates during (table), 6-111
heat-transfer coefficients to or from (chart),	formulas for, 4-21	of steel, 6 -110
4-86	pipe, 3 -55, 3 -56	of water tanks, 6-110
insulating, specifications for, 6-138	standard, 3-56	of wood products, 6-110
linseed, 6 -108	tap locations for, 3 -56, 16 -14	Paints and protective coatings:
lubricating, 6-177	Orsat apparatus (flue-gas analysis), 16-18	aluminum paint, 6 -109
additives for, 9-118	Orthocenter (def), 2-5	anodizing, 6 -111
antifoaming agents for, 6-180	Oscillating rolling (metalworking), 13-14	antifouling (ships), 6-109
antirusting agents for, 6 -180	Oscillation, axis of, 3-16	application of, 6 -110
ash in, 6 -179	Oscillators, 15-73	bituminous, 6 -109
gravity of, 6 -179	Oscilloscope, 16-17	bonded phosphates as, 6-111
SAE classifications of, 9-118	OSHA (Occupational Safety and Health Act),	chemical vapor deposition, 6-112
tests of, 6 -178	18-22	copper powder, 6 -109
oiticica, 6-108	Ostwald color system, 12-107	definition of, 6-108
for paint, 6 -108	Oswatitsch shock diffuser, 11-76	destroying agencies of, 6-110
petroleum (see Petroleum)	Ottawa sand for concrete, 6-161	driers for, 6-108
pour point, 6 -179	Otto cycle, 4-11	dry resin as, 6-110
soybean, 6 -108	Otto-cycle engines (see Internal-combustion	drying oils in, 6-108
specific gravity of, 6-179	engines)	ecological restriction on, 6-109
specific gravity and density of (table), 6-8	Outboard engines, 9-99, 11-55	electroplating as, 6-111
synthetic, 6 -177	table, 9 -99	emulsion paint, 6-109
tung, 6 -108	Outdoor air requirements for various locations	enamel, 6 -108
vegetable, 6-177	(table), 12 -67	fire-retardant, 6-109
viscosity of, 3 -32, 6 -178	Outer product (mathematics, def), 2-11	fungicides added to, 6-109
index of (def), 6 -179	Outside count test (statistics), 17-21	galvanizing as, 6-111
recommended (table), 6-182	Oven furnaces, 7-41	heat radiation of, 6-109
temperature variation of, 6 -179	Ovens:	heat-reflecting, 6-109
Oil burners (see Burners)	for carbonizing coal, 7 -33	heat-resisting, 6 -109
Oil cooling, internal-combustion engines, 9-118	core, 13 -6	hot dipping, 6-111
Oil engines (see Diesel engines; Internal-	electric (see Electric furnaces)	ingredients of, 6 -108
combustion engines)	resistor, 7 -52	lacquer, 6 -108, 6 -112
Oil grooves, arrangement of, 8-123	Overdamping, 3 -63	latex, 6 -108, 6 -109
Oil paint, 6 -108	Overdrive (automobiles), 11-9	lead coated copper as, 6-111
Oil Pollution Act of 1961, 11 -47	Overhead, in cost accounting, 17-14	pigments in, 6-108
Oil Pollution Act of 1990, 11-48	Overhead cranes (see Cranes, overhead)	plastic, hot, 6 -109
Oil quenching, 6 -20	Overhead trackage, 10-37	plasticizers for, 6 -108
Oilless bearings, 8-125	Overlap test (statistics), 17-22	plating, 6 -111
Oilstones, 6 -129	Oxidation tests for lubricating oils, 6 -180	porcelain enamels as, 6 -110
Oiticica oil, 6 -108	Oxygen:	primers for, 6 -109
Once-through boilers, 9-37, 9-45	corrosion in boilers, 9 -49	resins in, natural, 6 -108
Open channels:	high-pressure, effect on materials, 11 -113	synthetic, 6 -108
critical values for, 3 -60	liquid (rocket fuel), 7 -29	ship-bottom, 6 -109
flow of water in, 3 -59	in water, removal of, 9 -49	silicone, 6 -109
roughness coefficient of (table), 3 -59	Oxygen analyzers, 16 -19	solvents for, 6-108
specific energy in flow in, 3 -60		sputtering for, 6 -111
Open system (thermodynamics, def), 4-4		terne as, 6 -111
Operations, manufacturing, planning for, 17-3	Pack rolling, 13-14	thinners for, 6 -108
Optical character recognition, 10-71	Packet switching (in computer networks), 2-48	for traffic service, 6 -109

Paints and protective coatings (Cont.):	Patterns (Cont.):	Phosphor bronze, 6 -67
vacuum deposition for, 6-111	machine-finish allowances for, 13-2	tables, 6 -68
varnish, 6 -108, 6 -112	making of, 13-2	Photoelasticity, 5 -51
water-repellent, 6 -109	master, 13 -3	material-fringe value, 5 -52
water-thinned, 6-108	match-plate, 13-2	oblique incidence, 5-52
wood-preservative, 6 -109 PAL (programmable array logic), 15 -81	for mold making, 13-2, 13-5	stress separation, 5-52 three-dimensional, 5-52
Palladium, uses of, 6 -74	shrinkage allowances for, 13-2 skeleton, 13-3	Photoelectric cells, 16 -3
Pallets:	sweeps for, 13-3	Photometers, uses of, 16 -18
in industrial plants, 10-23, 10-72	types of, 13 -2	Photostress, 5-54
lift trucks for, 10-23	Paving, brick, 6-135	Photosynthesis, 9-10
loads on, 10 -23, 10 -72	PD (proportional-derivative) control, 16 -29	PI (proportional-integral) control, 16 -29
Panhandle equations (natural gas pipelines),	Pearlite (steel), 6 -17, 13 -8	Pickling, of steel, 6-15
11-127 Pomovi	Pease-Anthony venturi, 18 -11	Picric acid (military explosive, table), 7-21
Paper: bleaching of, 6 -145	Peat, 7 -9 moisture content of, 7 -9	Piece-rate wage systems, 17 -10 Pierls stress (def), 6 -23
coatings for, 6 -145	properties of, 7 -9	Piezoelectric force measurement, 16 -7
converting, 6 -145	specific gravity and density of, 6 -9	Piezoelectric transducers, 5 -66
grades of, 6 -144	Peck, dry measure (def), 1-16	Pig iron (def), 6 -13
insulating, 6 -139	Peck carrier buckets, 10-46	production of, 6 -13
plastic-fiber, 6 -145	PE-TFE, modified (resins): properties of (table),	Pigments, for paints, 6 -108
pulping, 6 -144	6-190 B. H. C. C. A. 24, 19, 17	Piles:
recycling of, 6-145	Peltier effect, 9 -24, 19 -17	atomic (see Reactors)
refining, 6 -145 sanitary (def), 6 -144	Pendulum:	capping of, 12 -27 concrete, 12 -26, 12 -58
Paper making: pollution from, 18 -15	compound, time of oscillation, 3-16 conical, 3-15	driving of, 12 -26
Parabola, properties of, 2 -19	simple, 3-15	for foundations, 12 -26
Parabolic differential equations, 2 -34	Penetrameters (radiographic), 5 -65	safe loads for, 12-27
Parallel circuits, 15 -8, 15 -52	Pentolite (explosive), 7 -20	spacing of, 12 -27
a-c, 15 -19	Perch (unit of length, def), 1-16	wood, 12 -26
Parallel operation of synchronous generators,	Percussion, center of, 3-16	Pillow blocks, 8-137
15 -34	Perfect gases, 4-10	Pinions (see Gears)
Parallelogram:	Perfectly diffuse surface, 4 -63	Pins:
area of, 2-7	Performance rating, of tasks, 17-29	spring, 8 -32
of motion, 3-10	Periodic table of elements, 6 -6	straight, 8 -32
Parametric equations, 2-20	Permanent set (def), 5-2	taper (table), 8-34
Parasite drag (aerodynamics, def), 11-66 Parasitic currents, 15-10	Permeability curves, 15 -9 Permeance, magnetic (def), 15 -4	tapered, 8 -32 Pipe (def), 8 -146
Parr formulas (mineral-matter-free coal), 7-2	Permittivity (def), 15 -2	aging of, 3-48
Parsec, 11 -101	Permutations and combinations, 2-10	allowance for water hammer, 8 -169
Partial derivatives, 2-25	Personal computers, 2-45	alloy, butt welding of, 8-211
Partial differential equations, 2-34	PERT (Program Evaluation and Review Tech-	aluminum (table), 8-192
Partial pressures, 4 -9	niques) for scheduling, 2 -54, 17 -5	anchoring of, 8-212
Particle clouds, 4-68, 4-69	PETN (explosive), 7-22	asbestos-cement, 8 -194
Particles of matter, 9-133	table, 7 -21	for ASME Boiler and Pressure Vessel Code,
Partitions: in industrial plants, 12 -15	Petroleum: analyses of (table), 7-11	8-143 bolting for, properties of (table), 8-199
reinforced-concrete, 12 -19	API and specific gravity (table), 7-11	branch flow in, compound, 3-52
Pascal (computer language), 2-53	distillates (charts), 7-11	brass (tables), 8 -189, 8 -190
Pascal's law, 3 -33	as fuel, 7 -11	butt-welded, 8-211
Pass-by noise test (trucks), 11-20	table, 7 -11	carbon steel, codes for, 8-169
Passenger cars (railroad), 11-33	(See also Fuels)	cast-iron, 8-187
train resistance, 11-39	heat values (table), 7-11	for fire protection, 18 -27
Passenger miles, of automobiles, 11-3	oil (See also Oil)	soil, 8 -189
Passivators (corrosion), 6 -104	refining of, 7-11	cement-lined, 8-191
Patents, 18-28	reserves of, 9-3	chromium-molybdenum steel, codes for, 8 -169
application for, 18 -28 cost of, 18 -29	specific gravity and density of (table), 6 -8, 6 -9 Petroleum oils, 6 -177	coils, 8 -185 center-to-center dimensions (table), 8 -185
documentation of invention for, 18 -28	Petroleum spirits (paint thinner), 6 -108	collapsing pressure, 5 -45
foreign protection for, 18 -29	Petzval image, 19 -43	commercial classifications of, 8 -146
infringement of, 18 -29	Petzval surface, 19-43	concrete, 8-193
International Convention for the Protection of	Pewter, 6 -74	copper (tables), 8-189, 8-190
Industrial Property, 18-29	pH value:	coverings for, 8-213
procedures, 18-29	definition of, 9 -50	heat transmission through, 4-88
reissues of, 18-29	indicators for, 9-50	distance between supports, 8 -213
rights of owner, 18 -29	relationship to hydrogen ion concentration	drain (table), 8 -194
terms of, 18 -28	(table), 9 -50 Phase converters, electric motors as, 15 -39	fittings for (table), 8-205
types of, 18 -28		drill, 8-146
what is patentable, 18 -28 Path (automatic control, def), 16 -28	Phase difference in alternating currents, 15 -18 Phase-transition temperatures:	dry-kiln, 8 -146 ductile-iron, 8 -187
Path gain (automatic control, def), 16 -28	of the elements (table), 4-53 , 4-58	bell-and-spigot (table), 8 -188
Patterns, 13-2, 13-5	of various substances (table), 4 -50	ends for, 8 -187
distortion allowances for, 13-2	Phenolic resins: properties of (table), 6 -191	centrifugally cast, 8 -187
draft for, for molds, 13-2	Philips Stirling engine, 9-20	for crossing waterways, 8-188
gated, 13-2	Phon (loudness level of sound, def), 12-118	fittings for (see Pipe fittings)
loose, 13 -2	Phono-electric bronze (electrical conductor), 15 -6	flexible-joint (table), 8 -189

Pipe, ductile-iron (Cont.):	Pipe, supports for (Cont.):	Pipe flanges (Cont.):
for gas supply, 8 -187	location of, 8 -213	faces of: male and female, 8 -198
joints for, 8 -187, 8 -188	stresses in line caused by, 5 -55	plain straight, 8-198
thickness of (table), 8 -188, 8 -189	sway braces for, 8-212	raised, 8 -198
Universal, 8 -186	variable-spring hangars for, 8 -212, 8 -213	serrated, 8-198
expansion of, thermal (table), 8 -208	taps, drills for (table), 8 -20	tongue-and-groove, 8 -198
expansion joints for (table), 8 -208	threads for, 8-17	V grooves for, 8-198
fabrication methods for, 8 -167	ANSI: straight (table), 8-19	steel: American classes, 8-197
cupping and drawing, 8-167	taper (table), 8-18	bolting for, 8-198
electric-fusion welding, 8-167	Dryseal threads (table), 8-19	companion (table), 8-202
electric-resistance welding, 8-167	engagement for tight joints (table), 8-203	dimensions of (tables), 8-201, 8-202
electric submerged-arc welding, 8-167	tap drills for, 8 -17	drilling templates for (table), 8-200
forged, turned, and bored, 8-167	tin-lined, 8 -191	facing dimensions of (tables), 8-201, 8-202
hollow-forged, 8-169	Transite (asbestos-cement), 8-194	fitting dimensions of, 8-198
fittings for (see Pipe fittings)	unions for, 8-201	metal thickness, 8-198
flanges for (see Pipe flanges)	vitrified-clay (table), 8-194	pressure-temperature ratings (table), 8-197
flow in: of compressible fluids, 4 -23	water hammer in, 3-61	ratings of (table), 8 -197
general formulas for, 3-50	water well, 8-146	ring joints for, 8 -198
of steam, 4-23	welding of, 8 -209	sizes of, 8 -197
friction factors for (table), 3 -51	wood-lined, 8-191	thickness of metal for, 8 -198
friction loss of water in (charts), 12 -94, 12 -95	wood-stave, 8 -191	welding-neck, 8 -198
hard rubber, 8-191	wrench torques for, 8-197	Pipe threads:
insulation for, 8-213	wrought-iron, butt welding of, 8-211	American national standard dry-seal, 8-17
heat transmission through, 4-88	Pipe fittings, 8-195	American national standard straight, 8-17
chart, 4-88	ammonia, 8 -205	American national standard taper, 8 -17
joints in: expansion, 8-207	cast-iron, elbows, 8 -197	Pipelines:
flanged, 8 -197, 8 -198	flanged (table), 8-196	coal, 11-133
gaskets for, 8 -138	drilling templates for (table), 8 -196	cost of transportation by, 11-131
unions, 8 -201 lead-lined, 8 -191	laterals, 8 -197 long turn, 8 -205	economics and design of, 11 -133 velocity in, 11 -134
line, 8 -146	pressure ratings, 8 -195	wall thickness of, 11 -134
materials for: allowable stresses in (table),	reducing, 8-195	compression, 11 -128
8-170	sizes of, 8 -195	for crude oil and oil products, 11 -129
nipple, 8 -147	tables, 8 -204, 8 -205	deflection (formulas), 5 -57
oil country goods, 8 -146	drainage, threaded (table), 8 -205	design of, 11 -128, 11 -131, 11 -133
orifices in (see Orifices)	ductile-iron, 8 -187, 8 -188	design pressures, 11-128
plastic, for gas service (table), 8-193	flanged, ANSI, 8-187	diameters of, 11-127
plugs for (table), 8-204	water pipe, 8-187, 8-189	economic analysis, 11-129, 11-131, 11-134
plywood, 8-193	head losses in (table), 12-97	flexure, 5 -55
in pneumatic conveyors, 10-53	for high-pressure and high-temperature steam,	flow in, 11 -127
polyethylene (table), 8-194	8 -185	flow equations for, 11 -127
pressure, 8-146	table, 8 -197	horsepower required, 11 -128, 11 -134
PVC (table), 8 -193	loss factors for (table), 3-51	materials transported in, 11-131, 11-132
quality factors for (table), 8-183	quality factors for (table), 8 -183	for natural gas, 11-126
refrigeration, 8-146	for railings, 8-205	operation of, 11 -127
reinforced-concrete, 8-193	resistance to fluid flow, 4-23	pipe for, 11 -127
resistance parameters for (fluid flow), 3 -50 return main, flow capacities of (table), 12 -96	schedule designations for, 8 -169 soldered-joint (table), 8 -206	pipe bends for, 11-127 prime movers for, 11-127
riser, for heating, flow capacities of (table),	steel: American classes, 8 -197	pumps for, 11 -129, 11 -131, 11 -133
12-96	bolting of, 8-197	repairs to, 11 -127
roughness in (table), 3-48	material for, 8-198	for solids, 11 -131
rubber-lined, 8 -191	butt-welded (tables), 8 -209, 8 -210	station spacing, 11 -131
schedule designations for, 8 -169	materials for, 8 -197	stresses: due to flexure, 5 -55
screw threads for, 8 -17	and weights of (tables), 8-155 to	formulas for, 5 -57
tables, 8-18, 8-19	8 -166	valves for, 11 -127
seamless-copper-lined, 8-191	pressure-temperature ratings (table),	Pipetran (pipeline computer program), 11-127
sewer (table), 8-194	8 -197	Piping (def), 8 -143
sleeve couplings for, 8-189	reducing, 8-198	ammonia (table), 19-20
spiral, 8 -185	ring joints for, 8-198	brine, for cold-storage rooms, 19-23
standard, 8-146	side outlet, 8 -198	colors for identification, 8-214
standard sizes of, 8-147	welding neck, 8-198	corrosion in, 6 -106
standards for, 8-143	threaded, 8-201	expansion and flexibility, 8-207
steel, butt welding of, 8 -211	cast-bronze, 8-205	refrigerant, 19 -20
as columns, 12-43	malleable-iron (table), 8-203	for ammonia, 19-20
concrete-filled, as columns, 12-56	for welding (tables), 8 -209, 8 -210	flexibility of, 19 -20
high-pressure steam, 8-185	Pipe flanges:	for other refrigerants, 19 -21
high-temperature steam, 8-185	cast-iron: ANSI, 8-195	for R 12, 19 -20
materials and weights of (tables), 8-148	bolting, 8-195	standards for, 8-143
properties of (tables), 8 -148 spiral welded, 8 -185	bolts for, 8 -195 dimensions of, 8 -195	Pirani gage (high-vacuum), 16 -9 Pistons:
thickness of (tables), 8 -148	drilling templates for (tables), 8 -196	inertia force of, 8 -65
weight tolerances of (table), 8 -167	facing of, 8 -195	packing for, 8 -140
stress relieving after welding, 8 -211	inspection limit, 8 -195	Pitch:
supports for, 8-212	nuts for, 8 -195	of gears: circular (def), 8 -88
cast-iron rollers as, 8-212	screwed companion, 8 -197	diametral (def), 8-88
constant-support hangars as, 8-212, 8-213	spot facing of, 8-195	of ships (def), 11-45

Pitch (Cont.):	Plastics (Cont.):	Polycarbonate resins: properties of (table), 6 -194
of sound, 12 -118	polyimide: properties of (table), 6 -197	Polychlorotrifluoroethylene resins: properties of
specific gravity and density of, 6 -9 Pitot tubes, 3 -57, 16 -14	polypropylene: properties of (table), 6 -197 polystyrene: properties of (table), 6 -198	(table), 6 -190 Polyester:
PLA (programmable logic array), 15 -81	polystyrene and styrene copolymers: proper-	alkyd resins: properties of (table), 6 -195
Placer dredges, 10-33	ties of (table), 6 -198	thermoplastic resins: properties of (table),
Plan equation, for steam engines, 9-54	polytetrafluoroethylene: properties of (table),	6-195
Plan position indicator (radar), 15-88	6-190	thermoset resins: properties of (table), 6 -195
Planck's constant, 9-134 Planck's law, 4-62	polyurethane: properties of (table), 6 -199 polyvinylidene fluoride: properties of (table),	Polyester fibers, 6 -140 Polyethylene: as electrical insulation, 6 -139,
Plane, inclined, 3-14	6 -190	15 -51
Plane areas:	properties of, at low temperatures, 19-34	Polyethylene and ethylene copolymer resins:
center of gravity of, 3-6, 3-7	PTFE-filled copolymer: properties of (table),	properties of (table), 6 -196
moments of inertia of, 3-8 Plane strain, 5-5, 5-44	6 -187 PVC: properties of (table), 6 -200	Polyethylene pipe (table), 8 -194 Polyethylene terephthalate resins: properties of
Planers:	PVC-acetate: properties of (table), 6 -200	(table), 6 -195
for metal, 13 -60	silicone: properties of (table), 6-199	Polygons:
for wood, 13-74	styrene and polystyrene copolymers: proper-	areas of, 2-7
Planets, data on (tables), 11 -102, 11 -103 Planimeters, 16 -7	ties of (table), 6 -198 styrene copolymers: properties of (table), 6 -198	construction of, 2 -6 of forces, 3 -5
Planning:	vinyl: properties of (table), 6 -200	regular, 1-4
in industrial management, 17-3	Plate-bending machines, 13-16, 13-23	table of, 1-4
in industrial plants, 12-3	Plate-straightening machines, 13 -23	Polyhedra, 2-9
Planté storage battery, 15 -13 Plants:	Plates: circular, strength of (chart), 5-48	Polyimide resins: properties of (table), 6 -197 Polynomials (def), 2 -3
chemical: water sources for (table), 6 -171	elliptical, strength of (chart), 5-48	Polyphase induction motors, 15 -37
water uses in (table), 6 -171	flat, 5 -47	Polyphase power:
industrial, 12 -2	rectangular, strength of (chart), 5-48	advantages of, 15-20
(See also Industrial plants)	strength of, 5-47, 5-48	transformation, 15 -35
material movement in, 10 -2 Plasma arc gouging, 13 -32	vibration of, 3 -74 Plating, 6 -111	Polyphase squirrel-cage motors, 15 -37 Polyphase wattmeter, 15 -22
Plastering, mortars for, 6 -162	Platinum:	Polypropylene resins: properties of (table), 6 -197
Plastic, ideal (def), 3-30	as resistor material, 15-62	Polystyrene and styrene copolymers resins: prop-
Plastic design, 5-19	uses of, 6 -74	erties of (table), 6-198
Plastic modulus, 5-50 Plastic range chart (metals), 13-10	Pliofilm, 6 -148 Pliolite, uses of, 6 -148	Polystyrene resins: properties of (table), 6 -198 Polytetrafluoroethylene resins: properties of
Plasticity (def), 13 -9	Plug-cocks, 8-207	(table), 6 -190
Plasticizers (in paints), 6-108	Plumbing, in industrial plants, 12-12	Polytropic expansion:
Plastics:	Pluto, planetary data for (tables), 11-102, 11-103	determination of exponent, 4-9
ABS: properties of (table), 6 -186 ABS/Nylon: properties of (table), 6 -186	Plutonium, use of, in nuclear energy applications, 6 -83	values of <i>n</i> for water vapor (table), 4 -11 Polyurethane resins: properties of (table), 6 -199
acetal: properties of (table), 6 -187	Plywood, 6 -124	Polyvinylidene fluoride resins: properties of (table), 6-199
acrylic: properties of (table), 6-188	allowable stresses in (table), 6-125	(table), 6 -190
acrylonitrile: properties of (table), 6 -188	back of (def), 6 -124	Pomaranchuk refrigerator (cryogenics), 19 -28
bisphenol: properties of (table), 6 -189 cellulose acetate butyrate: properties of (table),	center of (def), 6 -124 commercial standards for, 6 -128	Pop rivets, 8 -30 Porous-metal bearings, 6 -61, 8 -125
6 -189	crossbands of (def), 6 -124	Port and Waterways Safety Act of 1972, 11 -48
cellulosic: properties of (table), 6-189	exterior, 6-124	Portland cement, 6-159
epoxy: properties of (table), 6 -189	face of (def), 6 -124	uses of, 6 -159
ethyl cellulose: properties of (table), 6 -189 ethylene and polyethylene copolymer: proper-	interior, 6 -124 moments of inertia of (table), 6 -125	(See also Cement) Position descriptions, 17-2
ties of (table), 6 -196	section moduli of (table), 6 -125	Positron (radiation), 9 -134
fluoroplastic: properties of (table), 6-190	strength of, 6 -123	Potential difference (def), 15-2
Furan: properties of (table), 6 -191	PMMA resins: properties of (table), 6 -188	Potential energy (def), 3-17
LDPE copolymer: properties of (table), 6 -196 machining of, 13 -65	Pneumatic conveyors, 10 -53 Pneumatic hammers, 13 -23	Potential transformers (instruments), 15 -23 Potentiometers, 15 -25, 16 -5, 16 -12, 16 -17
modified PE-TFE: properties of (table), 6 -190	Pneumatic hoists, 10 -14	Pound (def), 1 -17
nylon type 6: properties of (table), 6 -192	Pneumatic riveters, 13 -24	Pound mol (def), 4 -3
nylon type 66: properties of (table), 6 -193	Point (printers' type measure, def), 19 -43	Poundal (def), 1 -23
PE-TFE, modified (resins): properties of (table), 6 -190	Poise (unit of viscosity, def), 3-31	Pour point of petroleum oils (def), 6 -179
phenolic: properties of (table), 6- 191	Poisson distribution, 2-11, 17-10 Poisson's equation, 2-34	Pourbaix diagrams (corrosion), 6 -95 Powder metallurgy, 6 -87
PMMA: properties of (table), 6 -188	Poisson's ratio (def), 5-4 , 5-15	(See also Powdered metals)
polyamide: properties of (table), 6-192	values of, 5-15	Powdered coal, 9-32, 9-34
polybutalene terephthalate: properties of	for metals (table), 5 -4, 6 -11	Powdered metals, 6 -87
(table), 6 -195 polycarbonate: properties of (table), 6 -194	Polar coordinates, 2-19 Polar moment of inertia (def), 3-8	bearings of, 6 -88 ferrous, properties of (table), 6 -88
polychlorotrifluoroethylene: properties of	Polarization in batteries, 15 -11	nonferrous, properties of (table), 6 -88
(table), 6 -190	Pole (unit of length), 1-16	particle shapes for, 6-87
polyester, alkyd: properties of (table), 6 -195	Polishing, 13-63	sintering of, 6-87
thermoplastic: properties of (table), 6 -195 thermoset: properties of (table), 6 -195	of plastics, 13 -65 Polishing wheels, 13 -63	soft magnetic, 6 -88 uses of, 6 -87
polyethylene and ethylene copolymer: proper-	Pollution, air (see Air pollution)	Power:
ties of (table), 6 -196	Polyamide resins: properties of (table), 6-192	atomic (see Boilers, nuclear; Reactors)
polyethylene terephthalate: properties of	Polybutylene terephthalate resins: properties of	conversion tables for, 1-34
(table), 6 -195	(table), 6 -195	cost of (see Power costs)

Demon (Cout)	Device along and an ACDS staff and as	December of the last of the set.
Power (Cont.):	Power plants, nuclear, ACRS staff reviews of	Pressure-enthalpy chart:
distribution (see Electric power distribution)	(Cont.):	for air, 4-34
electric (see Electric power) human-generated, 9 -4	operating and maintenance costs, 9-144	for ammonia, 4-34
	plant licensing, 9-146	description of, 4-14
from hydrogen, 9-23	plant safety, 9-145	Pressure equivalents (table), 1-31
of lenses, 19 -41 measurement of, 16 -15	preliminary safety analysis report for,	Pressure hose, 8-214
,	9-146	Pressure-volume diagram, description of, 4-9
one- and multiphase, 15 -21, 15 -22	public hearings on, 9-147	Prestone (antifreeze), properties of, 6 -142
muscular, 9-4	radioactive waste from, 9-147	Prevention:
nuclear (see Boilers, nuclear)	reviews for, 9-147	of accidents, 18 -19 to 18 -21
revenue from (table), 17 -38 solar (<i>see</i> Solar energy)	safety of, 9 -145 safety evaluation report for, 9 -147	codes for, 18-22
	standardized designs for, 9-147	of occupational disease, 18 -21 Primary cells, 15 -11
sources (see Energy sources) tidal, 9-21	(See also Atomic energy)	
units of, 1 -18	for peaking capacity, 17 -32	(See also Batteries) Printers' type, sizes of, 19 -43
wave, 9 -22	profits, comparison of private and public	Prisms, surface and volume of, 2-8
Power costs, 9-142, 17-32	(table), 17-35	Probability integral, 2 -29
using coal, 17-36	sulfur emission from (table), 18 -13	Probable error, table, 1 -14
of environmental controls, 17 -37	useful life of (table), 17 -36	Process air, fans to provide, 14 -50
fixed charges, 9 -143, 17 -35	Power presses (see Presses)	Process analysis, 17-3
cost of money in, 17-35	Power pumps (see Pumps, power)	Process annealing (def), 6 -17
depreciation, 17-36	Power series (def), 2 -30	Process planning, 17 -3
index for regions of the United States (table),	Power shovels, 10-33	Processes, automatic control of (see Automatic
17-33	Power spectral density (def), 11 -104	control)
for maintenance, 17 -37	Power steering (automobiles), 11 -12	Producer gas, flame temperatures in (table),
using natural gas, 17-37	Power transmission:	4 -29
using nuclear fuels, 17 -37	by belts, 8 -53, 8 -55	Product liability, 18 -31
operating and maintenance (table), 17 -37	by chain drives, 8 -59	Product of inertia, 3-8
operating expenses, 17-36	electric (see Electric power transmission)	Production control and planning, 17 -4, 17 -6
nuclear, 9 -144, 17 -37	hydraulic, 8 -39	Products of combustion of fuels, 4-25, 4-30
for operating labor, 17 -37	Power transmission systems, 15 -46	table, 4 -27
overall, 9 -144, 17 -37	Pozzolan portland cement, 6 -160	Professional engineer licensing and registration,
using petroleum fuels, 17 -36	Prandtl-Glauert rule (supersonic flow), 11 -77	18 -31
plant: combined cycle, 17 -34	Precipitators:	Profile drag (aerodynamics, def), 11 -62, 11 -69
gas-turbine, 17-34	applications of (table), 18 -15	Profile surveying, 16 -52
geothermal, 17-34	electrical (gas cleaning), 18 -11, 18 -16	Profilometers, 16 -18
hydroelectric, 17 -34	Precise length equivalents (table), 1-28	Profit-sharing plan, 17 -10
industrial, 17 -33	Precision, of numbers, 2-4	Projectiles, motion of, 3 -15
nuclear, 9 -142, 17 -33, 17 -34, 17 -37	Predictor-corrector methods, 2-39	Prony brake, 16-15
pumped storage, 17-34	Preferred numbers, 8-215	Proofreaders' symbols, 19-44
steam-electric, 17-33	Preheaters (boilers), 9-43	Proofreading, 19-43
prices based on, 17-38	corrosion of, 9-44	PROM (programmable read-only memory),
total (table), 17 -38	types of, 9 -43	15 -81, 15 -83
for transmission, 17-38	Present value (accounting), 17-18	Propane:
using various fuels (table), 17-37	Press fits, 8-45	commercial (table), 7-15
Power factor:	torsional holding ability, 8-46	properties of (chart, table), 4 -37, 19 -4, 19 -12
a-c (def), 15 -2, 15 -18	Presses:	as refrigerant, 19-7
of induction motors (table), 15-39	double-action, 13-21	Propellants, rocket (see Rocket fuels)
of loads, approximate values, 15-54	frames for, 13 -21	Propeller fans, 14-44
measurement of, 15-23	holding pressures required in, 13-17	Propeller shafts (ships), 11-56
Power plants:	hydraulic, 13 -19, 13 -21	Propeller-type turbines (hydraulics), 9-150,
costs of, 17 -32	power, 13 -21	9-151
(See also Power costs)	bearing pressures in, 13 -21	Propellers:
environmental considerations, 17-34	energy required by, 13-21	airplane (see Airplane propellers)
fuel expenses for, 17-37	flywheel capacity (formula), 13-21	ship (see Screw propellers)
geothermal, 9-18	shaft capacities (table), 13-21	Propfan engines, 11-84
cycles for, 9-19	screw, 13 -22	Proportional damping (vibrations), 3-72
heat rates of, 9-71	types of, 13 -21	Proportional elastic limit (def), 5 -2
interest charges for (table), 17-36	Pressure:	Propulsion:
investment costs of (table), 17 -33	absolute (def), 3 -33	jet (see Aircraft jet propulsion)
multipurpose, 17-38	between bodies with curved surfaces, 5 -47	of ships, 11 -48
nuclear, ACRS staff reviews of, 9-147	conversion table for, 1 -32	Protective coatings (see Paints and protective
antitrust reviews for, 9-147	critical, for gases (tables), 4-50, 4-58	coatings)
containment features for, 9-146	critical flow, flow of compressible fluids at,	Protons, 6-5 , 9-133
continuing reviews for, 9-147	4-21	Proximate analysis of coals, 7-2, 7-5
cycles for, 9-135	effect on volume of water (table), 6 -10	Psi function, for ideal-gas air (table), 4-31
decommissioning of, 9-144, 9-147	gage (def), 3 -33, 16 -8	Psychrometer, wet-bulb, 4-15, 16-18
emergency core cooling for, 9-146	mean effective, 4-11	Psychrometric chart, 4-16, 12-86
emergency power supplies for, 9-146	measurement of, 16 -8	normal temperatures, 12-86
environmental reviews for, 9-147	at low temperatures, 19 -37	in SI units, 12 -86 Psychrometrics, 12 -85
final safety analysis report for, 9-147 fuel enrichment costs, 9-144	partial, 4- 9 total, in air (def), 4- 15	•
fuels for (see Nuclear fuels)	units of, 1 -18	charts for, 12 -86 terminology for, 12 -87
individual plant examinations for, 9 -147	Pressure drop:	PTFE-filled copolymer resins: properties of
licenses for, 9-146, 9-147	in pipes, 4-23	(table), 6 -187
NRC staff review, 9-147	(See also Flow)	Pullers, lever-operated, 10 -13
	/	,

Pulleys, 8-50 man for, disign of, 8-50 man for, disign of, 2-9 cone, 8-52 magnetic conveys on, 9-3 magnetic conveys on, 9			
for belting, minimum diameters of (table), 8-52			
block, 8.8 efficiency of, 3-29 core, 8.52 core, 8.52 core, 8.52 core, 8.52 core, 8.53 core, 8.52 core, 8.52 core, 8.53 core, 8.52 core, 8.54 core, 8.52 core, 8.54 co			
efficiency of, 3-29 ficition of, 3-26, 3-28 ficition of, 3-26 ficition of, 3-2			
bearings for, 14-13 critical magnetic (conveyors), 18-51 m			
friction of 3.26, 3.28 magnetic (conveyors), 10-51 mins for, design of, 8-50 mins for, design of, 14-13 mins for, design of, design of, 14-13 mins for, design of, design			
magnetic (conveyors), 10-51 rins for, design of, 8-50 slep, 8-52 s			· · · · · · · · · · · · · · · · · · ·
rims for, design of, 8-50 step, 8-52 for V-belix (tabls), 8-54 ploy for papermaking, 6-144 Pulseiges, 11-83 Pulverized and, 9-32, 9-34 Pulverized lime, 6-160 Pulverized scord, 9-32 capacities of, 9-32 capacities of, 9-32 capacities of, 9-34 medium-speed, 9-34 apolitacitors of, 14-2 pumped storage bylon power, 9-157 papilications of, 14-2 pumped storage bylon power, 9-167 magnitications of, 14-2 pumped storage bylon power, 9-167 magnitications of, 14-2 pumped storage bylon power, 9-17 mechanical efficiency of, 14-13 duple-sement, 14-2 pulse, 14-12 mechanical efficiency of, 14-13 band powered, 14-3 hand powered, 14-2 piston, 14			
step, 8-52 pulp for pyermaking, 6-144 pilp for papermaking, 6-144 pilp for papermaking, 6-144 pilp for papermaking, 6-145 polarito dampenes, for pumps, 14-14 polarito dampenes, for pumps, 14-15 polarito dampenes, for pumps, 14-15 polarito dampenes, 14-2 polarito dampenes, 14-2 polarito dampenes, 14-2 polarito dampenes, 14-15 polarito dampenes, 14-2 polarito dampen			. ,,
for V-helis (table), 8-54 Pulsation dampeners, for pumps, 14-14 Pulsat			
Pulls for papermaking, 6-144 Pulsistent Amperes, for pumps, 14-14 Pulsistent Amperes, 14-12 Pumped storage lydro power, 14-13 Pumped storage lydro power, 14-13 Pulsistent Amperes, 14-12 Pulsistent Amperes, 14-12 Pulsistent Amperes, 14-12 Pulsistent Amperes, 14-12 Pumped storage lydro power, 14-13 Pulsistent Amperes, 14-12 Pulsistent Amperes, 14-14 Pulsistent Amperes			
Pulsaign dampeners, for pumps, 14-14 Pulsaign, 11-33 Pulverized coal, 9-32, 9-34 Pulverized into, 6-160 Pulsaign, 11-34 Pul			
Pulseigned and J. 9-32, 9-34 Pulverized lime, 6-100 Pulverized (and, 9-32) capacities of, 9-32 capacities of, 9-32 capacities of, 9-32 medium-speed, 9-34 medium-spee			
Pulverized coal, 9.32, 9.34 Pulverized ime, 6-160 Pulverizers (coal), 9.32 exist temperatures from (table), 9.33 exist temperature from (table), 9.44 exact 14.12 expected table, 14.20 exertified table, 14.2			
Pulverizers (cap. 1932 capacities of, 932 capac			
Pulverizes (coal), 9-32 exit temperatures from (table), 9-33 high-speed, 9-34 medium-speed, 9-34 medium-spee			
capacities of, 9-32 exit temperatures from (table), 9-33 high-speed, 9-34 slow-speed, 9-157 Pumps pumps classification of, 14-2 boiler-feed, turbines for, 9-64 centrifugal (see Centrifugal pumps) classification of, 14-2, 14-15 controlled-volume, 14-10 cushion chambers for, 14-14 diplacement, 14-2 volumenter efficiency of, 14-13 double-screw, 14-12 ficilencies of, 14-13 hand poetred 14-3			
exit temperatures from (table), 9-33 medium-speed, 9-34 medium-speed, 9-34 suction stabilizers for, 14-14 swash-plate, 14-12 system design for, 14-14 uses of, 14-2 particular gives (consistent), 9-157 pumped storage livido power, 9-157 pumped storage livido pow			
medium-speed, 9-34 punice (abrasive), 6-129 punged storage hydro power, 9-157 punge) storage hydro power, 9-157 punge storage hydro power, 9-157 punges for, 14-15 postification for storage hydro power, 9-157 punges storage hydro power, 9-157 punges storage hydro power, 9-157 punge storage hydro power, 9-158 pungers for, 14-15 power (eds.) 14-2 packing for, 8-140 power	exit temperatures from (table), 9-33		definition of, 4 -80
slow-speed, 9-34 Pumped storage hydro power, 9-157 Pumped hydro power, 9	high-speed, 9-34	suction stabilizers for, 14-14	direct view factors for, 4-63
Pumpel storage hydro power, 9-157 Pumps: Pumpel storage hydro power, 9-157 Pumps: Pumpel storage hydro power, 9-157 Pumps: Pumps: Pumpel storage hydro power, 9-157 Pumps:	medium-speed, 9-34	swash-plate, 14-12	emissive power (def), 4 -62
Pamped storage hydro power, 9-157 Pumps applications of, 14-2 politer feed, turbines for, 9-64 centrifugal (see Centrifugal pumps) classification of, 14-2, 14-15 controlled-volume, 14-10 mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-20 flexible-member, 14-12 efficiencies of, 14-13 beat (see Heat pump) high-vacuum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 motors for, 15-44 nomenclature, 14-2, 14-15 motors for, 14-2 piston, 14-2 piston, 14-2 piston, 14-2 power (def), 14-12 estatement of the statement of the statemen	slow-speed, 9-34	system design for, 14 -14	emissivity, of surfaces (table), 4-64
planpies applications of, 14-2 boiler-feed, turbines for, 9-64 centrifugal (see Centrifugal ceee Centrifugal ceee Centrifugal (see Centrifugal Ceee Centrifugal Ceee Centrifugal Ceee Centrifugal Ceee Centrifugal (see Centrifugal Ceee Ceee Ceee Ceee Ceee Ceee Ceee Ce	Pumice (abrasive), 6 -129	uses of, 14 -2	
applications of, 14-2 boiler-feed, turbines for, 9-64 centrifugal (see Centrifugal pumps) classification of, 14-2, 14-15 controlled-volume, 14-10 cushion chambers for, 14-14 direct-acting, 14-2, 14-10 mechanical efficiency of, 14-13 double-screw, 14-12 power fine protection, 18-26 flexible-menther, 14-12 purching of metals, 13-14 purching of metals, 13-1			
böller-feed, turbines for, 9-64 centrifugal (see Centrifugal year centrifugal (see Centrifugal year centrifugal (see Centrifugal year year centrifugal year year year year year year year year	Pumps:	valves for, 14-4	table, 4 -69
centrifugal (see Centrifugal pumps) classification of, 14-2, 14-15 controlled-volume, 14-10 cushion chambers for, 14-14 direct-acting, 14-2, 14-10 mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 replacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 freel-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) high wacum (see High-vacuum pumps) high-wacum (see High-vacuum pumps) high-wacum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 metering, 14-3, 16-15 motors for, 14-2 piston, 14-2 power (def.), 14-2 packing for, 8-140 positive-displacement, 14-2 power (def.), 14-2 packing for, 8-140 positive-displacement, 14-2 power (def.), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 cranschaffs for, 14-5 main bearings for, 14-7 NPSH curves for, 14-5 main bearings for, 14-5 plungers for, 14-8 power ends for, 14-5 selection charts for, 14-5 selection charts for, 14-5 spects for, 14-5 spects for, 14-6 power def., 14-7 NPSH curves for, 14-7 NPSH curves for, 14-5 spects for, 14-5 spects for, 14-5 spector, 14-6 power def., 14-7 suffling boxes for, 14-5 spects for, 14-5 spection charts for, 14-5 spects for, 14-6 spectrum for, 14-12 spectrum for, 14-12 spectrum for, 14-12 spectrum for, 14-12 spectrum for, 16-19 schedular, 14-12 spectrum for, 14-		,	
classification of, 14-2, 14-15 controlled-volume, 14-10 cushion chambers for, 14-14 direct-acting, 14-2, 14-10 mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 flow inching of metals, 13-15 for fire protection, 18-26 flexible-member, 14-12 flow inching of metals, 14-13 for fire protection, 18-26 flexible-member, 14-11 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 motors for, 15-41 nomenclature, 14-2, 14-15 motors for, 15-47 momenclature, 14-2, 14-15 motors for, 15-49 positive-displacement, 14-2 packing for, 14-5 cranshand for, 14-5 cranshands for, 14-5 main bearings for, 14-5 performance curves for, 14-7 NPSH curves for, 14-8 power ends for, 14-5 specto for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-6 performance curves for (chart), 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-8 power ends for, 14-5 specto for, 14-6 performance curves for, 14-8 power ends for, 14-5 specto for, 14-8 power ends for, 14-5 specto for, 14-6 performance curves for, 14-8 power ends for, 14-5 specto for, 14-8 power ends for, 14-5 specto for, 14-6 pulse forms for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-6 pulse forms for, 14-7 stuffing boxes for, 14-8 power ends for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-6 pulse forms for, 14-6 pulse forms for for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 specto for, 14-6 pulse for for forms for for, 14-6 pulse for forms for forms for for, 14-6 pulse for forms for forms for forms for forms for forms for			
controlled-volume, 14-10 cushion chambers for, 14-14 direct-acting, 14-2, 14-10 mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 fred-injection, for engines, 9-109, 9-111 gar, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum pumps) high-pressure, 14-3 heat (see Heat pumps) high-pressure, 14-3 heat (see Heat pumps) high-pressure, 14-3 heat (see Heat pumps) high-pressure, 14-3 how NPSHR in, 14-15 metering, 14-3, 16-15 motors for, 14-3 nomenclature, 14-2, 14-15 NPSH for, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 cranskafafs for, 14-5 cranskafs for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 profromance curves for (chart), 14-5 plungers for, 14-7 NPSH curves for, 14-7 NPSH curves for, 14-7 selection charts for, 14-5 plungers for, 14-8 power ends for, 14-5 cranskafs for, 14-5 cranskafs for, 14-5 main bearings for, 14-5 main bearings for, 14-5 preformance curves for (chart), 14-5 preformance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 main bearings for, 14-7 NPSH curves for, 14-7 NPSH curves for, 14-7 selection charts for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 power def), 14-1 Quality control, 17-6 statistical, 17-19, 17-24 quantum field theory, 9-134 Quarty machines, 10-30 Quart			
cushion chambers for, 14-14 direct-acting, 14-2, 14-10 mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 feliciencies of, 14-13 gear, 14-11 gear, 14-12 gear			
direct-acting, 14-2, 14-10 mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 for fire protection, 18-26 flexible-member, 14-12 fuel-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 motors for, 15-40 nomenclature, 14-2, 14-15 NPSH for, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rolds for, 14-5 cranshafts for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 power damed depeeds for, 14-5 main bearings for, 14-5 power damed depeeds for, 14-7 NPSH curves for, 14-5 power damed carried ficiency of, 14-14 minimum speeds for, 14-5 speeds for, 14-7 stuffing boxes for, 14-7 stuffing boxes for, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14	· · · · · · · · · · · · · · · · · · ·		
mechanical efficiency of, 14-11 displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 gear, 14-11 gear, 14-11 gear, 14-11 gear, 14-11 gear, 14-11 low NPSHA in, 14-15 ingering, 14-3, 16-15 metering, 14-3, 16-15 metering, 14-2 piston, 14-2 piston, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-7 selection charts for, 14-5 speeds for, 14-5 power deer, 14-7 syling flow speeds for, 14-7 syling flow speeds for, 14-5 speeds for, 14-7 syling powers of, 14-6 syling powers of, 14-7 syling powers of, 14-7 syling powers of, 14-6 syling powers of, 14-7 syling powers of, 14-6 syling powers of, 14-7 syling powers of, 14-6 syling powers of, 14			
displacement, 14-2 volumetric efficiency of, 14-13 double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 fuel-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high-vacuum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 momendature, 14-2, 14-15 power (def), 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 performance curves for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 speeds for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 speeds for, 14-6 under the speeds for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 speeds for, 14-6 under the speeds for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 speeds for, 14-5 speeds for, 14-6 under the speeds for, 14-6 un			
volumetric efficiency of, 14-13 double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 fuel-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 motors for, 14-2 power (def), 14-5 main bearings for, 14-5 main bearings for, 14-5 main manumeded speeds for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 performance curves for, 14-18 power ends for, 14-5 performance curves for (chart), 14-5 performance curves for, 14-7 stuffing boxes for, 14-5 speeds for, 14-7 stuffing boxes for, 14-8 power ends for, 14-7 stuffing boxes for, 14-7 stuffing boxes for, 14-8 power ends for, 14-7 stuffing boxes for, 14-8 power ends for, 14-5 speeds for, 14-7 stuffing boxes for, 14-8 power ends for, 14-6 punction of the formation meter), 9-12 punction for, 16-19 proportional cunter for, 16-19 oSHA exposure standards for, 18-22 to refraction me			
double-screw, 14-12 efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 fuel-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 momenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 cranshands for, 14-5 cranshands for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 pumper fine protection, 18-26 fire protection, 18-26 fexible-member, 14-12 fuel-injection, for engines, 9-109, 9-111 gear, 14-11 low NPSHR in, 14-15 motors for, 15-44 nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 cranshands for, 14-5 main bearings for, 14-5 main bearings for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 performance curves for, 14-18 power ends for, 14-5 selection cunter for, 16-19 proper (deb), 8-193 PVC resins: properties of (table), 6-200 PV-T relations, 4-8 PVM (pulse width modulation), 15-79, 15-86 Pyramids, surface and volume of, 2-9 Pyramometer (solar-radiation meter), 9-12 Pyres glass, 6-142 pyred glass, 6-142 pyred glass, 6-142 pyred glass, 6-142 pyred glass, 6-142 quadrant, trigonometric, 2-15 Quadrant, trigonometric, 2-15 Quadratic equations, 2-3 Quadrati	* *		<i>C J</i> ,
efficiencies of, 14-13 for fire protection, 18-26 flexible-member, 14-12 fleub-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) literal-gear, 14-11 low NPSHR in, 14-15 heat (see Heat pumps) literal-gear, 14-11 low NPSHR in, 14-15 motors for, 15-44 nomenclature, 14-2, 14-15 motors for, 14-2 pasking for, 8-140 positive-displacement, 14-2 power (def), 14-2 canceleration head in, 14-6 brake horsepower of, 14-15 main bearings for, 14-5 main hearings for, 14-5 main hearings for, 14-5 main hearings for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 speeds for, 14-6 speeds for, 14-7 stuffing boxes for, 14-5 speeds for, 14-6 study in the properties of (table), 6-160 speeds for, 14-6 speeds for, 14-7 stuffing boxes for, 14-6 stopping for the properties of the properties of the prope			
for fire protection, 18-26 flexible-member, 14-12 fuel-injection, for engines, 9-109, 9-111 gear, 14-11 hand powered, 14-3 heat (see Heat pumps) high PNSHR in, 14-15 high-vacuum (see High-vacuum pumps) himmal-gear, 14-11 low NPSHA in, 14-15 motors for, 15-41 nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 piston, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-15 cranshafts for, 14-5 cranshafts for, 14-5 main bearings for, 14-5 main bearings for, 14-5 performance curves for (chart), 14-5 plungers for, 14-5 performance curves for (chart), 14-5 plungers for, 14-5 performance curves for (chart), 14-5 speeds for, 14-			
flexible-member, 14-12 prover (afe), 14-10 prover (afe), 14-2 prostring for, 14-12 power (afe), 14-2 prostring for, 14-13 connecting rods for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 plungers for, 14-5 speeds fo			
fuel-injection, for engines, 9-109, 9-111 gar, 14-11 hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) high NPSHR in, 14-15 how NPSHA in, 14-15 motors for, 15-41 low NPSHA in, 14-15 motors for, 15-42 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 manimum speeds for, 14-5 pumper for, 14-5 performance curves for (chart), 14-5 pulmers for, 14-5 performance curves for (chart), 14-5 pelmers for, 14-5 pulmers for, 14-5 pul			
gear, 14-11 hand powerd, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum year, 14-11 low NPSHA in, 14-15 motors for, 15-44 nomenclature, 14-2, 14-15 npiston, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-7 NPSH curves for, 14-7 NPSH curves for, 14-5 plungers for, 14-5 specds for, 14-6 specds for, 14-7 suffign boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure publication in duetor), 15-79, 12-14 spectra; 16-10, 16-13 radiation, 16-10, 16-13 Radio-frequency allocations (tables), 15-87 Radio-frequency bloats, 15-87 Radio-frequency allocations (tables), 15-87 Radio-frequency allocations (tables), 15-87 Radio-frequency allocations			
hand powered, 14-3 heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) high NPSHA in, 14-15 high-vacuum (see High-vacuum pumps) high NPSHA in, 14-15 high-vacuum (see High-vacuum pumps) high NPSHA in, 14-15 high-vacuum pumps) high NPSHA in, 14-16 high part in the pyrac plass, 61-12 high pyr			
heat (see Heat pumps) high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 metering, 14-3, 16-15 motors for, 14-2 packing for, 8-140 positive-displacement, 14-2 packing for, 8-140 positive-displacement, 14-5 brake horsepower of, 14-14 connecting rods for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main media efficiency of, 14-14 minimum speeds for, 14-7 NPSH curves for, 14-5 performance curves for (chart), 14-5 pungers for, 14-6 power ends for, 14-7 pecked end volume of, 2-9 pyramida, surface and volume of, 2-9 pyramida, surface and volume eter), 9-12 pyres glass, 6-142 pyre glass, 6-142 paccuracy of, 16-13 radiation meter), 9-12 radiation meter), 9-1			
high NPSHR in, 14-15 high-vacuum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 motrors for, 15-44 nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 power (def), 14-2 acceleration head in, 14-6 brack horsepower of, 14-14 connecting rods for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main meromended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for, 14-5 puguing from for, 14-6 Quartz, as abrasive, 6-129 Quenching mediums, selection of, 6-19 Quenching mediums, 14-7 Quick freezing, 19-24 Quick rereing, 19-12 principation meter), 9-12 principation			
high-vacuum (see High-vacuum pumps) internal-gear, 14-11 low NPSHA in, 14-15 metering, 14-3, 16-15 motors for, 15-44 nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 specds for, 14-5 specds for, 14-5 spection charts fo			
internal-gear, 14-11 low NPSHA in, 14-15 metering, 14-3, 16-15 motors for, 15-44 nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 power (def), 14-2 power (def), 14-2 power (def), 14-5 crankshafts for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main bearings for, 14-5 main mearing off, 14-7 NPSH curves for, 14-5 performance curves for (chart), 14-5 power soft, 14-15 powers for, 14-5 power nds for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 power nds for, 14-5 power nds for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 power nds for, 14-6 power nds for, 14-7 power nds for, 14-7 power nds for, 14-5 power nds for, 14-6 power nds for, 14-7 power nds for, 14-7 power nds for, 14-6 power nds for, 14-7 power nds for, 14-			
low NPSHA in, 14-15 metering, 14-3, 16-15 motors for, 15-44 nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 performance curves for (chart), 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14			from suspended solids, 4-71
motors for, 15-44 nomenclature, 14-2, 14-15 nomenclature, 14-2, 14-15 nomenclature, 14-2, 14-15 noptical, 16-10, 16-13 noptical, 16-10 noptical, 16-10, 16-13 noptical, 16-10, 16-13 nodical requency bands, 15-87 nodical requency bands, 15-87 nodical requency bands, 15-87 nodical requency bands, 15-87 nodical requency bands or cevers, 16-19 nodical reactions, 2-3 noptical, 16-10, 16-13 nodical reactions, 2-3 noptical, 16-10, 16-13 nodical reactions, 2-3 noptical, 16-10, 16-13 nodical reactions, 2-3 noptical, 16-10 noptical, 16-10 noptical, 16-10 noptical, 16-10 noptical	low NPSHA in, 14 -15	Pyrheliometer (solar-radiation meter), 9-12	
nomenclature, 14-2, 14-15 NPSH for, 14-2 piston, 14-2 packing for, 8-140 positive-displacement, 14-2, 2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 cranshafts for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 power ofs, 14-5 power ends for, 14-7 NPSH course for, 14-5 power ends for, 14-7 speeds for, 14-6 power for, 14-7 power for, 14-7 power ends for, 14-7 power ends for, 14-7 power ends for, 14-5 power ends for, 14-5 power ends for, 14-7 speeds for, 14-6 power ends for, 14-7 power ends for, 14-8 power ends for, 14-7 power ends for, 14-7 power ends for, 14-8 power ends for, 14-7 power ends for, 14-7 power ends for, 14-8 power ends for, 14-9 power ends for, 14-9 power ends for, 14-10 p	metering, 14 -3, 16 -15	Pyrometers:	Radio batteries, 15-11
NPSH for, 14-2 piston, 14-2 piston, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 plungers for, 14-5 plungers for, 14-5 power ends for, 14-5 speeds for, 14-6 speeds for, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Packing for, 8-140 Quadrant, trigonometric, 2-15 Radio transmitters, 15-87 Radio active tracers, 16-19 Radioactive tracers, 16-19 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactive tracers, 16-19 Radioactive transformation (chemistry), 6-5 Radioactive tracers, 16-19 Radioactive tra	motors for, 15-44	accuracy of, 16-13	Radio-frequency allocations (tables), 15-87
piston, 14-2 packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 main bearings for, 14-5 main bearings for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for (chart), 14-5 power ends for, 14-5 po	nomenclature, 14 -2, 14 -15	optical, 16 -10, 16 -13	Radio-frequency bands, 15-87
packing for, 8-140 positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 plungers for, 14-5 plungers for, 14-5 plungers for, 14-5 plungers for, 14-5 speeds for, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 power ends for, 14-7 suffing boxes for, 14-8 pressure pulsations in, 14-7, 14-14 power ends for, 14-7 vertical, 14-3 power ends for, 14-7 power ends for, 14-7 vertical, 14-3 power ends for, 14-7 vertical, 14-3 power ends for, 14-7 power ends for, 14-7 vertical, 14-3 power ends for, 14-7 power ends for, 14-8 power ends for, 14-9 quick freezing, 19-24		radiation, 16 -10, 16 -13	
positive-displacement, 14-2 power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crossheads for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for (chart), 14-5 performance curves for, 14-5 pulmagers for, 14-5 performance curves for (chart), 14-5 performance curves for, 14-5 power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Radio transmitters, 15-87 Radioactive tracers, 16-19 Radioactive traces, 16-19 Radioactive traces, 16-19 Radioactive tracers, 16-19 Radioactive traces, 16-19 Radioactive traces, 16-19			
power (def), 14-2 acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for, 14-5 plungers for, 14-5 power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-7 stuffing boxes for, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quadrant, trigonometric, 2-15 Quadratic equations, 2-3 Radioactive tracers, 16-19 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactive tracers, 16-19 Radioactive traces, 16-19 Radioactive tracers, 16-19 Radioactive tracers, 16-19 Radioactive traces, 16-19 Radioscotpes, 16-19 Radiosc			
acceleration head in, 14-6 brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 crankshafts for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for (chart), 14-5 plungers for, 14-5 selection charts for, 14-5 speeds for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-7 stuffing boxes for, 14-8 tornecting rods for, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 acceleration head in, 14-6 Quadrature current (def), 15-18 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactive transformation (chemistry), 6-5 Radioactivity, 9-53, 9-134, 9-142 Radioactivity, 9-53, 9-144 Radioactivity, 9-53, 9-144 Radioactivity, 9-53, 9-144 Radioactivity		0.1	·
brake horsepower of, 14-14 connecting rods for, 14-5 crankshafts for, 14-5 crankshafts for, 14-5 crossheads for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for, 14-5 power ends for, 14-5 power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6 statistical, 17-19, 17-24 mover for, 14-8 power ends for, 14-5 puncting for, 14-5 speeds for, 14-7 stuffing boxes for, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 divided for formance curves (def), 15-18 Quadritare current (def), 15-18 Quadritare current (def), 15-18 Quadritare and of, 2-7 Radioiostopes, 16-19 rable, 9-148 Radiostorivity, 9-53, 9-134, 9-142 Radioiostopes, 16-19 rable, 9-148 Radiostric, 19 rable, 9-148 Radiostric, 19 rable, 9-148 Radiostopes, 16-19 rable, 9-148 Radiostric, 19 rable, 9-148 Radiostorie, 19 rable, 9-148 Radiostric, 19 rable, 9-148 Radiostorie, 19 rable, 9-148 Radiostric, 19 rable, 9-148 Radiostric, 19 rable, 9-148 Radiostore, 16 rable, 9-148 Radiostore, 19 rable, 9-148 Radiostric, 19 rable, 19 rable, 9-148 Radiostore, 19 rable, 19 rable, 9-148 Radiostric, 19 rable, 19 rabl		· · · · · · · · · · · · · · · · · · ·	
connecting rods for, 14-5 crankshafts for, 14-5 crossheads for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for, 14-5 plungers for, 14-8 power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-6 statistical, 17-19, 17-24 Quart (unit of volume, def), 1-16 Quartz, as abrasive, 6-129 fused, 6-143 Quenching, of steels, 6-17, 6-20 Quenching mediums, selection of, 6-19 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quart quilt deral, area of, 2-7 Quality circles, 17-11 table, 9-148 Radioisotopes, 16-19 table, 9-148 Radioistopes, 16-19 table, 9-148 Radioistopes, 16-19 table, 9-148 Radioistopes for for curvature, 2-26 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 5-27 of two angles (ables), 5-27 of two angles (ables			
crankshafts for, 14-5 crossheads for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for, 14-5 plungers for, 14-5 power ends for, 14-5 speeds for, 14-6 statistical, 17-19, 17-24 minimum speeds for, 14-5 pungers for, 14-5 power ends for, 14-5 speeds for, 14-6 speeds for, 14-7 speeds for, 14-8 table, 9-148 Radius: of curvature, 2-26 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 Railing fittings, 8-205 Railing fittings, 8-205 Railing fittings, 8-205 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quality circles, 17-11 Quality control, 17-6 Radius: of curvature, 2-26 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 Radius: of curvature, 2-26 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 Pacilom (def), 3-8 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 presure pulsations in, 14-7 Quartr, as abrasive, 6-129 Quartz, as abrasive, 6-129 Quenching, of steels, 6-17, 6-20 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 clearance, 11-38 curves in, 11-38 engines (see Locomotives)			
crossheads for, 14-5 main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 purgers for, 14-8 power ends for, 14-5 speeds for, 14-5 speeds for, 14-7 speeds for, 14-7 speeds for, 14-8 torque characteristics of, 14-7 svertical, 14-3 pressure pulsations in, 14-7, 14-14 Radius: of curvature, 2-26 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 Railins; of curvature, 2-26			
main bearings for, 14-5 maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-5 performance curves for, 14-5 power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 spressure pulsations in, 14-7, 14-14 maximum recommended speeds for, statistical, 17-19, 17-24 statistical, 17-19, 17-24 of curvature, 2-26 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 Railing fittings, 8-205 Rails, friction on, 3-22 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 clearance, 11-38 engines (see Locomotives)			
maximum recommended speeds for, 14-7 mechanical efficiency of, 14-14 minimum speeds for, 14-7 NPSH curves for, 14-5 performance curves for (chart), 14-5 plungers for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 minimum recommended speeds for, 14-1 Quantum field theory, 9-134 Quarty machines, 10-33 Quarty machines, 10-33 Quarty machines, 10-33 Quart (unit of volume, def), 1-16 Quarter-phase a-c circuit, 15-20 Quartz, as abrasive, 6-129 fused, 6-143 Quenching, of steels, 6-17, 6-20 Quenching mediums, selection of, 6-19 Quick freezing, 19-24 Quick-return motion, Whitworth, 8-3 Quicklime, 6-160 Quiet rooms, 12-119 of gyration (def), 3-8 for beam sections (tables), 5-27 of two angles (tables), 12-41, 12-42 of inertia (def), 3-8 of railway curves, 11-38 Raills, friction on, 3-22 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 clearance, 11-38 curves in, 11-38 engines (see Locomotives)			
mechanical efficiency of, 14-14 Quarty machines, 10-33 of two angles (tables), 5-27 mechanical efficiency of, 14-14 Quarty machines, 10-33 of two angles (tables), 12-41, 12-42 minimum speeds for, 14-7 Quart (unit of volume, def), 1-16 of inertia (def), 3-8 NPSH curves for, 14-5 Quarter-phase a-c circuit, 15-20 of railway curves, 11-38 performance curves for (chart), 14-5 Quartz, as abrasive, 6-129 Railing fittings, 8-205 plungers for, 14-8 Quenching, of steels, 6-17, 6-20 Railway engineering: selection charts for, 14-5 Quenching mediums, selection of, 6-19 speeds for, 14-6, 14-7 Queuing theory, 17-9 car wheels and axles, 11-31 stuffing boxes for, 14-8 Quick freezing, 19-24 cars, air resistance of, 11-39 vertical, 14-3 Quicklime, 6-160 quiet rooms, 12-119 engineer (see Locomotives)			
mechanical efficiency of, 14-14 minimum speeds for, 14-7 NPSH curves for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quarty machines, 10-33 Quart (unit of volume, def), 1-16 Quart (unit of volume, def), 1-20 Railing fittings, 8-205 Railing fi			
minimum speeds for, 14-7 NPSH curves for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 speeds for, 14-5 speeds for, 14-7 speeds for, 14-7 speeds for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 minimum speeds for, 14-7 Quart (unit of volume, def), 1-16 Quartz, as abrasive, 6-129 Quartz, as abrasive, 6-129 Railing fittings, 8-205 R			
NPSH curves for, 14-5 performance curves for (chart), 14-5 plungers for, 14-8 power ends for, 14-5 selection charts for, 14-5 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quict re-phase a-c circuit, 15-20 Quartz, as abrasive, 6-129 fused, 6-129 fused, 6-13 Quenching, of steels, 6-17, 6-20 Quenching, of steels, 6-17, 6-20 Railkay curves, 11-38 Railing fittings, 8-205 Rails, friction on, 3-22 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 clearance, 11-38 curves in, 11-38 engines (see Locomotives)			of inertia (def), 3-8
plungers for, 14-8 power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 pluse fused, 6-143 fused, 6-143 Rails, friction on, 3-22 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 clearance, 11-38 curves in, 11-38 engines (see Locomotives)		Quarter-phase a-c circuit, 15-20	of railway curves, 11-38
power ends for, 14-5 selection charts for, 14-5 speeds for, 14-6, 14-7 stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quenching, of steels, 6-17, 6-20 Railway engineering: braking, 11-32, 11-35, 11-37 car wheels and axles, 11-31 cars, air resistance of, 11-39 clearance, 11-38 curves in, 11-38 engines (see Locomotives)		Quartz, as abrasive, 6-129	
selection charts for, 14-5 speeds for, 14-6, 14-7 suffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quick freezing, 19-24 Quick freezing, 19-24 Quick-return motion, Whitworth, 8-3 Quicklime, 6-160 Quick freezing, 19-24 Quick-return motion, Whitworth, 8-3 Quicklime, 6-160 Quick freezing, 19-24 Cars, air resistance of, 11-39 Clearance, 11-38 Curves in, 11-38 engines (see Locomotives)			Rails, friction on, 3-22
speeds for, 14-6, 14-7 Queuing theory, 17-9 car wheels and axles, 11-31 stuffing boxes for, 14-8 Quick freezing, 19-24 cars, air resistance of, 11-39 torque characteristics of, 14-7 Quick-return motion, Whitworth, 8-3 vertical, 14-3 Quicklime, 6-160 curves in, 11-38 pressure pulsations in, 14-7, 14-14 Quiet rooms, 12-119 engines (see Locomotives)			
stuffing boxes for, 14-8 torque characteristics of, 14-7 vertical, 14-3 pressure pulsations in, 14-7, 14-14 Quick freezing, 19-24 Quick freezing, 19-24 Quick-return motion, Whitworth, 8-3 Quicklime, 6-160 Quiet rooms, 12-119 cars, air resistance of, 11-39 clearance, 11-38 curves in, 11-38 engines (see Locomotives)			
torque characteristics of, 14-7 Quick-return motion, Whitworth, 8-3 clearance, 11-38 vertical, 14-3 Quicklime, 6-160 curves in, 11-38 pressure pulsations in, 14-7, 14-14 Quiet rooms, 12-119 engines (see Locomotives)			
vertical, 14-3 Quicklime, 6-160 curves in, 11-38 pressure pulsations in, 14-7, 14-14 Quiet rooms, 12-119 engines (see Locomotives)			
pressure pulsations in, 14-7, 14-14 Quiet rooms, 12-119 engines (see Locomotives)			
proportioning, 14-10 Quieting (noise control), 12-120 Ireignt cars, 11-27			
	proportioning, 14-10	Quieting (noise control), 12-120	freight cars, 11-27

Railway engineering (Cont.):	Reactors (Cont.):	Refractories (Cont.):
passenger cars, 11-33	heat from, 4-20	heat radiation from, 4-66, 4-72
rails, 11 -37	materials for, 9-138	high-purity, properties of (table), 6 -156
starting resistance, 11-39	for control, 9-138	insulating, 6 -151
track, 11-37	damage to, 9-138	metal, properties of (table), 6 -81
gage, 11-37	fertile, 9-138	mortars for, 6-153
spacing, 11-38	fissionable, 9-138	physical properties of (tables), 6 -153, 6 -156
train resistance, 11-38	fuel, 9 -138	plastics and ramming mixtures for, 6 -154
curve and grade, 11-39	fuel diluents, 9-138	pure-oxide, 6-154
inherent, 11-38, 11-39 Pake of cutting tools 13 46 13 52	metals, 9-138	for space vehicles, 6-155
Rake of cutting tools, 13-46, 13-52 RAM (random-access memory), 15-83	moderating, 9 -138 properties of (table), 6 -84, 9 -139	specific heats of (tables), 6 -153 surface temperatures of, in combustion
Ramie fiber (table), 6 -141	neutron-level instruments for, 9-142	chambers, 4 -78
Ramjet engines, 11-82	power, 9 -136	types of, 6 -151
Ramps, for industrial plants, 12 -15	boiling-water, 9-136	Refrigerant 11:
Ramsbottom coking test for lubricating oils,	fast-breeder, 9-136	enthalpy-pressure diagram for (chart), 4 -38
6 -179	gas-cooled, 9-135, 9-136	properties of (table), 4-38, 4-51, 4-56
Random-load testing, 5-10	liquid-metal cooled, 9-136	Refrigerant 12:
Random variable (def), 2 -10	pressurized-water, 9-136	enthalpy-pressure diagram for (chart), 4 -39
Range (algebra, def), 2 -3	types of, 9 -136	properties of (table), 4 -39, 4 -51, 4 -56
Rank, of a matrix (def), 2 -14	power cycles for, 9-135	Refrigerant 13: properties of (table), 4 -51, 4 -56
Rank test (statistics), 17-22	power generators, isotopic, 9-148	Refrigerant 21: properties of (table), 4 -51, 4 -56
Rankine absolute temperature scale, 4 -2	research, 9-135	Refrigerant 22:
conversion to Fahrenheit degrees (eq), 4-2	safety of, 9 -146	enthalpy-pressure diagram for (chart), 4 -40
Rankine cycle, efficiencies, 4 -19	test, 9-135	properties of (table), 4 -40, 4 -51, 4 -56
in nuclear reactors, 9-135	Read-only memory (computers), 2-40	Refrigerant 32: properties of (table), 4 -41
Rankine formula, for retaining walls, 12-27	Real numbers (def), 2-3	Refrigerant 123:
Rateau formula, for steam flow, 4-21, 4-22	Reamers, 13-56	enthalpy-pressure diagram for (chart), 4-42
Rating, of electrical apparatus, 15-43	Reaming, of plastics, 13-65	properties of (table), 4 -41
Rational numbers (def), 2-3	Rear axles, automobiles, 11-10	Refrigerant 134a:
Rayleigh-Ritz method (vibrations), 3-76, 3-77	Reciprocating pumps, 14-2	enthalpy-pressure diagram for (chart), 4-43
Rayleigh's energy method (vibrations), 3-75	applications of, 14 -3	properties of (table), 4 -42
Rayleigh's method (dimensional analysis), 3-44	liquid end components for, 14-4	Refrigerant 143a, properties of (table), 4-43
Rayleigh's quotient (vibrations), 3-75, 3-76	motors for, 15-44	Refrigerant 152a:
Raymond concrete piles, 12 -26	packing for, 8-140	enthalpy-pressure diagram for (chart), 4 -45
Rayon fibers (table), 6 -141	plunger loads in, 14 -7	properties of (table), 4 -44, 4 -51
RCRA (Resource Conservation and Recovery	pressure pulsations in, 14 -7, 14 -14	Refrigerants, 19-2
Act), 18 -18	problems to avoid, 14-4	ammonia, properties of (table, chart), 4-33,
RDF (refuse-derived fuel), 7-10	pumping cycle in, 14 -5	4-34
RDX (military explosive), 7-22	quintuplex, 14 -4, 14 -6	fluorocarbon, properties of (table), 4 -51
table, 7 -21	slip of, 14 -13	ideal performance of (table), 19 -4
Reactance:	for slurries, 14-4	standard temperature range, 19-3
capacitive (def), 15 -3, 15 -18, 15 -19	stuffing boxes for, 14-4	identifying number, 19-2
inductive (def), 15 -3, 15 -18, 15 -19	triplex, 14-4, 14-6	pressure-temperature relations of (chart), 19 -12
table, 15-48, 15-52	uses of, 14-3	properties of (tables), 4-33, 4-35 to 4-44, 4-51,
Reaction turbines, hydraulic, 9-151	valves for, 14-4	19-3 to 19-7 (See also Ammonia)
Reactive current (def), 15 -18 Reactive power (a-c circuit, def), 15 -2	Rectangles, area of, 2 -7 Rectifiers:	Refrigerating machines:
Reactors:	electric, 15 -41, 15 -68	absorption, 19 -17
controls for, 9-141	circuits for (chart), 15 -72	processes in, 19 -17
coolants for, 9-138	full-wave, 15 -71, 16 -16	Servel process, 19-17
gas, 9 -140	half-wave, 15 -71	ammonia volume per ton of refrigeration
liquid metals, 9 -140	ignitron, 15 -71	(table), 19 -15
properties of (table), 9-140	Recuperators, for industrial furnaces, 7-44	coefficient of performance of, 4 -18, 19 -2
design of: breeding ratio, 9-141	Recycling, of paper, 6 -145	cold-air, 19 -17
control, 9 -141	Red lead (paint), 6 -110	compression in, 19 -14, 19 -15
of criticality, 9-142	Redler continuous-flow conveyor, 10-41	condensers for, 19-14
coolant temperatures for, 9-141	Reduced values (thermodynamics), 4-8	controls for, 19-15
coolant velocity, 9-141	Reduction of area, in tensile test, 5-2	horsepower per ton of refrigeration (ammonia,
cross sections, 9-140	Referencing a point (surveying), 16-57	table), 19 -15
for thermal neutrons (table), 9-141	Reflectance of heat, 4-63	household, 19-16
diffusion theory, 9-141	Reflection of light (def), 12-99	lubrication of, 6-184
gamma-ray attenuation, 9-142	Reflective heat insulation, 6-151	oil for, 6 -184
high power density, 9-142	Reformatted gasoline, 9-104	rating of (def), 19-2
hot-spot and hot-channel factors,	Refraction (optics), 19-41	unit of capacity of (def), 19-2
9 -141	Refractories:	Refrigerating plants:
instrumentation, 9-142	for arc furnaces, 7 -55	brines for, 19 -18
irradiation effects, 9-142	brick shapes and sizes, 6 -152	piping of cooling and storage rooms, 19-23
mechanical, 9-141	castable, 6-154	skating rinks, 19-25
multiplication factor, 9-140	coatings for, 6-154	Refrigeration, 4 -19, 19 -2
neutron attenuation, 9-142	composition of (table), 6 -152	absorption system of, 4-18
neutron balance, 9-140	fiber, 6-155	brine systems for, 19 -18
shielding, 9-142	furnace: heat radiation from (chart), 7-43	cascade system, 19-16
sources of heat, 9-141	selection of, 6-154	in the chemical industry, 19 -25
thermal, 9 -141 thermal design criteria, 9 -141	heat losses and heat-storage capacities of (table), 6-155	cold-storage, 19-21 compound low-temperature, 19-15
mermar design emeria, 7-141	(table), 0 -155	compound fow-temperature, 13-13

Refrigeration (Cont.):	Reinforced concrete (Cont.):	Rheostats:
in cryogenics, 19-27	T beams, 12 -56	materials for, 15-61
engines for, 19-27	two-way slabs, 12-56	table, 15 -61
cycles for, 19-12	walls of, 12 -59	Rhodium, uses of, 6-74
vapor-compression, 19-15	Relative density:	Rhombus, area of, 2-7
deep, 19 -25	of liquids: conversion tables for: API,	Ribbon, area of, 2-8
direct-expansion system of, 19-18	1-26	Riccati equation, 2 -32, 16 -44
expansion engines for, 19 -27	Baumé, 1 -27	Right-hand rule:
gas intercoolers for, 19-15	Relative humidity, 4 -15, 12 -87	for conductor current, 15 -11
for ice making, 19-25	Relative permeability (def), 15 -4, 15 -8	for generators, 15 -11
leak detection in, 19-7	Relative permittivity (def), 15-2	Rigid bodies:
low-temperature boosters for, 19 -16	Relative roughness (fluid flow), 3-47	dynamics of, 3-13
multiple-effect, compression in, 19 -14	Relativistic mass, 9-134	forces supporting, 3-4 to 3-6
power required for, 4-18	formula for, 9-134	instantaneous axis of, 3-13
processes for, 19-2	Relaxation test of metals (def), 5-10 Relief engles for outting tools 13 46 13 52	statics of, 3 -3 to 3 -6
quantity of fluid circulated, 4 -18 quick freezing (cold storage), 19 -24	Relief angles for cutting tools, 13 -46, 13 -52 Reluctance, magnetic (def), 15 -4	Rigidity: coefficient of (def), 5 -17
unit of (def), 19-2	Reluctivity (def), 15-4	modulus of, for metals (table), 5-4
vapor-compression circuits for, 19 -15	Remanence (magnetic hysteresis, def),	Ringelman chart, 18 -15
vapor-compression machines for (theory), 4 -18	15-10	Rings, strength of, 5 -46
water-vapor, 19 -16	Replacement of equipment, 17 -7	Rise time (automatic control, def), 16 -22
Refuse Act of 1899, 11 -47	Reports, annual, 17 -12	Risk, effect on decision making, 17 -7
Regenerative braking (def), 10 -10	Residuals, tables of, 1 -14	Riveted joints:
Regenerative cycles:	Resilience (def), 5-17	design of, 12 -35, 12 -43
for feedwater heating, 4 -19	of beams, 5 -32	punched vs. drilled plates, 8-29
for turbines, 4 -19, 9 -71	of beams and springs (table), 5-17	Riveters, 13-24
Regenerators:	modulus of (def), 5-17	Rivets:
for industrial heating furnaces, 7-44	ultimate, 5-17	aluminum, properties of (table), 6-60
tile sizes for, 6 -152	Resin-type adhesives (table), 6-131	blind, 8 -30
Register ton (def), 1-16	Resinoid grinding wheels, 6-129	conventional signs for (fig), 8-30
Registration: of engineers, 18 -31	Resins, in varnishes, 6 -108	forms and proportions of, 8-27, 8-30
Reheaters, 9-41	Resistance:	lengths and grips of (fig), 8-30
Reheating cycle for steam turbines, 4 -19, 9 -71	effective (electric circuits, def), 15 -19	pop, 8 -30
Reid vapor pressure (fuels), 9-104	electrical, 15-2	for steel-framed structures, 12 -35, 12 -43
Reinforced concrete:	of conductors: measurement of, 15 -24	tubular, 8 -29
beams of, 12 -52	specific (table), 15-4	Roads:
shear forces in, 12-54	of copper lay cables (table), 15-6	friction on, 3-24
bearing plates for, 12-58	of copper wire (tables), 15 -5, 15 -6, 15 -48,	rolling resistance on, 11-3
bearing walls of, 12-59	15-52, 15-56 of insulating materials (table) 15-16	Robots, 10 -56
columns of, 12-55	of insulating materials (table), 15 -16	accuracy of, 10-60
footings for, 12-58	of materials (table), 15 -61	anatomy of, 10 -57 articulations for, 10 -58
spiral reinforcement in, 12 -56 concrete for, 12 -50	of parallel circuits, equivalent, 15 -8 temperature coefficient of (table), 15 -4	configurations of, 10 -58
contraction and expansion joints for, 12 -60	unit of (def), 15-2	motion control of, 10 -50
dead load of, 12-51	welding by (see Welding, resistance)	payloads of, 10 -60
definition of, 12-49	of resistor alloys (table), 15 -61	programming of, 10 -61
dowels for, 12 -58	of ships, 11 -45	repeatability of, 10 -60
floor systems of, 12 -56	traction, of automobiles, 11-3, 11-5	resolution of, 10 -60
footings of, 12-58	of trains, 11-38	size of, 10 -58
for columns, 12-58	Resistance brazing, 13-29	specifications for, 10-58
combined, 12-58	Resistance furnaces (see Electric furnaces, resis-	speeds of, 10 -60
forms for, 12 -60	tance)	teach-pendants for, 10-61
design of, 12 -60	Resistance strain gages, 5-53	teaching of, 10-61
liners for, 12 -61	Resistance welding (see Welding, resistance)	using, 10 -62
removal of, 12-61	Resistivity (def), 15 -2, 15 -4	work cells for, 10-57
inspection of, 12-61	tables, 6 -50, 15 -4	work envelopes for, 10 -60
joints in, 12 -60	Resistor furnaces, 7-52	workspace of, 10-60
construction of, 12-60	Resistor materials, 15 -61	Robustness (automatic control, def), 16 -40
joist floors of, 12-56	table, 15 -61	Rock, pipelines for, 11 -131
live loads on, 12 -51 load factors for, 12 -51	Resistor ovens, 7 -54 Resistors for electric furnaces, 7 -53, 15 -61	Rocker (mechanism), 8-3 Rocket engines, 11-85
loads on, 12 -50	Resonance:	ablative cooling for, 11-85
moduli of elasticity for, 12 -50	in electric circuits, 15 -19	bipropellant, 11 -119
old, evaluation of, 12 -61	in vibration, 3 -64	chemical, 11 -85, 11 -119
partitions of, 12-59	Resonant cavities (electronics), 15 -73	combustion temperatures in, 11 -85
pipe of, 8 -193	Respirators, use of, in hazardous occupations,	electric, 11-86
precast units, 12 -60	18- 22	electromagnetic, 11 -87
prestressed, 12 -50, 12 -59	Respiratory protection, 18 -22	electrostatic, 11-87
allowable stresses in, 12-59	Response time (automatic control, def), 16 -22	electrothermal, 11-87
protection of reinforcement in, 12-50	Restitution, coefficient of (def), 3-19	fuels for (see Rocket fuels)
reinforcing steel for, 12 -50	Retaining walls, design of, 12-27, 12-59	liquid-bipropellant, 11-85
dimensions of (table), 12-50	Return on capital (accounting), 17-18	liquid-propellant, 11 -119
retaining walls of, 12-59	Reynolds number, 3-42, 3-43, 3-46 to 3-50,	mercury ion, 11-87
slabs of, 12 -56	11-45, 11-63, 11-65	mixture ratios in, 11-85
steel for, 12 -50	chart for, 3-48	monopropellant, 11 -119
sizes of, 12 -50	RFG (reformulated gasoline), 9-104	nuclear, 11 -119

Rocket engines (<i>Cont.</i>): nuclear heat-transfer, 11 -86	Roofs (<i>Cont.</i>): live loads on, 12 -18	Rubble masonry (table), 12 -28 Ruben cell, 15 -12
regenerative cooling for, 11-85	masonry, coefficients of heat transmission	Runge-Kutta methods, for differential equation
solar heating, 11-119	(table), 12 -71	solutions, 2 -39
solid fuels for, 11 -94 solid propellant, 11 -85, 11 -94, 11 -119	trusses (see Trusses) ventilation fans for, 14 -45	Rupture: modulus of (def), 5-26
thermal arc-jet, 11 -87	wind pressure on, 12 -19, 12 -21	unit work, 5-17
Rocket fuels:	Room sensible heat factor (def), 12 -87	Rzeppa universal joints, 8 -36
alcohol, 7 -29	Root locus method (automatic control), 16-27	•
ammonia, 7 -29	Root-mean-square value of a-c wave, 15 -18	
bipropellant, 7-29	Roots, arithmetical, 2-3	C. M. dia amount (factions and lands) 5 0
burning rates of, 11 -94 cartridge-loaded, 7 -29	Roots blowers, 9 -106, 14 -40, 14 -43 Rope, 6 -137	S-N diagram (fatigue analysis), 5-8 SAE viscosity grades, for crankcase oils (table),
case-bonded, 7-29	braided, 6 -138	6 -182
combustion instability in, 7-30	breaking strength of (table), 8-81	Safety, 18-19
composite, 7 -29, 11 -85, 11 -94	friction of, 3 -29	corrosion effects on, 6 -95
cost of, 7-28	for haulage, 10 -8 for hoist drums, 10 -8	in cryogenics, 19 -40
design criteria for, 7 -28 diergolic (def), 11 -85	knots, hitches, and bends for, 8 -81	of grinding wheels, 13 -63 Safety codes, 18 -22
double-base, 7 -29	lay of (def), 6 -137	Safety devices for machines, 18 -20
double-base powder, 11-85, 11-94	manila, U.S. specification (table), 6-138	Safety factor (def), 5-20
heterogeneous, 11-85, 11-94	materials for, breaking strength of (table), 8-81	Safety glass, 6-142
hydrazine, 7 -29	for mine hoists, 10 -17	Sagging (ships, def), 11-43
hydrogen peroxide, 7 -29 hypergolic (def), 7 -29, 11 -85	nylon, 6 -137, 6 -140 polyester, 6 -137, 6 -140	Salinometers, 19 -18 Salometers, 19 -18
liquid, 7 -28, 11 -85	sheaves for, 10 -10	Salt, common, as freezing preventive, 6 -141
liquid hydrogen, 7 -29	wire, 10 -8	Salts, inorganic, solubility of (table), 6 -5
liquid oxygen, 7 -29	Rotameter (for fluids), 16-14	Sampling (statistics), 17 -19, 17 -24
monopropellants, 7-29	Rotary blowers, 14 -44	Sand:
nozzle erosion by, 7-30	Rotary car dumps:	for cement (table), 6 -161
pressure and thrust control of, 7 -30 safety requirements for, 7 -28	gravity, 10 -22 power, 10 -22	for concrete, 6 -161 for cores, 13 -6
service life of, 7 -28	Rotary cranes, 10-27	binders for, 13-6
smokiness of, 7-28	Rotary pumps, 14-11	for mold making, 13-5
solid, 7 -28, 11 -85, 11 -94	Rotary shafts (see Shafts)	additives for, 13-6
case-bonded, 11-85	Rotating machines, balancing of, 3-15, 3-65, 3-66	bonded, 13-6
UDMH, 7-29 Rocket motors (<i>see</i> Rocket engines)	Rotation: of solid bodies about axes, 3-15, 3-16, 3-19	grain size of, 13-6 properties of, 13-6
Rocket nozzles, 11-75	Rotation moments of a couple, 3 -3	molding, 13-3
Rockets, nuclear, 11-119	Rotoclones, for gas cleaning, 18-10	specific gravity and density of (table), 6-8
space vehicle applications of, 11 -119	Rouge (abrasive), 6-129	Sand blasting, 13-64
specific impulse of, 11 -120 Rockwell hardness test, 5 -12, 16 -18	Roughness (metal surfaces, def), 13 -69 (<i>see</i> Surface texture)	Sand casting, 13-2 Sand castings, making of, 13-3
Rod (unit of length, def), 1 -16	Roughness factors for open channels, 3 -59	Sand-lime brick, 6 -135
Rods, vibration of, 3-72	table, 3 -59	Sand slingers (molding machines), 13-5
Roll (ships, def), 11 -45	Routh's stability criterion (automatic control),	Sanders, wood, 13-75
Roll-pins, 8-33	16-38	Sandstone, composition of, 6 -143
Roller bearings (see Bearings, roller) Roller chains (see Chains, roller)	Rubber and rubberlike materials: balata, 6 -148	Saran (fiber), 6 -140 SASOL (coal conversion process), 7 -19
Roller conveyors, 10-52	Buna S, 6 -147	Saturated ammonia, properties of (table), 4 -33
Rolling:	butyl, 6 -147	Saturated carbon dioxide, properties of (table),
cold, 13 -14	chlorinated, 6-148	4-35
contour, 13 -14	cyclized, 6-148	Saturated steam:
of foil, 13 -14 hot, 13 -14	derivatives, 6 -148 elastomers (def), 6 -146	properties of (table), 4 -44 vapor (def), 4 -13
operations, 13 -11	comparative properties of (table), 6 -148	Saturation of air, in spray chambers, 4 -17
oscillating, 13-14	uses of, 6 -147	Saturn, planetary data for (tables), 11-102, 11-103
segmented, 13-14	GR-S, 6 -147	Savonius rotors, 9-7
shape, 13-14	gutta-percha, 6 -148	Sawing, of plastics, 13-65
in tube-reducing mills, 13 -14 Rolling friction, 3 -25	latex, 6 -148 natural, 6 -147	Saws: metal-cutting, 13 -61
Rolling loads on beams, 5 -32	neoprene, 6 -147	wood, 13 -72
Rolling motion, 3-16	nitrile, 6 -147	classification of, 13 -72
Rolling-piston compressors, 14 -34	pigments in, 6 -147	gullet-feed index for, 13-73
Rolling surface (mechanism), 8-7	polysulfide, 6 -147	materials, 13 -73
ROM (read-only memory), 15 -83 Roofing:	polyurethane, 6 -147 properties of, 6 -147	power required for, 13 -73 table, 13 -74
asphalt, 6 -145	on roads, friction of, 3 -24	teeth for, 13 -73
elastomers for, 6 -146	silicone, 6 -139, 6 -151	set of, 13 -73
materials for, 6-145	specific gravity and density of (table), 6-7	spring-setting of, 13-73
metallic, 6 -146	Thiokol, 6-148	swage-setting of, 13-73
Roofing cement, 6 -146 Roofs:	vulcanization of, effect of, 6 -147 Rubber belts (<i>see</i> V-belts)	Saybolt Furol viscometer, 3 -33 Saybolt Universal viscometer, 3 -33
flashings for, 12 -15	Rubber bonding of grinding wheels, 6 -129	Scale deposits, heat-transfer coefficients (table),
heat gain through (table), 12 -74	Rubber-die forming, 13 -18	4- 85
for industrial plants, 12-15	Rubber hydrochloride, 6-148	Scale effect (aerodynamics), 11-63

Scales, 16-3	Screw threads (Cont.):	Sectors:
automatic, 16-4	pipe, American National Standard, 8-18	of circle: area of, 2-7
batch-type, 16-4	pitch diameter of (def), 8-9	center of gravity of, 3-7
continuous, 16-4	for power transmission, 8 -16	of sphere: center of gravity of, 3-7
spring, 16 -4	square, friction of, 3 -26	volume and area of, 2 -9
	stub, 8 -16	Seebeck effect, 9-24, 15-21
Scanning (television), 15 -89		
Scarfing, of steel, 6-15	tap drill sizes for (table), 8 -30	SEER (seasonal energy efficiency ratio, def),
Scavenging two-cycle engines, 9-107	tolerance classes for, 8 -9	19-2
Scheduling:	UN and UNR (table), 8-10	Seger cones, 16-10
using CPM (critical path method), 12-18, 17-5	UNC and UNRC (table), 8-12	Segments:
flow of materials, 17-6	UNEF and UNREF (table), 8-13	of circle, 2-8
using PERT, 17-5	UNF and UNRF (table), 8-13	center of gravity of, 3-7
production, 17-4	Unified thread standards for, 8 -8	of sphere, 2-9
Schiele's antifriction curve (tractrix), 2 -23	Screws, 8-8	1 '
	· · · · · · · · · · · · · · · · · · ·	center of gravity of, 3-7
Schlieren optical system (compressible-flow	cap (table), 8 -22	Seismic forces, 12-51
visualization), 11 -81	coach (table), 8-24	Seismometers, 3-78
Schmitt trigger (electronics), 15 -79	graphical markings for, ASTM (table), 8-28	Self-guided vehicles, 10-56
Scleroscope hardness test, 5-13	SAE (table), 8 -28	Self-inductance (def), 15 -2, 15 -16
Scott tap (transformers), 15-36	lag: holding power of, 12 -32	coefficient of (def), 15-2
SCR (silicon controlled rectifier), 15 -41	table, 8 -24	Self-induction, emf of, 15 -16
Scramjets, 11-82	machine (see Machine screws)	Self-tapping screws (table), 8-26
Scraper conveyors, 10-40	self-tapping, 8 -21	Selsyns, 15 -42
Scrapers, 10-25	forms of (table), 8-25	Semiconductor diodes, 15-68
Scratch coat (plastering), 6 -163	table, 8 -26	Semigels (explosives), 7-21
Scratch hardness (minerals testing), 5-12	threads for, ANSI metric (table), 8-14	Sensible heat factor (psychrometrics, def), 12-87
Screen scale, Tyler (for particle sizes, table),	V-thread, friction of, 3-26	Separating calorimeters, 16 -18
18 -10	wood (table), 8-24	Separators:
Screw conveyors, 10 -42		for dust exhaust systems, 18 -10, 18 -11
•	holding power of, 12-31	
Screw jacks, 10-15	Script alphabet, 19-44	steam, 9-51
Screw machines, 13-55	Scrubbers, gas, 18 -11, 18 -16	Sequence (def), 2 -30
free-cutting steel stock for (AISI and SAE),	Scruple (apothecaries' weight, def), 1-17	Series (def), 2 -30
6 -28	SDEL (sulfur dioxide emission limitation),	expansion of functions in, 2-31
Screw presses, 13-22	programs for, 18-14	Fourier's, 2-36
Screw propellers (ship):	Sea, as source of tidal energy, 9-21	semigeometric, 8-215
blade shapes for, 11-53	Seakeeping (ships), 11-44	Taylor's and Maclaurin's, 2-30
cavitation, 11 -53, 11 -54	Sealants, 6-155	Series circuits, 15 -16
controllable and reversible pitch, 11-54	acrylic latex, 6 -157	a-c, solution of problems in, 15 -19
design of, 11 -53	adhesion/cohesion of, 6 -156	Series generators, 15-26
developed area (def), 11-53	butyl, 6 -157	Series motors, 15-28
fitting to shaft, 11-57	compression set of, 6 -157	Servel process of refrigeration, 19 -17
partially submerged, 11-55	foamed-in-place, 6 -159	SES (surface-effect ship), 11-58
	forever-tacky, 6 -159	
pitch of (def), 11 -53		Set point (automatic control, def), 16 -22
projected area of, 11-53	formed-in-place, 6 -159	Sets:
shafts for, 11-56	as gasket, 6 -159	algebra of, 2 -2
slip ratio of (def), 11-53	hardness of, 6-156	algebraic, 2 -2
slip velocity of (def), 11-53	hot poured, 6 -159	elements of, 2-2
supercavitating, 11-55	modulus of, 6-156	operations on, 2-2
tandem and contrarotating, 11-55	oil-based caulks as, 6-157	subsets of, 2-2
ventilated, 11 -55	polysulfide, 6 -157	Setscrews:
wake velocity of (def), 11-53	polyurethane, 6-157	holding power of (table), 8 -23
Screw pumps, 14-12	properties of, 6 -156	points and heads for, 8 -19
Screw threads:	table, 6 -158	Settling time (automatic control, def), 16 -22
Acme (tables), 8 -16, 8 -17	relaxation of, 6-156	SEV (surface-effect vehicles), 11-58
American National Standard, drill sizes for	silicone, 6-157	Sewer pipe, 8-191
(table), 8 -30	types of, 6 -157	Sexagesimal measure of angles, 2-15
American Unified (tables), 8-10 to 8-13	urethane, 6-157	Shadow prices (linear programming), 17-9
coarse (tables), 8 -12	water-based, 6 -159	Shafting, marine, 11-56
extra-fine (table), 8 -13	weathering resistance of, 6 -157	Shafts:
fine (tables), 8 -13	Seals:	alignment of, 16-57
basic profile for, 8 -9	for shafts: controlled-gap, 8-142	bending moments in, 8 -47
design profile for, 8 -9	mechanical, 8-141	combined torque and bending in, 8-47
Dryseal pipe, 8-17	Seamless steel tubing (tables), 8-186, 8-187	couplings for (see Couplings)
efficiency of, 3-26	Seawater:	failure due to fatigue, 8 -47
fits for, Unified standard, 8 -9	galvanic series for metals and alloys in (table),	fits for, 8 -43
for high-strength bolting (table), 8 -18	6 -100	keys for, 8 -31
inserts for, 8 -27	purification of, 6 -173	leveling of, 16 -57
limiting dimensions of, 8 -9	specific gravity and density of (table), 6-8	packing for, 8-140
machine, 8-8	used in concrete, 6 -161	resilience of (table), 5-17
machines for cutting, 13-57	(See also Water, desalinization of)	for ship propellers, 11-56
major diameter of (def), 8-9	Seaworthiness (def), 11-41	splined, 8-33
metric, 8-9	Secants (trigonometry), 2-15	stiffness of, 8 -47
ANSI (table), 8 -14	Second (circular measure, def), 1 -17	strength of, 8 -47
	(unit of time, def), 1 -17	
ISO standard (table), 8-14		torsion of, 5 -36, 8 -47
tolerance classes for, 8 -16	Section modulus:	combined with other stresses, 5 -18, 5 -19,
minor diameter of (def), 8 -9	of beams (def), 5 -26	8-47
modified square, 8-16	table, 5 -27	table. 5 -38

Silk fibers (table), 6-141 Shafts (Cont.): Ships (Cont.): torsional vibration of, 3-72 high-performance, 11-41, 11-57 Silver, uses of, 6-74 vibration of, 3-72 hull forms for, 11-41 Silver soldering, 13-29 Shale oil: Similar figures (geometry), 2-5 Kort nozzles for, 11-55 fuel from, 7-19 lengths of (def), 11-42 Similarity, of models, 3-41 reserves of, 9-3 line shafts for, 11-56 Simplex method, of data transmission, 16-21 of optimization, 17-8 Shape factor (plastic design, def), 5-20 metacenter of (def), 11-44 Shape rolling, 13-14 molded beam of (def), 11-42 Simpson's rule, for area and volumes, 2-29, Shapers, 13-60 motions of, 11-45 2-39 nuclear, 9-148 Shaving (metalworking), 13-15 Simulation, on computers, 2-53 nuclear steam plants for, 11-49 Shaw process (molding), 13-3 Simultaneous equations, solution of, 2-12 powering of, 11-45 Sine (trigonometry), 2-15 propeller shafts for, 11-56 and bending, 5-16 Sine waves (a-c circuits), 15-18 and bending moment in beams, 5-31 propulsion plants for, 11-48 Sines, law of, 2-17 maximum pressure in, 13-14 propulsors for, 11-52 Single-phase induction motors, 15-39 modulus of elasticity in, 5-17 reduction gears for, 11-55 Single-phase power measurement, 15-21 Shear diagrams, for beams, 5-21, 5-31 to 5-33 resistance of, 11-45 Singular norm (def), 16-41 Shearing: frictional, 11-45 Singular values (matrices), 16-41 in dies, resistance to (table), 13-15 wavemaking, 11-45 Sink (automatic control, def), 16-28 of metals, 13-14 reversing of, 11-56 Sinking fund (table), 1-7 allowance for shaving, 13-15 screw propellers for, 11-53 Sintering, of powdered metals, **6**-62 power for, 13-15 shaft power of (def), 11-48 Siphons, **3**-53 Sirens, 12-118 Shearing modulus of metals (table), 5-4 stability of, 11-44 Shearing stress (def), 5-15, 5-16 steam plants for, 11-48 Sisal, properties of (table), **6**-141 at end of beams, 5-36 steam turbines for, 11-49 Sizing (flattening of forgings), 13-19 structural steel for, ASTM specifications for various cross sections, 5-16 Skating rinks, ice, piping for, 19-25 Shears, metal-cutting, 13-15 (table), 6-26 Skelp (steel, def), 8-167 structure of, 11-42 Sheaves: Skids (materials handling), 10-72 submarine, 11-41 Skim coat (plastering), 6-163 stresses in, 8-50 for V-belts (tables), 8-54, 8-56, 8-58, 8-59 tonnage of (def), 11-41 Skin friction (aerodynamics), 11-66 trim of, 11-42 for wire rope, 8-79 Skip hoists, 10-16 allowable radial bearing pressure on (table), loading and unloading of, 10-16 water-jet propulsion for, 11-55 Shock spectrum (vibrations), 3-69 Skylights: Shoran (navigation by radar), 15-90 minimum groove dimensions for, 8-80 coefficients of heat transmission through Shore scleroscope (hardness testing), 5-13 ratios for (table), 8-79 (table), 12-70 Sheet-metal gages (table), 8-85 Shovels, power, **10**-33 for industrial plants, 12-11 Shellac grinding wheels, 6-129 Shrink fits, 8-44 Slabs (see Reinforced concrete) Slackline cableways, 10-35 Shellac varnish, 6-112 Shrinkage: Shells, drawing of (metalworking), 13-18 of refractories (table), 6-153 Shielding: of rings on thick cylinders, 5-46 in boilers, 9-29, 9-32 of nuclear power plants, 9-142 Shunt generators, 15-26 specific gravity and density of (table), 6-8 of sound, 12-120 parallel operation, 15-27 Slagging index, of coal, 9-30 Shingles: Shunt motors, 15-28 Slate, **6**-143, **6**-146 asbestos, 6-146 starters for, 15-28 Sleds, friction of, 3-24 asphalt, 6-145 SI units (The International System of Units): Slenderness ratio of columns, 5-38 slate, **6**-146 base and supplementary (defs), 1-17, 1-24 Slider couplings, double, 8-35 wood, 6-145 conversion tables for, 1-19 to 1-24 Sliding bearings, 8-127 Shipping measure, 1-16 prefixes for (table), 1-19 Sliding-block linkage, 8-3 tons, United States and British, 1-16 Side-cutting-edge angle (tools), 13-52 Sliding friction (def), 3-21 tables, 3-23, 3-24 Ships, 11-40 Sidereal time, 1-25 air resistance of, 11-46 Sidewalks, moving, 10-22 Slimline lamps, 12-101 antirolling gyroscopes for, 3-20 Siemens (def), 15-2 Slip (of pumps), **14**-13 boilers for, 11-49 Sigma function for moist air, 4-16 Slip ratio, of screw propellers, 11-53 Signal bronze, 15-6 Slope, of a curve (def), 2-24 bottom paints for, 6-109 catamaran, 11-41 Signal validation (automatic control), 16-49 Sludge, in boiler feedwater, 9-48, 9-49 center of buoyancy of (def), 11-44 Significant figures, number of, 2-4 Slug (def), 1-23, 3-2 center of gravity of, 11-44 Silent chains, 8-62 Slump test, for concrete, 6-166 combined propulsion plants for, 11-52 Silica brick, 6-151 Slurry pumps, 14-4 condensate systems in, 11-49 Silica in steam, 9-50 Smart cards, 10-62 deadweight of (def), 11-41 Silicate grinding wheels, 6-129 Smoke (def), 18-8, 18-10 definitions of power and speed for, 11-46 Silicon carbide: Snatch blocks, 10-10 delivered power (def), 11-48 as abrasive, 6-128, 13-62 Snell's law (optics), 19-41 designed load waterline (DWL, def), 11-42 as refractory (table), 6-152 Soap, 6-137 diesel engines for, 11-50 as resistor material, 15-62 Sodium chloride brine, properties of (tables), displacement of (def), 11-41 for wood sanding, 13-75 **19**-19 draft of (def), 11-42 Soil pipe, cast-iron, 8-189 Silicon carbide furnace (electric), 7-59 drag, designed, 11-42 Soils: safe bearing power of, 12-26 Silicon controlled rectifier (SCR), 15-69 electric drives for, 11-56 Silicone greases, 6-151 Solar cells, 15-34 Solar energy, 9-11 engineering constraints, 11-47 Silicone oils, 6-151 applications of, 9-14 Silicone paint, 6-109 engines for (see Marine engines) environment of, 11-40 Silicone resins, 6-151 collectors, 9-13, 9-14 flat plate, 9-14 environmental constraints, 11-47 properties of (table), 6-199 feedwater systems for, 11-49 Silicone rubber, **6**-139, **6**-151 heat-transfer coefficients (table), 9-14 form coefficients of (table), 11-42 Silicone varnish, 6-138, 6-151 for cooking, 9-16 gas-turbine drives for, 9-132 Silicone water repellents, 6-151 direct conversion of, 9-17

Silicones, 6-151

equilibrium temperatures, 9-13

gas turbines for, 11-51

0.1 (0.1)	6 1	0 1:1 (0 .)
Solar energy (Cont.):	Sound:	Space vehicles (Cont.):
furnaces using, 9-16	absorption of: coefficient of (def), 12 -120	life-support systems for, 11 -120, 11 -121
for heating swimming pools, 9 -14	table, 12 -121	lubricants for, 11-115
for house heating, 9-15	attenuation of, 12 -117	materials for, 11 -111 to 11 -113
incident-angle determination, 9-12	audible range of, 12 -117	for high-pressure oxygen, 11 -113
instruments for: pyranometer, 9-12	beat-frequency oscillator, 12 -119	for high-temperatures, 11 -112
pyrheliometer, 9 -12	contact transducers, 12 -119	for low-temperatures, 11-111
opaque surface absorptance and admittance of,	industrial applications of, 12-121	noise from, effects of, 11-103
9-12	intensity of, 12 -117	nuclear motors for, 9-148
power from, 9-16	levels of, of various activities (table), 12 -119	nuclear rockets for, 11-119
radiation intensity of, 9-11	loudness of, 12 -118	propulsion of, 11-118
for refrigeration, 9 -15	masking of, 12 -119	radiative-heat-transfer systems for, 11 -108,
from solar ponds, 9-15	perception of, 12 -118	11-123
for stills, 9-15	pitch of, 12 -118	stability of, 11 -109
transparent materials for, solar-optical proper-	production and reception of, 12 -118	stresses in, 11 -116
ties of, 9-12	quality of, 12 -118	structures of, 11 -116
utilization of, 9-11	specific acoustic impedance, 12 -118, 12 -120	analysis of, 11 -116, 11 -117
heliochemical (def), 9-11	speed of, 3 -31	thermal management systems for, 11-120,
helioelectrical (def), 9 -11	testing of materials by, 12 -122	11-122
heliothermal (def), 9 -11	timbre of, 12 -119	vibrations in, 11 -117
processes, 9-11	total absorption of, 12-121	welding of, 11 -112
for water heaters, 9-15	transmission loss in building partitions (table),	(See also Space; Space flight; Space satellites
Solar ponds: energy from, 9-15	12 -120	Spacecraft (see Space; Space flight; Space satel-
Solar-powered vehicles, 9-17	velocity of, in various media (table), 12-117	lites; Space vehicles)
Solar radiation:	vibration pickups for, 12 -119	Span (unit of length, def), 1-16
annual variation (tables), 9 -12	wavelength of, 12 -117	Spanwise blowing (airplanes), 11 -64
on surfaces (table), 9-12	of whistles and sirens, 12 -118	Spark coil for ignition systems, 15 -66
Solar time, 1-25	(See also Noise)	Spark gaps for spark plugs, 9-114
Solder, alloys (table), 6 -76	· · · · · · · · · · · · · · · · · · ·	Spark-ignition (engines), 9-90 , 9-111 , 15-66
	Sound analyzer, 12-119	
Soldered-joints, fittings for (table), 8 -206	Sound-level meter, 12-119	Spark plugs for ignition systems, 15 -66
Soldering:	Sound levels, of various activities (table),	Spark voltages for ignition systems, 15 -66
sonic, 12 -122	12 -119	Specific gravity (def), 3-31
with ultrasonics, 12 -122	Sound spectrum (table), 12 -117	of brines (tables), 19 -19
Solders, 6 -74, 6 -76	Sound transducers, 12 -118	of calcium chloride solutions (tables), 19 -19
for brazing (tables), 6 -76	Source (automatic control, def), 16 -28	of liquids (conversion tables): API, 1-26
Solenoids, 15-63	Sources and sinks (radiation), 4 -66	Baumé, 1 -27
magnetic pull of (table), 15 -63	Soybean oil (paints), 6-108	of magnesium chloride brines (tables), 19 -19
Solid angle (def), 2 -9	Space, 11 -100	of sodium chloride solutions (table), 19 -19
Solids:	as data transmission symbol, 16-21	of various substances (table), 6 -7
buoyancy of, 3 -36	effects due to meteoroids in, 11-115	of water at various temperatures (table), 6-10
center of gravity of, 3-7	effects due to radiation in, 11-115	(See also Relative density)
melting points of (tables), 4 -50, 4 -57	table, 11 -115	Specific heat (def), 4 -3
moments of inertia of, 3-8	effects due to vacuum in, 11 -114	at constant pressure, for various materials
approximate, 3 -9	table, 11 -115	(table), 4 -52
radiation from, 4 -71	effects on lubrication, 11 -115	of gas mixtures, 4 -3
radioactive, control of, 18 -17	entry from, 11 -107	of gases, 4-3
rotation about axes, 3-15, 3-16, 3-19	orbital mechanics for flight in, 11-105	variable, 4-9
specific gravity and density of various (table),	planets in, atmospheres of (table), 11 -107	humid (def), 4 -15
6-7	solar system: astronomical constants of, 11 -101	of metals (table), 6 -11, 6 -50
by immersion, 3 -36	data on bodies in (tables), 11 -102, 11 -103	of mixtures, 4 -4
surface and volume of, 2-8	Space factor in winding magnets, 15 -65	ratios of constant-pressure to constant-volume
thermal conductivity of (tables), 4 -80, 4 -81,	Space flight:	for various materials (table), 4 -52
4 -83	hyperbolic excess velocity, requirements for	of refractories (tables), 6 -153
volume of, by immersion, 3 -36	(table), 11 -107	of solids, at low temperatures (chart), 19 -29
Solubility:	mechanics of, 11-104	of solutions, 4 -4
of gases in water (table), 6 -7	interplanetary, 11-107	of various materials (tables), 4-52, 4-57,
of inorganic substances in water (table), 6-5	lunar, 11 -107	4 -60
of salts in water (table), 6-5	trajectories, performance optimized, 11-108	of various solids (table), 4-57
Solutions, specific heat of, 4 -4	(See also Space satellites; Space vehicles)	Specific resistance (def), 15 -4
Solvents, 6 -148	Space lattice (metals), 13-8	Specific speed:
alcohols as, 6-148	Space satellites:	of centrifugal pumps (def), 14 -21
chlorinated, 6 -149	energy of, 11 -108	of hydraulic turbines (def), 9-150
esters as, 6-149	lifetime of, 11-106	Specific volume of ideal gases (eq), 3-31
hydrocarbons as, 6 -149	orbits, perturbations of, 11 -106	Specific weight of fluids (def), 3-31
ketones as, 6 -149		
	Space-time curve (kinematics), 3 -10	Spectral lumen (def), 12 -99
organic (cleaners), 6 -137	Space vehicles:	Spectrophotometers, 16 -18
petroleum, 6 -149	ablative systems for, 11 -108	Spectrum: electromagnetic (chart), 19 -42
for polymeric materials, 6 -149	berthing of, 11 -125	Speed control:
Sonar (underwater detection), 12 -122	components of (table), 11-100	of d-c motors, 15 -30
Sone (loudness level of sound, def),	control of, 11 -109	of induction motors, 15 -38
12 -118	damage to, by meteoroids, 11-115	Sphere gaps (high-voltage measurement),
Sonotone batteries, 15 -15	docking of, 11 -125	15 -24
Soot: luminosity of, 4 -68	inertia effects on, 11-126	Spheres:
Soot blowers, 9-31	engines for, 9-21	drag coefficient of (chart), 11-68
for air heaters, 9-31	environments, 11 -114	and flat plates, deformation of, under compres
automatic controls for. 9-32	launch environments of. 11-103	sion. 5 -47

Spheres (Cont.):	Sprinklers (Cont.):	Steam:
hollow: strength of, 5-47	preaction, 18-25	attemperation of, 9-44
volume of, 2 -9	tanks for, 18 -26	constant-pressure expansion of, 4-14
solid, deformation of, under compression, 5-47	temperature rating of (table), 18 -25 Sprocket wheels:	constant-volume expansion of, 4 -14 critical pressure of, 9 -45
surface and volume of, 2 -9	for chain drives, 8 -62	isentropic expansion of, 4 -14
theorems on, 2-9	chains for, 8-59	isothermal expansion of, 4 -14
Spherical degree (def), 2-9	diameters of (formulas), 8-62	moisture in, measurement of, 16-18
Spherical sectors, surface and volume of, 2-9	teeth for, design of, 8 -62	properties of (tables), 4 -44, 4 -46 to 4 -48
Spherical segments, areas of (formulas), 2-9	Spur gears, 8 -88, 8 -91	purification of, 9 -48, 9 -51
Spherical zones, surface and volume of, 2 -9 Spikes, 8 -82	Sputtering, 6-111 SRCI (solvent-refined coal), 7-18	quality of, 4 -13 determination of, 16 -18
tables, 8 -82 to 8 -84	Squaring shears, 13-15	reheating of, 9 -41, 9 -71
for timber construction, 12-31	Squirrel-cage motors, 15 -37	saturated (charts), 4-45, 4-49
Spiral bevel gears, dimensions of (table),	Stability:	pressure-temperature conversion (tables)
8-98	of airplanes, 11-70	9-78
Spiral convoyors 10 42	of automatic control systems, 16 -37 of floating bodies, 3 -36	tables, 4 -44, 4 -46 silica removal from, 9 -50
Spiral conveyors, 10 -42 Spiral pipe, 8 -185	of ships, 11-44	superheated (table), 4 -48
Spirals:	of submerged bodies, 3 -36	isentropic expansion of, 4-15
Archimedean, 2 -23	Stack effect:	tables for, 4 -44, 4 -46 to 4 -48
logarithmic, 2-23	air flow due to, 9-46	temperature control of, 9-44
Spiroid gears, 8-100	table, 9-47	temperature-entropy chart for, 4-45, 4-49
Splines, 8-33 dimensions of fittings for (table) 8-35	Stack emissions (see Air pollution)	wet: flow of, through nozzles, 4 -23 quality of, 4 -13, 16 -18
dimensions of fittings for (table), 8 -35 involute, 8 -33	Stack gases (see Flue gas) Stack molding, 13-5	Steam boilers (see Boilers)
parallel-side, 8 -34	Stacks: determination of verticality of, 16-57	Steam calorimeters, 16 -18
proportions of (table), 8-35	Stadia:	Steam condensers (see Condensers)
Split-ring piston packing, 8-140	distance measurements with, 16-55	Steam cycles, 4-19
Spontaneous combustion of coal, 7-8	leveling with, 16-55	Steam engines:
Spray chambers (air conditioning), 4 -17	Staff organization (def), 17-2	clearances in, 9-56 compound, 9-55
Spray painting, 6 -110 Spray ponds, 9 -86	Stagnation (fluids, def), 3 -46 Stagnation point:	compounding of, 9 -55
Spreader stokers, 9-32	in aerodynamics (def), 11 -61	economy factors for, 9-55
Springs, 8-66	in fluid flow, 3-46	efficiency of, 4-19
axially loaded, 8 -69	Stainless alloys, 6 -32	friction horsepower of, 9-54
brass for (table), 6 -72	Stainless steel (see Steel, stainless)	indicator diagrams for (theoretical), 9-54
coiled, 8 -68 compound (leaf or laminated), 8 -67	Stairways, safety provisions, 18 -20 Stalling angle (aerodynamics, def), 11 -62	indicators for, 16 -15 marine (<i>see</i> Marine engines)
conical, 8 -69	Standard atmosphere, international (table),	mean effective pressure in, 9-54
cylindrical-helical, 8 -68, 8 -69	4 -33	mechanical efficiency of, 9-54
strength and deflection of (table), 8-71	Standard deviation (statistics, def), 17-19	operation of, condensing, 9-55
deflection of, 8 -67	Standard time, 1-25	Rankine cycle for, 9-55
work done in, 8 -67	U.S. zones, 1-25, 1-26	Rankine efficiency ratio of (def), 9-56
elliptic, 8 -68 flat-leaf, 8 -67	Standard ton (refrigeration, def), 19-2 Standpipes for fire protection, 18-27	ratio of expansion for, 9-54 separation of inlet and outlet ports of, 9-55
helical, 8 -68, 8 -69	Star connections, three-phase circuits, 15 -20	steam jackets for, 9-55
design of: by formula, 8-70	Starting boxes for shunt motors, 15-28	steam rates for, 9-55
by table, 8 -70	Starting compensators for a-c motors, 15 -37	superheating, effects of, 9-55, 9-56
laminated triangular, 8 -67	Starting devices for a-c motors, 15 -37	theory of, 4-19
leaf, 11-11 materials for (table), 8-75	Starting resistance (trains), 11-39 Starting systems for automobiles, 15-67	uniflow, 9 -55 valve and port sizes for, 9 -56
rectangular-plate, 8 -67	Static balance, 3-66	Steam flow:
resilience of (table), 5 -17	Static electricity (def), 15 -15	effect of fittings on, 4 -23
semielliptic, 8 -68	Static friction (tables), 3-24	in nozzles, 4 -21, 4 -22, 9 -56 to 9 -60
single-leaf flat, strength and deflection of	Static inverters (electric current), 15 -18	in orifices, 4-21
(table), 8 -67 spiral-coiled, 8 -69	Static loads, safety factors for, 5-20 Statically determinate and indeterminate supports	in pipes, 4-23 throttling of, 4-24
steel, 6 -31	(def), 3 -5	in turbine buckets, 9-56 to 9-60
type and heat treatment of (table), 6 -32	Statics:	wiredrawing of, 4 -24
wire for, 6 -31	of framed structures, 12-18	Steam hammers, 13-22
straight-bar torsion, 8 -69	graphical, 3 -5, 3 -6	sizes of, 13 -22
time of vibration of, 8 -67	of rigid bodies, 3-3 to 3-6	Steam jackets, 9-55
torsion, 8 -69 triangular-plate, 8 -67	Stationary engines (internal-combustion), 9 -99 Statistical quality control, 17 -19, 17 -24	Steam-jet refrigeration, 19 -16 Steam lines, expansion joints for, 8 -207
truncated conical, 8 -69	Statistics, 17 -19 Statistics, 17 -19	Steam nozzles, 4-22
Sprinklers, 18-24	average (def), 17 -19	flow through, 4-22 , 4-23 , 9-57 to 9-66
alarms for, 18-25	confidence limits in, 17-20	Steam pipes (see Pipe; Piping)
deluge, 18 -25	correlations in, 17-21	Steam power plants:
dry pipe systems for, 18-25	go/no go data in, 17 -25	costs of, 17-33
over electrical equipment, 18-25 heads for, 18-25	for life tests, 17 -20 standard deviation (def), 17 -19	(See also Power costs) Steam pumps, 14 -10
alloys for, 6 -76	tolerance limits in, 17 -20	Steam purification, 9-51
location and spacing of, 18 -25	variability in, 17 -19	Steam reheaters, 9-41
nonfreeze systems for, 18-25	variance (def), 17 -19	Steam separators, 9-51
outside, 18 -25	Steady-flow process (def), 4-5	Steam tables, 4 -44, 4 -46 to 4 -48

Steam turbines:	Steam turbines (Cont.):	Steel, heat-treatment of (Cont.):
advantages of, 9-56	steam rate of (def), 9-69	maximum temperatures for, 6-19
back-pressure, 9-64	theoretical (table), 9 -69	quenching mediums for, 6 -20
balancing of, 9-62	superposition of, 9 -64	relation of design to, 6 -21
blades for: erosion of, 9-62	in tandem, 9-60	time of, and cooling rate of, 6 -19
materials for, 9-62	thrust bearings for, 9-63	high-carbon, welding of, 13 -43
vibrations of, 9-62	turning gears for, 9-63	high-speed, 6 -30, 13 -49
bleeding cycle for, 4-19	velocity ratio, effect on efficiency of (chart), 9-59	(See also Tool steel) high-strength low-alloy (table), 6 -27
bolting materials for, 9-63 buckets in, flow of steam through, velocity	Steam washers, 9-51	hot-working of, effect of, 6 -15
diagrams, 9-57, 9-62	Steel (def), 6 -13	hysteresis loss in (chart), 15 -10
casing materials for, 9-63	aging, 6 -26	joists of, 12 -43
classification of, 9-56	of magnets, 15 -63	Jominy test for, 6 -18
clearances in, 9-63	AISI, influence of heat-treatment on (tables),	local surface hardening of, 6 -21
for combined cycles, 9-69	6- 31	low-alloy, welding of, 13-43
combined thermal efficiency of, 9-69	properties of (tables), 6 -31	low-carbon, 6-25
corrosion in, 6 -106	AISI designations, 6-28	alloy, uses of, 6-27
cross-compound, 9-60	AISI specifications for (tables), 6- 28 to 6- 31	welding of, 13 -43
damage to, due to water induction, 9-74	alloy, composition of (table), 6 -29	Lüders lines in, 6-25
diagram-efficiency of, 9-58	alloys (see Steel alloys)	machinability of, 13-47
disk wheels for, 5 -51 divided flow, 9 -60	annealing of, 6 -17 ASTM specifications for, 6 -26	for machine parts (table), 6 -26
efficiency of: correction factors for, 9 -70	tables, 6 -26	McQuaid-Ehn test, 6 -18 magnet (permanent), 15 -62
chart, 9-70	basic oxygen, 6 -13	chart, 15 -62
engine efficiency of (def), 9 -69	boron, 6 -28	manganese, AISI specifications (table), 6 -28
extraction, 9 -64, 9 -70	carbon (def), 6 -13	manufacture of, 6 -14
in regenerative heating, 9 -72	AISI specifications for (table), 6 -28	manufacturing properties of (table), 13 -12
feedwater treatment for, 9-74	applications of (table), 6 -22	maraging, 6 -27
governors for, 9-64	bars, cold finished, 6 -30	martensitic, 6 -33
heat rates of (charts), 9-72	castings of, 6-43	mechanical properties of, 6-13, 6-22
effect of regenerative heating on, 9-72	high-manganese (table), 6 -28	(tables), 6 -26
representative (table), 9-71, 9-72	transformation reactions in, 6 -17	mechanical treatment, 6-15
helical flow, 9-64	carbon tool, 13-48	medium-carbon, welding of, 13-43
high-temperature bolting for, 9-63	carburizing of, 6 -21	microscopic structure of, 6 -17
impulse, 9-56	chromizing of, 6 -22 clad, 6 -21	molybdenum: AISI specifications (table), 6-29
bucket-velocity diagrams for, 9 -57, 9 -62 impurities in steam for, 9 -74	classification of, 6 -13	for tools, 13 -48 necking of, 6 -24
internal efficiency of (def), 9-59	cobalt, for tools, 13-48	nickel, AISI specifications (table), 6 -29
labyrinth packings for, 9-63	cold drawn, mechanical properties (table), 6 -32	nickel-chromium, AISI specifications (table),
leakage loss in, 9-58	cold-rolling of, 6 -15	6- 29
leakage of steam through, 9-63	cold-working of, effects of, 6 -15	nickel-molybdenum, AISI specifications
leaving loss in, 9-60	commercial, applications of (table), 6 -22	(tables), 6 -29
loss due to moisture in steam in, 9-60	constitution of, 6 -16	nitriding of, 6-21
low-capacity, 9-64	continuous casting of, 6 -15	normalizing of, 6 -17
low-pressure, elements of, 9 -60	copper-covered (high-voltage transmission),	patenting, 6 -17
lubrication of, 6 -183	15 -6	pickling, 6 -15
marine, 9 -64	corrosion of (see Corrosion)	piping in (cavities), 6-14
mechanical drive, 9-64, 9-70	creep rates for (table, chart), 5-10, 5-11	plastic range chart for, 13 -10
modern, large central-station, 9-66, 9-70 moisture loss in, 9-60	for cryogenic service, 6 -28 cyaniding of, 6 -21	precipitation hardening, 6-33
multirow stages in, 9-59	deep-hardening of, 6 -20	pressing of, effect of, 6 -15 for pressure vessels (table), 6 -26
nozzles for: design of, 9-57	liquids for quenching, 6 -20	quenched and tempered, 6 -27
efficiency of, 9 -57	defects in, 6 -14	quenching of (heat-treatment), 6 -20
mouth area of, 9-57	drawing of, 6 -17	refining of, ladle metallurgy for, 6 -14
theoretical work in, 9-57	dual phase, 6-27	reinforcing, for concrete, 12-50
throat area in, 9-57	electric, 6-14	rolling of, effect of, 6-15
velocity coefficient in, 9-58	electric-furnace (def), 6 -13	scabs in, 6 -14
oils for, 6 -183, 9 -74	electrical conductors of, 15 -6	scarfing, 6 -15
operating temperatures for, 9-72	extrusion of, 6 -16	seams in, 6 -14
packings for, 9-63	forging of, effects of, 6-15	segregation in, 6-14
performance calculations for, 9-70	foundry practice (see Foundries)	shallow-hardening (def), 6- 19
performance of, 9 -69 radius ratio of, 9 -57	fracture toughness of, 6 -24 free-cutting, AISI specifications (table), 6 -28	liquids for quenching, 6 -20 shapes of, properties of (tables), 12 -34 to 12 -48
reaction, 9-56	for general construction (table), 6 -26	sheet, electrical, 6 -32
bucket-velocity diagram for, 9-57, 9-62	H-type, 6 -28	shipments of, 6 -23
(See also Hydraulic turbines, reaction)	hammering of, effect of, 6 -15	silicon-manganese, AISI specifications (table),
regenerative cycle for, 4 -19, 9 -71	hardenability of (def), 6 -18	6- 29
reheating cycle for, 4 -19	effect of alloys on (table), 6 -20	special alloy, 6 -32
rotative speeds of, 9-62	hardened, tempering of, 6-17	spheroidizing of, 6 -17
rotor materials for, 9-62	hardening of, 6 -21	spring, 6 -21
silica deposits in, 9-50	effect of surface condition on, 6 -21	stainless, chemical composition (table), 6 -34
stage design of, 9-56	heat-resisting alloys, properties of (table), 6 -78	duplex, 6 -33
stage efficiency of, 9-58	heat-treatment of, 6 -17	families of, 6 -33
starting and loading of, 9-73	cooling rates for, 6 -19	ferritic, 6 -33
steam-bled (table), 9 -73 steam-path design, 9 -59	heating, 6-19	grades of, 6 -33
sicam-pain uesign, 3-39	heating rates for, 6 -19	L-grade, 6 -33

Steel, stainless (Cont.):	Step bearings, 3-28	Stress (Cont.):
maximum stress values for (table), 6 -37	friction of, 3-28	determination of, by method of joints, 3 -6
mechanical properties of (table), 6 -36	Step input (automatic control), 16 -27	in framed structures, diagrams for, 12 -22, 12 -24
plastic range chart for, 13-10	Step pulleys, 8-52	in pipelines due to flexure, 5-55
strength of, at high temperatures (table), 5-11	Steradian (def), 1 -17, 2 -9	shearing, 5 -15, 5 -16
welding of, 13 -43	Steregon (def), 2-9	simple, 5 -15 to 5 -17
strength of: AISI (tables), 6-31	Stereotype metal (table), 6-75	in static plane structures, 3-5, 3-6
ASTM (table), 6 -26	Stick-slip vibration (def), 3 -21	tangential, 5-15
low-alloy (table), 6-27	Stiffness of beams, 5-30	true, 5 -3
stretcher strains in, 6 -25	Stirling cycle, 4 -11	in turbine-disk wheels, 5 -51
structural: ASTM specifications, 6 -26, 12 -33	Stirling engines, 9-20	volume change due to, 5-17
fire-resistance of (table), 12 -48	for artificial hearts, 9-21	Stress concentration, 5-8
for locomotives, ASTM specifications	closed environment, 9-21	factors of (charts), 5 -5 to 5 -7
(table), 6 -26	for cryocooling, 9 -21, 19 -27	Stress corrosion, 5-8
materials for, 12 -33	Ford-Philips, 9-21	Stress-corrosion cracking, 6-102
paints for, 6 -110	free piston, 9-21	in space vehicles, 11 -113
properties of (tables), 12 -34 to 12 -48	for heat pumps, 9-21	Stress-cycle diagram (fatigue analysis), 5-8
for ships, ASTM specifications (table), 6 -26	liquid piston, 9-21	Stress intensity (def), 5-8, 5-15
specifications for (table), 6 -26	low-temperature, 9-21	Stress moment (def), 5-21
welding of, 12 -41	Stoddard solvent, 6-149	Stress-optic law, 5-52
structure of, 6-16	Stoke (unit of kinematic viscosity), 3 -33	Stress polygon, 3-5
temper rolling of, 6 -25	Stokers:	Stress-rupture test, 5-10
tempering of, 6 -17, 6 -19	chain-grate, 9-32	Stress-strain diagrams, 5-2 to 5-4
tensile properties of, 6 -22 chart, 6 -20	spreader, 9-32	description, 5-2
· · · · · · · · · · · · · · · · · · ·	traveling-grate, 9-32 underfeed, 9-32	Stresscoat (strain indicator), 5-54
thermomechanical treatment of, 6 -22	Stokes' law for settling of dust, 18 -10	Stresses, thermal, 5-17 Stresses, etraine, 5-3, 6-25
tool (<i>see</i> Tool steel) toughness of, 6 -24	Stone:	Stretcher strains, 5-3, 6-25 Strings, vibration of, 3-72
for turbine blading, 9 -62	for building, 6 -143	Stripping by power shovel, 10 -33
ultimate tensile strength (def), 6 -24	pipelines for, 11 -131	Stroboscopes, 16-3
uses of, 6 -13	properties of (table), 6 -144	Strouhal number (vibrations in fluids), 3 -42,
welding of, 13 -43	specific gravity and density of (table), 6 -8	3-43, 3 -47
heat affected zone in, 6 -24	Stonework, mortar for (table), 6 -162	Structural damping (vibrations), 3 -66
(See also Welding)	(See also Masonry)	Structural steel (<i>see</i> Steel, structural)
yield strength (def), 6 -23	Storage:	Structural timber (see Timber)
Steel alloys, 6 -13	of inflammable liquids, 18 -19	Structures:
AISI specifications (table), 6 -29, 6 -31	of materials, 10 -62	combining loads on, 12 -21
castings, 6 -38, 6 -43	equipment used for, 10 -71	statically determinate and indeterminate (def),
effect of alloying elements, 6-19	Storage batteries (see Batteries, storage)	3 -5
furnaces for (electric), 6-14	Stovewood, 7-9	stresses in, 3-5
hardenability of, 6-18	Straight lines, equation for, 2-18	steel-framed (see Steel-framed structures)
hardness of, influence on: of elements (table),	(See also Lines)	stresses in, by method of sections, 3-6
6 -20	Straightening operations (metals), 13-16, 13-23	wind pressure on, 12-19
of heat-treatment (table), 6-31	Strain:	Struts, drag of (aerodynamics), 11-68
of specimen size (tables), 6 -31	elastic, 5-49	Stubs gage (table), 8-85
strength of, at high temperatures (table), 5-11	plane, 5 -5, 5 -44	Stucco, 6 -162, 6 -163
Steel angles (See also Angles, steel)	plastic, 5 -49	colors for, 6 -163
Steel beams, deflection of (table), 12 -47	Strain gages, 3 -79, 5 -53, 16 -7	Student's distribution (statistics), cumulative, or-
(See also Beams, steel)	foil, 5 -53, 5 -54	dinates of (table), 1 -12
Steel castings (see Castings, steel)	in rosettes, 5-53	Studs, drilling and tapping cast iron for (table),
Steel columns, 5-38	transverse sensitivity of, 5 -53	8-30
table, 12 -36	Strain hardening:	Sturm's equation for collapse of cylinders, 5-45
Steel construction (see Steel-framed structures)	coefficient of, 5 -49	Styrene and polystyrene copolymers resins:
Steel-framed structures:	modulus of, 13-10	properties of (table), 6 -198
beams and girders for, proportions of, 12 -34	Strain-rate sensitivity, 5-5	Styrene copolymers resins: properties of (table), 6 -198
bolts for, 12 -35 columns for, 12 -34	Strandboard, 6 -126 Strands, wire, 8 -75	Submerged bodies, forces on, 3-34 to 3-36
compression members in, 12 -34	Strap hammers, 13-22	Submerged openings, flow through, 3-60
fire resistance of (table), 12 -48	Streamline forms (aerodynamics, def), 11-67	Submerged surfaces, pressure on, 3 -34 to 3 -36
riveted connections for, 12 -35	drag of, 11 -67	Subsonic velocity (def), 11-59
specifications for, 12 -33	Streamlines (def), 3 -36	Subtraction, arithmetical, 2-4
tension members in, 12 -34	Streams, flow measurement in (see Weirs)	Subway trains, 11-35
welding of, 12 -41	Strength:	Suction stabilizers, for pumps, 14 -14
Steel I beams (table), 12-35	of bolts (tables), 8 -27	Sulfur:
Steel pipes (see Pipe)	of metals (table), 5-4 , 6-11	in the atmosphere, benefits from, 18-13
Steel springs: heat treatment for (table), 6 -32	tensile (def), 5-2	in coal, 7 -6, 7 -31
Steel strip:	yield (def), 5-2	table, 18 -13
mechanical properties of (table), 6-23	Strength coefficient (def), 5-4	effect on vegetation, 18-13
temper rolling of, 6 -25	Stress (def), 5 -3, 5 -15	heat of combustion (table), 4-26
Steel tubing (tables), 8 -186, 8 -187	analysis of, 5-51	Sulfur dioxide:
Steel wire gage (table), 8-85	by birefringent coating, 5 -54	control systems for (table), 18-13
Steepest ascent, 2-39	by brittle-coating, 5 -54	effect on vegetation, 18 -13
Steering gear, automobile, 11-12	by holography, 5 -54	table, 18 -12
Stefan-Boltzmann law (radiation), 4-62, 4-74	theories for, 5-48	as refrigerant, 19-5
Steinmetz coefficients (table), 15 -10	combinations of, 5-5, 5-18	Sulfuric acid, freezing temperatures of water
Steinmetz law of hysteresis, 15-10	creep rates due to (table), 5-11	mixtures (table), 15-13

Sulfurized oils as cutting fluids (machining),	Surface finish (see Surface texture)	Synchronous motors, 15-40
13 -50	Surface integrals, 2-35	Synchros, 16 -5
Sulfurous acid (see Sulfur dioxide)	Surface temperature, measurement of, 16 -10,	Syngas, production of (table), 7-38
Sulzer two-cycle engines, 9-108 Summer dew-point temperatures (chart), 12-65	16-13 Surface tension (def), 3-33	Synthane process (gas making), 7-35
Summer dry-bulb temperatures (chart), 12 -64	of liquids (table), 3 -33	
Summer wet-bulb temperatures (chart), 12-65	Surface texture:	
Superalloys for high-temperature use (tables),	design criteria for, 13-68	Tachometers, 16-18
6 -78 to 6 -80	design requirements of, 13-69	Tail shafts (ships), 11-56
Supercharging (engines), 9-106	table, 13 -69	Tangential stress, 5-15
Superconductivity, 19-30	flaws in (def), 13 -70	Tangents:
of metals, 19 -30	lay of (def), 13 -70	to an ellipse, 2-20
Superconductors (cryogenics), 19-30	symbols used with (table), 13-71	to a hyperbola, 2 -21
columbium alloys for, 6 -81 Superdiode (integrated circuit), 15 -79	measurement of, 13 -70 produced by production processes (chart),	trigonometric, 2 -15 Tanks:
Superfinishing (honing process), 13 -64	13-72	corrosion in, 6 -106
Superheated carbon dioxide (table), 4 -35	roughness of, 13-69	water, for fire protection, 18 -26
Superheated steam, properties of (table), 4 -48	symbols for, 13-68	winds on, pressure coefficients for (table),
Superheated vapors, expansion of, 4-14	tolerances for, 13-70	12 -20, 12 -23
Superheaters:	waviness in (def), 13-69	Tantalum, uses of, 6-81
allowable stresses in (table), 9-42	Surge tanks, 9-160	Tap drill sizes: for pipe threads, 8-17
convection, 9 -41, 9 -42	Surveying, 16 -50	Tape:
hairpin, 9-42	distance measurements in, with electronic	for computers, 2 -44, 15 -83
nondraining, 9-42	distance meter, 16 -51	measurements with, 16-5 0
radiant, 9-41, 9-42 self-draining, 9-42	electronic total stations for, 16-54	Taper keys, friction of, 3 -26
steam flow rates in, 9-42	establishing bearings by, 16 -54 instruments, 16 -51	Taper pins, 8 -32 table, 8 -34
table, 9-42	automatic level, 16 -52	Tapping, of plastics, 13 -65
tubes for (table), 9-42	electronic distance meter, 16 -51	Taps:
Superheterodyne reception (radio), 15 -87	corrections for, 16 -51	pipe, drills for (table), 8 -20
Superplasticity (def), 5-11	electronic total station, 16-53, 16-59	sizes of (table), 8-30
Supersaturation, theory of, 4-23	transit, 16 -53	Tar:
Supersonic and hypersonic aerodynamics:	Y level, 16 -52	for roofing, 6-145
acoustic theory of, 11-77	laying out horizontal curves by, 16 -57	specific gravity and density of (table), 6 -9
aerodynamic heating, 11 -79	leveling, 16 -51	Tar sands: fuel from, 7 -19
airfoil sections for, 11-77	mapping, 16-55	Taylor's diagram for three-blade propellers, 11-54
area rule for, 11- 79 base drag in, 11- 79	measuring across streams by, 16 -56 measuring horizontal angles, 16 -54	Taylor's series, 2-30 Tees, cut from standard sections (table), 12-44
diffusers for: Oswatitsch, 11 -76	measuring inaccessible distances, 16 -56	structural steel, properties of (table), 12 -44
subsonic, 11-76	measuring vertical angles, 16 -54	Teflon: as electrical insulation, 6 -139
supersonic, 11-76	passing obstacles while, 16 -56	Telephone communications, 15 -90
force measurements in, 11-80	producing straight lines by, 16 -54	Telescopes, alignment, 16-6
gas dynamics relations for, 11-72	profile, 16 -52	Television, 15-89
table, 11 -73	referencing a point in, 16 -57	Temperature:
hypersonic flow in (def), 11-72	special problems in, 16 -56	absolute scales of, 4-2
lift in: of axially symmetric body, 11 -78	stadia used in, 16 -55	of adiabatic saturation, 4-15
coefficient of, 11 -77 curves for wings: delta plan-form, 11 -78	traverses for, 16 -54 Surveyor's measure, 1 -16	air volume correction factors due to (table), 12-91
rectangular, 11-78	Susceptance (electrical circuit, def), 15 -3, 15 -19	of combustion, 4 -29
swept-back, 11-78	Sutro weir, 16 -14	table, 4-30
interference, 11 -79	Swaging: of metals, 13 -19	critical: of gases (def), 4 -13
Mach angle in, 11-74	Swaging machines, rotary, 13-24	tables, 4-50, 4-58
Mach cone in, 11-74, 11-77	Swash-plate pumps, 14-12	dry-bulb, 4-15
Mach number in (def), 11-72	SWATH (small water-plane area twin hull),	effect on creep rate (table), 5-11
Mach waves in, 11-74	11-41, 11-59	effect on volume of water (table), 6-10
nozzles for: converging, 11-75	SWG (wire gage, table), 8-85	flame, with gaseous fuels (table), 4-29
ordinates for (table), 11-75 for rockets, 11-75	Swinging-block linkage, 8-3 Switch gear (electric), 15-46	inferred absolute zero of, 15 -5 of iron or steel by color, 4 -57
Prandtl-Glauert rule in, 11 -77	Switchboards:	measurement of, 4 -2, 16 -9
pressure measurements in, 11-80	bus bars for, 15-45	by pneumatic transmitter, 16 -11
recovery factor in (temperature), 11 -79	panels for, 15 -45	of surfaces, 16 -10, 16 -13
shock polar for, 11-74	equipment for standard, 15-46	wet- and dry-bulb (def), 4-15
shock relations in (table), 11-74	wiring diagrams for, 15-45	wet-bulb, thermodynamic, 4-15
shock tubes for, 11-76	Switches, electric, 15 -46, 15 -56, 15 -61	Temperature coefficient of resistance (def), 15 -4
shock waves in, 11-72	Symbols:	table, 15 -4
skin-friction drag in, 11-79	chemical (table), 6-3	Temperature-entropy chart:
stagnation temperatures in, 11 -79 subsonic flow in (def), 11 -72	for electrical apparatus, 15 -7 for electrical units (table), 15 -3	for air, 4-32 description of, 4-14
supersonic flow in (def), 11-72	proofreaders', 19 -44	for steam, 4 -45, 4 -49
past a cone, 11-74	Synchromesh (automobile), 11-8	Temperature gradient (heat flow), 4-81
chart, 11 -74	Synchronous condensers (electric), 15 -40	Temperature-humidity index, 12 -62
transonic flow in, 11-72	Synchronous converters, 15-42	Temperature inversion (Joule-Thomson effect),
wind tunnels for, 11-76	switchboard equipment for, 15-46	4 -24
(See also Aircraft jet propulsion)	Synchronous generators (see Generators, alter-	Temperature limits of electrical apparatus, 15 -43
Surface, of various solids, 2-8	nating-current)	Temperature stresses, deformation caused by,
Surface condensers, 9-75	Synchronous impedance, 15-32	5 -15

Thermocouples, **15**-21, **16**-9 to **16**-13 Temperatures: Timber floors, properties of (table), 12-28 high wet-bulb (chart), 12-66 temperature-millivolt relations (chart), 16-12 Timber piles, 6-124 summer dew point (chart), 12-65 use at low temperatures, 19-38 Timber poles, 6-124 summer dry-bulb (chart), 12-64 Timber trusses, 12-23 vacuum, 16-13 summer wet-bulb (chart), 12-65 Thermodynamic cycle (def), 4-4 Timbre (sound), 12-119 winter outdoor (chart), 12-63 Thermodynamic efficiency of steam engines, 4-19 Time (def), 3-2 Tempering (def), 6-17 measurement of, 1-25, 11-106 Thermodynamic notation and symbols, 4-4 furnaces for, 7-54 Thermodynamic processes (def), 4-4 sidereal (def), 1-25 of hardened steel, 6-21 reversible and irreversible (def), 4-5 solar and apparent solar, 1-25 of steel (def), 6-17 steady-flow, 4-5 standard, 1-25 (See also Steel, heat-treatment of) Thermodynamic properties, of various sub-NBS signals for, 1-26 Time constants (automatic control), 16-26 Tempilsticks, 16-10 stances (tables), 4-50, 4-53, 4-58, 4-60 Time standards (work measurement): development of, 17-31 Temporary hardness, of water, 6-170 Thermodynamics: Tension, elongation and contraction due to, 5-2 equations of state for, 4-7 Termites, destruction of wood by, 6-126, 6-127 first law of, 4-4 uses of, 17-32 Terne, 6-111 flow processes in (def), 4-5 Time study, 17-28 of gases, variable specific heat of, 4-9 Terneplate, 6-74 elements of, 17-26 Tesla (def), 15-3 second law of, 4-6 diagram, 17-26 Test specimens, 5-14 of vapors, 4-13 fatigue allowances in, 17-31 forms for, 17-29, 17-30 Thermoelectric cooling, 19-17 Testing: by acoustic signature analysis, 5-67 figure of merit for, 19-18 formulas for, 17-31 Thermometers, **4**-2, **16**-9, **16**-10 compression, 5-5 methods used in, 17-28 by eddy-current methods, 5-66 for alarms, 16-11 observations in, 17-28 by electrified particles, 5-61 with bimetallic elements, **16**-9 performance ratings by, 17-29 by gamma rays, 5-65 gas, 16-9 standard data for, 17-31 by infrared methods, 5-67 hydrogen, 4-2 standards developed from, 17-31 by magnetic particles, 5-61 for industrial applications, 16-11 Time zones, 1-25, 1-26 of materials, 5-13 mercury, **16**-9, **16**-10 Timers, 16-3 methods of, 5-61 partial immersion, 16-11 electronic, 16-3 table, **5**-62 resistance, 16-10, 16-12 Timesharing (computers), **2**-52 scales for, 4-2 Timing circuits (electronics), 15-74 by microwave methods, 5-67 nondestructive, 5-61 Tin, for bearings (table), 6-61 stem exposure corrections for, 16-11 by penetrants, 5-61 vapor-bulb, 16-9 Tin solders, melting points of (table), 6-76 of porous objects, 5-65 vapor-pressure, 19-38 Tires, automobile: constructions for. 11-16 by radiation, 5-65 Thermopiles, **16**-13 Thermoplastic substances, 6-139 details of (table), 11-4 radiographic, 5-65 ultrasonic: frequencies used in, 5-66 Thermoprene, uses of, 6-148 effect of temperature on rolling resistance of, materials used in, 5-66 Thermosetting plastics, 6-139 11-4 friction of, 3-24 standards for, **5**-66 Thermosiphon (water-cooled engines), 9-118 by X-rays, 5-65 Thinners for paint, 6-108 inflation pressures for (table), 11-4 Testing machines, 5-13 Thiokol (synthetic rubber): properties of, 6-148 load limits for (table), 11-4 calibration of, 5-13 metric size designations of (chart), 11-16 Thoma cavitation coefficient (hydraulic (See also Testing) turbines), 9-158 rolling resistance versus tire pressure (chart), Thorium, 9-5 Testing methods, nondestructive (table), Threading dies, 13-57 5-62 time to reach temperature equilibrium, 11-4 Tetraethyl lead (knock suppressor), 9-116 Threading machines, 13-57 Tirrill regulator (a-c generators), 15-34 table, 9-116 Titanium, production of, 6-91 Threads, screw (see Screw threads) Tetrahedron, 2-9 Three-phase a-c circuits, 15-20 Titanium alloys, 6-91 Tetryl (explosive), 7-22 Three-phase power, measurement of, 15-22 composition of (table), 6-92 properties of (table), 6-92 Tex (fiber fineness unit), 6-140 Three-phase transformers, 15-35 TNT (explosive), 7-22 Texaco gasification process, 7-38 Three-wire a-c distribution circuits, 15-54 Theorems, geometrical, 2-5 Throttling, efficiency loss due to, 4-24 table, **7**-21 Therbligs (motion study, table), 17-27 Throttling calorimeter, 16-18 Tobin bronze, plastic range chart for, 13-10 Thermal conductance, 4-80 Toggle joint, 8-8 Thrust, of jet engines, equations for, 11-90, 11-92 conversion table, 1-34 Thrust bearings (see Bearings, thrust) Token passing (computer networks), 2-48 Thermal conductivity (def), 4-80 Thrustor for wire rope brake, **10**-10 Token rings (computer networks), 2-48 of air (table), 4-82 Thyristors, 15-69 Tolerance (def), 8-43 of building materials (tables), 4-83, 4-84 capacitance for, in circuits, 15-71 Toluene, as solvent, 6-149 conversion table, 1-34 characteristics of (table), 15-70 Ton: of gases (table), 4-82 assay (def), 1-17 in rectifier circuits, 15-71 of insulating materials (tables), 4-84 turn-off time of, 15-69 long (def), 1-23 of liquids (table), 4-82 Tidal power, 9-21 metric (def), 1-23 Tile, roofing, 6-146 of metallic elements (table), 6-50 register (def), 1-16 of metals (table), 4-80, 4-81, 6-11 Timber: shipping (def), 1-16 of miscellaneous substances (table), 4-83 allowable stresses in (tables), 12-28 to 12-30 standard (refrigeration, def), 19-2 of nickel-chromium with iron (table), 4-80 connectors for, 12-31 Tongs, lifting, 10-10 of refractories (tables), 4-84 allowable loads (table), 12-32 Tonnage of ships (def), 11-41 of steam (table), 4-82 fire resistance of (table), 12-48 Tool steel, **6**-30, **13**-48 Thermal insulation (see Refractories) gluelam, design using, 6-123 cast alloys for, 6-78 compositions of (table), 6-81 Thermal properties of substances, 4-31 manufacture of, 6-123 Thermal stresses, 5-17 round, 6-124 classification of, 6-30 Thermal unit: specific gravity and density of (table), 6-7 cold-work, 6-30 British (def), 1-19, 4-3 (See also Wood) composition and uses of (tables), 6-32 IT calorie (def), **1**-20, **4**-3 Timber beams, 12-29 for cutting tools, 13-48 Thermistors (resistance thermometer), 16-10, Timber columns, 12-30 high-speed (table), 6-32

Timber construction, 12-28

hot-work, 6-30

16-13

Tool steel (Cont.):	Transients (electrical), 15-16	Tubes (Cont.):
shock-resisting, 6 -30	Transistors, 15-69	electron, 15 -71
special-purpose, 6 -31	bipolar junction, 15 -70	film coefficients for (heat transmission), 4 -83,
tungsten-alloy, 6 -31 water-hardening, 6 -30	characteristics of (table), 15 -70 JFET, 15 -70	4- 84, 4- 86 radiation factors for rows of (chart),
Tools:	metal oxide semiconductor, 15 -70	4-66
carbide, 6-62	MOSFET, 15-70	strength of, 5 -45, 5 -47
machine (see Machine tools)	Transit, 16-6, 16-53	(See also Pipe; Piping; Tubing)
Toothed and worm gearing efficiency, 3-27	adjustment of, 16 -55	Tubing (def), 8 -146
Topography, 16-55	angular measurements with, 16 -53	aluminum, 8 -191
Torch brazing, 13 -29 Torpex (explosive), 7 -22	and stadia, leveling with, 16 -55 Transmission:	boiler (table), 8 -187 brass, 8 -189
Torque, of electric motors, 15 -27	of electrical power (<i>see</i> Electric power	commercial classifications, 8 -147
Torque converters, hydraulic, 11 -7	transmission)	condenser (table), 8 -186
Torr (def), 14 -39	of heat (see Heat transmission)	copper (table), 8-191
Torsion, 5-36	of light (def), 12 -99	fabrication methods for, 8 -167
of circular sections, 5 -36	Transmission dynamometers, 16 -15	cupping and drawing, 8-167
of composite sections, 5-37 effect of external twisting moment, 5-37	Transmission mechanisms (automobiles), 11 -6, 11 -9	forged, turned, and bored, 8 -167 hollow-forged, 8 -169
of noncircular sections, 5-37	Transportation, by cableways, 10 -30	flash-controlled, 8 -147
of shafts, 5 -36, 8 -47	Trapezoidal rule, 2 -39	flash-in, 8 -147
of various cross sections (table), 5-38	Trapezoidal weirs, 3-57	heat-exchanger (table), 8-186
Torsion balances, 16-4	Trapezoids:	mandrel drawn, 8-147
Torsional vibration, of shafts, 3-72	areas of, 2-7	materials for, allowable stresses in (table),
Torus, surface and volume of, 2-10	center of gravity of, 3-6	8-183
Towers, wind pressure on, 12 -21 pressure coefficients for (table), 12 -20, 12 -23	Traveling cranes, 10 -26 Trees: effects of sulfur dioxide on (table), 18 -12	plastic, 8 -191 quality factors for (table), 8 -183
Track, railway, 11 -37	Trenching, setting stakes for, 16- 57	rectangular (table), 12-46
curves for, 11-38	Trepanning, 13-55	seamless, 8-147
nonstandard gages used, 11-35	Triacs, 15 -69	seamless mechanical, 8-185
superelevation of, 11 -40	Triangles, plane:	seamless steel, weight of (table), 8-186,
Track jacks, 10 -16	lengths and areas of, 2-7	8-187
Trackage, overhead, 10 -37 monorail, 10 -26	solution of, 2 -17 theorems on, 2 -5	square (table), 12-46 steel: as columns, 12-43
table, 10 -26	Triangular-notch weirs, 3 -57	finish classifications of (table), 8 -169
Tracta universal joints, 8 -36	Trigonometric functions, 2-15	mechanical properties of (table), 8 -169
Traction motors (railway), 11-22, 11-24, 11-25	inverse, 2-17	weights and dimensions of (tables), 8-186,
Tractive electromagnets, 15 -63, 15 -64	series for, 2 -31	8 -187
Tractive force, of locomotives (table), 11 -21	Trigonometry, 2-14 to 2-18	tolerances for (tables), 8 -167, 8 -168
Tractors, 10-24	solutions, of plane triangles, 2 -17 Triplex chain blocks, 8 -8	welded, 8-147
engines for, 9-98 wheeled, 10-24	Tripoli (abrasive), 6 -129	(See also Pipe; Piping; Tubes) Tubular heat exchangers, formulas for, 4-83,
Tractrix, 2-23	Trippers (conveyors), 10 -49, 10 -51	4 -84, 4 -86
Trademarks, 18-29	Trochoid, 2-22	Tung oil, 6 -108
Trains (see Railway engineering)	Trolley hoists, 10 -13	Tungsten:
Tramways, bicable, 10 -31	Trolley trackage, overhead, 10-26	as resistor material, 15 -62
cable, 10 -31	Tropical year, 1-25	uses of, 6-81
jigback, 10 -31 monocable, 10 -31	Troy weight, 1-17 Truck cranes, 10-29	Tungsten-alloy steel, 6 -31 Tungsten carbide alloys, 6 -62
saddle-clip, 10 -31	table, 10 -30	properties of (table), 6 -64
(See also Cableways, tramways)	Trucks, 11-18	Tungsten tools, 13-48
Transducers (sound), 12-118	access to plants, 12-14	Turbidimeters, 16 -18
Transfer functions (automatic control), 16 -39	classes of, 11 -14	Turbine disks, stresses in, 5 -51
Transfer prices, 17-17 Transfer (rineling computer program) 11 128	engines for, 9 -97 (See also Automobile engines)	Turbines: gas (see Gas turbines)
Transflow (pipeline computer program), 11 -128 Transformers, 15 -34	fork, 10 -23	hydraulic (see Hydraulic turbines)
compensator, 15-36	governors for, 11-20	steam (see Steam turbines)
data on, 15-36	lift, 10 -23	wind (see Wind turbines)
differential, 16-5	noise tests for, 11-20	Turbofan engines, 11-92
E, 16 -5, 16 -6	power requirements for, 11 -19	applications of, 11-92
efficiency of, 15 -35 grounding of secondaries of, 15 -53	service classes of, 11-19	blades for, 11-92
instrument, 15 -23	weight classifications of (table), 11 -18 (See also Automobiles)	fan noise of, 11-93 flutter in, 11-92
insulation for, chlorinated hydrocarbons as,	True stress-strain curve, 5-3	natural frequencies of, 11-92, 11-93
6 -139	Trusses:	thrust of, 11 -92
leakage flux in, 15-35	determination of stresses in, 12-23	Turbojet engines, 11-83
LVDT, 16-5	for floors, 12 -22	Turboprop engines, 11-84
polyphase, connections in, 15 -35	roof, 12 -21, 12 -23	Turbulent flow, 3 -46, 3 -48, 3 -49
regulation of, 15 -35 Scott taps for, 15 -36	timber, joints for, 12 -31 weight of (formula), 12 -23	Turn indicator (airplanes), 3-20 Turning (see Lathes; Machine tools)
T connections for, 15 -36	TTL (transistor-transistor logic), 15 -79	Turning (see Latnes; Machine tools) Turning-block linkage, 8 -3
testing of, 15 -35	Tubes, 8 -185	Turret lathes, 13 -52
theory of, 15 -34	boiler (see Boilers, tubes for)	Twist drills, 13-55
three-phase, 15-35	collapsing pressure of, 5-45	angles for, 13 -55
Transient analysis (see Automatic control,	for condensers (see Condensers, steam,	sizes of (table), 8 -86
transient analysis of system)	surface-type)	Twisting moments on shafts, 5 -37, 8 -47

Two-cycle engines, 9-91 advantages, 9-91, 9-100	V-belts (<i>Cont.</i>): for quarter-turn drives, 8 -56	Vegetation: effects of sulfur dioxide on (table), 18-12
diesel, 9-107	ribbed, 8-57	Vehicles:
Two-phase a-c circuits, 15 -20	selection of, 8-55	automatic, for materials handling, 10 -36, 10 -56
Tyler standard screen scale, 18 -10	service factors for (tables), 8 -51, 8 -55 sheave dimensions for (tables), 8 -58, 8 -59	road resistance of, 3-24
Type metals (table), 6-75 Type sizes, 19-43	standard designations for (table), 8- 54	solar powered, 9-17 Velocity (def), 3-10
Type sizes, 15-45	tensioning of drives for, 8-52 , 8-57	acoustic (def), 3-10
	V-bucket carriers, 10-45	angular (def), 3 -12
U-tube manometers, 16 -8	capacities and weights (table), 10-45	composition of, 3 -10, 3 -11
UART (universal asynchronous receiver-	V-guides, friction in, 3 -26	conversion table for linear and angular, 1 -32
transmitter), 15-83	V-notches, flow of water through, 3-57, 3-58,	hypersonic (def), 11-59
Ultimate analysis of coal (tables), 7-4	16-14 Vacuum, measurement of, 16-8	of light, 19 -41 resolution of, 3 -11
Ultrasonic machining, 13 -67	Vacuum gages, 16 -8	of sound: in ideal gases, 3 -31
Ultrasonic testing, 5-66	Vacuum pumps, for condensers, 9-83	in various media (table), 3 -32, 12 -117
Ultrasonic transducers, 5-66 Ultrasonics, 12-121	(See also High-vacuum pumps)	subsonic (def), 11-59
generation of, by whistle, 12 -122	Vacuum tubes (radio), 15 -71	supersonic (def), 11-59
industrial applications of, 12 -121	Valence of chemical elements (table), 6 -3	transonic (def), 11-59
for machining metal, 12 -122, 13 -67	Valves, 8-206	units of, 1-18
for testing materials, 12-122	for ammonia service, 8 -205 angle, 8 -206	Velocity coefficients, in turbine nozzles, 4 -23 Velocity diagrams (pumps), 14 -22
(See also Sound)	ball (pumps), 14 -13	Velocity distribution in pipes, 3-47 , 3-49
Underfeed stokers, 9-32	cocks, 8 -207	Velocity equivalents (table), 1 -32
Underground gasification, 7-35, 7-39	for compressors, 14-31	Velocity head (hydraulics), 3-37
Ungula, surface and volume of, 2 -8 Unified inch screw-thread standards, 8 -8	disks for, 8 -139	Velocity profiles, of fluids, 3-37
Unified screw-thread standards (See also Screw	gate, 8 -206	Velocity ratios (mechanism), 8-4
threads)	globe, 8 -206	Velocity-time curve (kinematics), 3-10
Uniflow engines, 9-55	head losses in (table), 12 -97 for high-pressure and high-temperature steam,	Venn diagrams, 2-2, 2-3 Ventilation, 12-61
Uniform distribution, 2 -10	8-185	outdoor air requirements for (table), 12 -67
Unijunction (semiconductor), 15 -71	hydraulic-power control, 8 -39	(See also Air conditioning)
Unions, pipe, 8-201	for hydraulic turbines, 9-156, 9-160	Venturi meters, 3 -54
Unit impulse (vibrations), 3 -69 Unit pole (magnetism), 15 -3	for reciprocating pumps, 14-4	ASME coefficients for (table), 3-54
Unit stress (def), 5-15	conical-faced wing-guided, 14 -5	factors for (table), 3 -54
Unit-train unloader, 10 -22	disk, 14-5	Venus, planetary data for (tables), 11 -102, 11 -103
U.S. customary system of units, 1-16	seats for, 8 -139 wedge gate, 8 -206	Vertex of parabola, 2 -19 Vertical-axis wind turbine, 9 -3
U.S. standard gages for sheet metal (table), 8-85	van der Waals equation, 4 -8	Vertical power pumps, 14 -3
United stirling engines, 9-21	Vanadium, in tool steel, 13 -49	Vessels (see Ships)
Units: of absolute and gravitational systems, 3 -2	Vapor, 4-13	Vibration:
table, 1-24	compressibility factors (chart), 4-8	absorption of, 3 -67
cgs system of, 1 -24	condensing, heat transfer coefficients for	axial, of shafts, 3-72
of common variables (table), 3-45	(chart), 4- 87 saturated (def), 4- 13	convolution integrals in, 3 -69 damped, 3 -62
electrical, 15-2	superheated (def), 4-13	of damped systems, 3-62
table, 15 -3	thermodynamic equations for, 4 -13	forced, 3-64
of heat (def), 4-3	Vapor-compression machines (refrigeration),	free, 3 -62
magnetic, 15 -3 table, 15 -3	4 -18, 19 -12	frequency of, measurement of, 16-3
systems of, 1-24	Vapor pressures (def), 4-13	with harmonic excitation, 3-64
Universal product codes, 10 -63	of water (table), 4-44	isolation of, 3-65
Unloaders:	Vaporization, latent heats of (tables), 4-50, 4-58 Vara (def), 1-16	caused by Kármán vortices, 12 -21 logarithmic decrement in (def), 3 -63
airslides for, 10-54	Variability (statistics), 17 -19	measurement of, 3-78
rotary car dumper, 10-22	Variance (statistics, def), 2 -10, 17 -19	of membranes, 3 -73
U.P.C. (universal product code), 10 -63 Upper atmosphere, 11 -59	Varnish, 6 -108, 6 -112	natural frequencies of, 3-71
Uranium, 9-137	catalytic, 6-112	natural modes of, 3-71
properties of (table), 6 -84	chemical-resistant, 6 -112	pickup of (sound), 12 -119
Uranus, planetary data for (tables), 11-102,	electrically insulating, 6 -138 flat, 6 -112	of plates, 3 -74 with proportional damping, 3 -72
11 -103	for floors, 6 -112	of rods, 3-72
Urea-formaldehyde adhesive, 6 -134	oleoresinous, 6 -108, 6 -112	self-excited, 3-21
USCS system of units, 1-16 USM (ultrasonic machining), 13-67	shellac, 6 -108, 6 -112	of shafts, 3-72
USIM (untrasonic machining), 13-6/	silicone, 6 -138, 6 -151	in ships, 11 -47
	spar, 6 -112	in space vehicles, 11 -104, 11 -117
V hand halts 9 55	spirit, 6 -108	stick-slip, 3-21
V-band belts, 8-55 V-belts, 8-54	water, 6 -112 Vars (reactive current, def), 15 -19	of strings, 3-72 of turbine blades, 9-62
cogged, 8-56	VAWT (vertical-axis wind turbine), 9 -3	of undamped systems, 3-62, 3-71
cross sections of, for required horsepower	Vector (def), 2 -11, 3 -2	unit impulse in, 3 -69
(chart), 8 -56	Vector addition, 2-11	Vibration absorbers, 3-67
groove dimensions for, 8-54	Vector calculus, 2-34	centrifugal pendulums as, 3-67
horsepower ratings for (tables), 8-56	Vector fields, 2-34	undamped, 3-70
length-correction factors for (tables), 8-54 , 8-55 minimum pulley diameters for (table), 8-54	Vector products, 2-11 Vegetables: effects of sulfur dioxide on (table),	Vibrators (mold making), 13-5 Vickers hardness test, 5-12
pitch lengths for, 8 -54	18-12	Vinyl resins: properties of (table), 6 -200
		· I I I I I I I I I I I I I I I I I I I

Viscometers, 3-33	Ward-Leonard method of speed control, 15-30	Water meters, 16-7, 16-14
Viscosimeters, 16-18	for mine hoists, 10 -17	Water pollution:
Viscosity (def), 3 -31, 6 -178	Warehousing, of materials, 10-62	control of, 6 -172
of cryogens, 19 -37	Washburn & Moen wire gage (table), 8-85	treatments for, 6 -173
dynamic (def), 3-31	Washers:	Water power:
of gases, table, 3-32	Belleville, 8-70	from tides, 9-21
kinematic, 3-33	for bolts, 8-21	(See also Hydraulic turbines)
conversion formulas for, 3-33	dimensions of (table), 8 -24 steam. 9 -51	Water quality (def), 6-169
of liquids (table), 3 -32 of lubricating oils, effects of pressure on, 6 -179	Waste disposal, solid, 18 -18	Water resources, 6 -168 Water runoff (def), 6 -169
effects of shear on, 6 -179	Waste recovery, 18-18	Water seals (packings), 8-140
tests for, 6 -178	of sewage as fertilizer (table), 18 -18	Water treatment (table), 6 -172
of oils, variation of, with temperature, 6 -179	Water, 6 -168	(See also Feedwater)
units of (def), 3 -31, 3 -33	agricultural (def), 6-169	Water-tube boilers, 9-36
Viscosity grades, for lubricants, 6-178	biological treatment for, 6 -173	Water turbines (see Hydraulic turbines)
Viscosity index, for lubricants (def), 6-179	boiler (see Feedwater)	Water vapor:
Viscous damping, in automatic control systems,	brackish (def), 6 -170	in air, 4 -15
16- 24	in chemical plants (tables), 6 -171	emissivity of (table), 4 -70
Vision, 12 -99	chemical treatment for, 6 -173	permeability, of various building materials
mesopic (def), 12 -99	compressibility of (tables), 6 -10	(table), 12 -69
photopic (def), 12 -99	consumption of (table), 6 -169	Waterproofed cement, 6 -160
scotopic (def), 12 -99	consumptive use (def), 6 -169	Waterproofed concrete, 6 -167
Vitallium (heat-resisting alloy, table), 6-79	cost of, 6-171	Watt (def), 1 -24, 15 -2
Vitrified grinding wheels, 6 -129 Vitrified pipe, 8 -191	critical pressure of, 9 -45 desalinization of, 6 -173	Watt-hour meters, 15 -23 Wattless current (def), 15 -18
table, 8 -194	costs of, 6 -174	Wattmeters, 15 -21, 15 -22
VLSI (very large scale integrated circuit), 15 -81	by distillation, 6 -174	polyphase, 15 -22
Voice recognition, 10-71	by electrodialysis, 6 -174	Wave equation, 2 -34, 2 -37
Voith-Schneider propulsion system (ships), 11 -55	energy required for, 6 -174	Wave-making resistance (ships), 11 -45
Volatility of liquid fuel (def), 9 -104	by flash distillation, 6 -173	Wave motors, 9-22
Volt (def), 15 -2	locations of plants, 6 -174	Wave power, 9-22
Voltage drops:	by reverse osmosis, 6 -174	Wavelength:
in a-c circuits, 15-54	dissolved oxygen in, 6-172	of light, 12 -99
Mershon diagrams for, 15-47, 15-49	domestic use of, average, 6-169	of radio waves (table), 15-87
Voltage regulation, of a-c generators, 15 -32	drinking, for industrial plants, 12-12	of sound, 12 -117
Voltage regulators:	for fire protection, 18 -26	Waves:
for automobiles, 15 -66	supply of, 18 -26	alternating-current, 15-18
Tirrell, 15 -34	flow of: in open channels, 3-59	radio, 15 -88
Voltmeters, 15 -20, 15 -21	through orifices, 3-55	Weber (magnetic flux, def), 15 -3
electronic, 15 -21	in pipes, 3 -47 to 3 -53	Weber's number, 3-42, 3-44
Volume: and capacity equivalents (tables), 1 -30, 1 -31	from tank openings, 3-60 over weirs, 3-57, 3-58	WECS (wind energy conversion system), 9-5 Wedges:
change under stress, 5-17	hardness of (def), 6 -170	friction of, 3 -26
conversion tables for, 1 -30, 1 -31	heat-transfer coefficients to or from, 4 -83,	spherical, volume of, 2 -9
measures of, 1-16	4 -84, 4 -86	Weighers, continuous, 16-4
of similar figures, 2 -5	industrial, 6 -171	Weighing scales, 16-4
of solids by immersion, 3 -36	for cooling, 6 -171	Weights:
units of (def), 1 -16	usage, 6 -171	atomic (table), 6-3
of various solids, 2-8	table, 6 -171	conversion table for, 1-31
Volumetric efficiency:	for industrial plants, 12 -12	corresponding to degrees API (table), 1-26
of compressors, 14 -30	ions in sea water (table), 6 -173	corresponding to degrees Baumé (table), 1-27
of internal-combustion engines, 9 -92	maximum usable, 6 -169	per cubic foot of various materials (table), 6 -7
Volute pumps, 14 -16, 14 -17	measurements of, 1 -16, 6 -169	equivalents (table), 1-31
Vortex theory of propellers, 11 -96	potable (def), 6 -169	fundamental equation of, 3-2
Vuilleumier refrigerating engine (cryogenics),	contaminant limits for (table), 6 -170	and measures: metric (see Metric measures
19-28 Vulcanized rubber, 6-147	as reactor coolant, 9 -140 saline (def), 6 -170	and weights) U.S., 1 -16, 1 -17
Vulcanized rubbel, 0-147	solubility, of inorganic substances in (table),	Weirs, 3-57 , 3-58 , 16- 14
	6-5	Cippoletti, 3-57
Waferboard, 6-126	solubility of, in gases (table), 6 -7	contracted, 3-58
Wage systems (industrial management), 17-10	specific gravity and density of (tables), 6 -10	hyperbolic, 3 -57
Waiting-line theory, 17 -9	temperatures of, for circulating water, U.S.	parabolic, 3 -57, 16 -14
Wakes in fluid streams, 3-47	(map), 9 -77	rectangular-notch, 3 -57, 3 -58, 16 -14
Walls:	thermal conductivity of (table), 4 -82	Sutro, 16 -14
building: heat gain through (tables), 12 -72	withdrawal use (def), 6 -169	trapezoidal, 3-57
thickness of (table), 12-26	Water brake, 16 -15	triangular-notch, 3 -58, 3 -59, 16 -14
corrugated sheeting for, 12 -25, 12 -42	Water gas, flame temperatures of (table), 4-29	V-notch, 3 -57 to 3 -59, 16 -14
masonry, coefficients of heat transmission for	Water hammer (def), 3-61	Welded connections, 13-32
(table), 12- 71	in penstocks, 9-160	effective throats for, 13-33
reinforced-concrete, 12-25, 12-59 retaining, design of, 12-27, 12-59	in pipelines, 3-61 relief devices for, 3-61	fillet welds for, 13 -32 groove welds for, 13 -33
sound-absorption coefficients for (table),	Water index (def), 6 -169	joint types for, 13-32
12-121	Water-jet machining, 13 -67	weld types for, 13-32
sound-transmission loss through (table), 12 -120	Water jets:	Welding, 13-24
of various constructions, heat-transfer coeffi-	abrasive, 6 -130	of aluminum, 13-44
cients for table, 12 -75	impact of, 3 -40	of aluminum alloys, 13 -44
Wankel engines, 9-102	for ship propulsion, 11-55	welding procedures for, 13-45

W. I.V. (G.)	W. I. (G.)	W
Welding (Cont.):	Welding (Cont.):	Wind energy conversion systems, 9-5, 9-8
arc, 13 -24 electrodes for, 13 -24	spot, 13 -29 of structural steel, 12 -41	economics of, 9 -10 Wind pressure:
carbon, 13 -24	ultrasonic, 13 -30	on buildings, 12 -19
consumable, 13-24	Weldments, 13-24	distribution of, 12 -19, 12 -21
tungsten, 13-24	Welds, 13 -32	on roofs, 12 -19, 12 -21
electrogas, 13-28	allowable strength of, 13-33	on structures, 12-19
electroslag, 13-28	aluminum, 13-44	on towers, 12 -21
filler metals for, 13-24	aluminum alloys, 13-44	Wind tunnels, 11 -76, 11 -77
flux cored, 13-25	welding procedures for, 13-45	intermittent, 11-76
advantages of, 13-26	base metals for, 13-42	shock tubes for, 11-76
equipment for, 13-26	austenitic stainless steels as, 13-44	supersonic, 11-76
procedures for, 13-26 fluxing of, 13-25	duplex stainless steels for, 13-44 ferritic stainless steels as, 13-44	transonic, 11-77 Wind turbines, 9-5
fluxing of, 13-25	high-carbon steels as, 13-43	blade-element theory for, 9 -6
fundamentals of, 13-24	hot cracking of, 13-44	Darrieus rotor, 9-5, 9-7
gas metal, 13 -27	low-alloy steels as, 13-43	general momentum theory of, 9-5
gas-shielded, 13-26	low-carbon steels as, 13-43	horizontal-axis, 9-5
gas tungsten, 13-28	martensitic stainless steels as, 13-44	vertical-axis, 9-7
globular transfer, 13-28	medium-carbon steels as, 13-43	augmentation of, 9-7
metal cored electrodes for, 13-28	precipitation-hardening stainless steels for,	blades for, 9-7
pulsed arc, 13 -28	13-44	drag devices as, 9-7
heat for, 13 -24 metal inert gas, 13 -27	sensitization of, 13-44 stainless steels as, 13-43	rotor configurations for, 9-7 Windmills (<i>see</i> Wind turbines)
microwire, 13 -27	cast iron, 13-44	Window glass, 6 -142
miniwire, 13 -27	fatigue strength of, 13 -38	Windows:
nontransferred arc, 13-29	Goodman diagram for, 13 -40	glass, shading coefficients for (tables), 12 -81,
plasma arc, 13 -29	filler metals for, 13-33	12 -82
process selection, 13-25	allowable shear value for, 13-34	for industrial plants, 12-11
self-shielded, 13-26	strength for, 13-33	Winds:
shielded metal, 13-25	fillet, 13 -32	gusts, 12 -21
manual, 13-25	allowable loads for (table), 13 -34	power in, 9 -8
stick, 13 -25	in structures, 12-41	on structures, pressure coefficients for (table),
shielding of, 13 -25 by gas, 13 -25	forces on, general formulas for, 13 -36 full-strength, 13 -33	12 -20, 12 -23 velocities of, 12 -19, 12 -21
by slag, 13 -25	intermittent, 13 -36	in the United States (table), 9 -9
short arc transfer, 13 -27	length of, 13 -36	Wings, aircraft (<i>see</i> Airfoils; Airplanes, wings)
spray arc transfer, 13 -27	spacing of, 13 -36	Winkler process (gasification), 7 -37
submerged-arc, 13-27	matching filler and base metal in (table),	Winter outdoor temperatures (chart), 12-63
advantages of, 13-27	13 -40	Wire:
multiple-electrode, 13-27	metal, strength of, at low temperatures,	airplane, 11-69
twin, 13 -27	19-34	copper (see Copper wire)
transferred arc, 13-29	metals for, allowable stresses in (table),	electrical, colors for, 15 -61
braze, 13 -29 of cast iron, 13 -44	13 -40 primary, 13 -33	insulated, types of, 15 -56 table, 15 -57, 15 -58
connections, 13-32	secondary, 13 -33	magnet (table), 15 -65
(See also Welded connections)	under simple loads, 13 -35	steel: gage of (table), 8 -85
of copper, 13-45	size determination of, 13 -36	Wire gage:
welding procedures for, 13-45	sizing of, 13 -33	table, 8 -85
of copper alloys, 13-45	subject to bending, 13-36	American (table), 15 -5
welding procedures for, 13-45	subject to horizontal shear, 13-35	annealed copper (tables), 15 -52, 15 -56, 15 -57
drafting symbols for (chart), 13 -33	general rules for, 13-35	Wire glass, 6 -142
electron beam, 13 -30	subject to twisting, 13-36 Weston cells, 15-12	Wire-guided vehicles, 10-36, 10-56
explosion, 13 -31 friction, 13 -30	Wet-bulb psychrometers, 4 -15	Wire nails (tables), 8 -82 to 8 -84 Wire rope, 8 -75, 10 -8
gas, 13 -29	Wet-bulb temperature, 4 -15, 12 -87	bending-life factors for (table), 8 -80
by acetylene, 13 -29	isoclines of (map), 9-84	brakes for, 10 -10
with carburizing flame, 13 -29	Wet cells (electricity), 15 -13	common, cross sections of (fig), 8 -76
with neutral flame, 13-29	Wetted perimeter (hydraulics), 3-37	cores for, 8-77
with reducing flame, 13-29	Wheatstone bridges, 15 -25	cutting of, 8 -79
laser beam, 13-30	for strain gages, 5 -53	drums for, 10 -9
continuous wave, 13-30	Wheels:	fittings for, 8- 80, 10- 9
pulsed, 13 -30 of piping, 8 -209	and axles (railway), 11 -31 friction coefficients for, 3 -25	for haulage, 10 -8 for hoisting, 10 -8
preheating for, 8 -211	tables, 3-25	drums for, 10 -9
projection, 13 -29, 13 -30	White cast iron (def), 6-13 , 6-38	idlers for, 10 -9
resistance, 13-29	White coat (plastering), 6 -163	IWRC, 8-77
electrodes for, 13-29	White iron (def), 6-42	lang-lay, 10 -8
machines for, 13-30	Whitworth quick-return motion, 8-3	load suspension with, 10-8
process of, 13-30	Wide-flange beams, properties of (tables),	lubrication of, 10-8
projection, 13 -29, 13 -30	12 -36	materials for, 8-77
seam, 13 -29	Williams and Hazen formula in pipeline flow,	nominal strength of (table), 8 -78
spot, 13 -29	11-131 Williams solf filling buckets 10 11	for power hoists, 10-8
safety, 13 -45 seam, 13 -29	Williams self-filling buckets, 10 -11 Wind-chill index, 12 -62	rotation-resistant, cross-sections of (fig), 8-77
solid state, 13 -30	table, 12 -62	seizings for, 8 -79
sonic, 12 -122	Wind-electric energy conversion, 9 -9	table, 8 -81
	,	•

Wire rope (Cont.):	Wood (Cont.):	Workers, selection of, 17-11
selection of, 8 -77	insect attacks on, 6 -127	Workman's compensation laws, 18 -19
sheaves for, 10 -10	internal friction of, 6 -116	Workplace design, 17-26
allowable radial bearing pressures on	marine-organism attacks on, 6 -127	Workstations, computers as, 2-45
(table), 8-79	mechanical properties of, 6 -113	Worm gears, 8 -99
special constructions, cross-sections of (fig),	moisture content of, 6 -113, 6 -126	Worm hoists, 8-8
8-77	moisture relations of, 6 -113	Worthington feather valve (compressor), 14 -32
tackle for, efficiencies of (table), 10 -10	naturally durable, 6 -126	Wrench openings, standard (table), 8- 20
terminators for, 8 -80	old, strength of, 6 -127	Wronskian determinant, 2 -32
track cables of, 10 -9	power factor of, 6 -118	Wrought-aluminum alloys, 6-53
table, 10 -9	preservative treatments for, against biological	Wrought iron (def), 6 -13
Wiredrawing (fluid flow), 4 -24	action, 6 -127	
5 ,	methods of, 6 -127	pipe (see Pipe, wrought-iron)
Wiring: calculations for: for a-c circuits, 15 -54	preservatives for, 6 -127	Wrought-magnesium alloys (table), 6 -86 Wythe (masonry, def), 12 -27
for d-c circuits, 15 -53	properties of (table), 6 -115	wythe (masonry, der), 12-27
interior, 15 -55	rheological properties of, 6 -116	
cable for, 15 -57		X-ray diffraction, uses of, 16-18
	sanding recommendations for (table), 13 -76	X-rays, testing with, 5 -65
conduit and tubing for, 15 -56	sapwood (def), 6 -113	Xylene, as solvent, 6 -149
grounds for, 15-59	shrinking or swelling of, 6 -113	rigione, as sorvein, o riv
insulation for, 15 -56	treatments to prevent, 6 -113	
table, 15 -58	slope of grain of (def), 6 -116	Y connections, three-phase circuits, 15-20
open, 15 -56	soapy, friction of, 3-22	Y level (surveying), 16 -52
protective devices for, 15 -61	softwood (def), 6 -113	Yachts, maximum safe power for, 11-46
switches for, 15 -57	sound transmission in, 6 -118	Yamauti principle (radiation), 4 -66
Wiring diagrams, for generator switchboards,	specific gravity of, 6 -116	Yard (def), 1 -16
15 -45	specific gravity and density of (tables), 6 -7,	Yarns (tables), 6 -141
Wittenbauer's analysis for fly-wheel perform-	6 -115	Yaw (airplanes), 11-71
ance, 8 -66	specific heat of, 6 -117	(ships, def), 11 -45
WJM (water-jet machining), 13-67	strength of, 6 -113, 6 -116, 6 -119	Year:
Wolfram (see Tungsten)	bolted (table), 12 -31	definitions of, 1-25
Wood, 6 -112	effect of age on, 6 -127	lengths of, sidereal and tropical, 11-101
allowable stresses for (tables), 6-115 to 6-124,	effect of heat on, 6 -117	Yield point (def), 5-3
12 -28 to 12 -30	effect of moisture on (table), 6-116	lower (def), 5 -3
beams, 12 -28, 12 -29	tables, 6 -115 to 6 -126	upper (def), 5 -3
char rate of, 6 -117	for various grain slopes (table), 6 -117	Yield strength (def), 5-2
chemical composition of, 6 -113	structural members of, fire resistance of	of metals (table), 5-3
classification of, 6 -113	(table), 12 -48	Yield-tensile ratio, 13-11
columns, 12 -30	swelling of, in liquids, 6 -113	Young's modulus (def), 5 -2, 5 -17
construction, 12-28	thermal conductivity of, 6 -117	
decay of, 6 -127	trusses of, joints for, 12 -31	
density and specific gravity, 6-116	walls of, stud, 12 -25	z-transfer function (automatic control), 16 -39
as dielectric, 6 -118	weight density of, 6 -116	z transformation (automatic control), 16 -38
dielectric constant of, 6-118	Wood alcohol, 6-148	Zeolite process (feedwater treatment), 9-48
dimensional stability of, 6-113	Wood pulp in paper manufacture, 6-144	Zinc:
electrical properties of, 6 -118	Wood screws, 8-21	alloys of, 6 -93
electrical resistivity of, 6 -118	Wood-stave pipe, 8-191	commercial, composition of, ASTM specifica-
fatigue properties of, 6 -116	Wood waste as fuel, 7 -9	tions for (tables), 6 -93, 6 -94
fire-retardant treatments for, 6-127	Woodruff keys, 8-31	corrosion resistance of, 6 -93
flame speed in, 6-117	table, 8 -32	die castings of, 6 -93
flooring, safe loads and deflections (table),	Wood's metal, 6-76	composition and properties of (table), 6 -94
12 -28	Woodworking machines, 13-72	dust, in paint, 6-109
as fuel, 7 -9	Wool fibers (tables), 6 -141	effect of temperature on, 6 -94
analysis of (table), 7-9	Word (computers, def), 2-41	fabrication of, 6 -93
heat value of (tables), 7-9	Word processors, 2-54	galvanizing, 6 -93
fuel value of, 6-117	Work (def), 3-2, 3-17	rolled, 6 -93
fungi in, 6 -127	computation of: diagram for, 3-17	white, in paint, 6-108
glue-laminated, 6 -123, 6 -124	rule for, 3-17	wrought, 6 -93
allowable stresses in, 6-123	conversion tables for, 1-33	Zirconium, 6 -84, 6 -92
(See also Plywood)	of friction, 3-25	mechanical properties of (table), 6-84
hardness test for, 5-13	muscular, 9-4	in nuclear technology, 6 -84
hardwood (def), 6-113	units of (def), 1 -18, 3 -17	slow neutron absorption cross-section (table),
heartwood (def), 6-113	Work hardenability, determination of, 5 -13	6 -82
heat of combustion of, 6 -117	Work-hardening exponent (def), 5-4	uses of, 6 -93
heat value of, 6 -117	Work measurement, 17-28	Zones, of spheres, area of (formula), 2-9
•	•	